Cessna 182Q, G-IRPC

AAIB Bulletin No: 11/97 Ref: EW/G97/08/30Category: 1.3

Aircraft Type and Registration:	Cessna 182Q, G-IRPC
No & Type of Engines:	1 Continental O-470-U piston engine
Year of Manufacture:	1977
Date & Time (UTC):	22 August 1997 at 1200 hrs
Location:	Gloucestershire Airport, Cheltenham
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 3
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Nose landing gear lower leg attachment bracket cracked
Commander's Licence:	Private Pilot's Licence with IMC and Night Rating
Commander's Age:	55 years
Commander's Flying Experience:	169 hours (of which 54 were on type)
	Last 90 days - 11 hours
	Last 28 days - 5 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The aircraft was being flown from Perranporth Airfield, Cornwallto East Midlands Airport when the pilot noticed that the ammeterwas indicating a discharge; the low voltage warning light wasnot illuminated. He reported that, to conserve power he turnedoff the strobe lights, the beacon and one of the radios. He attempted o make radio contact with Bristol Filton ATC but was unsuccessful. He decided to land as soon as possible and tried to contact GloucestershireAirport; again this was unsuccessful.

The weather was fine and the surface wind was westerly at about5 kt. The pilot selected 7,600, the radio failure code, on the transponder and flew around the airfield at 1,500 feet agl. Hesaw an aircraft take off from Runway 27 and, seeing no conflicting traffic, decided to land on that runway. The flaps are electrically operated and failed to lower when selected so he decided to doa flapless approach and landing. A high descent rate led to aheavy landing and go-around; the subsequent landing was normal.

A post accident inspection of the aircraft revealed that therewas a crack in the lower leg attachment bracket which appeared to have been a consequence of the recent heavy landing. The batteryelectrolyte level was found to be slightly low and was toppedup; when reinstalled the electrical system was checked and nofault was found.