

Lockheed L188C, G-LOFA

AAIB Bulletin No: 5/97 Ref: EW/A96/7/2 Category: 1.1

Aircraft Type and Registration:	Lockheed L188C, G-LOFA
No & Type of Engines:	4 Allison 501-D13 turboprop engines
Year of Manufacture:	1959
Date & Time (UTC):	30 July 1996 at 1941 hrs
Location:	Near Berlin Schonefeld Airport, Germany
Type of Flight:	Cargo
Persons on Board:	Crew - 5 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Localised tearing of structure and failure of rivets in region of freight-door aperture, distortion of crown skin, failure of door operating mechanism and damage to door securing shoot bolts. Flattening of forward end of dorsal fin
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	36 years
Commander's Flying Experience:	5,880 hours (of which 850 hours were on type) Last 90 days - 145 hours Last 28 days - 6 hours
Information Source:	AAIB Field Investigation

Investigation authority

The accident notification and initial investigation was carried out by the German authorities. However, as the aircraft and crew were based in the United Kingdom and the aircraft was due to be returning to its home base at Coventry Airport after temporary repair, the AAIB offered to complete the investigation. Subsequently, in accordance with Chapter 5.1 of Annex 13 to The Convention on International Civil Aviation, the German authorities delegated the investigation to the United Kingdom.

History of the flight

The crew arrived at the aircraft at 1850 hrs for a planned flight to Cologne-Bonn; they had operated the aircraft on the previous flight from Cologne-Bonn and had spent the day resting in an hotel. In

addition to the normal complement of commander, first officer, flight engineer and ground engineer, there was a trainee flight engineer with the crew. When they arrived at G-LOFA, the ground staff were around the aircraft, the doors were shut, external power was connected and steps were adjacent to the crew door.

While the flight crew went to the cockpit to complete their normal pre-flight duties, the ground engineer carried out a daily maintenance check and signed for this in the aircraft Technical Log. The flight engineer and his trainee also went to the cockpit where the flight engineer demonstrated his duties to the trainee. Once the company handling agent had been to the cockpit to inform the commander that loading was complete and had left with his copies of the Technical Log entry and Load Sheet, the commander initiated the pre-start checks. As he did so, the ground engineer entered the aircraft and closed the crew door; he had confirmed that the other external doors were shut by ensuring that they were flush with the fuselage and confirmed that the appropriate door open indicating lights were not illuminated on the instrument panel.

For the subsequent engine start and flight, the flight crew occupied their normal seats while the trainee flight engineer was in the cockpit 'jump seat' and the ground engineer was in the courier seat (located between the flight-deck bulkhead and the 9G cargo bulkhead). The cockpit door was open in accordance with normal company regulations with the courier seat occupied. Engine start was normal and no abnormal indications were noted then, or during the subsequent taxiing to Runway 25. Pre take-off checks were completed and the commander, as handling pilot, carried out the take-off and established the aircraft in the climb. The after take-off checks were completed and during these, the flight engineer confirmed that pressurisation was satisfactory; the aircraft was pressurising in accordance with his selection. As these checks were being actioned, the ground engineer went back to the cargo compartment.

As the aircraft climbed through Flight Level (FL) 60, the ground engineer came back to the cockpit and informed the commander that there appeared to be 'smoke' in the cargo compartment. The crew checked the appropriate systems, but detected no warnings. On this aircraft, the 'cargo smoke' warning light was immediately adjacent to the 'cargo door open' warning light located in front of the first officer. Shortly afterwards, as the aircraft was passing FL 115, with the ground engineer in the cockpit and the cockpit door shut, there was an explosive decompression. The cockpit door detached from its hinges and the cockpit filled with fine debris. The aircraft rolled right, pitched down and the crew were immediately conscious of significant airframe vibration. With the aircraft in cloud, the commander regained level flight using minimum and gentle control inputs. As he did so, the other crew members were making a thorough check of the aircraft systems. The flight engineer prepared to activate the crew oxygen but, with the aircraft descending below FL 100, decided that it was not required. The only apparent problem was the loss of aircraft pressurisation, but the commander was concerned about structural integrity. He therefore instructed the first officer to ask for radar vectors and a priority return to Schonefeld, and then commenced a shallow turn back towards the airfield.

As the flight crew were carrying out these actions, the ground engineer went back to the cargo compartment to ascertain what damage had occurred. There was cargo positioned close to the cargo door but the engineer was able to see daylight where the door should have been. As he got closer, he could see the door jacks still connected between the frame and the door, and estimated that the door was then open by approximately one foot. However, after moving closer to the open door, he became aware that the door jacks and door were no longer visible. From his position, he could partly see the left stabiliser and observed no obvious signs of damage. He then returned to the cockpit and reported to the commander that the cargo door was open.

By this time, the commander had established on track to Schonefeld at 180 kt. The vibration, although still significant, had reduced slightly. ATC offered the crew radar vectors for an approach to Runway 25 but taking into account the light surface wind the crew requested, and were granted, the more expeditious approach to Runway 07. For the recovery, the normal checks were completed apart from the decision to use less than full flap. This was selected gradually and at 78% flap, speed was reduced to 150 kt and the landing gear was lowered. With no control problems evident in this configuration, the commander decided to use 78% flap for landing and the appropriate threshold speeds were calculated. The subsequent landing on Runway 07 was uneventful and the cargo door swung back into view as the speed reduced on the runway. After parking the aircraft on stand and securing the engines, the crew noted that the 'cargo door unlocked' light was still not 'on' and that the main annunciator door warning light only illuminated when the crew door was opened.

The commander then disembarked from the aircraft and went to the open cargo door. He noted that the external door warning light located beside the cargo door was illuminated. On returning to the cockpit, he noted that the 'cargo door unlocked' warning light still appeared to be unlit but, as he touched it, he became aware that it was illuminated but that its brilliance could be varied from 'full off' (where it had been set) to 'full bright'.

Subsequent enquiries revealed that the cargo door was closed by a member of the airport ground staff. He was certain that the door had been correctly closed and that the adjacent external 'door unlocked' warning light had gone out.

Door design

The freight door on the aircraft was one of a variety of designs on Lockheed L188 aircraft on the British register, being a Supplementary Type Certificate (STC) modification of the original passenger-carrying L188, under STC number ST 852SO. It is understood to be the largest of the door designs available and is both actuated and latched by an electro-hydraulic system controlled normally from a switch under a hinged panel on the outside of the fuselage, near the door.

The door is hinged at the top and is secured in the closed position by a system of seven horizontal 'shoot-bolts' mounted at the junction of the fuselage side and the cabin floor. These are hydraulically driven and pass through a system of lugs attached to the doorsill. When the door is fully closed, the shoot-bolts engage in a set of corresponding lugs attached to the lower ends of seven frame members within the door structure. Thus the hoop loads due to cabin pressurisation are carried across the door aperture when the aircraft is in flight.

Two lights should be located under the hinged panel beside the external door operating switch, one of which should illuminate whilst the hydraulic door operating motor is running, the other illuminating whilst any of the door latching shoot-bolts are not fully engaged.

Aircraft examination

Examination of the aircraft showed that the door had not been fully latched at the time of departure, *ie* the seven tapered shoot-bolts were only partly engaged. The hoop loading due to pressurisation had become sufficient, as the aircraft climbed, to effectively 'guillotine-off' the small diameter ends of the bolts and thus release the door. Extensive damage to the fuselage structure in the area of the door aperture had occurred, and failure of the door operating mechanism had allowed the door to overtravel open to such an extent that the foremost section of the dorsal fin had been 'flattened' by

door contact and numerous rivets had failed in the fuselage structure. Local tearing of structural members had also occurred.

Door mechanism and warning system

A detailed study of the door showed that it was of a design which could not be reliably checked for correct security from outside. Opening, followed by re-closing and latching of the door illuminates and then extinguishes the door-latched light beside the operating switch to indicate that the door has correctly sequenced to the latched condition, with all seven bolts fully engaged. Once the door is closed, however, the shoot-bolts cannot be viewed from outside the aircraft and the relevant area inside the fuselage cannot be accessed if the rear of the hold is occupied by freight containers.

The associated cockpit warning in the STC modification consisted of the routing of the 'freight door unsafe' warning signal through the 'cabin doors unsafe' annunciator light.

The arrangement of the system on G-LOFA contained a number of modifications relative to the STC design standard and also contained some wiring changes which had either been made after the STC modification was complete, or were the result of failure to fully incorporate the STC features.

In particular, the wiring of the 'freight door unsafe' signal to the 'cabin doors unsafe' annunciator was completely absent, although a dedicated 'freight door unsafe' warning light, originally positioned beside the crew entry door (along with an alternative operating switch, which had been deleted at some time prior to this accident) had been re-positioned on the co-pilot's panel. This light had a dimming facility which had the ability to dim to such an extent that the light filament could become completely obscured. The light could thus be 'ON', yet not visible to the crew. Its 'press to test' facility, a feature of the STC modification, was also totally absent from this aircraft and there was thus no ready means of realising that the light was set to the 'bulb fully obscured' position.

Under all normal sequences of aircraft operation, the forward crew entry door would have been closed last, and so there were normally no circumstances when the crew would have been in the cockpit with the freight door open and all other doors closed. The absence of any warning on the 'freight door unsafe' annunciator, when the freight door was open or not correctly latched, would therefore never have been evident to any crew members.

The second of the two lights beneath the external hinged panel, intended to illuminate when the hydraulic motor was running, was absent from the aircraft.

Documentation

The Electra 188 C Operating Manual, a copy of which was held in the aircraft, incorrectly stated that the 'doors unsafe' annunciator would illuminate if any cabin door was not closed and latched. This statement not only failed to draw attention to the fact that the freight door warning was not connected to the annunciator on G-LOFA, but was ambiguous in failing to mention that the rear emergency door (on the right side) was also not monitored by the annunciator system. This last discrepancy appears to have existed in the Operating Manual since it was written for the original passenger aircraft in 1959.

A Flight Manual Supplement covering the freight door modification included a wiring schematic diagram which showed the 'freight door unsafe' signal as passing through the 'cabin doors

unsafe'annunciator. In this respect it agreed with the STC design standard but did not reflect the modification standard of G-LOFA.

Modification status

The STC modification incorporating the freight door on G-LOFA was designed by Aeronautical Engineers Inc (AEI) of the USA. At some later date it appears to have been modified in accordance with hydraulic and electrical system drawings produced by General Air Services Inc, also of the USA, to change from a system using a micro-switch operated sequence valve to one of a hydraulic pressure operated priority valve to control the sequence of door closing motion and shoot-bolt engagement. It is not known when the changes to the wiring of the warning system were made from the AEI standard or to what extent, if any, the AEI design was not fully implemented at the time the original freight door modification was incorporated.

In summary, the study of the STC and details of its implementation on G-LOFA showed that:

- 1 The STC door design presents considerable difficulties in establishing reliably the state of door security after closure.
- 2 The wiring of the door warning system differed from that in the STC and from the schematic in the Flight Manual Supplement for the freight door. Some of these wiring differences undermined the logic of the warning arrangements.
- 3 The dedicated warning light on the co-pilot's panel was designed so that its 'dimming' function could be adjusted such that it completely obscured the warning, yet had no placard warning to that effect.
- 4 Important safety related information in the Electra 188 C Operating Manual on board the aircraft was incorrect.

Safety Recommendations

In view of the potentially critical consequences that can arise from the in-flight opening of aircraft doors, and since this event could have resulted in a serious accident, the following Safety Recommendations have been made to the CAA and FAA.

96-66: In order to prevent the freight doors on Lockheed L188 Electra freighter aircraft from opening in flight, as a result of failure to ensure correct latching of such doors before flight, the CAA should require that the following safety action is applied to all such aircraft on the UK register, and the FAA should require the same safety action for all other such aircraft worldwide:

- 1 An inspection to confirm that the 'cabin-doors unsafe' annunciator illuminates when the freight door is not in the closed and fully latched condition, and when all other cabin doors are in a fully safe condition.
- 2 An examination of any wiring diagrams or schematics of the door warning system in L188 Flight Manual supplements and Maintenance Manuals to confirm that they correctly represent the state of the wiring of the individual aircraft to which they apply, are in accordance with an FAA approved design and have been the subject of a design safety analysis.

3 The revision of the Electra 188C Operating Manual to identify any door(s) which are not monitored by the 'cabin-doors unsafe' annunciator once the above actions have been carried out.

4 Consideration be given to providing a clear physical warning, in addition to the existing locks unsafe light, of the absence of correct lock engagement, visible from outside of outward opening freight doors on L188 freighter aircraft.