

BAC 1-11 408EF, G-AVGP

AAIB Bulletin No: 2/97 Ref: EW/C96/2/2 Category: 1.1

Aircraft Type and Registration:	BAC 1-11 408EF, G-AVGP
No & Type of Engines:	2 Rolls-Royce Spey 511-14 turbofan engines
Year of Manufacture:	1967
Date & Time (UTC):	13 February 1996 at 2142 hrs
Location:	Aldergrove, Belfast
Type of Flight:	Public Transport
Persons on Board:	Crew - 5 - Passengers - 14
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Flexible hydraulic brake hose ruptured
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	35 years
Commander's Flying Experience:	4,270 hours (of which 2,940 were on type) Last 90 days - 98 hours Last 28 days - 39 hours
Information Source:	AAIB Field Investigation

History of the flight

The initial part of the flight proceeded without incident but upon reaching a position approximately 30 miles southeast of the Isle of Man VOR, the crew noted that the No 2 hydraulic system contents had fallen to just inside the red sector of the associated indicator.

The QRH drill for low hydraulic contents was carried out and a PAN call made to Scottish Area Control Centre. In view of the runway length available at Aldergrove (2,777 metres), the planned destination, a decision was made to continue the flight and a successful approach and landing was carried out using 45° flap. After touchdown, normal reverse thrust was used followed by minimal application of the foot brakes; however, as the aircraft decelerated through about 30 kt the foot brakes failed completely and the aircraft was brought to rest using the parking brake.

During the rollout the airport fire service, which had positioned behind the aircraft, reported that smoke could be seen coming from the aircraft and the commander therefore instructed the

cabin crew to evacuate the passengers from the forward door using the airstairs, as soon as the aircraft stopped on the runway. However, the loss of hydraulic pressure prevented the L1 airstairs from being extended under power and a decision was taken to deploy the associated emergency slide. The evacuation was carried out successfully and there were no injuries.

Subsequent examination of the aircraft by maintenance personnel identified a leak from a flexible hydraulic pipe supplying the outboard wheel brake on the left main landing gear. The pipe was replaced with a serviceable item, and after replenishment and bleeding of the hydraulic system, the aircraft was returned to service.

The failed pipe was subsequently examined by AAIB on 15 March 1996, after the aircraft had returned to Birmingham. G-AVGP, and three other BAC 1-11 aircraft from the operator's fleet which happened to be parked on the stands at Birmingham, were also inspected with a view to obtaining a better understanding of the failure on G-AVGP, and to establish whether other aircraft were similarly affected.

Flexible pipe arrangement

Figure 1a shows the locations of the relevant pipes. There are three flexible brake pipes on each landing gear, the outer pair providing individual *primary* supplies to each brake unit, and the centre pipe providing a common *stand-by* supply. The detailed construction of the pipes can differ, but the pipe in question comprised a PTFE pressure tube inside an outer structural sheath of braided steel, which in turn was encased in a thin plastic outer sleeve.

At their upper ends, all three brake pipes connect to an articulated walking joint assembly, see Figure 1b. At their lower ends, the *primary* pipes pass through hard nylon support bushes fixed to the lower part of the landing gear leg (the manifold bracket assembly), approximately 150 mm (6 inches) above the end connections to their respective shuttle valves, as shown in Figure 1c. The bottom end of the stand-by pipe connects to a manifold assembly, also fixed to the lower section of the leg, which supplies the opposite ends of each shuttle valve via short sections of rigid pipe.

Pipe failure details

The pipe on G-AVGP, bearing the part number EN43-A435, had failed at the point where it passed through the (hard nylon) lower support bush, at approximately the position shown in Figure 1c. Deterioration and breakdown of the plastic sleeve at this location had allowed abrasion of the steel braid, leading to failure of numerous strands of the braid and a pressure-induced rupture of the plastic inner tube. Figure 3a shows a close-up view of the failure region.

The diagram at Figure 2 shows the position of the failure on the pipe. In addition to the abrasion and chaffing on the lower section of the pipe which had led to the failure, three additional areas of chaffing damage were evident: two on the upper regions of the pipe and a third slightly below the rupture location at the bottom of the pipe; these are also shown in Figure 2. The abrasion damage in the region 200 mm to 210 mm (7.9 inches to 8.3 inches) was consistent with fretting contact between the curved part of the pipe and the scissor-link element of the walking joint assembly. The damage region between 365 mm and 390 mm (14.4 inches and 15.4 inches) was positioned well away from any part of the walking joint, and had evidently been caused by rubbing contact against the inside face of the outboard main wheel tyre.

Other flexible brake pipes on G-AVGP

The other three *primary* brake pipes on G-AVGP exhibited similar chaffing damage in the area where they passed through the lower support bushes, and the sharp ends of broken strands of braid could be felt adjoining the edges of the bushes on two of these pipes.

It was noted that the replacement pipe fitted to G-AVGP following the incident was of a larger diameter than either the original (failed) pipe or the adjoining pipe on the left gear. It was also of markedly different construction, with a thick textile outer protective sheath in place of the thin plastic sheath. The corresponding pipes on the right landing gear were of yet different construction, having the larger external diameter of the replacement pipe, but with an outer protective sheath of braided steel. It was noted that the larger diameter variants of the pipes were a relatively snug fit in the lower support bushes (the chaffing location), whereas the smaller diameter pipes were a very loose fit, to the extent that they were free to 'rattle around' in the bush.

Service bulletin PM 5633

The flexible pipes originally fitted to BAC 1-11 aircraft were assembled from 12.1 mm (0.475 inches) outside diameter (OD) flexible hose having a rubber core. In 1979, Service Bulletin PM 5633 introduced a modification to replace rubber-cored flexible hydraulic hoses with PTFE-cored hoses. In the case of the main landing gear walking joint hoses, the Service Bulletin specified replacement of the main brake hoses with a *post-mod* standard pipe carrying the British Aerospace part number EN43-A435; new post-mod standby brake hose and upper clamp blocks were also specified. The 'description' part of the Service Bulletin states,

"To cater for a reduction in outside diameter on new nose wheel steering feed hoses and an increased outside diameter on new M.L.G walking joint hoses, new clamp blocks are introduced."

The nominal diameter of the post-mod pipes was 12.7 mm (0.500 inches). On the issue of interchangeability, the Service Bulletin states that,

".....the nose undercarriage steering feed and main undercarriage walking joint hoses must be replaced as complete hose assemblies, as new clamp blocks are required to cater for revised outside diameter of post-mod hoses. Pre and post-mod affected hoses should not therefore be mixed."

It is notable that whilst the Service Bulletin addresses the issue of replacement clamp blocks at the top ends of the pipes, in order to accommodate the increase in OD from 12.1 mm to 12.7 mm (0.475 inches to 0.500 inches), no mention is made of how this diameter difference is accommodated at the lower support bushes.

The part number marked on the pipe which had failed on G-AVGP was EN43-A435, the post-mod part number. However, contrary to the statement made in the Service Bulletin that the post-mod pipes were of increased diameter, the failed pipe utilised a PTFE type pressure hose of smaller outside diameter, 9.8 mm (0.385 inches) OD, and witness marks at the top end of the pipe suggested that the upper clamp block had been sized to match this reduced diameter.

Pipe manufacture

The BAe assembly drawing for the post-mod pipes comprises, in effect, a table of part numbers, dimensions, and other data which define a range of the flexible pipes used on BAC 1-11 series aircraft, including the brake pipes in question. For each of the pipes covered by the drawing, the table specifies flexible hose types from two alternative manufacturers, Aeroquip and Fliteline, by reference to those manufacturers' own part numbers. The drawing makes no explicit reference to

hose-stock diameter, but in the case of main landing gear walking joint pipes (and nosewheel steering feed pipes), the drawing states that where these are assembled using Aeroquip hoses, two diameter-increasing external sleeves must also be fitted at specified positions; one near the top end of the pipe and the other near the bottom. The additional sleeves are evidently not required in the case of pipes assembled from Fliteline hoses.

BAe manufacturing procedures require that the various sub-assembly part numbers are engraved onto a small metal collar, which remains permanently on the pipe. The assembly number EN43-A435, however, is engraved onto a temporary metal tag which is attached to the pipe temporarily with locking wire, and is required to be removed prior to installation on an aircraft. Consequently the primary means of identifying the pipe is lost once it has been installed.

Survey of in-service pipes

Pipe condition on other BAC 1-11 aircraft from the operator's fleet

The flexible brake pipes fitted to the three other BAC 1-11 aircraft from the operator's fleet examined at Birmingham were found to be in a broadly similar condition to those on G-AVGP, with damaged protective sheathing and worn braiding where they passed through the lower support bushes. In several cases, broken strands of braid were also evident.

In the light of these findings, the CAA area office with responsibility for Birmingham was informed. In addition, the operator independently undertook to inspect, and where necessary to replace, all of the walking joint flexible pipes on its fleet of 1-11 aircraft. Twenty-three of the pipes thus removed were later sent to AAIB to assist with the investigation. Examination of these pipes revealed the following:-

Small diameter types

Thirteen of the pipes were of the smaller diameter type (9.8 mm (0.385 inches) OD, similar to the failed pipe), of which: 9 had plastic identification tags bearing the (post-mod) EN43-A435 part number; 1 had a plastic tag bearing the part number EN63-A115 (a BAe sub-assembly part number for the hose) and 1 had a metal tag bearing this same EN63-A115 part number; 2 had metal tags with only partially legible part numbers; and 1 had no identification tag of any kind. The thin plastic covering had deteriorated and broken up over the lower part of the majority of these pipes.

The diameter-increasing protective sleeves, which should have been fitted to both the upper and lower ends of the (small diameter) pipes, were not present in the region of the pipe in contact with the lower support bushes on 11 out of the 13, but sleeves were present at the extreme bottom ends of these pipes, abutting the lower end-fittings. On almost all of these 11 pipes, the thin plastic sheaths in the region where the pipe passes through the lower support bushes was damaged or missing, and abrasion damage was evident on the steel structural braid; in many cases with broken strands (Figure 3b shows a typical example). The 2 remaining pipes had a pair of diameter-increasing sleeves fitted at their lower ends: the first abutting the pipe end-fitting, and the second abutting the first. The lower regions of these pipes were in noticeably better condition than the others, and the structural braid was undamaged; however, the higher of the two sleeves had in each case migrated down the pipe, puckering the sleeve 'concertina' fashion, with the result that the sleeve had only partially engaged in the support bush.

Single diameter-increasing sleeves were fitted to the upper parts of 7 of the pipes, but in most cases these were positioned too far down the pipe to engage the clamps; typically 45 mm to 50 mm (1.8 inches to 2.0 inches) below the upper clamp block, with the result that the clamps gripped the hose directly. Had the *correct* (post-mod) clamp blocks been used with these pipes, as required by the Service Bulletin, they would have been sized to clamp 12.7 mm (0.500 inches) OD pipes, and therefore too large to grip the 9.8 mm (0.385 inches) OD hose properly. In most cases, however, witness marks on the pipes suggested that the clamping pressure had actually been correct implying that, contrary to the BAe Service Bulletin instructions, clamps had either been modified, or made specially, to accommodate the smaller pipe diameter arising from incorrectly positioned sleeves.

The remaining two pipes had a pair of diameter-increasing sleeves fitted at their upper ends, one immediately abutting the end-fitting and a second abutting the first; these were the same 2 pipes which had the pair of sleeves fitted at their lower ends.

Large diameter types

Ten of the pipes were of larger diameter (typically 0.450 inches- 0.500 inches OD), with teflon or PTFE cores. Eight of the pipes had two layers of steel braid sheathing, of which 3 exhibited worn outer braids and/or broken strands (Figure 3c shows a typical example). The remaining 2 pipes had a single sheath of braided steel in addition to a protective sleeve of tough, woven, textile.

Of the 8 pipes with the double steel braid, 4 had plastic identification collars bearing the part number AQ43A211 (the BAe assembly part number for the original standard of pre-mod pipe), 2 had plastic collars bearing the part number EN63-A115 (a BAe sub-assembly part number), and 2 had no identification markings of any kind. The 2 pipes with the textile outer sheath were fitted with steel part number collars bearing identification numbers which included 107066 (a Fliteline part number), and EN63-A115 (BAe sub-assembly part number).

Pipe condition on BAC 1-11 aircraft from other fleets

In order to assess whether the abrasion problems encountered on the operator's fleet were more widespread, the type and condition of the walking joint flexible pipes were inspected on 5 in-service BAC 1-11 aircraft from another civil operator's fleet, and one aircraft operated by the Ministry of Defence. It was found that the flexible pipes on these aircraft were mainly of the smaller diameter type, many of which had damaged and missing sections of plastic sleeving and outer sheathing at the lower ends of the pipe, leaving the steel braid exposed and in loose chaffing contact with the bores of the support bushes. Figure 4 shows a typical example.

The diameter-increasing sleeves at the upper ends of the smaller diameter pipes had mostly been fitted below the actual clamp position (as noted previously). It was also noted that in several instances, the pipe cut-outs in the two halves of a given clamp block appeared not to match one another, suggesting that clamps of different types may have been mixed.

Component origin

It was not possible to determine with certainty the origin of any of the pipes examined during the course of this investigation.

To assist with identification, a sample pipe manufactured from the smaller diameter Aeroquip type hose-stock was supplied by BAe to serve as an exemplar, for comparison purposes. This pipe had a pair of diameter-increasing sleeves fitted at both the top and bottom ends of the pipe: in each case, one abutting the end-fitting and a second abutting the first. It is understood that this pipe was from a batch supplied originally to BAe by the hose manufacturer with the sleeves positioned incorrectly: effectively, with the top and bottom sleeve positions reversed; the top sleeve being too far from the end-fitting to engage the upper clamp block and the bottom sleeve abutting the end-fitting, below the position of the lower support bush. (In this regard the exemplar pipe, as supplied to BAe originally, was comparable to the majority of the small diameter pipes surveyed, as commented upon previously.) Upon receipt, BAe inspectors found the error and the pipes were returned to the hose manufacturer. Rather than attempt to remove the misplaced sleeves, with the attendant risk of causing damage, an agreement was reached with BAe that the problem could be remedied by the installation of a correctly positioned second sleeve at each end of the pipe, leaving the originally fitted sleeves still in place. The *rectified* batch was subsequently accepted by BAe and entered the spares supply chain.

Comparison between the exemplar pipe and the pipes surveyed by AAIB suggested that those fitted with plastic identification collars (the majority) probably had not been sourced from BAe. However, three of the hoses did have metal identification collars bearing the BAe EN63-A115 sub-assembly number together with several of the hose manufacturer's own part numbers. These metal collars, and the character of the markings on them, appeared visually identical to the exemplar, suggesting that these pipes had been supplied by BAe. Of these:-

two had a pair of diameter increasing sleeves installed at each end, suggesting these had been part of the batch on which the supplier had originally mispositioned the sleeves.

one pipe had both sleeves positioned too far down the pipe, *ie* the upper and lower sleeve positions reversed, comparable to the majority of the non-BAe supplied pipes and to the exemplar pipe as supplied originally to BAe.

Part numbering, identification, and conformity issues

Part numbering

No good reason was evident for BAe's practice of putting the assembly number on a separate *temporary* steel tag which must then be removed prior to installation, rather than adding the assembly number to the existing metal collar which records the other identification numbers, or to an additional *permanent* collar. This practice deprives operators and maintenance organisations of a ready means of checking that installed pipes are of the correct type; it certainly led to unnecessary confusion during the course of this investigation, and was probably a factor in the confusion which evidently exists regarding the *correct* combination of pipe and clamp block.

Conformity

The high incidence of incorrectly positioned diameter-increasing sleeves appears to lie at the heart of wider problems of hose and upper clamp block incompatibility, and excessive abrasion at the lower support bush, which are indicated in respect of many in-service aircraft in the UK (and possibly elsewhere).

The BAe pipe assembly drawing was examined, and it was confirmed that the drawing does take due account of the diameter differences between Aeroquip (small diameter) and Fliteline (larger diameter) hoses by specifying diameter-increasing sleeves for Aeroquip-type hoses. The positions at which these sleeves should be fitted to the upper and lower ends of the pipe were also correctly specified. However, it was notable that whilst this information was strictly correct, the manner in which it was presented appeared open to possible misinterpretation, resulting in the positions of the top and bottom sleeves being effectively reversed, and failing to match the positions of the hose support clamp and bush as a consequence.

BAe do not supply pipe manufacturing drawings, except to their own approved suppliers. However, it is understood that uncontrolled copies of original drawings do exist outside BAe, and it is possible that these may have been used in the manufacture of some, if not all, of the non BAe supplied pipes examined. Alternatively, it is possible that a BAe supplied pipe with incorrectly positioned sleeves (*ie* with the top and bottom sleeve positions reversed, as on the exemplar prior to rectification) may have been used as a pattern for the manufacture of replacement pipes. In either case, misinterpretation of the assembly drawing appears to be the underlying reason for the preponderance of incorrectly positioned sleeves on in-service pipes; it was almost certainly the cause of the initial mispositioning in the batch of BAe pipes from which the exemplar was drawn.

The large number of the *in service* pipes examined which did not conform to the manufacturer's drawings suggests that *new* pipes presently in operator's stores holdings also may not conform. It also raises a similar question in connection with clamp block held as part of existing spares holdings.

Pipe deterioration

By far the majority of the smaller diameter Aeroquip type hoses surveyed displayed extensive deterioration and breakup of both the thin plastic protective sleeve and of the diameter increasing sleeves, particularly at their lower ends where they passed through the lower support bushes. In addition, a significant number of the diameter increasing sleeves at the bottom ends of these pipes had migrated from their original positions, often in combination with *concertina* folding of the sleeves. Many of the pipes also had worn or damaged steel braiding.

Although a visual inspection of the damaged plastic coverings and sleeves did not suggest embrittlement of the type usually associated with prolonged exposure to ultra violet, it was evident that in the case of the majority of pipes examined by AAIB, neither the *protective* nor the *diameter-increasing* sleeves on Aeroquip type pipes were providing the required protection throughout the in-service life of the pipes.

The prevalence of severe abrasion and multiple strand failure of the steel braiding of Aeroquip pipes suggests that operators may not be fully aware that the steel braid on these pipes is structural (unlike the earlier hoses, where the braid was primarily intended to provide abrasion protection). Consequently, any deterioration of the braid will give rise to a significant risk of hose rupture.

Implications of pipe failure

A ruptured brake hose will result in fluid loss whilst foot brake pressure is applied, leading potentially to exhaustion of all fluid and consequent loss of normal brake functions, including anti-skid. A minimum of six full brake applications should be possible thereafter using the hand brake, from pressure stored in the hand brake accumulator, but with no anti-skid function available.

The primary supply to the foot brakes is taken from the No 2 hydraulic system. However, the flying control system is designed so that loss of one hydraulic system should not affect adversely the handling of the aircraft.

Safety action

On 15 February 1996, the CAA Regional Office Manager at East Midlands Airport (the office with responsibility for Birmingham) was advised by telephone of the high incidence of pipe abrasion and braid failure found during the AAIB initial investigation.

Subsequent detailed investigation has brought to light a number of problems affecting the walking joint flexible hose assemblies of a significant number of in-service aircraft on the UK register, and identified a range of apparent shortcomings. Specifically:-

Incorrect location of the diameter-increasing sleeves at both ends of Aeroquip type hoses appears widespread; specifically, upper sleeves are invariably positioned too far from the end-fitting, and the lower sleeves too near.

The adequacy of the plastic anti-abrasion sleeving on Aeroquip type walking joint hoses is called into question.

The security of the plastic diameter-increasing sleeves fitted to the lower ends of Aeroquip type walking joint hoses appears inadequate.

Severe chaffing and abrasion damage to the steel structural braid of Aeroquip type hoses, at the lower ends where they pass through the (hard plastic) support bushes in the manifold bracket, appears widespread.

Upper clamp block incompatibilities appear to be prevalent; specifically, mismatching of pre and post-mod hose/clamp sets, and clamp blocks which do not conform with British Aerospace specifications for either the pre or the post-mod standard of clamps.

The lack of any form of permanent assembly number marking on BAe supplied walking joint hoses, despite the presence of metal collars bearing several sub-assembly numbers, compromises an operator's ability to positively identify the part number of pipes once they have been installed, adding to the potential for pipe and clamp incompatibilities to arise.

The clarity of the Service Bulletin implementing the revised hoses is less than ideal.

The British Aerospace hose assembly drawing appears open to misinterpretation.

Safety Recommendations

As a result of the findings arising from this investigation, the following Safety Recommendations have been made:

97-4: British Aerospace Airbus Ltd should issue a Service Newsletter, or comparable document, to promulgate to all operators of BAC1-11 aircraft information on the correct installation of landing gear walking joint flexible brake hoses and associated clamp block assemblies, and to raise awareness of related compatibility issues and correct maintenance procedures required.

96-48: British Aerospace Airbus Ltd, in conjunction with the CAA, should take action to require inspection of BAC 1-11 aircraft for abrasion damage to the structural braiding of landing gear walking joint flexible brake hoses, particularly in the hidden region within the lower support bush, and to require replacement of all damaged hoses found.

96-49: British Aerospace Airbus Ltd should critically review BAC 1-11 Service Bulletin PM5633 and amend the contents as necessary to ensure that these are correct and unambiguous.

96-50: British Aerospace Airbus Ltd should consider introducing a scheme for the permanent marking of BAC 1-11 landing gear walking joint brake hoses with the BAe assembly part number and take action to ensure that all new post-modification hoses, presently in the supply chain and held by operators as spares, have correctly positioned diameter-increasing sleeves.