

DHC-8-311A Dash Eight, G-BRYM, 18 September 1996

AAIB Bulletin No: 4/97 Ref: EW/C96/9/5 Category: 1.1

Aircraft Type and Registration:	DHC-8-311A Dash Eight, G-BRYM
No & Type of Engines:	2 Pratt & Whitney Canada PW-123 turboprop engines
Year of Manufacture:	1991
Date & Time (UTC):	18 September 1996 at 0926 hrs
Location:	Plymouth City Airport
Type of Flight:	Public Transport
Persons on Board:	Crew - 4 - Passengers - 49
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Minor fuselage skin damage Frangible 'Touched Runway' sensor destroyed
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	50 years
Commander's Flying Experience:	15,191 hours (of which 727 were on type) Last 90 days - 152 hours Last 28 days - 30 hours
Information Source:	AAIB Field Investigation

History of flight

The crew reported at 0505 hrs to operate six sectors, being twiceround the route Plymouth-Newquay-Heathrow-Plymouth. Towards the end of the third sector, inbound to Plymouth at 0922 hrs, the crew contacted Plymouth Approach Control while 13 miles east of the airport. The 0850 hrs METAR observation for Plymouth had been passed to the crew previously by London Military Radar Control as 100°/26 kt gusting 39 kt, visibility 17 km, cloud few at 2,500 feet. The temperature was 13°C and the QNH 1009/QFE 992 mb. The aircraft was cleared to self position onto a left base leg for a visual approach to Runway 13. The First Officer was the handling pilot for this sector. The

landing crosswind component was within the company limits for him to complete the landing as handling pilot (aircraft crosswind limit 30 kt, First Officer handling crosswind limit 20 kt). The First Officer had been flying the type for some two years and had a total flying experience of 2,834 hours, of which 893 were on type. His 28 and 90 day flying totals were 85 and 178 hours respectively.

The maximum permitted landing weight was 41,885 lb and the actual landing weight was 40,644 lb. The crew elected to make an approach with full flap (35°), using a VREF of 100 kt, which was appropriate to a landing weight of 41,000 lb. The approach speed to be used was as recommended by the manufacturer at VREF, to which was added half of the gust value (with an overall maximum increment of +10 kt), giving a target approach speed of 107 kt. Plymouth Runway 13 has a Landing Distance Available of 1,038 metres. For a 35° flap landing, the LDA from the company Operations Manual was 1,007 metres (still air), or 897 metres when factored for the steady headwind component.

The flight crew commented that flying conditions were smooth until the aircraft descended below 1,000 feet when constant moderate turbulence and indicated airspeed fluctuations were experienced. This turbulence had been anticipated as the crew were based at Plymouth and were familiar with the local effects of strong winds. They decided to configure the aircraft early on the approach, so 35° flap was selected at about 800 feet agl and the aircraft settled at an approach speed of around 110 kt, but fluctuating with the turbulence being experienced. The landing checks were completed, landing clearance was obtained from ATC and a final wind check was passed as 100° at 20 kt gusting 30 kt. The First Officer requested confirmation that the airspeed was acceptable on short final and the commander replied that it was good. The aircraft flared normally with the left wing slightly down to compensate for the crosswind component and the power was progressively reduced to flight idle. The crew considered that the aircraft touched down earlier than anticipated, on the left main wheel first followed quickly by the right main wheel. A slight bounce then followed before a further firm touchdown. A normal rollout ensued. The pitch attitude at the flare and bounce did not seem excessive to the crew.

Ground contact with the rear fuselage went unnoticed by the aircraft occupants, but the flight deck crew noted that the Red 'Touched Runway' warning caption on the CAUTION/WARNING LIGHTS PANEL was illuminated during the taxi in. The aircraft was parked and shutdown normally before being withdrawn from service for repair.

The commander considered that the approach had been normal given the nature of the turbulence and windshear experienced. He considered that an application of power at the flare to compensate for the sudden loss of airspeed may have prevented the firm touchdown and rear fuselage strike.

The previous landing aircraft was a Piper PA-28 which landed on Runway 13 at 0924 hrs. Its pilot indicated that he experienced a loss of airspeed of about 20 kt on short finals. He did not comment by R/T to ATC on this experience.

Airport information

The UK AIP entry for Plymouth contains the warning note: *'In strong wind conditions, windshear and turbulence may be experienced on the approach to or climb out from any runway. Down draught effect and sudden changes in wind velocity are possible in light wind conditions.'*

Plymouth Airport is equipped with a Vaisala WAD21M Anemometer system with two wind sensors, one by the threshold of the main instrument Runway 31, the other close to the intersection

of the two runways. On the day of this accident the latter sensor was unserviceable so all references to surface wind for R/T transmissions and METAR observations were taken using the Runway 31 threshold anemometer. The crew were neither advised of this situation by ATC, nor was there any requirement to pass such information. The standard practice is for ATC to pass the 2 minute average wind by R/T for aircraft movements, but to supply the 10 minute average value for METAR purposes. METAR observations are compiled by ATC personnel holding Met Observer Certificates and are currently taken at hourly intervals.

Engineering Inspection

The frangible switch for the 'TOUCHED RUNWAY' flight deck caption had been destroyed in the contact between the aft fuselage and the runway. The two fuselage frames adjacent to the frangible switch (stations 626.5 and 642.5) had both suffered skin damage and the geometry of these marks showed that, at contact with the runway, the aircraft had been close to wings level and almost straight (nose 3° to the right). The corresponding mark on the runway started some 131 metres from the runway threshold, close to the runway centre line, and extended for 4.8 metres. The airframe damage was similar, but slightly less severe, to that caused to another DHC-8-311 in Jersey in May 1995 (reported in AAIB Bulletin 7/95).

From the aircraft geometry it is apparent that the fuselage attitude at which the rear fuselage of a DHC8300 will contact the runway is approximately 8.5° - 9°, with the main landing gear oleos fully compressed.

Flight Recorders

The aircraft was fitted with a Loral F800 Flight Data Recorder (FDR) and a Sundstrand Cockpit Voice Recorder (CVR). Both recorders were removed from the aircraft and replayed using standard techniques. The FDR contained a recording of aircraft data from the last 25 hours of aircraft operation whilst the CVR contained the last 30 minutes of the accident flight.

The data from the FDR showed that the flight had been uneventful until the landing. During the final approach, at a radio altitude of 14 feet, there was an increase in indicated airspeed from 100 kt to 107 kt, coincident with the start of a reduction in angle of attack. One second later, at a radio altitude of 5 feet, the indicated airspeed dropped sharply to 89.5 kt and the angle of attack decreased further to -3.7°. Between 12.5° and 14° of nose-up elevator was applied at that time and the aircraft began to pitch up. Over the subsequent second the angle of attack increased rapidly to +12.8° and the indicated airspeed increased to 99 kt. While the pitch attitude of the aircraft was still increasing, 7.5° of nose-down elevator was applied. Engine torques had decreased steadily during whole of this period from 20% to 5%.

The aircraft's rear fuselage struck the ground at this time and the resultant acceleration pulse caused the FDR to corrupt the data recording for a period of 0.25 seconds. The uncorrupted data immediately after the rear fuselage strike showed that the pitch attitude of the aircraft was 7.3° nose-up, angle of attack was +11.1° and vertical acceleration was 1.75 g.

Following the rear fuselage strike, the aircraft bounced to a height of 5 feet for a period of just over 2 seconds before landing and rolling out. This second landing occurred at 91 kt with a pitch attitude of 4° nose up and, although it had resulted in a vertical acceleration of 2 g, data corruption within the FDR did not occur.

Although ground speed was not recorded on this aircraft it was derived using a stabilised airspeed and wind information for an initial point and subsequently longitudinal acceleration and aircraft pitch attitude. During the period immediately prior to the rear fuselage strike, although indicated airspeed showed a momentary decrease of 17.5 kt, no such variation was seen in the derived ground speed, indicating that the wind speed had decreased and not the speed of the aircraft.

Aircraft information

The Aircraft Flight Manual contains the following Caution note: *'Pitch attitudes greater than 6° in the landing flare may cause the fuselage to contact the runway.'*

Apart from this incident and the previous occurrence in the UK referred to above, three other landing rear fuselage strike events have been experienced on the -300 series. In each case, the 'Touched Runway' sensor has correctly alerted the crew to the situation.

The manufacturer was supplied with the FDR data from this occurrence and concluded that the aircraft was being flown at the proper approach speed. Given the sudden loss of airspeed at the flare, the only crew action that could have prevented the rear fuselage strike was an immediate advancement of the power levers in order to reduce the aircraft's sink rate without having to exceed the recommended pitch attitude of 6° for a normal landing.

Subsequent actions

Following this occurrence, the operator has introduced the following revised standard operating procedures:

"First Officers may carry out landings at Plymouth subject to the discretion of the Captain and the following limitations;

1. Maximum wind speed of 15 kt including gusts
2. Maximum tailwind of 5 kt
3. Minimum cloud base of 500 feet and visibility of 2,000 metres

Furthermore, First Officers, who are not Plymouth based, are not permitted to carry out landings at Plymouth until they have completed 3 months line flying."