

DH112 Venom FB50, G-VIDI, 7 July 1996

AAIB Bulletin No: 4/97 Ref: EW/C96/7/3 Category: 1.2

Aircraft Type and Registration:	DH112 Venom FB50, G-VIDI
No & Type of Engines:	1 DH Ghost 48 Mk 1 turbine engine
Year of Manufacture:	1955
Date & Time (UTC):	7 July 1996 at 1436 hrs
Location:	Hawarden Airfield, Broughton, Chester
Type of Flight:	Aerial Work (Flying Display)
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - Minor - Passengers - N/A
Nature of Damage:	Extensive
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	51 years
Commander's Flying Experience:	13,233 hours (of which 9 were on type) Last 90 days - 187 hours Last 28 days - 69 hours
Information Source:	AAIB Field Investigation

The event was an Open Day and flying display at an aircraft manufacturing facility, organised by the airfield operator and approved by the CAA in accordance with the requirements laid down in CAA publication CAP 403. The pilot also held the required Display Authorisation from the CAA.

The aircraft had been refuelled before the display flight. Therefuelling was supervised by the aircraft operator's Chief Engineer who confirmed that the fuel load had been symmetrically loaded. A total of 364 gallons was on board, being distributed as 90 gallons in the centre tank, 59 gallons in each main wing tank and 78 gallons in each wing tip tank.

The aircraft was taking off from Runway 23 as the number four of a four aircraft formation comprising two Vampires followed by two Venoms. The departures were as two pairs, each in echelon starboard formation, about 15 seconds apart. The surface wind was from 310° at 14 kt, with

gusts reported to 20 kt. The runway width is 45 metres and the span of each aircraft is 12.7 metres. For each pair take off, the lead aircraft was positioned on the downwind half of the runway width.

The pilot noted that his lead aircraft's nose wheel had left the ground at the time of the 80 kt airspeed indicator check and he stated that both aircraft maintained a nose up attitude until lift off occurred. The pilot stated that after lift off, G-VIDI suffered a rapid right wing drop which required a large opposite aileron input to correct. The aircraft then rolled rapidly left to a bank angle which the pilot estimated was 60°. Full right aileron and some right rudder application was necessary in order to stop the roll and reverse the direction. The pilot assessed that the roll oscillation was becoming divergent and elected to land the aircraft back on the runway. However, the aircraft touched down to the left of the runway centreline, initially on the right wing tip fuel tank, which ruptured. The aircraft yawed to the right but touched down with the left main gear on the grass and the right main gear on the runway. The aircraft left the runway to the left and continued on the grass, striking a displaced threshold marker light. The pilot applied the brakes and attempted to recover the aircraft towards the runway centreline, but the aircraft went onto the runway and departed off the end, causing damage to the ILS Localiser transmitter facility. When the pilot assessed that an over-run was likely, he attempted to raise the landing gear, but could not operate the emergency retract system because of the violent ride.

The aircraft's right wing finally struck a grass mound forming part of the airfield fuel installation. This caused a yaw to the right and the aircraft came to rest against the wire mesh perimeter fence just short of a public road running along the outside of the airfield boundary. The final position of the aircraft was some 100 metres to the right of the runway centreline.

The pilot shut down the engine and switched off the electrics. He opened the canopy, released his harness and made safe the seatpan ejection seat handle. The airfield fire service arrived at the scene quickly and made safe the ejection seat top handle before removing the pilot to a waiting ambulance. Despite the rupture of the right wing tip fuel tank with consequent fuel spillage and impact with the airfield fuel storage installation, there was no fire.

Video Analysis

Several spectators provided video tapes showing the sequence of events. These indicated that the nose landing gear of G-VIDI lifted off early and that the aircraft became airborne about three seconds before the lead aircraft's nose wheel left the runway. From this point, G-VIDI appeared to fall back from the leader. Shortly after lift-off, the aircraft rolled slightly to the left and moved over the runway centreline. This was corrected, apparently with opposite aileron and some rudder input. There was then a significant yaw and roll to the right to about 20° bank, which took the aircraft over the right hand edge of the runway, almost touching the ground with the right wing tip fuel tank. This was then followed by a roll and yaw to the left, achieving a bank angle of about 60°. During this reversal, the aircraft began to cross towards the left side of the runway and nose up elevator input was still apparent. The lead aircraft by this time was airborne, had moved over to the left hand edge and was pulling away from G-VIDI.

The final roll reversal produced a bank angle of about 45° to the right. The right wing tip fuel tank struck the runway surface about 15 metres from the left hand edge. The tank ruptured and released its fuel load. The bank angle reduced rapidly and the aircraft's nose yawed to the right as a result of the impact, but its overall ground track was still towards the left edge of the runway. The main wheels touched down straddling the left edge, with the aircraft yawed some 20° to the right. The left wing again lifted as the crab angle increased, the aircraft then running along scuffing its right main

wheel only. The final full touchdown occurred on the grass area to the left of the runway with about 40° of crab angle. The aircraft then ran onto the hard surface once again, in the undershoot area of the Runway 05 displaced threshold, crossing the area at an angle and departing off the end diagonally onto the grass overrun area. In this area, a collision occurred with the ILS Localiser hut and the right wing struck the earth mound protecting the fuel installation. The aircraft finally came to rest up against the wire mesh fence at the airfield boundary.

Analysis of the video coverage of the lift off point of G-VID indicated that the aircraft became airborne at a speed between 99 kt and 106 kt. The stalling speed of the aircraft in this take-off configuration was estimated by the operator to be about 90 kt. The Aircraft Flight Manual handling notes, Take-off section, note that *'Care must be taken not to raise the nose too high during the take-off run as the aircraft may fail to accelerate'* and *'The aircraft should be flown off at about 110 kt at normal load and at about 120 kt at maximum load. Because of the possibility of a wing drop, the aircraft should not be pulled off the ground below the recommended speeds.'*

The pilot stated that at no time during the sequence of events did the stall warning system operate (warning horn and light). The operator commented that, when the aircraft was inspected after the accident, the switch controlling the operation of the system was in the off position. It could not be determined if the switch had been on for the take off.

It was noted during the analysis of the video recordings that several other aircraft were experiencing the effects of turbulence and crosswind.

Airfield Facilities

Runway 23 at Hawarden is the main instrument approach runway. The Take-off Run Available is 2,034 metres and the Take-off Distance Available is 2,184 metres. The LDA after a displaced landing threshold, is 1,738 metres. This accident highlighted certain physical features in the over-run area of Runway 23.

The airfield fuel storage installation is believed to date from around the time of the second world war. It currently comprises two 10,000 gallon tanks used to store Jet A-1 turbine fuel. These tanks are contained within concrete bunkers covered with earthmounds. These are positioned some 30 metres from the runway extended centreline and are 190 metres beyond the end of the paved surface. It was fortunate in this case that no damage was caused to the installation by the aircraft.

The airfield boundary fence comprises wire mesh netting supported by concrete posts which are not intended to be frangible in the event of an impact by an aircraft. The boundary fence crosses the extended centreline of Runway 23, within 250 metres beyond the end of the paved surface. Adjacent to and outside the boundary fence runs a public road (the B5125). It was fortunate in this case that the aircraft came to rest within the airfield boundary and did not cross the boundary onto the road, from where some members of the public were observing the flying activities.

Safety Recommendation 97-12

British Aerospace Airbus Ltd. should carry out a safety review of the over-run area of Runway 23 at Hawarden with a view to the removal of the fuel storage installation to an area more remote from the runway. The review should consider the replacement of the boundary fence crossing the extended centreline with a suitably frangible fence. In view of the proximity of the public road, consideration

should also be given to the provision of greater protection for the public for example, by the use of a soft bed arrester system in the over-run area and/or the installation of traffic lights on the road.