

Denney Kitfox Mk III, G-PPPP

AAIB Bulletin No: 9/97 Ref: EW/G97/07/08 Category: 1.3

| | |
|--|---|
| Aircraft Type and Registration: | Denney Kitfox Mk III, G-PPPP |
| No & Type of Engines: | 1 Rotax 582 piston engine |
| Year of Manufacture: | 1991 |
| Date & Time (UTC): | 7 July 1997 at 1515 hrs |
| Location: | Magclough Farm, Eyam, Derbyshire |
| Type of Flight: | Private |
| Persons on Board: | Crew - 1 - Passengers - 1 |
| Injuries: | Crew - None - Passengers - None |
| Nature of Damage: | Landing gear collapsed, propeller, radiator and lower cockpit area damaged |
| Commander's Licence: | Private Pilot's Licence with Night Rating |
| Commander's Age: | 73 years |
| Commander's Flying Experience: | 3,076 hours (of which 497 were on type) Last 90 days - 53 hours Last 28 days - 25 hours |
| Information Source: | Aircraft Accident Report Form submitted by the pilot |

The aircraft was engaged on a local flight in the area of the Lady Bower Dams. Shortly before reaching the dams and at a height of 4,000 feet, the engine stopped. The area around the dams was of rugged terrain with very few areas suitable for landing a light aircraft. The pilot chose a field but when committed to the forced landing saw that the field was on a steep upward slope. During the landing the aircraft's landing gear collapsed.

Initial examination of the engine indicated that it had seized, with no other external indications of mechanical failure. Subsequent strip examination of the engine by the pilot revealed that there had been a major failure of the rear cylinder 'big end' bearing, but further examination found no fault within the lubrication oil injection system.

Similar seizures of Rotax 582 engines have occurred and three earlier AAIB Bulletins (ie 12/95, page 55, 10/96, page 29 and 5/97, page 63) which reported on engine seizures on a Renegade Spirit, a Kolb Twinstar and a Avid Speed Wing, drew attention to this problem. Although no statistics

appear to be available, the Popular Flying Association advised that there had been a history of big-end failures on Rotax 582 engines, due to worn bearings. This was particularly the case for engines installed in heavier aeroplanes and those used in the training role which use extended running at high power. There were also indications that long periods without use could be detrimental. 'Drying' of the roller type bearings may occur and residual products of combustion, which can be significantly acidic, can accelerate corrosion of the bearing materials. If corrosion occurs, this preconditions the bearings to wear rapidly when used subsequently, although it may then take several flights for the bearings to deteriorate to the point of failure.

The largest service centre for Rotax engines in the UK has devised an instrument, the 'Cyclone Conrod Bearing Clearance Tester', for testing the combined big/little-end bearing clearances, which has apparently proved extremely effective in preventing such failures.

The Bearing Clearance Tester is essentially a dial gauge mounted on an extension tube which screws into the spark-plug holes and bears on the piston crown when at top dead centre. A syringe is used to 'suck/blow' the piston up and down, the difference in gauge readings being converted into combined bearing clearance. The instructions recommend that this check be performed every 12.5 flight hours when the spark-plugs are removed for inspection in accordance with the Rotax service schedule. Maximum wear figures are provided with the instrument, but records should also be kept so that any trend can be detected in advance. It is understood that the Popular Flying Association acknowledges that this device has been effective in preventing failures of this nature and has published an article entitled 'KNOW YOUR BIG END WEAR' in the December '95/January '96 edition of its magazine, *Popular Flying*.

At the time of the accident the engine had achieved 730 hours since manufacture. At 298 hours since manufacture the engine's crankshaft failed and the engine was rebuilt by a manufacturer's approved agent. Between 5 and 6 hours before the accident the pilot and an engineering friend had performed a check of the big end bearing wear using the 'Cyclone Conrod Bearing Clearance Tester'. The rear cylinder bearing wear was found to be 0.015 inch, which was within the limits specified.