

Europa, G-BWFX, 9 September 1996

AAIB Bulletin No: 12/1996

Ref: EW/G96/09/05 Category: 1.3

Aircraft Type and Registration:	Europa, G-BWFX
No & Type of Engines:	1 Rotax 912 piston engine
Year of Manufacture:	1996
Date & Time (UTC):	9 September 1996 at 1000 hrs
Location:	Kemble Airfield, Gloucester
Type of Flight:	Private
Persons on Board:	Crew - 2 - Passengers - None
Injuries:	Crew - None
Nature of Damage:	Damage to landing gear, propeller and engine cowling
Commander's Licence:	Commercial Pilot's Licence
Commander's Age:	34 years
Commander's Flying Experience:	458 hours (of which 85 were on type) Last 90 days - 52 hours Last 28 days - 18 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot, and additional AAIB inquiries

The aircraft had been on an airtest for the purpose of obtaining a Permit to Fly and was loaded close to its maximum weight. The test was successfully completed and the aircraft returned to Kemble, where the wind was 12 to 15 kt, but only some 10° off the runway direction. The approach was normal and the aircraft was flared at an indicated airspeed of 50 kt. The pilot reported that the rate of descent did not appear to be excessive, however as the aircraft touched down, the main landing gear gave way resulting in the propeller and lower engine cowling striking the runway. The aircraft skidded along on its main and tail wheels for approximately 50 metres before coming to rest on the grass at the side of the runway.

The Europa is a home-built aircraft constructed from a kit, and the landing gear consists of a single retractable main wheel in addition to a tail wheel and two outrigger wheels under the outer wings. The principal components of the main landing gear are shown in the attached diagram. It was found that

the main landing gear support frame had failed, leading to the collapse of the main gear. The support frame was not examined by the AAIB, but the kit manufacturer concluded that the failure had been due to overload, such as might result from one, or more, heavy landings.

It was subsequently revealed that immediately prior to the air test, the aircraft had suffered a 'ground loop' incident in which it had veered off the runway at 90° during the take-off roll. The next take-off attempt was successful. This incident, and the possibility of previous heavy landings, suggested that the failure following the air test may have been the result of cumulative damage.

The main landing gear had been designed to Joint Aviation Requirements (JAR)-VLA (Very Light Aircraft), although home-built aircraft do not need to comply with these standards. Associated drop tests had shown that the landing gear met the 'reserve energy' requirement of a descent rate in excess of 10 ft/second, at which some distortion of components might be expected. However, since the drop tests had been carried out, a shock absorber assembly had been added which resulted in minor changes to the landing gear geometry, and which incorporated a 'limit stop'. The kit manufacturer subsequently considered that this may have slightly altered the loads in some of the landing gear components. Following additional testing, a modification is now offered featuring, for new kits, a revised shock absorber with increased thickness of rubber and with the limit stop deleted. For existing aircraft, packing pieces are incorporated into the shock absorber. The deletion of the limit stop means that shock absorber movement is limited by the natural compression limit of the rubber. The modification, which the kit manufacturer considers should be mandatory, also includes additional reinforcement of the support frame. The Popular Flying Association are currently considering whether to confer mandatory status on this modification.

A similar landing gear collapse is known to have occurred on one other aircraft, and there are unsubstantiated reports of cracks having been found in the support frames of other Europa aircraft.