

CEA Robin DR220A, G-BKOV

AAIB Bulletin No: 2/98 Ref: EW/G97/11/06 Category: 1.3

Aircraft Type and Registration:	CEA Robin DR220A, G-BKOV
No & Type of Engines:	1 Rolls-Royce Continental O-220-A piston engine
Year of Manufacture:	1967
Date & Time (UTC):	22 November 1997 at 1415 hrs
Location:	Hucknall Airfield, Nottinghamshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - Minor - Passengers - Minor
Nature of Damage:	Substantial and beyond economic repair
Commander's Licence:	Private Pilot's Licence
Commander's Age:	60 years
Commander's Flying Experience:	606 hours (of which 246 were on type) Last 90 days - 11 hours Last 28 days - 4 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot plus aftercast from the Meteorological Office

The aircraft was taxied to the holding point of Hucknall's Runway 04. There was an Antonov AN2 biplane ahead of the Robin which departed in what the Robin pilot described as calm wind conditions. When the biplane was airborne, the Robin lined-up and started its take-off roll on the same runway. The Robin became airborne after travelling a greater distance along the runway than the Antonov which, at the time was starting its crosswind departure leg. As the Robin was climbing through an estimated 50 feet at between 65 and 70 KIAS it suddenly rolled to the left through about 80° for no obvious reason. The pilot applied full right aileron and rudder but the aircraft remained steeply banked to the left as the nose began to drop and the aircraft entered a spiral dive to the left. After a few seconds, control was regained for a moment before the aircraft again rolled into a steep bank to the left. By this time the aircraft had lost most of its height and the pilot concentrated on levelling the wings before it hit the ground. He was partially successful as the aircraft struck the ground wingtip first at a shallow bank angle which slewed it around in a flat attitude. There was no

fire and the cockpit remained intact although the empennage was almost completely severed from the fuselage. Both pilots suffered whiplash injuries, minor cuts and bruising inflicted by their harnesses which withstood the crash forces. Both were able to escape from the aircraft unaided.

The Robin pilot deduced that loss of control was caused by wake turbulence from the preceding Antonov. His take off was witnessed by the local Flying Club's Chief Instructor who agreed with his diagnosis regarding the initial loss of control. However, the CFI thought that the second loss of control may have been more attributable to the 'down wind turn' section of the aircraft's spiral descent during which the pilot throttled back the engine. According to a Meteorological aftercast the surface wind was less than 5 kt and variable in direction between 030° and 140°.

Although both aircraft types are in the same UK 'light' category for wake turbulence purposes (see AIC Pink 178/1993), at MAUW the AN2 is seven times as heavy as the Robin and has about twice the wing span. General Aviation Safety Sense Leaflet 15A entitled 'Wake Turbulence' describes the characteristics of wake vortices and states 'The heavier the aircraft and the slower it is flying, the stronger the vortex.' It also states 'In simple terms, the lighter the aircraft you are flying, the greater the degree of upset if you encounter a wake vortex. Thus a general aviation aircraft will be vulnerable to the vortices of a similar sized aircraft ahead of it, and microlight aircraft will be vulnerable to the vortices of many general aviation aircraft.'