

AIB Bulletin

6/86

No: 6/86

INDEX

		Page
1. Aeroplanes —	(a) over 5700 kg Maximum Total Weight Authorised (MTWA)	
	HS 748	G-BCOF 1
	Shorts SH5 Belfast	G-BFYU 3
	(b) under 5700 kg MTWA	
	Cessna 150E	G-ATEG 5
	Cessna F150H	G-AVUH 7
	Cessna F152	G-BFZS 8
	Cessna 172M	G-BBKZ 9
	Cessna 180C	G-ARAT 10
	DH82A Tiger Moth	G-ANFI 11
	DH82A Tiger Moth	G-ANFW 12
	Gulfstream AA-5A	G-BGFG 13
	Jodel D117	G-AYKJ 14
	Mooney M20K	G-BJGT 15
	Piper PA-18 (modified)	G-AYPO 16
	Piper PA-23-250	G-BHXX 17
	Piper PA-25-235	G-BEII 18
	Piper PA-28-161	G-BFDK 19
	Piper PA-28-180D	G-AXOR 20
	Piper PA-28R-200-2	G-BDKV 21
	Piper PA-34-200T	G-BFLH 22
	Piper PA-44-180	G-BGJB 23

(Continued)

This Bulletin contains facts relating to the accidents which have been determined up to the time of issue. This information is published to inform the public and the aviation industry of the general circumstances of the accidents at the preliminary/stage and must necessarily be regarded as tentative and subject to alteration or correction if additional evidence becomes available.

Short extracts can be published without specific permission providing that the source is duly acknowledged.

		Page
	Varga 2150A Kachina	G-CHTT 25
	Wilson Cassutt 11/M	G-AZHM 26
2. Rotorcraft —	(a) over 5700 kg MTW	
	None	
	(b) under 5700 kg MTWA	
	Bell 47G-5	G-AWRZ 27
	Enstrom F-28A	G-BDKD 28
	Robinson R22	G-BMBX 29
3. Others —	None	
Corrigendum to Bulletin 4/86		30

The aircraft's technical documents recorded that it had been repaired in mid-January 1986, following the discovery of similar but more severe damage to the rudder. No evidence of any defect in the repaired structure was found which could have contributed to the incident on 10 March 1986. However, between 3 February 1986 and 7 March 1986 there were several entries recorded by pilots in the technical log, referring variously to 'in-flight vibration', 'the auto-pilot applying excessive right rudder trim', and 'difficulty in engaging the gust locks'. As a result of these reports the aircraft was inspected and various remedial actions taken. However, as there was no consistency or apparent pattern in the reported defects nor any reports of vibration through the controls, a detailed inspection of the rudder was not carried out until after the incident on 10 March 1986. Detailed examination has shown that the spring strut connecting the rudder to the gust lock and stop system was serviceable and capable of performing its function as a shock absorber. The hinge failure had occurred under a single overload, and had resulted, most probably from strong lateral wind loads when the gust locks had been dis-engaged.

The freedom of the rudder to move at the bottom hinge could well have produced control effects which could explain both the 'in-flight vibration' and the 'excessive application of right rudder trim' applied by the autopilot. The rudder had freedom to move rearwards at the bottom hinge by about 1 cm. With a fixed pilot input this would cause a servotab movement to the right and a corresponding left rudder movement. The autopilot, when engaged could be expected to counter this with opposite movement on the trim tab, and the lack of security and stiffness in the rudder location might well have produced vibration. The HS 748 aircraft requires increasing right rudder trim with increasing speed. If, therefore, the autopilot was engaged at a low airspeed, say in the climb, there would exist a significant out of trim condition when the autopilot was disengaged at 225 knots in the descent. Given the condition of the bottom rudder hinge, such an out of trim condition could well have the effect that initiated the severe roll/yaw oscillation described by the flight crew.

In view of the fact that there is considerable evidence that the damage to the rudder hinge was caused by strong lateral wind gusts, the Meteorological Office, Bracknell, were requested to provide details of the maximum recorded gusts at various highland and island aerodromes into which the company operated. The figures show that, between 26 January 1986 and 10 March 1986, the subject aircraft was parked over-night on 11 occasions in wind speeds between 25 and 30 knots, on 6 occasions in speeds between 31 and 35 knots, and on 4 occasions at speeds between 36 and 40 knots. In addition, during the same period there were 6 occasions when, during daylight operation, gusts in excess of 55 knots were recorded.

Following the incident on 10 March 1986, and other reported incidents of wind slam damage to rudder hinge bearings, the aircraft manufacturer issued a Notice to Operators giving guidance to HS 748 pilots on procedures recommended to reduce risk of such incidents occurring in high surface wind conditions.