

Fokker F27 MK 050, PH-KVK, 8 December 1996

AAIB Bulletin No: 8/97 Ref: EW/C96/12/1 Category: 1.1

Aircraft Type and Registration:	Fokker F27 MK 050, PH-KVK
No & Type of Engines:	2 Pratt & Whitney PW125B turboprop engines
Year of Manufacture:	1991
Date & Time (UTC):	8 December 1996 at 1254 hrs
Location:	London Heathrow Airport
Type of Flight:	Public Transport
Persons on Board:	Crew - 4 - Passengers - 41
Injuries:	Crew - None - Passengers - 3 Minor
Nature of Damage:	Substantial to left rear fuselage, left propeller and left wing tip
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	30 years
Commander's Flying Experience:	2,600 hours (of which 370 were on type) Last 90 days - 130 hours Last 28 days - 40 hours
Information Source:	AAIB Field Investigation

The aircraft was on a scheduled service from Rotterdam to London Heathrow with 4 crew and 41 passengers on board. As the aircraft approached the London Terminal Manoeuvring Area (TMA) the crew were instructed to hold at the Lambourne (LAM) VOR. After three holds the aircraft was radar vectored for an ILS approach to Runway 27 left. The landing gear was selected down normally but the crew noticed that the left main landing gear showed an unsafe indication. The commander, who was the handling pilot, therefore, decided to carry out a go-around in order to investigate the problem. Before initiating the go-around manoeuvre, however, he asked the first officer to consult the 'MAIN GEAR UNSAFE AFTER DOWN SELECTION' check list to see whether he should raise the gear. The first item on the checklist was to recycle the gear. The gear was therefore raised during the go-around as the first part of that procedure.

After the go-around, which was carried out at 1153 hrs, the crew were instructed by ATC to take up a heading of 120° and climb to 3,000 feet. ATC then asked for the reason for the go-around and whether the crew wished to make a further approach. The crew needed time for their investigation, so ATC suggested that the aircraft should hold at the Epsom NDB. The aircraft entered the hold at 1201 hrs and the crew returned to the 'MAIN GEAR UNSAFE AFTER DOWN SELECTION' checklist. They re-selected the gear down, completing the recycle. This, however, was also unsuccessful. The first officer then left the flight deck to check visually if the left main gear was down and locked by looking for alignment of painted red lines on the landing gear strut. His inspection showed that the gear was not in a safe condition (Figure 1).

On his return to the flight deck the crew initiated the 'ALTERNATE DOWN PROCEDURE'. As this was also unsuccessful the commander, in accordance with the checklist, requested clearance from ATC to carry out a level '2g' (60° bank) turn at 170 kt. This manoeuvre, however, did not affect the left main gear unsafe indication.

At this stage the crew were now committed to an emergency landing. At 1212 hrs they transmitted to ATC that "WE HAVE THE INTENTION TO MAKE AN EMERGENCY LANDING AT HEATHROW.... AND WE NEED APPROXIMATELY 15 MINUTES FOR PREPARATION... THE LANDING GEAR SYSTEM IS DOWN BUT NOT LOCKED SO THERE IS A HIGH RISK OF THE GEAR COLLAPSING AFTER TOUCHDOWN". The airport emergency services were alerted and brought to an 'AIRCRAFT ACCIDENT IMMINENT' status.

At 1222 hrs the Heathrow Director informed the crew that the surface wind was now favouring a landing on the easterly runways and that Runway 09R would be used. The weather was passed to the crew as visibility 8 km, scattered cloud at 400 feet, overcast cloud at 600 feet and a surface wind of 140°/4 to 7 kt.

In preparation for the landing the crew actioned the 'ONE MAIN GEAR UP or UNSAFE' checklist. At 1232 hrs ATC asked if the crew were ready for the approach. The crew replied that "THE CABIN IS STILL BEING PREPARED SO WE NEED AT LEAST ONE OR TWO MORE HOLDS". At 1238 hrs, having updated ATC on the number of persons on board the crew declared a 'MAYDAY' and stated that "WE HAVE 600 KG OF FUEL LEFT WHICH GIVES US A LOW FUEL EMERGENCY UPON LANDING AND WE EXPECT A COLLAPSE OF THE LEFT-HAND GEAR UPON TOUCHDOWN".

At 1248 hrs, after a very comprehensive preparation of the aircraft and cabin, the aircraft, having been radar vectored, intercepted the ILS to Runway 09R. The aircraft's track had taken it clear, to the south-west, of the built-up areas of the outskirts of London. The aircraft however had not presented any danger to areas beneath its flight path as the emergency situation would only develop on landing.

The aircraft's touchdown was normal at 1253 hrs right main wheel first. About 5 seconds after all the landing gear were in ground contact the left main landing gear collapsed and the aircraft left wing tip, left propeller and the rear left portion of the fuselage contacted the runway. The aircraft veered to the left coming to rest on the hard surface clear of the runway Block 81.

A full aircraft evacuation was then carried out with approximately half the passengers leaving the aircraft via the front left door whilst the remainder exited via the half open rear left door. The commander was the last to leave the aircraft via the rear left door.

The front left door, which is hinged at its lower edge and incorporates several steps, opened normally but the door adopted a horizontal attitude because of the fuselage's close proximity to the

ground. The rear left door opened normally but its lower corner contacted the ground with the door only 90° open. Although the width available for evacuation was reduced the passengers exited the aircraft without difficulty.

Flight Recorders

The Flight Data Recorder (FDR) and Cockpit Voice Recorder (CVR) were removed from the aircraft and replayed at the AAIB. The recorded data on the FDR showed that the aircraft had made the initial go around at an altitude of 1,040 feet agl.

The aircraft then levelled at 3,000 feet agl and joined the holding pattern over Epsom. During the second hold, whilst carrying out the unsuccessful attempt to lock down the left main gear, the aircraft had made a tight 360 degree turn which resulted in a recorded maximum vertical acceleration of 1.95g. The Epsom hold was then re-established and flown a further seven times. At 1253 hrs the aircraft touched down at 92 kt with flap 35 selected rolled 0.5 degrees to the right. The right main gear touched first. Five seconds later the FDR recorded that all three oleos were on the ground.

Ten seconds after the initial touchdown, at a speed of 67 kt, a sharp roll of 13 degrees to the left and a large vertical acceleration were recorded as the left main gear collapsed. The aircraft began to slew to the left, finally coming to rest, after a further 12 seconds, on a heading of 017°M. During this time the left hand propeller came into contact with the runway and slowed from 80% RPM to 63% RPM. The sound of the propeller blade tips striking the ground was audible on the CVR recording.

Once the aircraft came to rest the non-handling pilot pulled the engine 1 fire handle whilst the Captain set the parking brake. The Captain then called for the on-ground emergency checklist and the First Officer pulled the No 2 engine fire handle and set the fuel levers to off before the CVR and FDR recording terminated.

Engineering Aspects

The aircraft came to a halt on a taxiway having slewed through about 90° to the left. It rested on its nose and right main landing gears, the fuselage underside and the left wing tip. The left main landing gear had partially retracted into its well. For recovery the aircraft's left wing was lifted using air bags and then supported on a jack. The left gear began to extend as the wing was lifted and as it emerged from the wheel well it could be seen that the platform which forms one half of the over-centring stop in the lock-link (Figure 2) was not fully secured and was slightly displaced. The platform was aligned and taped in place. As the wing was lifted further and the gear reached full extension the lock-link went over-centre and the gear locked down.

One of the two bolts used to secure the platform was found to be missing and the other one was loose. At the position of the missing bolt contact marks showed that a bolt had been present at one time. The head of the remaining bolt was drilled for wirelocking but no wire was present. The wheel well was searched for the missing bolt. This was not found but a washer was found which matched the washer on the remaining bolt for type, size and paint colour. The platform was free to rotate about the remaining bolt and some damage marks showed that it had fouled an adjacent stepped surface of the lock-link and this had prevented the lock-link from achieving the over-centred condition. When this condition was replicated the lock-link was seen to be in the position described by the crew in which the ground lock pin holes in the two sections of the lock-link were misaligned by one diameter. No other defects were apparent in the left main landing gear, the

extension jack and the lock-link over-centring spring were tested separately, and the investigation concentrated on the retention and locking of the platform.

On manufacture, when the initial assembly of the lock-link has been completed and after locking wire has been fitted, the link is coated with a primer paint and a cosmetic silver paint. Evidence for the presence of locking wire should, therefore, be visible in the paint coating on the bolt head as well as in contact marks on its metallic surface (it is cadmium plated). The head of the remaining bolt was examined closely and at one of the three locking wire holes there was damage on the edge of the hole at each end which appeared consistent with the use of locking wire. The other two holes were clear of any such contact damage. Microscopic examination of the head of the recovered bolt revealed no evidence that it had been untightened at any time, in fact the condition of the painted surfaces indicated that it had not. (Under the paint there were some contact marks on the hexagon faces consistent with spanner or socket application in the tightening direction.) The paint on the bolt head had suffered some in-service damage or erosion and there were two small impact marks on the top edges of the head almost diametrically opposite one another. It could not be determined what the cause, or effect, of these impacts might have been.

Manufacturing and Overhaul Documentation

The landing gear manufacturer's assembly drawing for the lock-link did not show locking wire drawn at the location of the two bolts which secure the platform and a drawing note (specifying wire locking) which had been applied to other locations which required wire locking was not applied to the bolts. The bolts which were shown on the drawing (and supplied in the kit of parts for assembly) were specified as NAS 1303-15H. On this bolt, holes are provided in the hexagon head for wire locking. The assembly drawing referred to a manufacturing standards document which itself referred to a company process specification which defined standard practices for component assembly. This document contained the statement:-

"Where a drawing does not call out this specification together with an item reference, the appropriate instructions in paragraph 4 shall apply, in the absence of specific instructions to the contrary."

Paragraph 4 contained the process specifications including wire locking.

The lock-link was assembled in accordance with a document containing a list of numbered operations and inspections for the numbered operations were recorded on separate sheets. The subject lock-link was assembled as one of a batch of four, all being recorded on one set of paperwork. Three other batches of four were assembled at around the same time by the same team and, for the investigation, these were considered to form one batch and an attempt was made to trace these. In the instruction which included the final torque tightening of the platform bolts there was a note giving the process specification for the torquing of the bolts but no instruction or note on the locking of the bolts. Nevertheless, staff at the landing gear manufacturer stated that it was standard practice to apply wire locking to all nuts or bolts to which it could be applied and the physical evidence from the remaining bolt was that wire had been present in one of the holes in the bolt at some time. After the incident the assembly drawing, as the master reference document for the build of the lock-link (though it was only used within the company), was re-issued with wire locking shown and appropriate notes applied.

The landing gear manufacturer also found that the Component Maintenance Manual (CMM) for the lock-link (Chap 32-10-53 Rev 10) did not contain an instruction to wire lock the platform bolts even

though there were specific instructions to this effect for other fasteners. The CMM is the document that would be used by any agency other than the manufacturer that might overhaul a Fokker 50 landing gear or one of its component parts. This information did not affect the investigation of the collapse of the gear on PH-KVK as that gear had not been overhauled but the CMM, which was in the process of being re-issued while the investigation was in progress, was amended to include an instruction for the wire locking of the platform bolts.

The landing gear manufacturer reported that the company had recorded some cases of problems with the quality of wire locking between 1991 and 1995. The outcome of an investigation which was carried out was to improve the training of fitters in the required procedures and standards.

Maintenance History

The aircraft's records did not show that the landing gear on PH-KVK had been changed or overhauled since the aircraft had been built and so the gear had been last assembled during its original build by the manufacturer. There were two anomalies between the left landing gear component serial numbers recorded in the records and those found on the aircraft but these were single digit differences and were probably transposition errors. There was no discrepancy between the lock-link serial number as found and as recorded.

Detailed inspection of the landing gears is required in the scheduled "B" Checks at 650 hour intervals:-

"1.11 Examine the MLG, and make sure that:

- All the bolts, the nuts and the attachment points are correctly installed.
- All the split-pins, the lockwires and the lock plates are correctly installed and intact."

The last "B" Check had been conducted on 18 October 1996 at 9,552 airframe hours and 9,443 cycles.

A search of the records of unscheduled maintenance or rectification revealed no work directly affecting the platform and the stores record showed that this component had never been replaced. The downlock microswitch is contained within an open housing or bracket the front face of which is immediately behind the heads of the platform bolts. It was considered that, if work was being carried out on the microswitch, it was possible that the platform bolts could be mistaken for the front retention bolts of the bracket. In fact, the front of the bracket is secured by two countersunk screws transversely installed but its rear flange is held by two bolts of the same size as the platform bolts which are not wirelocked. It is not necessary to remove the bracket from the lock-link in order to remove or change the microswitch as the microswitch can be extracted with the bracket remaining in place. The last action recorded affecting the microswitch arose from the rectification of an indication fault in the right main gear on 13 February 1994. During rectification the left microswitch system was cleaned and adjusted as well as the right. However, adjustment of the microswitch operation is made to the striker bolt, not the microswitch itself, and should not have involved any disturbance of the bracket, its attachment bolts and screws or the platform bolts and there would seem to be little opportunity for their mistaken disturbance in that operation.

Safety Actions

On 9 December, the day following the accident, Fokker Services issued an All Operators Message (AOM) (AOF50.005) reporting the occurrence and recommending that an inspection for the presence of correct wire locking should be considered. As a result of the AOM a report was returned of a broken locking wire on another aircraft, with one section of the wire completely missing, and on 13 December the AAIB and the Accidents and Incidents Investigation Bureau (AIIB) of the Netherlands Aviation Safety Board issued recommendations to the Netherlands Airworthiness Authority (RLD) that Fokker's recommendation be strengthened, and that they require operators to carry out inspections. The AAIB recommendation reads as follows:-

Recommendation 96/83: It was recommended:-

That the Netherlands regulatory authorities should require operators of the Fokker 50 to inspect the retention bolts of the main gear down lock platforms to confirm the presence and condition of the locking wire between the two bolt heads, report back and repair any deficiency found, after advice from the manufacturer.

On 18 December, in an All Operators Message (006), Fokker announced the issue of Service Bulletin SB F50-32-033 which was mandated by RLD (Airworthiness Directive BLA1996-146(A)) and on 20 December the RLD raised an Action Record Sheet (ARS27-04-07) which required Fokker Services "to review the downlock platform retention design and provide changes to comply with JAR 25.607/1309".

In the feedback from operators, out of the existing 210 aircraft information was obtained on 138 plus information on 11 spare lock-link units. Two additional anomalies were reported; in one case the lock wire was wrongly applied and in the other (overhauled) case the wiring was missing. Included in these reports were 10 other units from the manufacturing batch containing the subject lock-link. (Amongst the lock-links not traced some had been overhauled and therefore their original condition was lost.) No anomalies were reported in these units.

The actions of the crew, in following the emergency procedures, left the normal landing gear selector and the "ALTERNATE" gear selector in the "DOWN" position. The "ALTERNATE" selector operates a cable system which, in the "DOWN" position, opens a dump valve which vents hydraulic pump pressure and mechanically releases the uplocks of the main gears and then the gear front doors. In this condition, with the normal gear selector also selected "DOWN", hydraulic pressure on both sides of the actuator is vented so that there is no hydraulic resistance to the leg descending under its own weight and aerodynamic loads. None of these functions were relevant to the circumstances in this accident and once the aircraft had touched down the hydraulic system offered no resistance to the leg retracting, allowing the wing tip, fuselage and left propeller to contact the ground. In view of this a further recommendation was made:-

Recommendation 97/25 Revision 1:-

(As revised following discussions with the Dutch AIIB)

It is recommended that Fokker Services consider, in the light of this accident and considering the variety of emergency situations which may arise, including leakage in the hydraulic system, whether changes to the landing gear emergency extension procedures are possible in order either,

1) to enable flight crews to decide when an "ALTERNATE DOWN" selection is appropriate

or

2) to return the landing gear hydraulic system finally to "NORMAL" operation with "DOWN" selected to pressurise the extension side of the landing gear actuator and reduce the likelihood of a landing gear retraction after landing.

Fokker Services should ensure that any changes are consistent with the design philosophy of the system and the check list.

Discussion

The platform bolts are secured by two mechanisms; primarily bolt torque and secondarily wire locking. A number of different cases were considered to explain the loss of bolt security and the absence of the locking wire.:-

- 1) Incorrect assembly. (Bolt torque incorrect, locking wire omitted or incorrectly applied.)
- 2) Wire intentionally removed by mechanic, possibly during microswitch work.
- 3) Wire broken accidentally during maintenance.
- 4) Wire broken by some damage in service.
- 5) Operating loads reduced bolt torque and were transferred to the locking wire after the bolts had become loose and causing it to break.

Evidence was found that a tightening torque had been applied to the remaining bolt and that locking wire had been present on the head of the bolt though the evidence is not sufficient to show whether the torque was correctly set or the wire locking correctly performed (Case 1).

The only work which the maintenance documentation for this area records, apart from inspection, lubrication and cleaning, is adjustment of the microswitch. This is effected through an adjuster on the pivoting lever arm in the downlock assembly and there seems little potential for mistaken interference with the platform bolts (Case 2).

The two small marks on the head of the remaining bolt show that there had been an impact (or impacts) on the head but this evidence is not sufficient to show what the cause or effect of this might have been and so, though Cases 3 and 4 are possible means by which the wire locking could have been lost, the evidence is insufficient to confirm either.

Close consideration of the platform and its retention bolts suggested that the bolts could be subjected to untightening loads in service though these proved difficult to assess (Case 5). Once the bolts started to turn these loads would be transmitted to the wire itself and could cause it to fail. The Action Record Sheet raised by the Netherlands airworthiness authorities initiated a review of the design of the downlock platform retention system.