

# **Fokker F27 Mk 500 Friendship, G-JEAH, 4 August 1995**

**AAIB Bulletin No: 4/96 Ref: EW/C95/8/1 Category: 1.1**

**Aircraft type and registration:** Fokker F27 Mk 500 Friendship, G-JEAH

**No & Type of Engines:** 2 Rolls-Royce Dart 532-7 turboprop engines

**Year of Manufacture:** 1986

**Date & Time (UTC):** 4 August 1995 at 0709 hrs

**Location:** Belfast City Airport

**Type of Flight:** Public Transport

**Persons on Board:** Crew - 4 Passengers - 18

**Injuries:** Crew - Nil Passengers - Nil

**Nature of Damage:** Turbine burnout on both engines

**Commander's Licence:** Airline Transport Pilot's Licence

**Commander's Age:** 58 years

**Commander's Flying Experience:** 8,410 hours (of which 2,788 were on type)

Last 90 days - 204 hours

Last 28 days - 77 hours

**Information Source:** AAIB Field Investigation

## **History of the Flight**

The aircraft, using callsign JY 1730, took off from Leeds Bradford Airport at 0605 hrs for a scheduled flight to Belfast City Airport with the commander as the handling pilot. Take off and climb were normal and the commander established in the cruise at Flight Level (FL) 145 at an indicated airspeed of 185 kt; no problems were recorded in the technical log or noted by the crew during the flight.

Approximately 45 nm from Belfast, where Runway 04 was in use, the crew requested and were given initial descent clearance. As he commenced his descent, the commander asked the first officer to select the high pressure cock (HPC) levers to 'Open'. However, the first officer had just recently completed his line training and was slightly unsure of the procedure, and so the commander took the opportunity to demonstrate the correct way to select the HPC levers to 'Open'; this action was corroborated by evidence from the CVR. The other descent checks were completed

by the first officer and monitored by the commander. As the aircraft levelled at FL 120, JY 1730 was transferred to Aldergrove ATC who then informed the crew that Runway 22 was now in use at Belfast City Airport. The crew had already briefed for an approach to Runway 04 and so the commander then rebriefed for the new runway. Over the next few minutes, the aircraft was cleared for a further descent and transferred to Belfast City ATC. Then, once JY 1730 was cleared to an altitude, the commander asked the first officer for the approach checks. According to the CVR evidence most of these checks were completed but there was no mention of the HPC levers during this time; in the company checklist the HPC check is required between those for the Decision Height and the Pneumatic Pressures. The CVR reflects a conversation about Decision Height and then covers the Pneumatic Pressure check. However, the first officer recalled pushing the HPC levers to 'Lockout' and the commander recalled monitoring this action. Subsequently, the commander intercepted the ILS at approximately 13 nm from touchdown and commenced his final approach. During this time the first officer completed the landing checks and these included a response from the commander that he saw 'Two Blues', which indicated to him that the cruise locks had withdrawn; this call was clearly recorded on the CVR. Touchdown was at the normal landing point with Flap 40 selected and at the correct speed; threshold speed had been assessed as 95 kt. For landing, the weather was good with a surface wind of 080°/05 kt and a temperature of 18°C.

After landing, the commander retarded the throttles and then selected the throttles to 'Ground Fine'. At this stage the priority for the first officer was to monitor the lights relating to the propeller locks and associated propeller pitch angles. He was immediately aware that the required 6 lights, comprising 2 Blues, 2 Ambers (indicating that the flight fine locks had been withdrawn) and 2 Reds (indicating that the propellers had decreased through 18° pitch) were not all on; the 2 Ambers were on, but he was not certain that any others had illuminated. He advised the commander who looked for the 2 Red lights and confirmed that they were out. Additionally, the commander did not feel the normal retardation, or hear the normal propeller noise, and so he reselected 'Ground Fine' again. This still had no effect on the propellers and so, after one further attempt to select "Ground Fine", he selected 'Gust Lock', but again this had no apparent effect on the propellers. G-JEAH was still at approximately 80 kt and the commander commenced braking; he also noted that both TGTs were close to 950°C but did not notice the propeller RPMs. He then closed both HPC levers to 'Shut' and brought the aircraft to rest on the runway using moderate braking. Shortly after G-JEAH stopped, a crew member of another aircraft called JY 1730 to report flames coming from the left engine of G-JEAH; the ATC controller heard this call and immediately alerted the Airport Fire Service. Within the cockpit, the commander looked and could see a little smoke but no fire from the left engine. The first officer looked to the right and could also see some smoke but could not identify the source. There were no cockpit fire warnings, but the commander selected the HPC levers to 'Feather', pressed the 'Feather Buttons' and fired 2 fire bottles into each engine. By this stage, the Fire Section was on scene and saw fire coming from both engine exhausts; the fires were quickly extinguished by the Fire Section. The commander had already called one of the cabin attendants to the cockpit to brief her and, because the situation was under control, decided not to order an emergency evacuation. The passengers then disembarked through the normal exit using a ladder provided by the Fire Section.

After disembarking from the aircraft, one of the passengers took a series of photographs showing the left side of the aircraft. The first of these photographs shows the left propeller in the feathered position; subsequent photos show the propeller back out of feather.

## **The F27 Rolls Royce Dart powerplant**

The 4 blade Rotol propeller can be varied in pitch from 0°(ground fine) to 87° (feather). During normal flight, engine(and propeller) RPM is maintained at the selected value by a conventionally hydromechanical constant speed unit (CSU), from a maximum enginespeed of 15,000 RPM to a minimum of 11,000 RPM. The propeller incorporates two pitch locks: a *cruise lock* at 32° propeller pitch, and a *flight fine* lock at 20°. The purpose of the cruise locks is to provide protection in the event of a fault causing a single propeller to fine off, which, at true airspeeds in excess of 265 kt, could create asymmetric loads or propeller overspeeds capable of hazarding the aircraft. The flight fine pitch locks prevent the propeller pitch moving inadvertently below the flight fine position, and are withdrawn only when the aircraft is on the ground. Engagement and disengagement of the cruise locks is automatic when the HPC levers are set to 'Open', and occurs as the propeller passes through 34° pitch, sensed by hub switches built into each propeller; the cruise locks can also be withdrawn manually, by selecting the HPC levers to "Lockout". Removal of the fine pitch lock is achieved by selecting *ground fine* pitch on either power lever, or engaging the gust locks.

Because the Rolls Royce Dart is a single-shaft engine, the mass flow of air through the turbine is proportional to propeller speed. It is therefore essential that propeller pitch is maintained at a suitably low setting until the engine has spooled up adequately, otherwise RPM stagnation and associated over-fuelling will cause rapid turbine burnout. In practice, this dependency means that if the propellers are at the flight fine pitch setting and the aircraft is static on the ground, or at low speed, then even with the power levers fully retarded the RPM will be too low for the scheduled fuel flow, causing the TGT to rise progressively before stabilising at an abnormally high level, albeit one which is not likely to cause damage to the turbines; if the throttles should be advanced even moderately under these conditions, however, turbine burnout will occur in a matter of seconds. Similarly, if a propeller is on the cruise lock and the airspeed is allowed to decay with the power lever retarded, for example should the propeller hang on the cruise lock during an approach to land, then the RPM on that engine will decay below normal and the TGT will rise as airspeed reduces; if the throttles are then opened rapidly, over-fuelling and immediate burnout of the affected turbine will occur.

For reasons which are explained later, a failure of the 34° hub switch contacts on a single propeller will prevent both cruise locks from withdrawing, leading potentially to a double engine burnout. Such an event could have critical consequences should it occur whilst airborne, for example during an overshoot. For this reason, the Flight Manual calls for selection of HPC lever to 'Lockout' (manual override) for approach, take off, and climb.

## **Propeller control system**

Compared with modern multi-shaft engines fitted with mechanically simple propellers, the pitch control system on Rotol propellers fitted to the single shaft Dart engines is complex. Both the CSU control and safety lock systems are electro-hydraulic, using engine oil. The CSU pump output pressure is nominally 600 psi, but whenever the propeller pitch is above 34° and the cruise locks are engaged, the oil pressure in the *fine pitch* side of the CSU control circuit is reduced to 180 psi by a hydraulic servo valve (the fine pitch relief valve); below 34° pitch, the *fine pitch* oil pressure is restored to the full 600 psi. The *course pitch* supply to the propeller is maintained at 600 psi at all times.

### **Pitch lock mechanism**

The pitch lock comprises a spring collet with a series of baulk blocks mounted on spring fingers, see item "D" in Figure 1, which intrude into the path of the internally stepped sleeve ("E") formed on the forward side of the pitch change piston. An internal support sleeve "G", which has three steps machined onto its outer diameter, slides inside the lock collar such that the stepped section engages the inside of the baulk collar, limiting the extent to which the lock fingers can collapse inward. The support sleeve has three operating positions:

- i) Cruise lock engaged
- ii) Flight fine lock only engaged
- iii) Neither lock engaged

A large spring pushes the support sleeve toward the fully engaged position at all times. Withdrawal of the sleeve to the second and third stage positions is achieved by two independent hydraulic pistons: the cruise lock withdrawal piston ("F"), and the flight fine pitch lock withdrawal piston ("H") respectively. (The electro-hydraulic system controlling the operation of these pistons is described in detail later.)

With the propeller at a pitch setting above  $34^\circ$ , as shown in Figure 1, the lock fingers are extended fully and the internal support sleeve is fully engaged inside the spring collar. In this condition, the cruise lock is engaged. Should the propeller pitch fine off with the cruise lock engaged, the outer end of the pitch change piston sleeve "E" would abut the lock fingers, as shown in Figure 2, preventing any further reduction of pitch. In this condition, the propeller is (hung) on the cruise lock. It should be noted that without the support provided by the internal support sleeve, the inward thrust developed across the chamfered interface between the piston sleeve and the lock fingers (see enlarged view in Figure 2) would flex the fingers inward and allow the piston sleeve to override the lock collar.

Withdrawal of the cruise lock is achieved by moving the cruise lock withdrawal piston ("F") to its fullest extent, pushing the internal support sleeve forward to the second stage position and freeing the lock fingers to collapse inward as far as the second step on the support sleeve. The pitch change piston can then override the lock collar and reduce the blade pitch back to the point where the internal shoulder on the piston sleeve comes into contact with the lock collar, as shown in Figure 3: this is the *flight fine* stop position.

Withdrawal of the flight fine lock is achieved by movement of the flight fine lock withdrawal piston ("H"), which draws back the support sleeve to the third stage position, freeing the lock collar to collapse fully. The internal step on the piston sleeve can then override the lock fingers, and the propeller pitch can move fully back to ground fine (zero pitch), as shown in Figure 4.

### **Pitch lock control and indicating systems**

The supply of hydraulic oil to the pitch lock withdrawal pistons is controlled primarily by solenoid valves signalled by a system of microswitches and/or latching relays, the circuit design of which provides the appropriate control logic. In broad terms, the circuits controlling the operation of each pair of locks (i.e. the left/right flight fine locks, and the left/right cruise locks) are arranged in series across the aircraft, i.e. the condition for lock removal must be met on both engines before the logic requirements for lock withdrawal are met, thus protecting against asymmetric conditions.

Independent comparators in the cruise lock and flight fine lock control circuits monitor the electrical integrity of the solenoids and relay windings, and will illuminate a warning light on the flight deck to indicate an anomalous (unsafe) condition of the relevant lock circuit should a fault be detected; the crew can then isolate the affected circuit using either the *cruise lock isolate* or *flight fine lock isolate* switch, as appropriate. The cruise locks can be removed at any time, even with the cruise lock circuit electrically isolated, by placing the HPC levers into the "Lockout" position, which invokes a hydro-mechanical override system to *manually* remove the locks.

### Cruise lock control

In normal circumstances, the cruise locks engage automatically as the propeller pitch increases through 34°, and withdraw again when the propeller pitch decreases below 34°. Propeller blade angle is sensed on each propeller by a pair of hub switches comprising carbon brush contacts connected via a cam linkage to the blade root, and which move into contact with a slip ring mounted on the reduction gearbox housing as the blade angle reduces through 34°, (Figures 1 to 4 show the 34° hub switch in schematic form.) Because the hub switches *make* at a blade angle 2° above the cruise lock setting, the locks will normally withdraw slightly in advance of the blade reaching the actual lock position.

Figure 5 is a schematic circuit diagram of the propeller control and indicating systems. Those circuits relating to cruise lock operation are coloured blue. When both left and right propeller hub switch contacts have closed, the logic requirement for cruise lock withdrawal is met and both cruise lock withdrawal solenoids are activated, porting hydraulic oil at 600 psi to the fine pitch relief servo valve (not shown in the diagrams). Operation of this valve has two separate functions:

- i) it causes the pressure in the fine pitch oil galleries to revert from 180 psi back to the full CSU pump output pressure of 600 psi, and
- ii) it closes off a drain (vent) line connected to the sensing chamber of a pressure switch (identified as the *cruise lock "unlocked" pressure switch* in Figure 5, and discussed in more detail later under the heading "Cruise lock indicating system").

The increase in pressure within the fine pitch oil gallery from 180 to 600 psi causes the spring biased staging valve (item "J" in Figure 1) to move forward against its bias spring, porting oil at 600 psi to the dual bodied cruise lock withdrawal piston ("F"), which moves fully forward against its stop, moving the internal support sleeve "G" to the second stage position and withdrawing the cruise lock.

It can be seen from Figure 5 that the cruise lock withdrawal solenoids are connected in series, the *supply* being fed through the left propeller hub switch and the *earth return* path being provided by the right hub switch. Therefore, a failure of either hub switch will inhibit cruise lock withdrawal on both propellers, leading potentially to a double engine burnout.

In order to provide a measure of redundancy and reduce the probability of failures of this kind, the 34° hub switch on each propeller actually comprises two separate sets of brush contacts actuated by independent blades, which operate in parallel. Thus, provided at least one switch contact on each propeller *makes*, the logic requirement for lock withdrawal will be met satisfactorily and the locks will withdraw. The *manual override* provides a further measure of safety. When the HPC levers are moved fully forward to the "Lockout" position, hydraulic oil at 600 psi is ported

directly to the fine pitch relief servo valve from the CSU, in lieu of the cruise lock removal solenoid. (The flight manual requires "Lockout" to be selected for approach, take off, and climb.)

### **Cruise lock indicating system**

Each cruise lock hydraulic circuit incorporates a pressure switch (the *cruise lock 'unlocked' pressure switch* in Figure 5), which operates a blue *cruise lock unlocked* light on the flight deck. The sensing chamber of the switch is connected to:

the *inlet* to the CSU controller pump (which is supplied with engine oil at 75 psi), via a restrictor, and

the 3rd oil line (the supply line to the flight fine lock removal piston), via ports in the fine pitch valve servo spool.

Whenever the lock collar inner support sleeve ("G") is fully engaged, ie the cruise locks are engaged, an annulus in the bore of the sleeve connects the 3rd oil line to drain, see Figure 1.

Thus, if:

the cruise lock is engaged (support sleeve annulus closed)

AND

the fine pitch relief valve is in the *cruise* position,

.....then the pressure switch will be vented to drain, the contacts will be open, and the blue light will remain out; closure of either the annulus OR movement of the fine pitch relief valve spool will therefore cause the blue light to come on.

Removal of the cruise locks, whether automatically (via the 34-hub switches) or through use of the manual override (HPC lever to "Lockout"), will supply pressure to the fine pitch relief servo valve, causing the valve spool to move and close off the connection to the 3rd oil line. The pressure in the sensing chamber of the switch will thus rise to 75 psi and cause the blue light to illuminate on the flight deck.

Should the spool of the fine pitch relief valve jam for any reason, the *fine pitch* control pressure supplied to pitch change piston will remain at 180 psi; the staging valve therefore cannot move and consequently no oil will be ported to the cruise lock removal piston, the lock sleeve will not withdraw, and the cruise lock will remain engaged. In these circumstances, the vent path to drain will be maintained and the blue light will not illuminate, correctly indicating that the lock is still engaged.

Should the fine pitch relief valve spool move correctly but the lock sleeve fail to withdraw for any reason, then the blue light will illuminate, giving a false indication on the flight deck.

In summary, a *false* blue light indication on the flight deck could occur only if:

the fine pitch relief valve spool moves correctly

**AND**

the staging valve was jammed

**OR**

the PCU pump failed to provide sufficient oil pressure to break through the lock eg. due to leakage

**OR**

the cruise lock withdrawal piston or the support sleeve was jammed,

**OR**

one or more lock fingers was jammed or deformed

**OR**

there was a partial seizure of one or more blade root bearings.

### **Flight fine lock control system**

The flight fine lock control circuit is coloured amber in Figure 5. Operation of the flight fine pitch lock withdrawal mechanism is controlled primarily by a system of microswitches on the power lever quadrants, with backup control being provided by a second set of microswitches in the gust lock mechanical circuit. As with the cruise lock electrical circuits, the signal and control system components are distributed between the two propellers in series mode: those associated with the left propeller control the *supply* side of the electrical circuit, and those associated with the right propeller control the *earth* side of the circuit. The electrical signals from these switches control latching relays and solenoid valves which, when all the logic requirements of the circuit have been met, send hydraulic oil at 600 psi via the 3rd oil line to the flight fine lock withdrawal piston.

Withdrawal of the flight fine locks is achieved by pulling either, or both, power levers fully back, through the lift/spring detent to the ground fine position. This results in closure of the ganged microswitch contacts "A1" and "A2", allowing current to flow through the windings of the two lock removal solenoids (the supply being fed through "A1" and the earth return path being provided by "A2"); current also flows through the windings of the latching relays R1 and R2. Once latched, relays R1 and R2 maintain the *supply* and *earth return* paths to the lock withdrawal solenoids so that when the power levers are released and the spring returns them to the idle position (opening contacts A1 and A2 once again), the lock removal solenoids remain energised. Movement of either power lever beyond the 14,000 RPM position, ie sufficiently to cause contact B1 or B2 to open, will simultaneously break the circuit to the lock removal solenoids and the latching relays, causing the lock withdrawal piston to retract and allowing the flight fine lock mechanism to re-engage as blade pitch increases past 20°.

A failure of either A1 or A2 to close for any reason would prevent withdrawal of both flight fine locks. Engagement of the gust lock mechanism, however, will cause the alternative pair of contacts C1 and C2 to close, thus making and latching the solenoid removal circuit. The circuit will remain latched, as before, until either of the power levers is advanced to the 14,000 RPM position.

### **Flight fine lock indication**

A pair of amber "flight fine unlocked" indicator lights on the flight deck are wired in parallel with the flight fine removal solenoids. Although these comprise two separate lights, they actually provide a single indication that the electrical supply to the flight fine lock withdrawal solenoids has been made.

Positive confirmation that each propeller has moved below the flight fine pitch lock is provided by separate and independent indicator lights on the flight deck, which are supplied

from supplementary hub switch contacts on each propeller, similar to those which control cruise lock withdrawal, but which in this case close as the propeller pitch passes below 18°. The 18° indicator light circuits are coloured red in Figure 5.

### **Summary of propeller controls and indication**

Operation of the cruise lock is solely automatic if the HPC levers are at 'Open', when the system relies on the hub switches to retract the lock as the propeller pitch decreases through 34°. A malfunction of the cruise lock withdrawal solenoids or relays will cause an amber "unsafe" warning light to illuminate on the flight deck, and the *cruise lock* electrical system can be isolated by means of an isolate switch; however, a hub switch failure will not be detected. The cruise lock can be retracted manually by the selection of the HPC lever to "Lockout", regardless of the state of the electrical control circuit. Illumination of a "Blue Light" indicates that the hydraulic system demand for cruise lock withdraw has been made on that propeller, and that the fine pitch relief valve spool has moved, increasing the fine pitch control pressure to 600 psi; it does not indicate that the locks have physically withdrawn, or that the blades have moved below the lock position.

The flight fine pitch locks are operated manually by selecting either or both power levers to "Ground Fine". Illumination of the "Amber Lights" indicates that both flight fine pitch locks have been demanded to withdraw. Illumination of a "Red Light" provides positive confirmation that the associated propeller is below 18° pitch. Selection of gust locks engaged (on the ground) provides an alternative means of withdrawing the flight fine pitch locks. Re-engagement of the flight fine pitch lock requires that one or other power lever is moved toward the *high power* end of the quadrant, to about the 14,000 RPM position. A malfunction of the flight fine pitch lock withdrawal solenoids or relays will cause an amber "flight fine pitch lock unsafe" warning light to come on; the electrical system can then be isolated by means of an isolate switch.

## **Examination of the aircraft**

### **Engines and propellers**

Both engine exhaust ducts contained small fragments of debris consistent with a turbine burnout, but there were no external indications of fire or excessive temperature affecting the nacelles or the external surfaces of the engines. Based on the amount of debris in the exhaust ducts, the right engine appeared to be slightly more damaged than the left engine. Neither propeller would turn freely, consistent with burnout debris jamming the turbine sections of the engines.

Because the propeller blades had been moved to feather immediately after the incident, and then moved back out of feather again, it was not possible to determine the pitch of either propeller when the aircraft landed.

The control linkages connecting the power levers and HPC levers in the cockpit to their respective engine components were intact; the linkages operated freely, and the rigging was within limits.

The propellers were moved into feather without difficulty, and both propellers removed. A visual inspection of each propeller, so far as this was possible, revealed nothing unusual except for excessive wear of the 34° hub switch brush contacts on the right propeller, both of which were worn below the limits specified by the manufacturer. [The worn brushes would have increased significantly the probability of the right hub switches failing to close when blade pitch reduced

through 34°; such a condition would have prevented both cruise locks from withdrawing automatically, but moving the HPC levers to "Lockout" should still have effected withdrawal.]

Both engines were removed and replacement units installed on the aircraft. After replacement of the worn hub switch brushes on the right propeller, both propellers were reinstalled. Post installation checks revealed that one of the fuel trimmer switches in the cockpit was defective and this was replaced, but no other abnormalities were noted.

Full (static) functional checks of both propellers were carried out, in accordance with the maintenance schedule, during which the pitch change mechanisms and lock systems on both propellers functioned entirely satisfactorily. The engines were then started and full functional checks of both engines and propellers were carried out per the maintenance schedule; again, both propeller pitch change and lock systems operated entirely satisfactorily. The aircraft was then returned to service.

During the initial stages of the first take off following the engine change, the flight fine pitch lock unsafe warning light illuminated and remained on. (Transient illumination of this light is not unusual as the power levers are pushed forward past the 14,000 RPM position in preparation for take off, but it is not usual for the light to remain on thereafter.) The take off was abandoned, and the aircraft impounded for further detailed examination and testing under AAIB supervision. The fault condition was found to be stable and repeatable, allowing a progressive analysis and testing program to be undertaken involving all of the relays and solenoids controlling the propeller lock systems. This identified an electrical fault in the flight fine pitch lock removal solenoid on the (replacement) left engine. Replacement of this solenoid by company maintenance personnel effected a positive cure of the fault condition. (It should be noted that the defective solenoid valve comprised part of the replacement engine, and was not fitted to the aircraft at the time of the original incident.) After satisfactory static checks of the propellers, followed by further comprehensive functional tests with the engines running, the aircraft was released to service with no further faults being reported subsequently.

## **Fire bottles**

Inspection of the engine fire extinguisher bottles showed that, of the four bottles reportedly fired by the crew, only one had actually discharged. The electrical circuits to the fire bottles were checked and found to be serviceable. The fuseheads from each of the unfired bottles were therefore taken to the manufacturer for inspection and testing under AAIB supervision.

Continuity and resistance checks showed all fuseheads to be within specification. One of the fuseheads was fired under test conditions, and was found to perform within specification; the remaining fuseheads were sectioned and inspected visually, and the charge contents weighed. Again, no abnormalities were found.

It is possibly relevant that the specification for the fuseheads allows a firing time of up to 500 ms, ie if the extinguisher *discharge* button is not held down for at least 1/2 second, some bottles may not fire.

## **Flight Recorders**

The CVR (Fairchild A100A) and FDR (Sundstrand Universal Flight Data Recorder) were replayed satisfactorily using AAIB equipment. The CVR covered a 30 minute period which included the descent, approach and landing into Belfast City Airport. The four tracks contained the pilot's and copilot's microphones, an area microphone, and the public address channel. The FDR recorded five parameters; altitude, airspeed, heading, normal acceleration and flap; there was no recording of engine power.

The area microphone on the CVR contained frequencies from which engine RPM could be derived. This analysis showed that when power was reduced during the descent, the engine RPM which had initially been around 11,000 reduced to 8,700 RPM. When the landing checks were carried out the derived engine RPM was 8,200, then flap 26 was selected at 149 kt IAS and around a minute later RPM reduced to 7,800. At 130 kts IAS flap 40 was selected with an engine RPM at this stage of 7,500; this RPM gradually reduced during the landing and ground roll. Higher harmonics of the engine frequencies were then evident on the recording, and the lowest frequency recorded before the signal level became too low gave a derived RPM of 4,000.

A comparison was made with the engine frequencies recorded on another CVR containing a normal landing on G-JEAH. This showed that the derived engine RPM was initially around 14,000 RPM. This reduced during the approach, and the crew included in the landing checks a check of the RPM at 11,000 which confirmed the CVR derived value. During final approach the power reduced and after touchdown the RPM was between 6,830 and 7,500 before power increased again to taxi.

## Potential causes of double engine burnout

The CVR recorded verbal comments associated with the movement of the HPC levers from "Lockout" into the "Open" position at the top of descent; however, there is no corresponding confirmation of them being moved back to "Lockout" prior to the landing approach or subsequently, although a reference is made during the early stage of the approach to "blue lights". The first indication to the crew that anything was amiss was the failure to achieve the red 18° pitch lights after *ground fine* was selected during the rollout; both amber lights were illuminated, however, confirming the electrical demand for flight-fine pitch lock withdrawal had been made. As the speed decayed through 80 kt both TGTs were seen to be rising through 950°C but further attempts by the crew to achieve ground fine, including selection of gust locks, failed to produce the desired red lights.

There was no need to advance the power levers to expedite clearance of the runway or for any other reason, and the crew are positive that the power levers were not moved at any stage during the landing except for their attempts to select ground fine; nevertheless, flames were seen in the exhaust ducts as the aircraft came to rest. From the evidence, it is clearly apparent that both propellers must have hung either on the *flight fine* locks, or the *cruise* locks.

Since both amber lights illuminated after landing, current must have been supplied successfully to both flight fine withdrawal solenoids. A failure of either flight fine lock removal solenoid would have resulted in the *fine pitch lock unsafe* warning light illuminating on the flight deck; this did not occur. Furthermore, the consequences of both propellers hanging on the flight fine locks is not consistent with the evidence.

Had the propellers hung on the flight fine pitch locks, the RPMs and temperatures during the approach would have been entirely normal; following touchdown, a failure to achieve ground

fine would have resulted in a slow rate of temperature rise, but this could not have caused engine damage in the short time between the aircraft touching down and reaching the end of the landing roll. Tests carried out by the AAIB to assess the rate of temperature rise with the propellers on the flight fine locks confirmed that the rate of TGT rise was low, and that it would take at least 35 seconds to reach 950°C - even with the aircraft stationary throughout. For damaging temperatures, ie significantly in excess of 1,050°C, to have occurred during the landing roll, both propellers must have been at a pitch setting considerably higher than flight fine pitch stop, ie hung on the cruise locks.

The CVR analysis showed that the engine RPMs during the subject approach were significantly lower than normal. Comparison of the figures obtained with theoretical RPM-vs-airspeed data supplied by the propeller manufacturer showed that the RPM decay was comparable to that which would be expected from propellers at the cruise lock pitch setting.

### **Failure of the cruise locks to withdraw automatically**

If, as the crew believe, the HPC levers were placed in the "Lockout" position prior to the start of the approach, and both blue lights illuminated, then there is no single fault condition which could have caused disablement of both cruise lock withdrawal systems in the circumstances described. Specifically, the action of selecting HPC levers to "Lockout" would have bypassed entirely the electrical control circuits, and the presence of two blue lights would have confirmed that hydraulic oil at 600 psi had been supplied to the lock withdrawal systems on both propellers. For both propellers to hang on the cruise locks in these circumstances would require two entirely separate failures, one on each propeller, involving jamming or partial seizure of the staging valve, the withdrawal piston or support sleeve, or the lock fingers. Since, neither propeller's mechanical components was disturbed subsequent to the event, and both propellers functioned normally on test and in service subsequently, it is clear that neither propeller mechanism can have been defective in the manner implied.

The only defect found, despite extensive investigation, was the excessive wear of both 34° hub switch brush contacts on the right propeller. With this defect present, it is likely that the hub switch on the right propeller would have been rendered inoperative; intermittently at least. This would have prevented both cruise locks from withdrawing automatically, but only if the HPC levers had been left in the "Open" position.

## **History of cruise locks**

### **Service Bulletin F27/61-40**

On 9 January 1992, Fokker Aircraft B V issued Service Bulletin F27/61-40 applicable to aircraft serial numbers 10102 through 10692 equipped with Dart RD7 engines modified to post SB DA72-198 and DA72-348 configuration. This service bulletin comprised procedural changes which effectively required the HPC levers to be placed in the "Lockout" position at all times during flight.

In the Bulletin's introduction, Fokker state the following: "The purpose of the cruise lock is to prevent inadvertent reduction of propeller blade pitch below the cruise lock position. Such a malfunction could result in exceeding the maximum RPM for which the propeller and engine were designed, and high asymmetric drag. It could be caused by a propeller drive disconnect or a propeller control system failure leading to inadvertent movement into fine pitch. As operational

experience accumulated, the modes of drive disconnect became known and two improvements to the engine were introduced to prevent drive disconnect. Past experience with the latter standard of engines has demonstrated that drive disconnect is now extremely remote. The effect of high asymmetric drag due to inadvertent selection of fine pitch without drive disconnect has proved to be acceptable. Consequently, the cruise lock is no longer necessary."

Compliance with Service Bulletin F27/61-40 was recommended; however, operators generally chose not to implement it.

### **Hub switch brush wear inspections**

The hub switch brushes on G-JEAH were last inspected on 25 April 1995, during a C Check, some 584 hours prior to the incident.

In October 1987, Dowty issued a service bulletin applicable to Rotol propellers fitted to all Dart engined aircraft, which addressed the issue of carbon brush wear. In essence, the bulletin specified brush wear tolerances and instructed operators to institute an interim inspection program during which the brush wear rates in practice were to be established by each operator, having due regard to variations within the operator's fleet which might cause the brushes on certain aircraft to wear at higher rates than the norm; for example, on aircraft used for training. Operators were then required to use the information obtained to establish a maintenance interval appropriate to their operation, and incorporate such inspections into their schedules.

At the time the service bulletin was issued, G-JEAH was maintained under the auspices of another large F27 fleet operator, and was inspected in accordance with the findings of that operator's implementation of the service bulletin.

Subsequently, the (present) operator of G-JEAH took over the maintenance of its own F27 fleet. Since the check interval into which the brush inspections were incorporated under the new arrangements was shorter than that applicable previously, it was believed that the *new* interval would be acceptable under the terms of the Dowty service bulletin. However, no specific account was taken of the increased wear rates which might be achieved on aircraft used for training purposes. In the light of this incident, the operator is reviewing hub brush wear rates in order to ensure that the inspection intervals are consistent with the requirements of the service bulletin.

### **Flight crew operating instructions**

At the time of the accident, the relevant instructions and information available to the crew were contained within the Flying Manual and in "Notices To Aircrew":

#### **Flying Manual:**

In the "Descent Checks" the HPC levers could be selected "as required", with the proviso that the TAS was restricted to 265 kt if the HPC levers were left at "Lockout".

In the "Approach Checks" the HPC levers were to be selected to "Lockout"; the expanded checklist required a check that the two blue lights were on. There was also a note contained within the "Flight Handling Section" that the HPC levers should be at "Lockout" at speeds below 140 kt, to safeguard against cruise lock "hang up" causing excessive TGTs at low speed.

In the "Landing Checks" there was no further requirement to check the propeller lights although the commander's normal practice was to include a check of the blue lights in addition to his checking of gear lights.

Within the "Systems Operations Section" there was the following paragraph: "To safeguard against propeller hangup at the cruise lock, this lock should be manually withdrawn at speeds below 140 IAS (HP cock from OPEN to LOCK OUT). If, after "Lockout" has been selected, the propeller does not pass below the cruise pitch stop (indicated by continued decrease in engine RPM and rise in TGT, even with the cruise pitch stop removed lights illuminated) the propeller is "HUNG" on the cruise pitch stop."

### **Notices To Aircrew:**

The notice relating to HPC levers was dated 15 March 1993. It emphasised the need for careful and correct cruise lock control on the various phases of flight and included the following instructions:

"HP Cocks MUST BE to lockout for take off and climb, there is no requirement to place the HP Cocks to open in the cruise. The temperature at 20,000 ft would have to be in excess of +20°C to exceed 265 knots TAS.

During descent, the HP Cocks must be moved from lockout to open if the TAS exceeds 265 knots.

Care must be taken when entering the hold or reducing speed after a high speed descent. If the HP Cocks are left at open (particularly in the hold) when the speed has reduced to 140 knots or less, and the throttles are opened, the engines can be destroyed in seconds."

After the accident, the following additional Notices To Aircrew were promulgated by the operator:

The first was dated 11 August 1995 and updated all crews on the progress of the investigation. It also formalised the requirement to check and call "2 Blues" in addition to the gear check during the "Landing Checks".

Thereafter, on 17 August 1995, all crews were instructed to operate HPC levers in "Lockout" and restrict airspeed to below 265 kt TAS.

On 14 September 1995, a further notice detailed changes to the checklists. These were as follows:

Descent Check: "HP Cocks-LOCKED OUT, 265 kt MAX"

Approach Checks: "HP Cocks-LOCKED OUT, 2 BLUE LIGHTS"

Landing Checks: After "Landing Gear" include new check: "Propellers-2 BLUE LIGHTS, RPM 11,000 Approx"

## **History of propeller induced Dart engine burnouts**

Accident reports were reviewed to ascertain the number and extent of engine burnouts on Dart engines in which the propeller cruise locks were implicated. Between February 1964 and May 1991 a total of 71 events were identified, of which 25 involved double engine damage on twin engine

aircraft, and 2 involved multiple engine damage on 4 engine aircraft. The remaining events involved damage to a single engine only. The incident involving G-JEAH is the only other identified propeller cruise pitch lock related event since May 1991.

All except one of these events occurred during flight training (involving low speed handling) or during the approach/landing phase of scheduled operations; the exception occurred shortly after take-off when the aircraft entered a heavy rain cloud.

In many cases, detailed information about these events was limited. Nevertheless, of the double engine burnouts, crews apparently admitted to not selecting HPC to 'Lockout' on 5 occasions and, on one fatal accident, the HPC levers were found at 'Open' during examination of the wreckage. Additionally, electrical problems were identified in 10 of the multi-engine occurrences. In the remaining cases of multiple engine burnout, whilst the HPC levers were reportedly at "Lockout" on all occasions, the available evidence suggested otherwise.

In those cases involving a single engine burnout, a malfunction of the cruise lock system on the associated propeller was implicated, rather than a failure by the crew to select 'Lockout'.

During the period reviewed, no report was discovered which involved a propeller drive disconnect or a propeller control system failure, i.e. the hazardous conditions against which the cruise locks were intended to protect.

## **Recommendations**

The historical evidence suggests that the cruise locks themselves tend to cause problems, whereas in the case of the F27, the hazards which they were designed to overcome do not appear to have materialised as a significant issue in practice. Since Fokker Aircraft BV stated in Service Bulletin F27/61-40 that "the cruise lock is no longer necessary", it would appear that the practice of moving the HPC levers to 'Open' in flight is an unnecessary and potentially dangerous action. The following Safety Recommendations are therefore made:

96-9: The CAA should make the implementation of Fokker Service Bulletin F27/61-40 (requiring high pressure cock levers to be kept in 'lock out' during all phases of flight) mandatory for all F27 aircraft on the UK Register, in order to minimise the risk of turbine 'burnout'. Implicit in this recommendation is the requirement for all affected engines to meet the modification standard specified by SB F27/61-40.

96-10: Fokker Aircraft BV should urge all operators of F27 aircraft to implement Service Bulletin F27/61-40 (requiring high pressure cock levers to be kept in 'lock out' during all phases of flight) in order to minimise the risk of turbine 'burnout'.

96-11: The CAA should review other Rolls Royce Dart powered turboprop aircraft to determine whether engine operating procedures require changing to minimise the risk of turbine 'burnout' as a result of propeller pitch lock malfunction.