

Grumman AA-5B, G-OCAZ, 5 May 1996

AAIB Bulletin No: 9/96 Ref: EW/C96/5/2 Category: 1.3

Aircraft Type and Registration: i) Grumman AA-5B Tiger, G-OCAZ
ii) Schleicher, ASK13 Glider

No & Type of Engines: i) 1 Lycoming O-360-A4K piston engine
ii) None

Year of Manufacture: i) 1977
ii) 1996

Date & Time (UTC): 5 May 1996 at 1005 hrs

Location: Westcott, near Aylesbury, Bucks

Type of Flight: i) Private
ii) Private

Persons on Board: i) Crew - 1 Passengers - Nil
ii) Crew - 1 Passengers - 1

Injuries: i) Crew - Fatal Passengers - N/A
ii) Crew - Nil Passengers - Nil

Nature of Damage: i) Destroyed
ii) Right wing tip destroyed

Commanders Licences: i) Private Pilot's Licence
ii) BGA Assistant Instructor

Commanders' Ages: i) 27 years
ii) 36 years

Commanders' Flying Experience: i) 82 (of which 79 were on type)
Last 90 days - 4 hours
Last 28 days - 1 hour
ii) Total 450 hours

Information Source: AAIB Field Investigation

History of the flights

The accident was a mid-air collision in Class G airspace in daylight VMC conditions. The meteorological aftercast reported the weather as surface wind 300°/5 to 10 kt, visibility 25 to 30 km, temperature 5°C, no precipitation and scattered cumulus cloud at base 4,000 feet.

Both aircraft departed their respective airfields at about 0940 hours. The glider was being flown partly by the instructor from the rear seat and partly by the passenger who was once an active glider pilot. They were winch launched from Aylesbury (Thame) airfield which is on the north-western side of the village of Haddenham. One mile south of the airfield the base of Class A controlled airspace is 3,500 ft but to the north of it the base is flight level 55 (approximately 5,500 feet). Immediately after releasing the winch cable the glider entered a strong thermal and climbed to 3,400 feet over the village. To avoid penetrating controlled airspace the instructor then headed north into wind along a 'cloud street'. Intermittently the glider penetrated regions of rising and sinking air and the airspeed was varied to suit the conditions: 38 kt in lift and 55 kt in sink. The glider lost height and, as it approached the village of Westcott, it had descended to about 2,500 feet on a heading of about 330°.

The Grumman Tiger pilot took off from Elstree aerodrome near Watford on a pre-planned navigation exercise for which the first leg was a direct track from overhead the aerodrome to the disused airfield at Westcott. The exercise had been planned on a proprietary VFR flight log and the headings and leg times took account of the prevailing wind conditions. The pilot had planned to fly at 2,000 feet altitude and 100 kt IAS. This airspeed is more applicable to the AA-5A with the lower powered engine but the club operated both AA-5A and AA-5B types and the pilot had previously flown both variants.

Recorded secondary radar data showed the Tiger was transponding on Mode A code 7000 but not on Mode C (encoded altitude). Primary radar returns from the glider were also recorded but not secondary returns since it had no transponder. The radar at Heathrow tracked the Tiger as it made its way towards Westcott; in the process it overflew Aylesbury and appeared to be following the A41 Trunk road which leads from there to Westcott. Just before Westcott the Tiger passed over Waddesdon Manor on a westerly heading; the Manor is on top of a hill about a mile and half to the east of Westcott. The angle of convergence between the two radar tracks was some 60°. The Tiger was in the glider's 3 to 4 o'clock position and the glider in the Tiger's 10 o'clock position. The sun was in the glider's 6 o'clock position.

Two people standing in the grounds of Waddesdon Manor were watching the glider whilst they waited for relatives. They became aware of the Tiger when it flew almost overhead. It appeared to be flying straight and level at a steady speed and they were surprised when it did not take early action to avoid the glider. They continued to watch both aircraft and at a very late stage, they saw the Tiger bank to the right as if to avoid the glider. They thought that the aircraft had come extremely close to each other but had not touched. However, almost immediately the Tiger entered a diving turn to the left from which it did not recover. The witnesses heard the Tiger's engine running all the way down the dive and both were of the impression that the aircraft was behaving as if there was no corrective action from the pilot. Another witness in the garden of a house close to the impact site saw the Tiger in the final moments of what appeared to be a vertical, high-speed dive. She immediately instigated a 999 telephone call and the police logged the reporting time as 1105 hr (1005 hrs UTC).

The glider pilot had been on the point of returning to Thame when he heard a loud bang and felt the glider shudder. He looked at the left wing first which was undamaged and then at the right wing which had obvious damage at the tip and shreds of fabric and tape trailing behind it. He realised almost at once that he still had control of the glider and then he became aware of a light aircraft below him in his one o'clock position. It was in a gentle left turn but about 20° nose low and he soon lost sight of it beneath the glider's nose. His passenger had a better view in the front seat and he too saw it ahead and beneath them on their right hand side. Initially the Tiger was in a right turn but it

steadily rolled to the left and reversed its turn from right to left. He too remarked upon the nose-low attitude and lost sight of the Tiger some distance away but beneath the glider's left wing. Initially the instructor attempted to return to Thame but he lost height rapidly through sink and the increased drag caused by the damage and the requirement for crossed yaw and roll control inputs. He selected an open field and made one left turn to land into wind without difficulty.

Wreckage Examination

Examination of the glider after its landing showed most of the damage to be confined to its right-hand wing tip. In the ASK13 glider, the wing structure is of conventional plywood and fabric construction with a fibreglass tip: at the trailing edge the outboard 240 mm of this wing tip was missing, leaving the aileron and its mechanism intact. The line of damage into the wing was diagonal and approximately 1350 mm of the leading edge was missing: this corresponded to about half the width of the aileron and to a length of fabric, with pieces of fibreglass and plywood attached, found in an adjacent field. Further structural damage, just inboard of the aileron, confirmed that the glider wing tip had been struck predominantly from the rear. Lateral movement of the control stick showed a slight constriction near the end of travel but the instructor commented that this had not affected his control of the glider.

The ground impact damage to the AA-5B Tiger was, in contrast, massive and showed that the aeroplane had dived into the ground at high speed and at an angle of some 85° to the horizontal. The impact damage was distinctly symmetric, with similar ground impact damage to both wings and both wing tips. During the recovery of the wreckage, the airframe was closely examined for evidence of collision with the glider. There was no evidence of any such contact on the fuselage, propeller or wing leading edges but a number of small pieces of plywood were found in the ground impact marks made by the Tiger's left-hand wing tip and substantial fibreglass pieces of the glider's right-hand wing tip were found within the remnants of the Tiger's left-hand wing tip.

The physical evidence showed, therefore, that the airborne contact was simply between the glider's right-hand wing tip and the left-hand wing tip of the Tiger; analysis of the geometry and relative speeds at contact show that the Tiger's tail surfaces would not have struck the glider. The AA-5 design does, however, incorporate a mass balance cantilevered from the aileron hinge mechanism and this mass moves within the cavity of the fibreglass wing tip. It was within this cavity that portions of the glider's wing tip had lodged, with the probability of interference with free movement of the Tiger's aileron system.

Human factors

Post-mortem examination of the pilot did not reveal any medical condition which was likely to have contributed to the accident and he had no need for corrective spectacles. He was wearing sunglasses at the start of the flight and the frames of sunglasses were recovered from the accident site.

Gliders which are painted white (a structural integrity requirement for GRP gliders) can be notoriously difficult to see in certain light conditions, especially when they are viewed against a backdrop of cumulus clouds. Other aircraft are often first seen because they are moving relative to the aircraft from which they are viewed or sometimes because the sun glints off the canopy or structure. In this case, the sun was directly astern the glider and since both aircraft were on steady headings, neither would have been moving relative to the other.

