

Gemini Flash IIA, G-MVEP

AAIB Bulletin No: 5/2000 Ref: EW/C97/10/5 Category: 1.4

Aircraft Type and Registration: Gemini Flash IIA, G-MVEP

No & Type of Engines: 1 Rotax 503 piston engine

Year of Manufacture: 1988

Date & Time (UTC): 27 October 1997 at 1059 hrs

Location: Roydon Hamlet, Essex

Type of Flight: Private (Training)

Persons on Board: Crew - 1 - Passengers - None

Injuries: Crew · 1 Fatal - Passengers · N/A

Nature of Damage: Aircraft destroyed

Commander's Licence: Student pilot

Commander's Age: 43 years

Commander's Flying Experience: 31 hours (all of which were on type)

Last 90 days · 18 hours

Last 28 days · 11 hours

Information Source: AAIB Field Investigation

This bulletin provides information on tests to the Flash 2A wing carried out since the accident. The information presented in the original bulletin is repeated to put the test results in context.

History of flight

The pilot was on a qualifying solo cross-country flight for the award of a Private Pilots Licence. The planned route was from Hunsdon Airfield, near Harlow, Essex to Headcorn Airfield in Kent, where the aircraft would be refuelled for the return flight to Hunsdon. There was low cloud in the area and the pilot was briefed to return to Hunsdon if this became a problem; the planned altitude was 1,500 feet initially and then 2,000 feet.

The pilot had programmed his route into his Global Positioning System (GPS) equipment. Data stored in the GPS was used to determine, in part, the history of the flight. At 1032 hrs, the aircraft took off from Hunsdon Airfield and flew a complete left hand circuit before tracking south down the western side of Harlow. At 1042 hrs the aircraft turned left and tracked east, over Junction 7 of the M11 towards the village of Moreton. At 1051 hrs, shortly before it reached Moreton, it made a 180° turn to the left and tracked along the southern edge of Harlow. It then turned to track north and, shortly afterwards, the GPS stopped logging data. The last relevant position logged was at 1058 hrs after the aircraft had started a left turn in a position about 260 metres northeast of the accident site. The final part of the track was confirmed by comparing it with recorded data from Heathrow radar; the time of the final return was also 1058 hrs.

Witnesses were consistent in their observations. They reported hearing a sharp crack and seeing the left wing move up almost to the vertical. Shortly afterwards the right wing did the same and, the aircraft spiralled to the ground with the wings folded together and the trike assembly describing a circle beneath them. The aircraft was in the vicinity of the final GPS/radar contact when the observations were made and one witness called the emergency services while it was still falling; the call was recorded at 1058 hrs.

The pilot survived the impact but died shortly afterwards from his injuries. Post mortem examination revealed no pre-existing medical condition which would have contributed to the accident.

Pilot's flying experience

The pilot started a course of microlight flying training in March 1997. Initial training was in a Mainair Blade aircraft. His first flight in the Gemini Flash IIA, G-MVEP, was on 26 August 1997. He made good progress through the course and went solo on 20 September 1997 after 19 hours. His last flight before the accident was on 26 October 1997, after which he had flown a total of 19 hours dual and 11 hours 40 minutes solo.

Meteorology

An aftercast was obtained from the Meteorological Office at Bracknell. There was a weak cold front lying from Kings Lynn to Folkestone; it was moving slowly westwards.

Surface wind 100°/10 kt

2,000 feet wind 130°/15 kt

Visibility 9km

Cloud FEW base 600 feet

SCT base 1,000 feet

BKN base 4,500 feet

Temp/Dew point +10C/+8C

QNH 1027 mb

Global positioning system

The GPS equipment carried in the aircraft worked throughout the accident flight. It uses satellite navigation to establish its position which it then displays on a small screen. The equipment has a logging facility which saves position, time and date into non-volatile memory, on a periodic basis when direction or speed change significantly. The equipment was found to operate satisfactorily after the accident.

The data logged during the accident flight was downloaded onto a computer. As the downloaded data was based on a datum other than that used for Ordnance Survey maps, a correction factor was applied to each latitude/longitude point logged and the results plotted onto a 1 to 25,000 map. The plotted points correlated well with the known positions of the take off and the accident. It was not possible to determine the height of the aircraft during any part of the flight as GPS altitude, although displayed on the screen, is not logged in the non-volatile memory.

From 1058 hrs, the GPS stopped logging data for a period of twenty four minutes. It is considered that this was because the GPS was unable to receive sufficient satellite signals to calculate its position. It was probably carried in the document pocket on the right side of the aircraft and consequently the accuracy of the recorded data may have been degraded because of satellite obscuration by the pilot or the metal framework of the aircraft. This degradation may have been more noticeable when tracking west as five of the eight satellites in view would have been behind the aircraft.

Further geographical positions consistent with that of the accident site were recorded in the equipment; two points at 1122 hrs, two points at 1229 hrs and a period of uninterrupted operation from 1406 hrs to 1443 hrs. It is likely that, as the aircraft wreckage was moved during the post accident recovery, the GPS may have periodically received adequate satellite signals before it was eventually turned off when the AAIB arrived on the scene.

Accident site

The microlight was found lying on its left hand side with the wing folded in two. The only significant ground mark had been made by the muffler and did not show any signs of aircraft rotation. The guarded magneto switch was found in the off position. The aircraft was carrying 50 kg of ballast in an appropriate container.

The propeller had disintegrated and the majority of it was retrieved from a 400 metre long trail, however only 45% of the leading edges was recovered. The fabric nose cone was found 275 metres from the accident site along the line of the propeller debris. No vibration damage was apparent on the engine mounts, muffler, air filter or engine casing.

Subsequent examination at the AAIB facility at Farnborough revealed heavy indentations on the lower left hand side of the keel, and wood dust embedded in the left vertical face of the keel fabric in the area over the indentations. The indentations were very similar to keel damage on another wing which was known to have had a propeller strike on the keel.

The following structural damage had occurred before the microlight hit the ground:

The outer 1.33 m of both leading edge tubes had broken in a downwards direction.

The right hand leading edge tube had detached from the nose plate.

The control bar had failed at the inner end of the right hand grip by being forced through the front strut; the front strut had a corresponding slight bend.

The wires on the upper wing did not show any curling typically associated with excessive tension, and the king post was undamaged by compression. The structural damage was consistent with negative g and the trike dropping into the wing. The aircraft had a renewal of its certificate of validity on 30 July 1997 and had flown for a total of 152 hours, and the log book did not contain any record of significant maintenance actions.

Insufficient evidence of this accident has been accumulated to determine the cause with any degree of confidence. The AAIB therefore intend to rebuild the sail, using as many of the original parts as possible, with the initial objective of determining the pitch moment and stall characteristics of this specific wing. The results of these tests will be published when they are available. (Original Bulletin text in the future tense, tests complete to date are reported on below).

Tests

A series of tests were carried out in March 1998, using the British Hang Gliding and Paragliding Association's (BHPA) test rig at Rufforth to determine the lift and pitching moment vs angle of attack (AoA) graphs. The results implied that the wing could become unstable in pitch, but the accuracy of the data was insufficient to provide an adequate degree of confidence in the results. Accordingly, it was decided to retest the wing on a new rig that the BHPA intended to buy, with better control, instrumentation and data logging. After many delays in delivery and provision of adequate software, the tests were rerun in September 1999.

The test data were analysed by the BMAA (see graph); and the results for 45 kt and a weight of 283 kg are discussed. Under these conditions the lift coefficient vs AoA graph gives a flight AoA of 7° in level flight, or 6° in a maximum descent.

The graph for pitching moment vs angle of attack *for this wing* shows that a maximum (at which bar forces reduce for either an increase or decrease in AoA) occurs in pitching moment at approximately minus 7 1/2° AoA. A similar result was shown for 48 kt, although not for 38 kt. If the wing's angle of attack were to reduce below this value, it could be expected that the wing would become divergent in nose-down pitch, probably leading to a loss of control and in-flight breakup. Thus in the best possible conditions, an angle of attack change of -14 1/2° would have this result. The strength of a downward gust to cause this change would be 11.63 kt.

Using the JAR-VLA formula, a gust with a maximum strength of only 15 kt would require a time of 0.33 seconds to go from still air to the strength of 11.63 kt required to cause a departure. The time delay will reduce as the maximum strength of the gust increases. This would not be sufficient time for the pilot to react to the gust in any useful way.

It is also noteworthy that, at around the trimmed condition, the wing shows low to neutral pitch stability, although never becoming divergent around this condition. This is consistent with the description of this aircraft's flying characteristics given verbally by the manufacturer's test pilot, who considered that this characteristic was poor and should be corrected.

The analysis of the test data remains subject to some uncertainty, particularly with regard to the relationship between steady state and dynamic aerodynamic characteristics of the wing; the latter are not possible to determine with any currently available test facility.

Conclusions

These results indicate that the wing of G-MVEP, rigged as it was for the accident flight, has characteristics that could cause it to become divergent in nose down pitch through the action of a vertical gust of a strength that could reasonably be expected in British summer flying conditions. The onset of this gust associated departure would be sufficiently rapid so as to preclude any significant pilot recovery response before the manoeuvre was catastrophic.

This is only evidence from this one wing. As the manufacturer's test pilot considered that it was not trimmed correctly near the trim point, it may not be representative of other similar wings in service. The Flash 2A has a great many adjustment points, and it is possible that this wing may have been adjusted to give near neutral pitch stability, which some experienced microlight pilots consider to be desirable as it reduces pitch forces in cruising flight.

Further work

Since 1986, there have been 12 accidents to Flash 2 and 2A wings in the UK in a variety of circumstances, involving a loss of control in flight. Some of these accidents were accompanied by in-flight breakup, and seven lives were lost. The tests carried out indicate only the characteristics of one specific example of a Flash 2A and the AAIB considers there is a need for further test work. The AAIB intends to determine why this wing was unstable in pitch, and whether other Flash 2/2A wings are susceptible to the same problem. This programme will include finding a Flash 2A wing with a trouble free record and testing it on the BHPA rig, with adjustments as may seem necessary at the time.

The AAIB also consider that tests should be carried out on a range of other wings, to include, Pegasus, Raven and Flash 2 wings, to put the Flash 2A results into context; and make the following safety recommendation.

Recommendation No 2000-22

It is recommended that the BMAA determine the lift and pitching moment characteristics of a range of wings, to include, the Pegasus and Raven wings, to provide data to help define an adequate standard.