

Boeing 737-46B, G-OBMN, 23 June 1997

AAIB Bulletin No: 12/1997

Ref: EW/A97/6/1 Category: 1.1

Aircraft Type and Registration:	Boeing 737-46B, G-OBMN
No & Type of Engines:	2 CMF56-3C1 turbofan engines
Year of Manufacture:	1989
Date & Time (UTC):	23 June 1997 at 1708 hrs
Location:	Mahon Airport, Menorca, Spain
Type of Flight:	Public Transport
Persons on Board:	Crew - 6 - Passengers - 179
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Skin damage on the underside of the rear fuselage
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	58 years
Commander's Flying Experience:	17,010 hours (of which 5,150 were on type) Last 90 days - 185 hours Last 28 days - 61 hours
First Officer's Flying Experience:	8,153 hours (of which 2,840 were on type) Last 90 days - 128 hours Last 28 days - 49 hours
Information Source:	AAIB Field Investigation

History of the Flight

The flight was planned to operate a flight from London (Stansted) to Mahon, Spain, before returning to Luton. The aircraft was serviceable prior to departure and carried 179 passengers, which represents a full passenger load. Because of the cost of fuel at the destination it was normal to carry surplus fuel from Stansted in order to reduce the amount required during the refuel at Mahon.

Therefore, the limiting weight considered for the departure from Stansted was the maximum landing weight at Mahon. Thus with a take-off weight of 61,724 kg and a projected fuel burn of 5,566 kg the planned landing weight was 56,158 kg, which was 87 kg below the maximum authorised landing weight of 56,245 kg. However, whilst the planned arrival fuel was 6,484 kg the recorded arrival fuel was 6,680 kg; the aircraft thus arrived with 196 kg more fuel than planned which resulted in the aircraft being 109 kg above the maximum authorised landing weight when shutting down at Mahon. Whilst not significant in itself this did ensure that the aircraft was at a high mass for the approach and landing.

The weather obtained by the crew for the arrival at Mahon included a surface wind of 230/10 kt, variable between 190 and 270, visibility in excess of 10 km, scattered cloud with a base of 2,000 feet, the surface temperature was 24°C and the QNH was 1016 mb. Runway 19 was the runway in use. It has a High Intensity Approach Lighting System with the PAPIs set at 3 and is 7,710 feet long. The crew elected to fly the VOR/DME approach for Runway 19 with the commander as the handling pilot; Flap 30 was the planned landing flap setting. When both crew members could clearly see the runway and the approach lights the commander reverted to a visual approach and he deselected the auto-pilot at an estimated altitude of 1,200 feet at which point the aircraft was in the landing configuration with the gear down and the flaps set to 30. At this stage the crew estimated that the aircraft was a little high on the glide path but by 600 feet the aircraft was stabilised on the correct visual approach path. The reference landing speed for the weight and configuration was 143 KIAS and the crew planned to fly the approach 5 kt above this speed in accordance with both their Standard Operating Procedures and guidance provided in the Boeing Flight Training Manual; their approach speed was therefore 148 KIAS. The crew considered the approach and subsequent landing to be entirely satisfactory although they were aware that the attitude indicator reached approximately 10° during the flare which, whilst slightly prolonged, led to a soft touchdown. Although the crew were not concerned that they may have scraped the tail during the landing the commander did inspect the tail bumper during his walk round at Mahon and saw no indications of damage. There were no comments from either the cabin crew or the passengers suggesting that the tail of the aircraft may have contacted the ground.

Flight Recorders

The Flight Data Recorder, a Sundstrand UFDR was replayed at the AAIB; Figure 1 shows an extract from the FDR for the approach from about 2,000 feet and the subsequent landing at Mahon. At 1,600 feet the power was reduced to Flight Idle, the initial rate of descent was 1400 feet/minute with an airspeed of between 160 and 170 kt CAS. Below 500 feet the rate of descent reduced to 600 feet/minute, and the power was increased at around 200 feet, to 50% N1. The airspeed was 150 kt.

At 50 feet the elevator angle began to increase to 16° Nose Up initially, and the pitch angle increased to 8.4°. The aircraft touched down at 137 kt, the pitch attitude increased after touchdown to a maximum 9.66°, remaining at about 9.5° for three seconds. The body pitch angle for runway contact at zero roll given in the flying manual is 9.5°. The maximum elevator angle was 19.1° as the pitch attitude began to reduce. The touchdown was gentle with a maximum normal acceleration of 1.24g. The subsequent landing at Luton was normal.

Examination of aircraft

The aircraft had sustained skin damage over Frame Stations 887,907 and 927, on the underside of the rear fuselage. In addition, the tip of the aft galley drain mast had been lightly scraped. It was apparent that the tail bumper, located aft of the damaged area, had not contacted the runway.

Ultrasonic test equipment showed that the skin on Frames 887 and 927 had been abraded to the extent that the thickness was reduced from a nominal 0.063 inches to a minimum of 0.046 inches. A joint between two adjacent skin panels occurred at Frame 907; this was achieved by means of an internal butt strap, with the edges of both skin panels being attached to the frame flange through the butt strap. The forward panel had been abraded through its full thickness at one point, thus exposing part of the butt strap. The fact that the latter had not been worn through meant that aircraft pressurisation had not been affected.

The damaged areas were all repaired in accordance with the aircraft Structural Repair Manual, and involved fitting temporary patches intended to last for 3,000 landings.

It was noted that when a piece of string was held taut between the tail bumper and the bottom of a main landing gear wheel (thus simulating the ground plane with the aircraft at a high pitch angle), it cleared the damaged area of the fuselage by approximately 3 inches. This suggested that only this amount of additional oleo compression/tyre sidewall deflection was needed to bring the lower fuselage, rather than the tail bumper, into contact with the ground. The pressures in the tyres and oleos were found to be normal, and the DFDR data showed that the landing at Mahon was not hard.

Regarding the positioning of the tail bumper on this type of aircraft, the manufacturer stated "... the function of the unit was to protect the horizontal stabiliser jack screw assembly from damage which could be sustained due to an over rotation immediately after lift-off (*ie with the oleos at maximum extension*). ... Apparently there has been some misunderstanding concerning the function of this device in that it is really only a "protector" of the jack screw assembly. We have initiated a change to the 737400 Maintenance Manual to clarify this point".

Summary

The rear fuselage contact with the runway during landing appears to be the result of a combination of factors. The aircraft flew the approach at a weight close to the maximum authorised landing weight in variable wind conditions. At 1,200 feet the aircraft was high on the approach and the 30 flap setting was maintained; the maximum drag flap of 40 was not selected. The pilot maintained the engine power at flight idle, until around 200 feet, in order to regain the required flight path at the correct speed and then, when engine power was increased, only 50% N1 was applied. Furthermore, the flare was initiated at 50 feet, as evidenced by the increasing elevator angle and this elevator input was maintained after touchdown.

The Boeing 737 Flight Crew Training Manual states that during the flare and touchdown "*Initiate the flare when the main gear is approximately 15 feet above the runway by increasing pitch attitude approximately 3°*". The same manual also explains that "*The usual causes for an aft fuselage contact with the runway during landing are: early (high) flare, early thrust reduction, low airspeed or rapid speed reduction during flare, prolonged flare or holding the aircraft off the runway in an attempt to achieve a soft landing and /or applying excessive nose up elevator after touchdown to control derotation*".