

Piper PA-34-200T, G-BOCG

AAIB Bulletin No: 3/98 Ref: EW/C97/10/7 Category: 1.3

Aircraft Type and Registration:	Piper PA-34-200T, G-BOCG
No & Type of Engines:	2 Continental TSIO-360-EB1 piston engines
Year of Manufacture:	1978
Date & Time (UTC):	31 October 1997 at 1604 hrs
Location:	Fairoaks Airport, Woking, Surrey
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Propellers damaged and engines shock loaded, nose gear doors and nose-cone deformed and abraded
Commander's Licence:	Commercial Pilot's Licence with Instrument Rating
Commander's Age:	52 years
Commander's Flying Experience:	1,670 hours (of which 400 were on type) Last 90 days - 22 hours Last 28 days - 5 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The pilot had taken the aircraft for a local flight from Fairoaks, which had been uneventful. On returning to the airfield and contacting the tower, the pilot was given approval for a straight-in approach to Runway 06; the weather was good with a wind speed of less than 5 kt, and variable in direction.

A normal approach was made and the pilot observed the 'down-and-locked' landing gear indications. He reported that the flare and touchdown had appeared to be normal but that he became aware that the nose was dropping further than usual, despite full back movement of the control column. The engines, which were at idle, stopped after the propellers contacted the runway as the aircraft dropped gently onto its nose. The aircraft then veered off the runway to the left and came to rest on the grass with the landing gear warning horn sounding. The aircraft was shut down and the pilot, who was uninjured, got out unaided.

The aircraft was recovered by a team from a local maintenance organisation who noted that, in addition to the nose gear being partially retracted, the main landing gear legs were also unlocked, as found. The aircraft's main landing gear was then fully extended and ground safety locks were fitted. When attempting to lower the nose landing gear, it was found that damage to the nose gear doors and their operating mechanism (a passive mechanism driven by gear movement) was obstructing free movement of the landing gear. The nose of the aircraft was, therefore, supported on a trolley and the aircraft was towed to a hangar.

Recent history of the aircraft

The aircraft, which had been purchased recently by the pilot, had been in regular use by another operator up to 1 December 1995. The aircraft was then flown on two occasions (2 February and 4 March 1996), after which it had accumulated a total flying time of 5316 hrs 07 min. From that date until the end of September 1997 the aircraft had been parked, mainly in the open, with storage maintenance being performed by the same organisation as had maintained it when it was last in regular use. A C of A renewal inspection was recorded on 2 July 1996, but no test flight was conducted at that time. The aircraft was then sold and, before the present owner took possession, a 'Star Annual' inspection was carried out, in conjunction with a C of A Renewal and change of category from 'Private' to 'Transport'. During this inspection the landing gear was lubricated and several retraction test cycles, with the aircraft on jacks, were performed satisfactorily.

On the C of A Renewal flight test (3 October 1997), when the landing gear was retracted after take off, the left main gear green ('down-and-locked') indicator light remained illuminated. The gear was therefore selected down again and the resulting indications were two 'greens' for the main gear, but nothing for the nose gear. The pilot then flew past the control tower and the controller confirmed that the nose gear appeared to be 'up'. The pilot then attempted to lower the gear using the emergency procedure, but to no avail. He reconfirmed the position of the landing gear by flying past the control tower again. The pilot then attempted to free the nose gear by manoeuvring the aircraft, but this was also unsuccessful. The pilot then performed a low pass over the engineering staff of the maintenance organisation who relayed to him their observation that the nose gear door seemed slightly open and made some suggestions for him to try to lower the gear.

The pilot then retracted the landing gear again and although both main gears were heard to retract into lock, the left leg green indication remained illuminated, suggesting that the gear was still down and locked. He then lowered the landing gear, but again obtained no nose gear indication. He then started the emergency lowering procedure again. When he got to the point in the procedure when the hydraulic pump circuit breaker had just been disengaged, the nose gear dropped free and a nose wheel green indication was obtained.

After the subsequent uneventful landing, the aircraft was placed on jacks and a number of retraction tests performed, during which the landing gear cycled apparently faultlessly. It was found, however, that the 'down' microswitch for the left main landing gear had failed in the 'made' condition. This microswitch and the nose wheel shimmy damper, which had also been found to be unserviceable, were replaced and the landing gear lubricated again. During this work, no adjustments to the nose landing gear retraction system were made. A Mandatory Occurrence Report was sent to the CAA concerning this incident. A subsequent satisfactory flight test was performed on 7 October; the accident which is the subject of this report occurred some 2.5 flying hours later, on the second flight following this successful flight test.

Post accident investigation

Having been towed to a hangar, the aircraft was placed on jacks, the trolley removed and the obstructing nose gear doors and mechanism cleared. The nose gear dropped to a nearly fully extended condition and the locks of the main gear released again. The landing gear was cycled repeatedly and appeared to operate correctly; all extensions resulting in a safe down-and-locked indication. It was noted, however, that with the gear extended and a safe down-and-locked indication showing the nose landing gear drag brace stops did not appear to be hard abutted (see Figure 1) as required in the Service Manual. It was also found that, if the drag brace centre pivot were lifted by hand, it took very little force to move it into an 'unsafe' condition and there was no spring action either resisting the movement or trying to return the brace to a 'safe' position.

A series of tests was conducted with the aircraft still on jacks, applying forces to the nose wheel axle in the fore and aft direction. When a forward force was applied, attempting to force a retraction, the drag brace stops could be seen to close up as the drag brace moved into a more positively 'overcentre' condition. When the forward force was released the drag brace appeared to relax slightly. If the wheel was forced aft, the drag brace stops opened as the centre pivot was drawn into line with the two end pivots and when the rearwards force was relaxed, the drag brace did not return fully to the overcentre condition achieved after gear extension. When snatch loads were applied to the wheel, the drag brace was seen to move out of, and then back into, an 'overcentre' condition. During this series of tests, the electro/hydraulic unit which should, by design, activate when the down microswitch 'unlocks' and return the landing gear to the 'down' position, did not operate.

It was observed, however, that if some residual forward force was maintained on the nose wheel following the application of a snatch load, the gear would occasionally come to rest with the drag brace in an unsafe condition; the downlock spring not being sufficiently effective to force it back into a safe condition (see Figure 2). It was found that if a reasonable forward force (as might arise from the forward component of vertical load on the raked nose leg) were then applied to the nose wheel, the nose gear could be retracted. During this process the down microswitch operated and the hydraulic pump started. It was, however, not difficult to retract the gear against the force of the actuator.

Inspection of the nose gear operating mechanism showed that both the actuator link and the upper eye end of the downlock spring link had become bent. This appeared consistent with the effects of the forces required to force the landing gear to retract by weight being applied to the nose wheel when the drag brace was in an 'unsafe' condition; the spring link being put into compression by the folding of the drag brace and consequently forcing the actuator link to swing forwards. It was not possible to determine whether the bending of the linkage had first occurred at the time that the nose gear had collapsed during the landing, during the subsequent testing or had been present for some time.

Further inspection of the spring link (see Figures, 3a, b, c & d) revealed that, at some time whilst the sliding spring-end washer had been resting on the top of the pin head, its outer sleeve had become 'belled' out, as a result of the link being overcompressed, and the spring-end washer had jammed on the top of the belled section. This had prevented the spring from extending the link to ensure that the drag brace was positively biased into the 'overcentre' condition. The loss of the spring action of the link was the reason that the drag brace was able to be moved into an 'undercentre' condition by snatch loads on the nose wheel. The degree of polishing of the wear mark where the washer had jammed indicated that it had probably been in this state for some time.

An independent survey of the nose landing gear, conducted at AAIB's request, concluded that although there was wear in the nose landing gear mechanism, it was not abnormally slack apart from the deficiencies in the spring link and a weak actuator.

Analysis

The link can only become overcompressed to the extent that the pin can distort the upper end of the slot in its outer sleeve if the top eye-end is adjusted to make the link too long in its fully compressed state. Such maladjustment can only occur at a time when the nose landing gear retraction mechanism is being set up, since any in-service wear at pivots will reduce the tendency of the pin to come hard up against the end of the slot in its outer sleeve. If the initial distortion of the upper end of the slot had occurred with the spring-end washer correctly located on the pin and the washer had become jammed on the outer sleeve at that time, it is possible that the pin head could move under the washer when the spring link extended slackly during a subsequent retraction or extension cycle. Once the pin head was under the washer it would lift the washer to the position in which it was found at the next occasion on which the strut was fully compressed.

Examination of the instructions, in the manufacturer's Service Manual, for setting up the nose landing gear retraction system, showed these to be unclear and not supported by informative diagrams. They appeared to be particularly unclear with respect to the adjustment of the spring link and gave no indication of the action of this link during the process of extension and retraction of the landing gear. The nose gear linkage had not been adjusted during recent maintenance and had not caused any concern until the flight test on 3 October. Since, even after this occurrence, it was not examined critically, it has not been possible to establish the time at which the downlock link spring became ineffective as a result of the jamming of the sliding washer.

The bell of the spring link outer sleeve could only occur as a result of overcompression of the link. The possible occasions on which this might have happened were at the time the link length was adjusted, when it might have been made too long at the intermediate adjustment, and at the time the landing gear was driven up into the retracted position. It was thought unlikely that this latter occasion was relevant because if the spring link had been operating correctly, the drag brace should not have been able to flick into the unsafe 'undercentre' condition necessary for the gear to be forced up against the action of the hydraulic actuator.