


<b>GLARE SHIELD</b>	nothing of note	Strobe	OFF
		Recog	ON
<b>P1 PANEL</b>		Aux Inverter	OFF & selected to LEFT BUS
Horizon	topped		
Stby Horizon	OFF	Pitch trim	NORM
RAD ALT	Bugged at 100ft		
VSI	zero	<b>P2 PANEL</b>	
Altimeter	set 1015mb 100ft	ASI	zero, bugged at 125 kt
HSI	Hdg 167°	ADF/VOR	165
Turn and slip	nothing useful	DI	170
VOR/ADF	indicator 165°	ALT	100ft on 1014 mbs
ASI	zero, bugged at 127 kt	VSI	zero
Emergency Battery	OFF	Turn & Slip	undamaged, nothing useful
<b>CENTRE PANEL</b>		<b>CIRCUIT BREAKERS</b>	
ADF1A	277		all IN except 'toilet' and 'eng synch'
ADF1B	351		
Alt select	set 1800 and OFF	<b>THROTTLE PEDESTAL</b>	
NAV1	115.1	Throttles	retarded
NAV2	115.1	Flaps	OFF
Engine Instruments	all zero	Spoiler switch	see report
COM2	131.92	Jetpumps	ON
COM1	130.35 / 124.97	Standby pumps	OFF
DME	113.6	Fuselage tank feed	CLOSED
Transponder	5330	Fuel qty	1500 lbs, selected to TOTAL
Flap indicator	Approach	Primary yaw damper	ON
Gear selector	DOWN	Secondary yaw damper	OFF
Generator switches	GEN		
Battery Master	OFF	<b>MISC</b>	
Stall warning x2	OFF	Frangible wire on emergency brake	broken.
Anti skid	ON	1/2 scale deflection on emergency air gauge.	
Inverters Pri and Sec	OFF	Chart for Northolt on P2 column.	
Air ignition L & R	OFF		
Hyd pump	OFF		
Landing gear	selected to DOWN		
Nav and beacon lights	all ON		

(Extract from Gates Learjet Corporation Maintenance Manual)

Gates Learjet Corporation  
**maintenance manual**




Brake System Schematic  
 Figure 1 (Sheet 1 of 2)

EFFECTIVITY: 25-061, 25-070 THRU 25-184


32-43-00  
 Page 3  
 Apr 30/82

MM-99

(Extract from Gates Learjet Corporation Maintenance Manual)



Spoiler System Electrical Control Schematic  
Figure 1





Spoiler System Hydraulic System Schematic  
Figure 2


EFFECTIVITY: ALL

MM-98

27-60-00  
Page 2  
Nov 15/91



**DOT/FAA/CT-93/80**  
**"SOFT GROUND ARRESTING SYSTEMS FOR AIRPORTS"**  
 James C. White/Satish K. Agrawal/Robert E. Cook



Runway Exit Speeds During an Overrun

The diagram above was published in the above report, prepared by the Federal Aviation Administration Technical Center, Atlantic City NJ. The data was drawn from National Transportation Safety Board and International Civil Aviation Organisation sources and the work was credited to David, 1990. The data indicates that there have been few instances when aircraft have left the runway at more than 70 knots, and none found where the speed exceeded 80 knots.