

# Agusta Bell 206B, G-FLYR

## AAIB Bulletin No: 1/98 Ref: EW/C97/7/2 Category: 2.3

<b>Aircraft Type and Registration:</b>	Agusta Bell 206B, G-FLYR
<b>No &amp; Type of Engines:</b>	1 Allison 250-C20 turboshaft engine
<b>Year of Manufacture:</b>	1973
<b>Date &amp; Time (UTC):</b>	13 July 1997 at 1050 hrs
<b>Location:</b>	Glamis Castle, Forfar, Scotland
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 - Passengers - 5
<b>Injuries:</b>	Crew - None - Passengers - 1 Fatal
<b>Nature of Damage:</b>	Aircraft damaged beyond economic repair
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence for Fixed Wing Aircraft and a Commercial Pilot's Licence for Helicopters
<b>Commander's Age:</b>	55 years
<b>Commander's Flying Experience:</b>	Fixed Wing: 13,484 hours Helicopters: 1,830 hours (of which 1,770 were on type) Last 90 days - 64 hours Last 28 days - 30 hours
<b>Information Source:</b>	AAIB Field Investigation

## Background to the accident

The 24th Scottish Traffic Extravaganza was held at Glamis Castle on the 13 July 1997. One of the major events planned for the day was to be a series of helicopter flights for children with special needs. This element was organised by a registered charity, whose objective is to offer children, between 6 and 16 years of age and with a variety of special needs, the opportunity to experience a flight in a helicopter. This charity arranged for the provision of the three helicopters and organised the administration and reception of the children and their families but contracted the organisation of the operational aspects of the helicopter flying to a helicopter operator based at Edinburgh Airport. This operator had agreed to arrange the site facilities including the necessary safety equipment, provide aircraft handlers and overall site management and provide, at commercial rates, one of the

three helicopters, an Enstrom 480. Since this operator did not have an Air Operator's Certificate (AOC) it had previously arranged, with the agreement of the Civil Aviation Authority (CAA), that this helicopter would be operated under the auspices of another company's AOC. An AOC is required for the operation of a Public Transport flight. The second helicopter, an AS350 Squirrel, was contracted from a separate helicopter operator, based at Inverness Airport and was operated under that company's own AOC. The third helicopter, an Agusta Bell 206B, was provided by a commercial organisation. Since the services of this helicopter and its pilot were donated completely free of any charge the helicopter was operating in a Private capacity and was therefore not required to operate under an AOC. This commercial organisation had donated the services of the same helicopter and pilot to support the charity at similar events on two previous occasions.

### **History of the flight**

At 0715 hrs on the morning of 13 July 1997 the pilot of the Bell 206B took off from a private helicopter strip located to the south of Edinburgh with the intention of flying to Glamis Castle. Initially the weather was fine but just to the north of Glenrothes the pilot encountered low cloud and poor visibility; he decided to land at Glenrothes to await an improvement in the weather. After about two hours the weather conditions had improved and the pilot took off again by which time he was in radio contact with the pilot flying the Enstrom 480. This helicopter was about seven minutes ahead of the Bell 206B and its pilot relayed details of the weather conditions en route. When they arrived at Glamis the Enstrom 480 landed first followed by the Bell 206B; the AS350 landed five minutes later, at about 1005 hrs, having flown from Inverness. The weather conditions on arrival were estimated by the pilot of the AS350 to include a visibility of approximately 5,000 metres in light rain with complete cloud cover at about 600 feet above ground level (agl).

When the three helicopters had landed and shut down the pilots conducted their briefing. They agreed upon the departure and arrival paths and the route to be flown, however, during this briefing doubts were expressed about the viability of the weather by the pilots of the Bell 206B and the AS350. Whilst the conditions were safe for flight they were concerned with flying a high intensity operation, involving three helicopters, in such conditions. It was agreed that the pilot of the Enstrom 480 would conduct an initial flight with the purpose of confirming the suitability of the weather for the planned operation.

Meanwhile the teams of aircraft handlers received instruction on the use of the seatbelts and doors of their allocated helicopters and were then required to demonstrate their ability to operate these items. Each team consisted of four people and their function was to control the passengers allocated to their helicopter. They were required to monitor them closely when in the proximity of the helicopter and to ensure that each passenger was correctly strapped into their seat and the doors of the helicopter securely closed before flight. The teams consisted mainly of experienced handlers from Edinburgh Airport, helicopter pilots and airport firemen, all of whom were familiar with helicopter operations. The team allocated to the Bell 206B did include one inexperienced handler and she had been comprehensively briefed on her duties and during the familiarisation had been shown how to operate the doors and the seatbelts.

The allocated passengers were loaded into the Enstrom 480 which departed on its first flight during which it completed a weather check, the pilot radioed back to the other two helicopter pilots that the cloud base was estimated to be 600 feet agl with an in-flight visibility of 5,000 metres although the intensity of the rain had increased. Both pilots on the ground regarded these weather conditions as acceptable to at least commence the planned flying programme and began loading their passengers. On the Bell 206B the inexperienced aircraft handler strapped in the passenger seated in the rear left

seat and the seat belt was then checked by one of the more experienced handlers. As soon as the doors of this helicopter were closed the windows and windscreens began to mist up: the passengers were wet and the relative humidity was high. An aftercast issued by the Meteorological Office indicated that the relative humidity was 92% at the nearby airfield of Strathallen and 98% at the RAF station at Leuchars, 17 miles to the south-east.

Meanwhile the pilot of the Bell 206B had started the engine of his helicopter, he opened the air vents and selected the Defog Blower to ON in an attempt to clear the condensation from the windscreens. He also asked the site manager to retrieve a lint cloth from the rear baggage compartment which he then used to wipe the windscreens in a further attempt to clear them. The pilot stated that prior to take-off the screens were clearing but the aircraft handlers, standing approximately 30 yards in front of the helicopter, described the transparencies as "hazy" or "misted" and they could barely see the passengers inside. A video recording of the helicopter as it lifts off shows that the view through the forward transparencies to the interior is obscured as a result of the condensation. The AS350 also misted up as soon as the doors were closed but after approximately ten minutes with the engine set to Flight Idle Power (a high power setting for ground operations), the demister selected to ON and the heating set to Maximum the misting cleared: the Enstrom 480 apparently suffered no misting problems.

Once airborne the pilot of the Bell 206B intended to follow the pre-arranged route but within about 30 seconds he was aware that the misting on the forward windscreen was increasing. After approximately one minute he decided that the misting had become so significant that he would have to land and he made a radio call on the frequency in use to say that he was returning to the landing site. The pilot of the AS350, who at this stage was still on the ground, heard this call as "I can't see anything, I am returning" so he asked the pilot of the Bell 206B if he meant that the external visibility had reduced because of rain but the reply was, "I can't see out of the windscreen". As the intensity of the misting increased the Bell 206B pilot decided to avoid returning to the landing site because of his restricted vision and instead looked elsewhere for somewhere suitable to land the helicopter. Initially he selected a field to the south of the landing site but at a late stage he decided that it was not suitable and instead made for an adjacent open field further to the west. When established over that field, at a height of about 4 feet, he was aware of some nearby cattle and decided to hover taxi away from the cattle maintaining a height of 3 to 4 feet and at a speed equivalent to a fast walking pace. Whilst attempting to do so the helicopter ran into a wire strand fence, tipped over onto its nose and eventually came to rest on its left side. The pilot had not seen the fence. The pilot undid his own seat belt and then assisted the passengers to release their seat belts and get out of the helicopter. The young child who had been seated in the left rear seat was trapped through the door aperture with his upper body underneath the fuselage and despite attempts by the pilot and a local farmer they were unable to lift the helicopter to release him. The farmer, who had arranged for the emergency services to be called when on his way to the crash site, then went for a tractor and loader which could be used to raise the helicopter. At this stage the first police units arrived and when the helicopter was eventually raised a policeman cut through the seat belt in order to free the young child: previous attempts to release the seat belt had been unsuccessful. Attempts were made to resuscitate the child but to no avail.

### **Post crash activities**

The pilot of the Enstrom 480 was aware that the Bell 206B had misted up and that its pilot was intending to land nearby; whilst he was on his second flight he saw that helicopter hovering close to the ground in a field due south of the landing site. After clarifying the situation with the Enstrom pilot the pilot of the AS350 took off for his flight. However, he encountered deteriorating weather

conditions with heavy rain and reduced visibility and immediately decided to return to the landing site, he made a radiocall to this effect and returned to land. The Enstrom 480 pilot had also decided to curtail his flight and returned to land. Both helicopters shut down and the pilots agreed to suspend the flying until the weather improved. The pilot of the AS350 was very concerned for the safety of the Bell 206B and after landing made frequent attempts to make contact on the radio but without success, he also expressed his concerns repeatedly to the pilot of the Enstrom 480 and the site manager. The pilot of the Enstrom 480, who had seen the Bell 206B in a stable, low hover in a field to the south and with no immediate obstructions nearby saw no reason to be concerned. The site manager had seen the Bell 206B descending to the south in a controlled manner and also felt no reason to be concerned for the safety of that helicopter, particularly when he heard the description provided by the pilot of the Enstrom 480.

The telephone call to the emergency services was logged at 1052 hours and all three emergency services responded. The fire service and police units arrived at the crash site at 1055 hours and the ambulance arrived at 1104 hours. The focus of the initial activity at the crash site was in attempting to assist the child who had been trapped under the helicopter but at 1126 hours the survivors of the accident, two adults and three children, who were physically uninjured but suffering from shock were despatched to the Dundee Royal Infirmary.

### **Arrangements for seating in the helicopter**

When organising such an event the charity did not select the specific children that were to fly, believing that this was best left to the relevant school or special needs unit who had the detailed knowledge of the children under their care. The charity tasked these organisations to arrange the children into groups of three plus one adult/carer who would accompany the children on the flight, thus, there would then be five people on each flight including the helicopter pilot. From this information the charity prepared passenger manifests for each helicopter. This process was followed for Helicopter 1, the Enstrom 480, but the charity produced passenger manifests which allocated four children plus an adult/carer to Helicopter 2, the AS350, and Helicopter 3, the Bell 206B. These helicopters were thus tasked to carry a pilot plus five passengers and whereas the AS350 was configured to carry this number the Bell 206B only had seating for the pilot plus four passengers. The passengers were directed to their allocated helicopter by reference to the relevant passenger manifest which was annotated Helicopter 1, 2 or 3 together with the associated aircraft registration.

The site plan that was constructed by the site manager in charge of the helicopter operations placed the Enstrom 480 (Helicopter 1) at Gate 1, the Bell 206B (Helicopter 3) at Gate 2 and the AS350 (Helicopter 2) at Gate 3. Therefore the Enstrom 480 received the passengers that were allocated to it but the Bell 206B received the passengers originally allocated to the AS350 and the AS350 received the passengers allocated to the Bell 206B. However, despite this confusion the Bell 206B would still have received five passengers even if it had been parked at Gate 3. The charity stated that it had sent copies of the passenger manifests to the site manager in advance, however, he is adamant that he had not received these manifests when the first flight took place despite repeated requests for them.

When passenger loading of the Bell 206B commenced the young child initially placed in the front left seat, next to the pilot, was judged by the pilot to be unsuitable for that seat because his small stature prevented him being adequately restrained by the seatbelt; the pilot was also concerned that the child's constant arm movements might interfere with some of the controls. The pilot therefore instructed the handlers that this child should be placed in the rear seating, he was then placed on his

father's lap in the centre rear seat and a single lap strap was fastened around them both. One of the other children was placed in the front left seat and the other two were secured in the rear left and rear right seats.

The Flight Manual issued with this helicopter incorporates additional limitations required by the CAA. Included in these is the requirement that '*The number of persons carried shall not exceed 5 nor exceed the number for which seating accommodation approved for use during take-off and landing is provided. Children under the age of three years who are carried in the arms of passengers may be left out of the account for these purposes.*'

### **On-site examination of the wreckage**

The helicopter was in a field belonging to a farm which was self-evidently concerned with the breeding of cattle. The fuselage lay on its left side pointing roughly opposite to the direction in which it had been travelling. The tailboom was missing from the main fuselage but could readily be seen to be present around the site in the form of many small fragments. This had been caused by multiple strikes from the main rotor blades - the main rotor itself had detached and was lying close to the main wreckage. It bore signs of severe damage caused by both the tailboom strikes and impact with the ground. There were at least two heavy slashes in the ground and it was concluded that the main rotor had been rotating at normal speed under considerable engine power at the start of the impact sequence. A strand from a wire fence was wrapped around the fuselage.

Looking back along the aircraft's track, there were two marks associated with the landing gear skids. These commenced about 2 metres before a fence which had been largely destroyed but had comprised six strands of wire supported by wooden posts together with electric fence conductors. It had been a little over 1 metre high and the helicopter's heading upon contacting the fence was 235° M. Contacting the wire strands at roughly right-angle to the line of the fence, it was evident that the machine had been pitched heavily onto its nose, breaking the lower perspex window panels and one of the skids. It had then continued for another 18 metres with the skids on the ground, dragging and breaking some of the wire fence strands behind it.

The helicopter then appears to have become airborne again, as the marks disappeared and a further, single-strand electric fence was not broken, however a heavy main rotor slash and fuselage impact marks were found a little beyond this. The effect of the main rotor hitting the ground would be to rotate the fuselage violently clockwise (viewed from above) and the main rotor probably simultaneously made a series of strikes on the tailboom. The rear of the fuselage then struck the ground and structural distortion caused the baggage compartment on the left side to burst open, releasing its contents which comprised life jackets, spare headsets and tie-down equipment etc. In addition this impact probably allowed the passenger door on the left side to open.

As the machine came to rest on its left side, a final main rotor blade ground-strike caused detachment of the complete main rotor assembly. The left-hand passenger door was open and, as the fuselage stopped moving, it broke from its hinges and was found under the fuselage in the correct orientation for a wide-open door but detached.

### **Subsequent examination of wreckage**

Upon completion of the site examination, the wreckage was transported to the AAIB facility at Farnborough. By this time evidence from witnesses and observations on-site strongly suggested that there was no reason to suspect other than that the engine was delivering power and the helicopter

was under control up to the point at which it had contacted the fence. Effort was therefore concentrated on the performance of the demisting system and the question of survivability.

G-FLYR had been an Agusta-Bell 206A which had been converted to a 'B' model after original manufacture in 1973. The cabin heating system had also been modified to be supplied with engine bleed air rather than the original combustion heater but, because of engine performance limitations, use was prohibited during take-off, landing or hover. The heater selector was found in the OFF position and it should be noted that the heater output was fed solely into the floor-level vents in the cabin. There was no separate feed of heated air supplied for windscreen demisting.

The pilot had two controls associated with windscreen demisting. The first was a switch in the overhead panel labelled DEFOG BLOWER. Selecting this to ON supplied power to two electric fans in the front of the cockpit which blew recirculated cabin air onto the left and right windscreens. This switch was found in the OFF position but the pilot is certain that it had been selected to ON prior to flight. Since it is adjacent to the Battery and Generator switches which the pilot switched off before exiting the helicopter it is probable that this switch was also selected to OFF at this stage. There were also two VENT knobs to the left and right of the instrument panel which, when pulled, allowed fresh air from outside to be directed onto the windscreens. These were only effective when the helicopter was moving forwards, since the electric fans could not boost the flow of fresh air. The VENT knob was found to be pulled on the pilot's side. In this configuration, assuming the DEFOG BLOWER switch was ON, with the aircraft stationary the fan would have been blowing cabin air over the pilot's windscreen but, as the aircraft gathered forward speed this would change to a mixture of outside and cabin air.

Consideration of the design of the heating/demisting system shows that, given the weather conditions of the day and the fact that the passengers' clothing was also probably very damp, there was no combination of selections available to the pilot which would have been efficient in keeping the windscreen from misting. It would require relatively dry, warm, unsaturated air to be blown across the screen and no such source was available. After the accident the DEFOG BLOWER motor on the pilot's side was serviceable but the motor on the passenger's side did not function and had considerable white deposits, resembling corrosion products, which prevented the fan from turning freely. Chemical analysis of these deposits showed that they were associated with the constituents of fire-fighting foam that had entered the interior of the motor itself, causing a commutator brush to seize out of contact. This was the reason that the motor did not work when first tested. The maintenance company stated that both motors were checked and serviceable at the last 50 hour check on 7 July 1997.

Evidence from those first on the scene of the accident was unanimous that the young victim of the crash in the rear left seat was properly strapped-in. However the simple lap-strap supplied for rear seat passengers was demonstrably incapable of preventing his upper body from hanging outside the helicopter as it rolled onto its left side in the absence of the door. There is no requirement to fit upper body restraints for rear-seat passengers and, indeed, such provision is uncommon in civilian aircraft. By using an anthropomorphic (crash-test) dummy as close to the victim's height and weight as possible it was demonstrated that, by placing it in the seat which the boy had occupied and properly adjusting and fastening the seat belt, it was still possible for his upper body to fall outside the cabin and be trapped underneath as the helicopter rolled onto its left side with the door fully open.

The aircraft's technical documentation was examined and found to be in order. It possessed a valid Certificate of Airworthiness in the Private Category.

