

Boeing 747 SP-94, YK-AHB, 14 April 1996

AAIB Bulletin No: 8/96 Ref: EW/C96/4/2 Category: 1.1

Aircraft Type and Registration: Boeing 747 SP-94, YK-AHB

No & Type of Engines: 4 Pratt & Whitney JT9D-7turbofan engines

Year of Manufacture: 1976

Date & Time (UTC): 14 April 1996 at 0840 hrs

Location: Stand R36R, London Heathrow Airport

Type of Flight: Public Transport

Persons on Board: Crew - 13 Passengers - 155

Injuries: Crew - None Passengers - None

Others - 1 (minor)

Nature of Damage: Damage to No 4 engine intake cowl

Commander's Licence: Airline Transport Pilot's Licence(Syria)

Commander's Age: N/K

Commander's Flying Experience: 21,147 hours (of which 3,504 were on type)

Last 90 days - 109 hours

Last 28 days - 13 hours

Information Source: AAIB Field Investigation

The aircraft was operating a scheduled service route Damascus-Munich-Heathrow, landing on Heathrow's Runway 09L at 0836 hrs. Heathrow Ground Control instructed it to taxi via the outer taxiway, changing to the inner taxiway at block 21 and to park on stand R36, which was only a short distance away from the landing runway. The taxiing instructions were acknowledged by the flight crew. The handling agent's dispatcher had not arrived at Stand R36 by the time the aircraft was ready to enter the stand. The electronic Stand Entry Guidance System (SEGS) was thus not switched on.

The aircraft proceeded onto the stand, but was positioned towards the right side of the stand area. During the parking process, the outboard section of the number 4 engine intake cowl contacted the upper front part of a catering loader vehicle which was correctly located within the inter-stand clearway area. The impact pushed the vehicle until it came into contact with a second

catering vehicle positioned behind the first. The accident was observed by an Airside Operational Support Unit officer, who passed a radiomessage to ATC to advise the aircraft to shut down its engines immediately. The two occupants of the vehicles had been transferring catering items. They made a rapid egress during which one of them sustained minor laceration injuries. The aircraft's engines were shut down and the passengers deplaned normally.

Examination of the position of the aircraft after the accident showed that the nose landing gear was on the centreline for stand R36R, instead of the correct R36 centreline. The aircraft's wingtip and number 4 engine thus encroached across the inter-stand clearway between stands R36R and R38. The main landing gear were not equally straddled across the R36R centreline, being biased toward the central R36 stand.

The commander was familiar with operations into Heathrow Airport and the available SEGs, but R36 was not one of the stands normally used by the airline.

Stand Description, Identification and SEGs

Stand R36 is configured as a Multiple Aircraft Ramp System (MARS) stand, such that the central (main) stand may be occupied by one large aircraft, such as the B747. Alternatively, if required, two smaller aircraft may occupy the same stand area by use of additional centrelines provided at appropriate distances either side of the main stand centre. These additional centrelines are identified by the alpha-numeric R36 Left (R36L) and R36 Right (R36R).

The main centreline is marked with a continuous yellow paint line. The additional Left and Right centrelines are each painted with a continuous line, alternating white and yellow in colour. Only the central stand has an identifier plate at the head of the stand (marked R36).

The three centrelines (R36L, R36 and R36R) are identified by means of yellow identifiers painted on the taxiway surface. They are located adjacent to arrows pointing from the taxiway centre toward the appropriate stand centreline. The stand centrelines commence at the stand/taxiway boundary. There is thus a gap between the taxiway arrow and the start of the centreline. Repeater identifiers are painted on the surface at the start of the centrelines for R36L and R36R only.

Visibility from the flight deck of the Boeing 747 is such that the stand identifier markings on the taxiway and stand entrance would not have been visible once the aircraft had begun to enter the stand.

Centreline manoeuvring guidance is provided only for the central (main) stand by means of the Azimuth Guidance Nose-In Stands (AGNIS) light system. Stopping guidance is provided only for the main stand by means of a Parallax Aircraft Parking Aid (PAPA) board, located to the right side of the head of the stand. These systems are operated through an electronic timer, such that a ground handling agent is required to activate the system prior to the aircraft arriving to park on the stand. The substands have no electronic parking guidance systems available in the case of R36L/R.

Aerodrome Information and Navigation Charts

During this investigation, four sets of documentation relating to the layout and nature of the parking stands at Heathrow was examined, namely:

UK CAA Aeronautical Information Publication (AIP), Aerodromes (AGA) Section

Heathrow Airport Limited, Operational Safety Instructions (OSI)

Aerad Flight Guide, aerodrome charts for London Heathrow

Jeppesen Airway Manual, airport charts for London Heathrow

None of the documents examined contained any diagram indicating which stands are configured for the MARS system. The AIP entry, while making vague reference to the MARS concept, did not describe the layout of such stands in any detail. The current Heathrow OSI's did not contain any references or descriptions of the MARS system, although other aspects of SEGS were covered in detail.

The Aerad charts contained the most comprehensive description of the MARS system, correctly defining the centreline paint colours and AGNIS provision. The Jeppesen charts did not mention the presence of MARS stands at all and there were conflicting statements on different pages regarding the paint colour of the "normal" stand centrelines. However, Jeppesen correctly conveyed the content of a Heathrow OSI and highlighted the fact (in bold type) that ***'on no account should aircrew attempt to self-park if the Stand Entry Guidance is Unserviceable, Uncalibrated or Not Switched On'***. The chart library available to the flight crew involved in this accident included the Jeppesen chart containing this statement.

The commercial chart producers rely on information published in the AIP as a basis for the production of navigation charts. In turn, the information presented in the AIP is gathered from specific airport data. As a result of the apparent inconsistencies and omissions found during this investigation, both Heathrow Airport Limited and the CAA were advised by AAIB of the anomalies. The need for a comprehensive, accurate description to be made available for flight crews was also highlighted.

Heathrow Airport Limited indicated that a comprehensive OSI relating to all aspects of parking stands was in preparation and that its production would now be expedited. The CAA indicated that the appropriate aerodrome inspector would liaise with Heathrow Airport Limited to agree a suitable AIP revision. With these two improvements in hand, it was not deemed necessary to issue a formal Safety Recommendation.