

Europa, G-BVLV, 25 May 1996

AAIB Bulletin No: 8/96 Ref: EW/G96/05/18 Category: 1.3

Aircraft Type and Registration: Europa, G-BVLV

No & Type of Engines: 1 Rotax 912 piston engine

Year of Manufacture: 1996

Date & Time (UTC): 25 May 1996 at 1430 hrs

Location: Runway 28, Leicester Aerodrome

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Propeller, tailwheel and adjacent fuselage area, port wing outrigger mount

Commander's Licence: Private Pilot's Licence

Commander's Age: 50 years

Commander's Flying Experience: 355 hours (of which 20 were on type)

Last 90 days - 21 hours

Last 28 days - 19 hours

Information Source: Aircraft Accident Report Form submitted by the pilot, telephone enquiries made of pilot and aerodrome operators

The aircraft type is equipped with a large retractable main wheel on the centreline, a steerable tailwheel coupled to the rudder pedals and outrigger legs well outboard on the wings.

The pilot reported that he entered Runway 28 and received a radio report of the wind as 280 degrees/10 kt. The wind recorded at about that time at the field was 280 degrees 10 degrees, 10 kt gusting 20. An aftercast provided by the Met-Office for that time and location indicates 260 degrees/10 kt. It was also reported that at about that time a student pilot was on a first solo flight which was completed successfully.

The pilot of G-BVLV reported that he lined up on the centre-line, applied full power and maintained the centre-line using into-wind aileron (believing that there was some wind component from the left) and slight aft control input to keep the tailwheel on the ground. He had no difficulty initially in

keeping the aircraft straight. Soon after he raised the tailwheel, however, the aircraft suddenly swung to the left and although the pilot arrested the swing once it had progressed to about 30-40 degrees off the runway heading he was not able to bring the aircraft back onto that heading before it ran onto the grass.

He believes that the effect of the bump as the aircraft left the runway projected the machine into the air and he then considered it unwise to attempt to land on the grass as its surface was of unknown quality.

As he was by now heading for a row of parked aircraft, but was travelling into wind, he attempted to accelerate in the air, initially keeping the aircraft level a few feet above the ground, although some witnesses believe the aircraft progressively gained height. After approximately 80 yards, the aircraft stalled, dropped the left wing and struck the ground, coming to rest at approximately 90 degrees to the runway heading.

At the time of the accident, the aircraft was equipped with the original design of main landing-gear which consisted of the large diameter central wheel and tyre mounted on a swinging arm with a plastic material block acting as a springing medium. Experience has shown that, without the addition of damping, the characteristics of this gear on rough surfaces or during all but the smoothest landings are not very satisfactory. It is reported by the pilot that during take-off from anything other than a smooth surface, the action of the undamped suspension tended to project the aircraft into the air well below a safe flying speed. In addition the pilot reported that the aircraft normally dropped a wing in the stall.

A modification to add a damper has become available and was incorporated on G-BVLV during the repair after this accident. The pilot reports that this greatly improves take off, landing and taxiing characteristics, enabling the aircraft to take off from rough surfaces without becoming prematurely and involuntarily airborne. No defects were found with the aircraft during the repair other than damage resulting from the ground impact.