

Replica Viking Spitfire, G-BRDV

AAIB Bulletin No: 3/98 Ref: EW/C97/9/7 Category: 1.3

Aircraft Type and Registration:	Replica Viking Spitfire, G-BRDV
No & Type of Engines:	1 Jaguar V-12 piston engine
Year of Manufacture:	1984
Date & Time (UTC):	22 September 1997 at 1230 hrs
Location:	Keevil Airfield, Wiltshire
Type of Flight:	Test Flight
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Damage to propeller, underside of aircraft and fuselage structure
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	56 years
Commander's Flying Experience:	10,796 hours (of which were on type) Last 90 days - 111 hours Last 28 days - 41 hours
Information Source:	AAIB Field Investigation

The aircraft was a full size wooden replica based on the prototype Supermarine Spitfire and it carried the markings K5054. It was much lighter than an original Spitfire, with a basic weight under 3,000 lb. It was powered by a Jaguar V12 motor car engine which had been extensively modified to increase the capacity and was fitted with a 2.77:1 reduction gearbox driving a Hamilton Standard Hydromatic two bladed constant speed propeller. Although the normal Electronic Control Unit (ECU) for the engine was retained, the installation was modified by the addition of dual ignition, dual fuel pumps and a variable mixture control. It had not been flown for several years and had been sold on to a new owner, but before he could fly the aircraft it was necessary for a Permit to Fly renewal flight to be undertaken. This was the purpose of the accident flight, and the aircraft was being flown by a CAA test pilot when the accident occurred.

While the aircraft closely resembled an original Spitfire, there were some differences and the test pilot was carefully briefed on these by the builder of the replica, before the flight. In particular a tendency to 'float' during the flare, due to the light weight, was discussed as was the use of the mixture control, which was unconventional in layout.

A video of the entire flight including the ground running and power checks was available and this, together with the pilot report and assistance from the builder and owner, provided the basic information on the circumstances associated with the accident.

Following engine start, the aircraft was taxied to the hold where lengthy power checks were made. From the video, it appeared that at times during these power checks the engine sounded rather uneven. However, during the take off the engine had accelerated normally and the aircraft climbed away satisfactorily. It was then lost from the video coverage for a few minutes while the pilot familiarised himself with the aircraft and conducted his checks. When the aircraft appeared again on video, it was on final approach with the landing gear down and the flaps retracted. There is some doubt about the intention of this approach; the pilot stated that he had intended to go-around from this first approach and that he had discussed this beforehand, but the builder thought that he was landing. There had also been some discussion over the RT between the pilot and the builder about the oil and coolant temperatures, which the pilot thought were high, but which the builder advised were allowable.

From the video, the aircraft was observed to cross the threshold and power was then reduced. However, at about the point where the flare would have been initiated, the power was again increased. The engine accelerated normally at first, but then began to run roughly. The aircraft was seen to continue down the runway at a very low height. After about 20 seconds, the landing gear was retracted but the aircraft continued, without climbing, for a further 15 seconds until it disappeared from view some 35 seconds after power had been applied, still low and apparently on the runway heading. Shortly after this, the pilot reduced power and made a forced landing in a field beyond the runway. The damage to the aircraft was considerable and some difficulty was encountered in opening the cockpit door due to distortion of the fuselage. However the pilot was uninjured, and the aircraft was later recovered to a hangar.

Audio analysis

The harmonic content of the audio recording from the domestic camcorder was analysed and a time history of propeller rotational speed was derived. Following the accident, the aircraft was inspected to determine the engine-to-propeller gearbox ratio, which was found to be 2.77 to 1. The analysis showed that the increase in engine speed prior to the take-off had been smooth and in two stages, culminating in a constant speed of approximately 5,890 RPM. During the attempted go-around, the engine speed smoothly increased to 5,000 RPM, following the same rate change profile as during the take-off. However, at 5,000 RPM the speed held constant for half a second before reducing to approximately 4,800 rpm. This speed was maintained for at least the next two seconds after which the amplitude level of the recorded audio dropped below that required to analyse the harmonic content.

Examination of the aircraft

The propeller was found at a pitch setting corresponding to a position several degrees above the fine pitch stop. This type of propeller relies on oil pressure and centrifugal twisting moments to control the pitch; there are no springs controlling the pitch angle. However the audio analysis had

confirmed that the engine had accelerated normally at first and so propeller pitch was not considered to have been a factor.

The engine seemed to have suffered no mechanical distress, but examination of the spark plugs and exhaust ports indicated that it had been running rather 'lean'. The engine behaviour was considered to have been consistent with lean operation.

The ECU, of a type normally used in cars, is programmed to compensate for altitude and pressure changes. It was not reprogrammed for this installation. A further two fuel injector nozzles were fitted in the inlet manifold to richen the mixture, and a rotary mixture control rheostat was wired into the ECU. This allowed the mixture to be made rich, or leaned-out as required. The normal full-rich setting was at less than the full rotation of the rheostat. The induction air was supplied by a ram air chin intake, with alternate air from static ports located adjacent to the wing leading edge root fillet fairing. A fuel pressure regulator which referenced inlet air pressure, as for the normal car installation, was also fitted.

It was decided that the behaviour of the fuel/air system could not be fully investigated without a programme of flight test measurements, which was not practical in this case. The aircraft had made a reasonable number of flights over past years with different pilots and no fuel mixture problems had been reported. Since this was the only aircraft of its type, there was no possibility of further evaluation. It was therefore concluded that the engine had probably lost power due to an incorrect fuel/air mixture which could have arisen as a result of either a technical malfunction or inappropriate use of the mixture control.