

SA341G Gazelle 1, G-HAVA

AAIB Bulletin No: 2/98 Ref: EW/C97/7/9 Category: 2.3

Aircraft Type and Registration:	SA341G Gazelle 1, G-HAVA
No & Type of Engines:	1 Turbomeca Astazou 3A turboshaft engine
Year of Manufacture:	1974
Date & Time (UTC):	28 July 1997 at 1410 hrs
Location:	Gamston Airfield, Retford, Nottinghamshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - Serious - Passengers - Serious
Nature of Damage:	Helicopter destroyed
Commander's Licence:	Private Pilot's Licence (Helicopters)
Commander's Age:	49 years
Commander's Flying Experience:	Approximately 170 hours (of which 25 hours were on type) Last 90 days - 9 hours Last 28 days - 4 hours
Information Source:	AAIB Field Investigation

The aircraft was owned and operated for private purposes by the husband and wife who were involved in the accident. Both the pilot and her husband had an equal amount of flying experience on the helicopter as they had undertaken their type conversion together in April 1997 and shared all the flying. Earlier that day they had flown from a private helipad at their home near Darlington to Gamston Airfield in Nottinghamshire to collect some headsets from a Hughes helicopter that they had owned previously; the wife was the handling pilot. After an hour and ten minutes on the ground they were setting off to fly to a hotel close to Chatsworth Hall in Derbyshire; the wife was again the handling pilot seated in the right hand seat. She was wearing her normal footwear of low-heeled slip-on shoes.

The helicopter had been parked next to the grass and approximately parallel to Runway 03 on the opposite side of a concrete parking area to a line of hangars. Start and pre-take-off checks took longer than normal as the pilot was waiting for her husband to complete the Global Positioning System (GPS) programming and there was some discussion about waypoints. However, whilst she could not recall details, the pilot had no reason to believe that she had not followed the checklist in

her normal meticulous way and that the helicopter was other than fully serviceable. The surface wind at the time was NW at 10 kt or less and the intended departure direction was across the airfield to the west as there was no conflicting traffic. The pilot was therefore conscious of the need to turn left after take off. She reported that the lift-off and initial left turn felt normal but that she very quickly became aware of a rapidly increasing yaw rate. Her husband, who was in the left-hand seat, shouted to her to apply 'more right foot' and she replied to the effect that 'she had right foot'. She had no further recollection of her actions but remembers that, after a short period of time, the helicopter was left skid low and that she could see sky in front of her. Her subsequent recollection is of post-crash actions. Her husband has no memory of any events on the day of the accident. Eyewitness reports are contradictory as to whether the lift-off was gentle or rapid but it was clear that the helicopter began to turn to the left almost immediately the skids left the ground.

The helicopter was seen by eyewitnesses to accelerate in yaw, rise to a height of between approximately 60 and 80 feet and to make more than one complete revolution. As it reached its maximum height it was seen to oscillate in both pitch and roll before descending across the hard-standing area and colliding with the corner of the adjacent hangar. It came to rest right side up against the corner and immediately caught fire. The pilot unfastened her husband's seat belt and called to him to get out, only to find that she was unable to get out herself. She was rescued by eyewitnesses at the scene. A ground engineer attempted to pull her husband through the shattered windscreen but he was impeded in his rescue by the fact that the husband's feet had become entangled in the pedals. Later his ankle was found to have been pierced by some structure. To clear this difficulty he therefore pushed him fully back in his seat before disentangling his feet and then pulling him forward and through the windscreen. The airport fire service were attempting to suppress the fire during this period but the husband suffered approximately 20% burns and three cracked ribs. The ground engineer had minor burns to his head. The pilot received a fracture of the T12 vertebra. At the date of this report both occupants are recovering from their injuries.

Previous incident

On 4 June 1997 the husband had flown the helicopter to a hotel at Ullswater with his wife as passenger. On departure that evening in light wind conditions he carried out a normal vertical takeoff from the site but at approximately 20 feet above the ground the helicopter commenced a rapid yaw to the left. He applied full right pedal and after about one and a half turns the rotation stopped and he flew the helicopter away in the opposite direction to that originally intended. He had not considered landing the helicopter immediately the yaw occurred as the initial rotation took it over adjacent bushes. The incident was not reported.

Following the incident, both he and his wife carried out practice into-wind and out-of-wind take offs and landings at their farm and each took an additional flying lesson with their instructor.

Yaw control system

Yaw control on the Gazelle is provided by a fenestron: a thirteen-bladed fan located within a duct in the base of the fin which is driven by a shaft from the main rotor gearbox. Horizontal stabilisers with a vertical fin at each tip are mounted on either side of the tail boom just forward of the fin. In normal flight the flow through the fenestron is from left to right (as the main rotor torque reaction attempts to yaw the fuselage to the left), although in the cruise most of the side thrust to counter the main rotor torque is generated by slipstream effects over the cambered fin. The pilot's yaw pedals vary the pitch angle of the fenestron blades and thereby control the airflow through the fenestron duct. This duct has lips on the inflow side and is slightly divergent on the outflow side. A proportion

of anti-torque thrust is generated by pressure difference across the fin induced by the flow of air through this duct. The pedals are mechanically connected to the fenestron blades by a rod, bellcrank and cable system, which incorporates a damper to limit the rate of pedal movement, and a hydraulic servo jack to reduce pedal forces.

Fuel flow to the engine is controlled by a governor which maintains the engine speed constant at a nominal 43,700 RPM. A fuel flow control valve lever mounted in the cabin roof close to the centreline provides control over engine start, idle, and normal cruise settings through the fuel governor. Adjacent to this is a fuel cock shut-off lever. Unlike most other single engine helicopters, there is no 'twist grip' style engine control on the collective lever and in the Gazelle the pilot must remove his left hand from this lever in order to, for example, reduce engine power without lowering the collective.

Stability augmentation system

The aircraft was fitted with a SFENA Ministab Stability Augmentation System (SAS) which could be selected 'ON' or 'OFF' as required by the pilot. Following the accident the switch was found in the 'OFF' position. When engaged, the SAS acts to oppose motion in the pitch, roll and yaw axes through limited authority hydraulic actuators in the cyclic and pedal control systems. It responds to rate of movement in the appropriate axis and therefore provides a damping effect on aircraft response to rapid control inputs by the pilot and to external disturbance by turbulence. Following the accident the switch was found in the OFF position. Furthermore, the SAS had been disabled on G-HAVA, as operating information was not available for the SFENA system.

Site examination and impact parameters

Examination of the apron where G-HAVA had been parked revealed witness marks that appeared to have been made by this helicopter. [See Figure 1]. Analysis of these suggested that it had yawed to the left whilst some weight remained on the skids before it became fully airborne. Witness marks attributable to this helicopter were located some 100 feet to the east, close to the corner of the hangar, and consisted of marks made by the tail boom bumper (beneath the fin), main rotor blade tips and main skids. These were located some 35 feet west of the hangar corner and indicated that the helicopter had touched down with a high rate of descent whilst yawing relatively slowly to the right, tail and right skid low, and on a heading of 220°M, before it bounced to the left and into the corner of the hangar. Debris from this break-up, including sections of the main rotor blades and the fenestron drive shaft, had been scattered over a wide area surrounding the wreckage, including the apron and an area of long grass to the side of the hangar. Witness marks of the main rotor blade tip strikes on the ground, main rotor blade slashes on two sides of the hangar forming the corner, the severely damaged condition of the three blades themselves and the wide distribution of debris, left little doubt that the main rotor had been turning at a high speed the time of the accident. The helicopter had come to rest on a heading of 225°M adjacent to the northern corner of the hangar complex on the airfield. A post-impact fire broke out which consumed most of the tail boom and lower rear fuselage and seriously damaged the remainder of the helicopter aft of the two front seats, forward of which relatively light heat damage occurred.

For several hours after the accident the battery continued to supply electrical power to the instrument panel and, when first examined, all the warning lights, instrument and radio lights and gyro operated instruments were seen to be functioning. The distribution of the wreckage at the accident site indicated that the tail boom suffered structural disruption prior to the accident such that the fin/fenestron had become detached from the tail boom. Two of the thirteen fenestron blades

were missing, only one of these being recovered from the site despite several searches. It was apparent that the tip of one main rotor blade had passed through the leading edge of the fin sufficiently deep to leave a witness mark on the fairing over the fenestron hub.

Wreckage examination

The wreckage was recovered to the AAIB at Farnborough for a detailed examination; the yaw control system in particular. Here, it was established that all failures seen in the fenestron drive system aft of the inclined gearbox were due to overload, consistent with being caused during the accident. Evidence of fenestron driveshaft rotation was only found as far aft as the inclined gearbox, located close to where the tailboom joins to the fuselage, beyond which the characteristics of all shaft failures indicated the shaft had not been rotating, or rotating only very slowly, when struck. Despite the severe post-impact fire it was apparent that the tail boom had been distorted upwards, as a result of contact with the ground, effectively pivoting about its upper edge close to where it attached to the fuselage. There was evidence to indicate that this had caused the drive shaft to tear out of the flexible coupling immediately aft of the inclined gearbox, whilst rotating, and allow the tail boom to progressively intersect the main rotor disc resulting in the blade strikes which disrupted the tailboom.

Examination of the recovered fenestron blade showed this to have failed in a single event overload by lateral bending, but in the opposite direction to the tip direction of the main rotor blades, and probably resulted from being struck by debris during the accident. The stub of the missing blade indicated that this item had also failed in overload, the direction of failure strongly suggesting that it had been struck by the tip of a main rotor blade. Examination of the yaw control system failed to reveal any pre-accident disconnect or failures in the system, and it was apparent that the input system, including both sets of pedals, had been frozen by the impact/fire in the full right position. A strip examination of the main rotor servo jacks also revealed no evidence of pre-accident defects, and it was established that all mechanical input linkages from the main rotor head to both cyclic and collective levers in the cockpit had been intact. The collective lever itself had failed just below the pilot's handgrip. As found, the hydraulic servo power selector switch, located on the collective lever switchbox, was in the 'OFF' position but deformation between the toggle and the switch body suggested that this had been moved to this position with some force. The pilot recalls that the switch was 'ON' and that no hydraulic caption was illuminated on the warning panel. The hydraulic system itself had been severely damaged in the fire, but examination of all remaining components showed no evidence of pre-accident defects.

Service history

This helicopter was manufactured in France in 1974 and, prior to being placed on the UK register in 1997, saw service in the Middle East and Portugal. At the conclusion of each period of service it had been returned to the manufacturer for re-furbishment. The helicopter's maintenance history was well documented and it had yet to reach its first 50 hour check since the issue of the UK Certificate of Airworthiness. At the time of the accident it had achieved a total of approximately 2,530 flying hours over 3,850 flights.

Gazelle yaw characteristics

A total of 29 Gazelles have been entered on the UK Register of which 18 remain. Approximately 76,000 flying hours had been accrued by the fleet at the end of 1996 and there are 5 recorded accidents involving loss of yaw control where there was no related mechanical or system failure. The

UK Armed Forces have operated Gazelles since 1973 in training and operational roles and have suffered 15 similar loss of yaw control accidents or incidents during a approximately 600,000 flying hours. There is anecdotal evidence of further unrecorded incidents to military Gazelles.

In the majority of civil and military cases, loss of yaw control occurred in the hover or at low forward speed in light winds from the right. A few occurred in stronger winds or with wind from the left. Both inexperienced and highly experienced pilots were involved in the military accidents and loss of control of pitch and roll during the subsequent high rates of rotation was a common feature. An 'optimised fenestron' was fitted to military Gazelles in the early 1980s as part of a weight upgrade programme. The optimised fenestron had revised duct and hub fairings but did not appear to improve the incidence of sudden loss of yaw control.

The sudden loss of yaw control was attributed to 'fenestron stall' and, in response to concern, the Ministry of Defence (MOD) sponsored a trial by the manufacturer, Eurocopter France, to investigate the phenomenon. The trial took place in 1992/93 and demonstrated that, in conditions of low natural wind, a relatively small left pedal input of 5% (of total pedal travel) from the hover position can result in a yaw rate of 150°/sec being achieved in 10 seconds. It also showed that high yaw rates to the left (165°/sec) can be rapidly arrested by application of full right pedal without any tendency for aerodynamic stall of the fenestron. The MOD advice included a statement that the extremely rapid build up of yaw rate in these circumstances was exacerbated if the SAS was not engaged.

The MOD trial did not establish why a small pedal input can result in the rapid build up of very high yaw rates. However, an earlier study, in 1991, by Westland Helicopters Limited had suggested that the trigger mechanism might involve a coupling of fenestron rotor induced swirl with the circulation contained in the main rotor tip vortices which may become aligned with the fenestron in certain flight conditions. The study also suggested that considerations should be given to changing the direction of rotation of the fenestron to become top-blade-aft which would probably solve the interactional aerodynamic problem. Subsequent fenestron-equipped helicopters such as the SA365 Dauphin, EC135 and EC120 have top-blade-aft fenestron rotation; they are not known to suffer from sudden loss of yaw control.

Effect of hydraulic system de-selection or failure

The effect of hydraulic system failure or de-selection by the pilot using the collective-mounted SERVO switch is to increase control forces and to cause the collective lever to move to the 8° pitch setting and the cyclic stick to the aft and right. The Flight Manual cautions that greater force is necessary to actuate the flying controls and that considerable force will be necessary to move the pedals. Following failure or de-selection in flight, it is recommended that landing is made at the end of a very flat final approach. Normal practice is to avoid hovering by making a running landing to minimise power changes and reduce pedal requirements.

Analysis

Had the take off been made with the SERVO switch selected 'OFF', it would have been extremely difficult to control the helicopter in all axes and a high rate of yaw might have developed, and been very difficult to counter, if the pedals had not initially been in the position required for the prevailing conditions. In that case, however, the controls would have felt distinctly abnormal. Despite the distraction caused by her husband's programming of the GPS, the pilot was certain that

all pre take-off checks had been completed and that the helicopter felt normal on initial lift-off. It is therefore unlikely that the take off was made with the SERVO switch selected 'OFF'.

It is also unlikely that the pilot's feet had slipped off the pedals whilst attempting to counter the yaw as she was quite used to wearing her low-heeled shoes when flying, had not walked across grass or muddy areas, and was sure that she had been applying full pedal when challenged by her husband.

The wind was from the left and the intended departure direction was to the west. The pilot was therefore conscious of the need to turn to the left after take off and may inadvertently have applied left pedal during the take off process. The helicopter's behaviour would then have been consistent with the skid marks indicative of it yawing whilst still in ground contact and with witness descriptions of it turning immediately on leaving the ground. Conditions would then have been conducive to the rapid increase in yaw rate experienced in other Gazelle accidents and incidents, particularly if the wind had been modified by adjacent hangars to provide a less favourable local wind component from the right. It is therefore likely that the pilot experienced a sudden loss of yaw control induced by her early left pedal input.

It is therefore recommended that the Civil Aviation Authority (CAA) reconsider the type-rating training requirements for the Gazelle to determine whether additional emphasis needs to be placed on yaw control during take off, landing and low speed manoeuvres (Recommendation 97-62).

Flight Manual advice

Prior to the MOD trial, the advice in the military Aircrew Manual in respect of sudden loss of yaw control was that the dramatic increase in rate of yaw to the left was due to so-called 'fenestron stall' and that application of right pedal would not arrest the rate and might even exacerbate it. Following the trial, the advice was amended to emphasise the tendency for small left pedal inputs to generate high yaw rates under some circumstances, delete reference to 'fenestron stall', and to state that immediate and positive application of right pedal, up to the maximum, should be applied and maintained to arrest the rate of yaw.

The CAA Approved Flight Manual for the Gazelle, at Change Sheet 1, Issue 1 dated 16 March 1992, retains reference to 'fenestron stall' in the section referring to 'uncontrolled yaw breakaway'. It recommends the same recovery technique as for tail rotor failure in the hover or at low speed and low altitude. That is, "establish autorotative flight and, during the final approach, switch the engine off and land with an accentuated flare. In the event of failure near the ground, immediately reduce the pitch, even if a very rough landing will result".

Although control of G-HAVA was lost during the rotational sequence, marks indicated that it was rotating slowly to the right at impact. It is therefore likely that the pilot's right pedal input had eventually countered the left rotation.

The AAIB recommended in 1991 that the CAA liaise with MOD and Aerospatiale (now Eurocopter) regarding the 1992 trial and, if applicable, invite the manufacturer to suggest a cure for sudden loss of yaw control. The recommendation was accepted by the CAA which advised that any relevant results of the liaison would be acted upon as appropriate. It is not clear whether any action was taken, but it is recommended that the CAA review the Approved Flight Manual to determine whether the advice regarding uncontrolled yaw breakaway should be amended in the light of the MOD trial results (Recommendation 97-63).

Safety Recommendations

Recommendation 97-62

It is recommended that the CAA reconsider the type-rating training requirements for the Gazelle to determine whether additional emphasis needs to be placed on yaw control during take off, landing and low speed manoeuvres.

Recommendation 97-63

It is recommended that the CAA review the Approved Flight Manual for the Gazelle to determine whether the advice regarding uncontrolled yaw breakaway should be amended in the light of the MOD trial results.