

# Robinson R22 Beta, G-BROX, 23 April 1996

**AAIB Bulletin No: 7/96 Ref: EW/G96/04/24 Category: 1.3**

**Aircraft Type and Registration:** Robinson R22 Beta, G-BROX

**No & Type of Engines:** 1 Lycoming O-320-B2C piston engine

**Year of Manufacture:** 1989

**Date & Time (UTC):** 23 April 1996 at 1650 hrs

**Location:** Greenham Common, Berkshire

**Type of Flight:** Private

**Persons on Board:** Crew - 1 Passengers - 1

**Injuries:** Crew - None Passengers - None

**Nature of Damage:** Heavy landing damage to skids and tail boom plus damaged main rotor blade

**Commander's Licence:** Private Pilot's Licence

**Commander's Age:** 42 years

**Commander's Flying Experience:** 293 hours (of which 152 were on type)

Last 90 days - 38 hours

Last 28 days - 13 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The helicopter was returning on a southerly heading to a private landing site in Hampshire. The weather conditions were good visibility outside heavy rain showers and a westerly surface wind of 10 to 15 kt. In the showers the visibility reduced to 5 km. The flight plan route passed close to the disused military airfield at Greenham Common and the pilot decided to overfly it so that his passenger could see the sights. As he approached the northern boundary of the airfield the pilot checked for carburettor icing and noted that the carburettor air temperature gauge indicated 15°C. However, there was a rain shower upwind of the airfield and so as a precaution he applied half travel on the carburettor heat control and continued to monitor the air temperature gauge. On reaching the western end of the airfield the aircraft encountered rain and the aircraft started to climb. At that point the pilot applied full carburettor heat and lowered the collective control in order to regain his cruising altitude of 1,500 ft QNH. Shortly afterwards, on an easterly heading, the aircraft encountered sink whilst descending in the region of the edge of the squall. Noting that the carburettor air temperature was 20°C and that the helicopter had lost some 500 ft of altitude, the

pilot returned the carburettor heat control to the cold position and increased engine power to 24 in manifold pressure.

The unwanted descent was arrested at 800 ft QNH but shortly afterwards at about 900 ft the pilot felt that the helicopter was unstable and the engine felt and sounded 'lumpy'. As he checked the engine instruments the engine RPM decayed rapidly and so he lowered the collective lever and opened the throttle but the engine did not recover power. He then entered full autorotation, declared a MAYDAY and turned to the left to bring the helicopter into wind. Half way around this turn the aircraft entered a region of sinking air on the edge of the squall and the descent rate increased. The pilot then re-evaluated his options and decided to turn back to the right and accept a forced landing, downwind, into a field of grass just beyond a construction site. He reduced airspeed to 40 kt in order to reach the field and applied full collective just prior to ground contact to cushion the landing. The helicopter's ground speed was high because of the tailwind and it bounced off the ground and turned to the left. After the second touchdown the aircraft slewed to the left and tipped to the right but the pilot was able to stop it rolling over with full left cyclic control. The engine was still running and the helicopter upright after the landing but the vertical impact forces bent the skid cross tubes and creased the tail boom. The damage to the trailing edge of one main rotor blade was incurred during the landing but the cause was unexplained.

The 1550 hrs weather observation at nearby Farnborough recorded an air temperature of 10°C and a dew point of 7°C. These conditions are well inside the boundary for serious icing at any power setting according to the CAA's General Aviation Senseleaflet 3B. The main features of the carburettor icing probability diagram are reproduced below.

### CARBURETTOR ICING PROBABILITY

