

# Boeing 747-436, G-BNLF

## AAIB Bulletin No: 11/97 Ref: EW/A97/4/01 Category: 1.1

<b>Aircraft Type and Registration:</b>	Boeing 747-436, G-BNLF
<b>No &amp; Type of Engines:</b>	4 Rolls Royce RB211-524G turbofan engines
<b>Year of Manufacture:</b>	1989
<b>Date &amp; Time (UTC):</b>	5 April 1997, at 0825 hrs
<b>Location:</b>	Lilongwe Airfield, Malawi
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 15 - Passengers - 135
<b>Injuries:</b>	Crew - 1 Minor - Passengers - 2 Minor
<b>Nature of Damage:</b>	Extensive but undetected structural damage to lower fuselage skins aft of the wing and distortion of keel beam web
<b>Commander's Licence:</b>	Air Transport Pilot's Licence
<b>Commander's Age:</b>	50 years
<b>Commander's Flying Experience:</b>	16,550 hours (of which 3,550 were on type) Last 90 days - 113 hours on type Last 28 days - 32 hours on type
<b>First Officer's Flying Experience:</b>	13,010 hours (of which 3,400 were on type) Last 90 days - 160 hours on type Last 28 days - 56 hours on type
<b>Information Source:</b>	AAIB Field Investigation

## History of the Flight

The aircraft was planned to operate a weekly scheduled passengerservice from London (Gatwick) to Lilongwe (Malawi) via Lusaka(Zambia) and the return to Gatwick was also via Lusaka. One crewflew the leg from Gatwick to Lusaka and a separate crew, alreadyat Lusaka, flew the legs to and from Lilongwe. The aircraft wasserviceable for the approach to Lilongwe where the runway in usewas Runway 14. This runway has a high intensity approach lightingsystem including VASIs set at 3\_, the landing distance is 11,614feet on an asphalt surface, it is served by an ILS which was

serviceable and the touchdown threshold is 4,028 feet amsl. Prior to the approach, the reported weather conditions for the airfield included a surface wind of 100/07 kt, visibility greater than 10 km with no significant cloud and a surface temperature of 21\_C; however, showers were reported in the vicinity.

With the First Officer (FO) as the handling pilot the aircraft was positioned onto the ILS at about 15 miles; the landing reference speed (V<sub>Ref</sub>) was 145 kt. The Captain took control for a visual approach and landing at 1,000 feet at which time he observed a small rain shower crossing the runway threshold but he remained unconcerned because he could see through it without difficulty. He later described the rain as "sheeting but bright" and he had no problem seeing the runway at 500-600 feet. The Captain did not select his windshield wipers, even when prompted by the FO, because he had previously found the movement and noise of the wipers to be distracting. He described the rain rippling over the windshield but was never in any doubt that he had sufficient visual cues to continue the landing although he did note that the rain appeared to intensify. He heard the FO call '50 Above' and 'Decide' and responded with 'Landing'. The next sound that the Captain heard was the GPWS warning "Sink Rate" and then the aircraft hit the runway hard.

The FO described flying into the rain shower at 500 to 600 feet whereupon he immediately selected his windshield wipers to the 'High' position, thereafter he maintained sufficient visual reference with the runway. He offered to select the wipers for the Captain but this offer was declined. Because of the intensity of the rain he decided to revert to the height calls required during an instrument approach and called '50 Above' and 'Decide'. He estimated that at about 200 feet the aircraft was stabilised slightly to the right of the centre line but adequately positioned for the landing. In the final stages of the approach he was aware of the aircraft sinking so he placed his hands on the control column, however, before he could intervene the "Sink Rate" warning occurred followed immediately by a very hard landing from which the aircraft bounced. He was not conscious of any check or flare being initiated by the Captain and this is substantiated by the Flight Data recordings.

The FO realised that the aircraft was now airborne and displaced over the right hand side of the runway; he considered that they were not in a safe position to attempt to continue with the landing so he called 'Go Around' and applied full power. When they were safely away from the ground he called for the Autopilot to be engaged; after checking the EICAS for failure indications to the Hydraulics system, Landing Gear, Tyres and Doors, he retracted the gear. The Cabin Services Director came onto the flight deck to tell the crew that there was some damage in the cabin, the crew responded that they would be landing in 5 minutes. The FO positioned the aircraft for a visual approach to Runway 32 since he noted that the shower was still over the threshold of Runway 14, the Captain then took control and continued the visual approach which culminated in a normal landing.

Once on the ground and after the shutdown checklist had been actioned the Captain completed the technical log and an Air Safety Report and informed the accompanying ground engineer that a "Heavy landing check" would be required. The FO completed his own walkaround, paying particular attention to the undercarriage, but could see nothing amiss with the exterior of the aircraft. In the cabin approximately 12 Passenger Service Units (PSUs) had broken loose as had an over-aisle panel containing the video display screen, all of these displaced units were at the rear of the aircraft. One elderly couple had been struck by one of the PSUs but declined the offer of medical assistance.

## **Analysis of the Landing**

Although the aircraft was initially stabilised on the approach, a series of pitch inputs, which were initiated by the pilot below 250 feet, caused the aircraft to strike the ground with a high rate of descent. There was no attempt to flare the aircraft. It is probable that the visual references used by the Captain during the landing phase were distorted by the presence of water on the windscreen. The distortion would have been significantly reduced by the use of the windscreen wipers, as was demonstrated by the perceptions and actions of the FO.

## **Flight Recorders**

The Flight Data Recorder (FDR) and Optical Quick Access Recorder (OQAR) fitted to the aircraft were replayed by the Operator once the aircraft had returned to Gatwick. The voice recording of the accident landing had been over-written.

The FDR and OQAR recordings contained the accident and subsequent landings and, as the OQAR data was more comprehensive and at a higher sample rate, this was the data used for the investigation.

The data showed that the first approach into Lilongwe was stable on a glide slope of approximately 2.8° and was flown manually with an aircraft pitch of approximately 3° nose up on a magnetic heading of approximately 131°M. Flap 25 had been selected and the landing gear was down.

Fourteen seconds before the landing, at a height of 240 feet agl and a speed of 153 kt ( $V_{ref}+8$  kt), the aircraft was slightly high on the glide slope. Corrective nose down elevator was applied and the pitch attitude of the aircraft reduced to 2.5° nose up as the sink rate increased from 700 feet/min to 1,400 feet/min over a period of seven seconds. As the nose down elevator was applied the heading increased to 132.5°M. With the aircraft now at 120 feet agl, the nose was briefly raised to 2.8°, temporarily reducing the descent rate to 900 feet/min, before it was lowered to 2.2°, allowing the descent rate to increase to 1,488 feet/min.

In the four seconds before touchdown, from a height of 70 feet agl, the handling pilot raised the pitch to a maximum of 3.7° before lowering it to a minimum of 1.3° nose up. As the descent rate increased the GPWS Sink Rate warning was activated for the last two seconds.

At 0823 hrs the aircraft struck the ground, with a roll of 2.1° left wing down, at a speed of 149 kt ( $V_{ref}+4$  kt), a last recorded descent rate of 1,344 feet/min and a peak vertical acceleration of 2.86g. The air/ground sensor was active for a period of two seconds and the localiser reading indicated that the aircraft was slightly right of the runway centreline. There was no recorded activation of the windshear alert nor was there any evidence of windshear from the correlation of the airspeed and ground speed of the aircraft during this landing.

Having struck the ground the aircraft was pitched up, became airborne and maintained a height of approximately 15 feet agl for six and a half seconds before full engine power was achieved. Flap 20 and gear up were selected and the aircraft climbed away with a pitch attitude of between 13° and 15° nose up. At 0829 hrs the aircraft made an uneventful, flap 25 landing on a heading of 314° magnetic, 6 minutes after the initial incident.

## **Engineering aspects**

Because this operator only flies one scheduled service into Lilongwe each week, engineering coverage is supplied by the operator's Station Maintenance Manager (SMM) travelling with the

service from Lusaka, Zambia, and using local airline engineering resources as necessary at Lilongwe. The SMM had originally received his technical training and experience in the RAF and then worked for this operator for some 30 years.

At the time of the heavy landing, the SMM was, therefore, seated in the forward passenger cabin, having joined the aircraft at Lusaka. As the aircraft was taxiing to the stand the cabin crew advised him of the damage in the aft cabins and, after the aircraft was parked, he made his way to the flight deck where the Captain requested that he perform a "Heavy landing check". The SMM then recorded the cabin damage before going to the engineering office and printing a 'hard' copy of the relevant Maintenance Manual pages of the required Hard Landing Inspection.

The Hard Landing Inspection in the manufacturer's Maintenance Manual is distinct from the Overweight Landing Inspection and is divided into two parts: Phase I and Phase II. The inspection is at the discretion of the commander and the Manual states that if Phase I does not show that damage has occurred, no more inspections are necessary: if the Phase I Inspection **does** show that damage has occurred, then the more extensive Phase II is required. The Phase I Inspection covers four sheets from the Maintenance Manual and directs attention primarily at the landing gears, at the engine nacelles and at the engine attachments to the wing. In addition, items are included for the wing leading edge fairings, the trailing edge flap mechanisms, the horizontal stabiliser fuel tank and the APU supports. The only reference to fuselage inspection is "aft of body station 2000 for signs that the runway was touched". The Phase I Inspection is qualitative and no measurements are specified.

During his initial 'walk around' the exterior of the aircraft, the SMM looked, from experience, for signs of bursting or over-pressuring of tyres, integrity of the main and body landing gears, the airframe in general and engine alignment marks: there were no signs of structural damage. He then started the formal Phase I Inspection, which he performed over a period of about 6 hours. Although the SMM performed the inspections himself, he was assisted in accessing the various areas (for example, the engine struts) by personnel assigned from the national airline. In addition to the Phase I items specified, he performed a number of checks based on his experience, such as opening and closing all the exterior cabin and baggage doors on the aircraft, looking for any signs of misalignment or mismatch. From previous experience of heavy landing checks he also looked at the condition of the water tanks and re-tightened a number of leaking joints around the potable water tanks.

The only item from the Phase I check not included in the SMM's inspection was the horizontal stabiliser tank, which was not required as the tank did not contain fuel. For the inspection of the APU support intercostal, the SMM was concerned as to whether the equipment available was adequate for full access within the compartment itself, although he did open the APU doors and inspected the area, ascertaining that there was no visible damage. At the end of the Phase I Inspection, having found no evidence of structural damage from the heavy landing, the SMM raised an ADD form (Acceptable Deferred Defect) for a precautionary repeat Phase I Inspection, with a 'Cat Q 2' limitation for two landings to cover the aircraft's sectors returning to London Gatwick. The aircraft manufacturer has since confirmed that the SMM's inspection of the APU intercostal, viewing from a distance of some 6 feet, met the requirement of the Phase I Inspection.

During his inspection the SMM was conscious of a number of Telex messages between Lilongwe and the operator's Maintenance Control ('Maintrol') at London Heathrow. These were handled directly by local Customer Service Manager as the SMM stayed with the aircraft and he states that he was not conscious of any particular interest from Maintrol in the level of vertical G recorded in

the ACMS (Airplane Condition Monitoring System). This figure was not available through the ACARS (Aircraft Communications Addressing and Reporting System) as the ACARS printer had previously been disabled fleet-wide and an early attempt to interrogate the ACMS directly had been unsuccessful. The SMM also comments that the Maintenance Manual instructions for the Phase I Inspection, which he was following, do not refer to any recorded data.

By about 1730 hrs local (UTC+2), with his exterior work completed, the SMM was back in the aircraft cabin, tidying the remaining cabin problems caused by the heavy landing but without extra time to address Cabin Log deferred defects. At about 1800 hrs local the flight crew came back on board and the SMM reported that there was "no damage other than in the cabin" and that the Phase I Inspection had been negative. With the Transit check completed and signed by the SMM, the Captain accepted the aircraft and at 1840 hrs local the aircraft departed for Lusaka, on time, with the SMM aboard.

At Lusaka no further defects were entered in the aircraft Technical Log. There was a complete crew change and the 'heavy crew' accepting the aircraft each did normal external inspections. The SMM again attempted to interrogate the ACMS and managed to acquire a form of the report of the exceedance event but this report did not include values either for sink rate or vertical G. After the aircraft had departed for London Gatwick, approximately on time, the SMM received a Telex message from Maintrol enquiring about the ACMS information and he transmitted the very limited ACMS data to Maintrol by Telex.

### **Aircraft damage**

During the repeat Phase I Inspection at London Gatwick signs of fuselage skin damage were noted, just aft of the wing (stations 1480 to 2181), with substantial areas of 'quilting' and 'rippling' of the skin panels. It was determined that the level of vertical G deceleration had been recorded as 2.86G in the ACMS, with a related sink rate of 1070 ft/min. The aircraft was ferried to the maintenance facilities at London Heathrow and the full Phase II Inspection was conducted, with extensive support from the manufacturer. It was determined that there was further structural damage to the left-hand web of the fuselage keel beam, in the area of the landing gears, and slight 'out-of-round' damage to some of the wheel hubs which was discovered only during detailed workshop inspection. There had been no discernible damage in the areas covered by the Phase I Inspection, including the APU support intercostal. The aircraft underwent extensive structural repair at London Heathrow with support from the manufacturer and was returned to service on 1 June.

### **AAIB investigation**

The AAIB investigation included interviews with the SMM who had performed the Phase I Inspection at Lilongwe, the flight crew for that sector and the operator's technical and quality staff. Examination of G-BNLF and other aircraft at London Heathrow confirmed that, as most B747 lower fuselage panels show some degree of skin waviness, it can be difficult to determine what constitutes a damaged condition.

It was established that the requests from Maintrol to the SMM for the record of vertical G from the ACMS had been at the suggestion of the Fleet Technical Manager. With no limitations or strictures within the Maintenance Manual's Phase I Hard Landing Inspection, there was no question of this G recording being used as a criterion for determining the aircraft serviceability nor of requiring that this parameter be read from the ACMS prior to the aircraft's return to service at Lilongwe.

Regarding the SMM's concern about access for inspection of the APU support intercostal, the operator's engineering organisation concluded that the normal procedure would have been for the SMM to contact the Fleet Technical Engineer at Maintrol, who would, in turn, have contacted the relevant Fleet Technical Design Engineer (FTDE). In this case, any additional inspection of the APU support intercostal arising from such an exchange would have found no damage. It is highly unlikely that any extra activity in the area of the APU would have resulted in detection of the damage to the fuselage skin panels.

### **Manaus incident**

On 22 March 1997 N707CK, a B747-200 cargo aircraft, suffered a heavy landing on arrival at Manaus, Brasil, and the incident was later investigated by the National Transportation Safety Board (NTSB).

The crew stated that the heavy landing had occurred because of a lack of flare: playback of the FDR confirmed that the flare had only been initiated about two seconds before the impact. The FDR also indicated a maximum recorded vertical G level of 2.77 with a descent rate greater than 1100 feet/min. The crew reported the landing weight as 629,500 lbs, close to the maximum landing weight.

In the subsequent Phase I Inspection at Manaus, the engineer noted skin waviness in the fuselage, aft of the wing, and eight 'popped' fasteners. Following exchanges between the operating company and the manufacturer, and further inspections inside the fuselage, the aircraft was ferried to Miami and then to Oscoda, Michigan, where it was surveyed and repaired. During the manufacturer's survey at Oscoda skin panel wrinkling was detected up to a depth of .250", considerably more severe than in G-BNLF, and damage in the keel beam area of N707CK was also more severe. Some minor contact damage was noted around the main landing gears.

The significance of this incident to N707CK, in relation to G-BNLF, was that substantial structural damage in the fuselage was not accompanied by significant damage within the Phase I Hard Landing Inspection.

### **Manufacturer's response**

In response to a number of questions put by the AAIB, the airframe manufacturer confirmed that the fuselage damage would have had no discernible effect on the structural strength of the aircraft on its two return sectors and that, after the repairs, full structural durability was restored to G-BNLF.

Concerning the significance of the maximum recorded values of vertical G deceleration, the Maintenance Manuals consistently state that the pilot must make the decision as to whether a structural inspection is necessary. The manufacturer has concluded from flight tests and analysis that definition of a particular vertical G exceedance level is not a reliable method to define a Hard Landing. This is partly due to the variations of time and magnitude of deceleration due to such factors as aircraft attitude and rates, structural dynamics, weight and CG, and partly due to the filtering characteristic and sampling rate of the accelerometer itself. In response to appeals from several customers the manufacturer has, however, developed a limited procedure for touchdowns with less than 2° roll. The roll attitude of G-BNLF at touchdown was 2.1°.

The manufacturer also responded that it is unusual, but not unknown, for fuselage structural damage such as that on G-BNLF to have been found whilst not exhibiting damage in those areas specified in

the Phase I Hard Landing inspection. Further, if the SMM had spotted the damage to the fuselage or keel beam, the manufacturer suggests that the correct course would have been contact with the manufacturer for guidance on limits to wrinkle depth and containment. The manufacturer states that, as a result of the two recent occurrences, the 747 Maintenance Manual Phase I and Phase II Hard Landing Inspections will be reviewed and updated; it is planned that inspection and acceptance criteria for panel wrinkling will be included.

### **Operator's response**

The operator of G-BNLF notes that the ACARS printers are being reinstated and a figure of 1.8g or above will initiate a print-out. In addition, a development programme has been initiated to link the printer automatically to ACARS for transmission to the main Engineering base.

### **Recommendations**

During the investigation, the AAIB noted that significant structural damage had occurred to G-BNLF as the result of a heavy landing and this damage was not reflected in the Phase I Inspection. It was also noted that, had the SMM, an experienced engineer, noted the possible skin damage, there was no ready means of distinguishing this from normal skin waviness. The AAIB therefore makes the following recommendations:

#### **Recommendation 97-42**

It is recommended that the CAA and FAA monitor the manufacturer's review of the Hard Landing Inspections and any subsequent amendment to the 747 Maintenance Manual to ensure that there is a high level of confidence in detecting structural damage which follows a heavy landing.

#### **Recommendation 97-43**

It is recommended that, to aid flight crew in determining the need for inspections, the CAA and FAA consider methods for quantifying the severity of landings, based on aircraft parameters recorded at touchdown.