

# Piel CP301A Emeraude, G-BIJU, 27 May 1997

## AAIB Bulletin No: 8/97 Ref: EW/G97/05/25 Category: 1.3

<b>Aircraft Type and Registration:</b>	Piel CP301A Emeraude, G-BIJU
<b>No &amp; Type of Engines:</b>	1 Continental O-200-A piston engine
<b>Year of Manufacture:</b>	1957
<b>Date &amp; Time (UTC):</b>	27 May 1997 at about 1730 hrs
<b>Location:</b>	Stapleford Tawney Airfield, Essex
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	Damage to propeller, engine cowlings and some engine components
<b>Commander's Licence:</b>	Private Pilot's Licence
<b>Commander's Age:</b>	60 years
<b>Commander's Flying Experience:</b>	136 hours (of which 41 were on type) Last 90 days - 5 hours Last 28 days - 3 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot

The aircraft, a tail-wheeled Emeraude, took off from Runway 04 at Stapleford Airfield at about 1650 hrs. The surface wind, reported by ATC, was 040\_/12 kt and this was confirmed by the windsock indications; the wind at 1,000 feet was reported to be 040\_/15 kt. During the take-off run the pilot was aware of a slight crosswind from the left and after take off he encountered turbulence which continued up to about 400 feet agl. Following some local flying the aircraft returned to Stapleford at about 1725 hrs where the runway in use and the surface wind were unchanged. During the approach to land the pilot again noticed turbulence below about 500 feet agl with an associated drift to the right. During the landing roll, with the aircraft tracking along the runway, a gust of wind from the left caused the aircraft to deviate to the right. Despite the application of left rudder and aileron the aircraft departed from the dry grass runway surface and went onto the uncut grass where it came to rest on its nose. The pilot turned off the magnetos and vacated the aircraft. He then returned to turn off the fuel and the master switches. The airfield

fire and rescue services attended the scene immediately and helped move the aircraft from the edge of the runway.