

Team Minimax 91, G-MYKZ, 14 July 1996

AAIB Bulletin No: 9/96 Ref: EW/C96/7/6 Category: 1.3

Aircraft Type and Registration: Team Minimax 91, G-MYKZ

No & Type of Engines: 1 Rotax 503 piston engine

Year of Manufacture: 1994

Date & Time (UTC): 14 July 1996 at 1630 hrs approximately

Location: East Ginge Down near Wantage,
Oxfordshire

Type of Flight: Private

Persons on Board: Crew - 1
Passengers -
N/A

Injuries: Crew - None
Passengers -
N/A
Others - 1
(serious)

Nature of Damage: Substantial to main landing gear, engine and propeller

Commander's Licence: Private Pilot's Licence (Microlight Aeroplanes)

Commander's Age: 50 years

Commander's Flying Experience: 500 hours (of which 80 were on type) approximately

Last 90 days - 17 hours

Last 28 days - 6 hours

Information Source: AAIB Field Investigation

The home-built aircraft had been completed by the pilot in 1994 and was kept at Ginge Farm airstrip close to East Ginge, approximately half a mile to the north of the 'Ridgeway', which is a public right-of-way and scenic walk on the crest of the Downs.

On the day of the accident the pilot, accompanied by his wife, brother and partner, and two dogs, arrived at the farm airstrip for the start of an afternoon walk along the 'Ridgeway'. The pilot remained behind, in order to prepare his aircraft for take off, as the group ascended the hill. He planned to reposition the aircraft in a large 100 acre field on top of the Downs and to meet up with his group for the walk. On their return he would depart the field, fly for some 20 minutes and return to the farm strip in the valley below. The pilot reported that the weather at the time was fine with visibility in excess of 25 km with a light north-westerly wind of 5 kt, broken cloud above 2,500 feet and a temperature of approximately 25°C. Having landed in the upper field the pilot parked his aircraft in some rough grass close to a line of trees, removed the aircraft keys, closed the canopy and rejoined his family.

When the group returned to the field after their walk the pilot decided that, as there was now insufficient time available for the planned 20 minute flight, he would just take off, climb to a suitable height and position for a downwind right-hand circuit to land on the farm strip below. His wife, with the two dogs, remained in the field to watch his departure while his brother and partner started to make their way down the hill.

After engine start the pilot manoeuvred the aircraft in a sweeping 'S' turn to take off in a north westerly direction. After takeoff the aircraft was seen to climb sharply and enter a steeply banked turn to the right. The pilot reported that as he entered the turn the canopy appeared to come unlocked and he removed his left hand from the throttle to hold the canopy closed. As he did so engine power reduced. The pilot was not aware of the reason for the power reduction at the time although he later surmised that engine vibration may have caused the throttle to close. Believing that he had an engine failure, he continued to turn right in order to land back close to his point of departure. With the tree line close by he tightened the turn which resulted in the aircraft stalling, 'flicking' into a level attitude and descending in a stalled condition. With the wings level and the aircraft in a high nose attitude there was insufficient time and height for the pilot to effect a stall recovery. His only option was to stall straight ahead. The aircraft hit the ground in a high nose attitude and came to rest within a very short distance damaging the main landing gear and dislodging the engine from its mountings. As soon as it was stationary the pilot switched off the fuel and fully opened the canopy whereupon he became aware that his wife lying on the ground close to the rear of the fuselage in a state of distress. It was only at this time that the pilot realised that his wife had been struck by the aircraft during the landing.

The pilot's wife, who had been watching the manoeuvring aircraft, did not realise until it was too late that the aircraft was out of control and heading straight for her. The aircraft collided with her and the propeller struck her head as she passed beneath the fuselage but above the strut connecting the two main wheels. Although suffering from head and leg injuries she remained conscious. The dog that she had been holding in her left hand on a lead was killed in the collision. The pilot was quickly joined by the two other members of the group who tended to his injured wife. A nearby witness summoned help using a mobile 'phone. The emergency services were alerted and at 1650 hrs the Thames Valley Police helicopter, flying in the vicinity at the time, landed close by the crashsite. At 1735 hrs, with a paramedic in attendance, the wife was airlifted from the scene and arrived at hospital ten minutes later.

Aircraft handling characteristics

A British Microlight Aircraft Association (BMAA) test pilot, familiar with this type of aircraft, was consulted on the aircraft's handling characteristics. He stated that the aircraft shows a tendency to 'flick' level if banked steeply and pulled through the turn, with either high or low power settings. The rate of 'flick' exceeds the rate of roll achieved through normal aileron application. Moreover the aircraft will 'mush' in the stall with no proper 'break'. In this condition the nose remains high and the view over the front cowling is limited particularly if the engine installation is raised as in the case of the accident aircraft. Due to the full span ailerons, the roll control remains effective throughout the stall envelope, though the authority is much reduced due to the low speed.

Ground impact marks

The aircraft had landed on grass on a heading of 240°(M) on a slight up-slope. Three distinct gouges in the earth marked the impact positions of the main wheels and the propeller. The aircraft had then bounced nine metres forward, where it had come to rest. The initial entry angle of the first ground mark indicated an angle of 22° below the horizontal. The ground marks showed that the aircraft had hit the ground with wings level at a low forward speed and a high sink rate, compatible with being in a stalled condition. The lightly loaded tail wheel had probably contacted the ground first, arresting the descent of the tail. The main energy had been dissipated through the main wheels and their supporting structure.

Aircraft Information

The impact had collapsed the fixed main landing gear, and had fractured the alloy hub on the left main wheel. The three propeller blades were still loosely attached to their boss. The tip of one blade had detached, and another showed evidence of impact damage; the boss attachment bolts had bent and released most of the wedges used to determine the propeller blade angles. All three glass-reinforced plastic (grp) blades showed evidence of rearwards bending in the form of gel coat fractures on their forward faces and buckling on their rear faces.

The engine mounting structure had failed and the engine had rotated forward through 90° allowing the nose section to ride over one propeller blade. Apart from this damage to the nose structure, the fuselage and wing structure were largely devoid of obvious signs of damage caused by the impact.

One alloy rod in the over-centring canopy locking mechanism was bent, preventing the mechanism from locking the canopy shut. It was not known whether this damage had been caused by the impact.

Engine

The engine fitted was a Rotax 503, but it had retained the Mikuni fuel pump associated with its original 447 cc engine. The fuel pump output may have been marginal for the larger engine. The carburettor vent lines were contaminated; blockage of these lines could have prevented air entering the float chamber and caused loss of power. The fuel filter bowl was contaminated with fine silt; the fuel pump filter had been cleaned as part of the preparation for the permit renewal.

The fuel cock was 'OFF', and the throttle was found in the fully forward position, however, this could have been caused by the movement of the engine off its mountings. The choke cable had been similarly affected and had pulled the inner cable out of its soldered housing at the cockpit end.

The nature of the Rotax engine means that the throttle is spring loaded to the idle position. To apply power the carburettor spring tension must be overcome. Most builders of the Minimax incorporate friction clamping for the throttle, by using friction washers at the pivotal point on the throttle lever. The accident aircraft was similarly fitted. There is a tendency, however, for these to lose their friction and they regularly need tightening.

Propeller

The relative lack of damage to the propeller, and the lack of propeller slash marks on the ground indicated that the engine had been running at low RPM. This would be consistent with a throttle setting at idle power.

Documentation

The aircraft did not have a current Permit to Fly, but had satisfied the technical part of the application procedure. The engine and aircraft log book details were incomplete, and inaccurate regarding the engine and propeller. The aircraft was fitted with a three-bladed propeller which had not been cleared by the Popular Flying Association (PFA) for the aircraft type, although it may have been accepted if the results of a satisfactory air test had been presented to the PFA.