

# Boeing 757-236, G-BIKF, 5 April 1996

## AAIB Bulletin No: 10/96 Ref: EW/C96/4/1 Category: 1.1

<b>Aircraft Type and Registration:</b>	Boeing 757-236, G-BIKF
<b>No &amp; Type of Engines:</b>	2 Rolls-Royce RB211-535C turbofan engines
<b>Year of Manufacture:</b>	1982
<b>Date &amp; Time (UTC):</b>	5 April 1996 at 0650 hrs
<b>Location:</b>	Stand C49, London Heathrow Airport
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 7 Passengers - 89
<b>Injuries:</b>	Crew - None Passengers - None
<b>Nature of Damage:</b>	Damage to auxiliary power unit air ducting
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	49 years
<b>Commander's Flying Experience:</b>	12,000 hours (of which 2,500 were on type) Last 90 days - 55 hours Last 28 days - 18 hours
<b>Information Source:</b>	AAIB Field Investigation

The aircraft was about to push back from stand C49 on a scheduled service from London to Zurich with 7 crew and 89 passengers onboard (6 club class, 83 economy). Passenger boarding had been routine, all doors were closed but not yet armed, and the boarding jetty had been removed. The ground power supply to the aircraft had been disconnected as the auxiliary power unit (APU) was providing aircraft electrical power and air for cabin conditioning. The tug and towbar were attached and a ground engineer was in contact with the flight crew via the external intercom.

The commander requested, and was granted, push-back clearance from ATC but was told to wait for other ground traffic to clear from behind his aircraft before moving. He therefore selected the anti-collision beacon 'ON', but kept the parking brake applied. The crew, in preparation for engine start, had actioned the 'Before Start' checklist and had selected their conditioning 'PACKS' to 'OFF'.

At this stage, the cabin service director (CSD) was making his final check of the cabin and was walking to the rear of the aircraft. As he approached seat rows 19 to 20, he heard a "thud" and saw what appeared to be a shower of "confetti" rise into the air adjacent to seat row 24 (the last row before the centre toilets). He also noticed the cabin atmosphere become contaminated with a blue-grey mist. He turned and immediately made his way to the flight deck to inform the commander that "there had been an explosion and that the cabin was filling with smoke". The commander, who had also heard a faint thud and felt a slight pressure surge on his ears, looked past the CSD into the cabin and was able to see a 'bluish smoke haze' to the rear.

The commander immediately instructed the first officer to call for the airport emergency services on the ground movement frequency whilst he called the company on the ground handling frequency to request full ground support and for the jetty to be repositioned at door L1. He then made a public address (PA) to the passengers instructing them to move forward. On hearing the first officer transmit that there had been an explosion on board the aircraft, the ATC watch supervisor, using the omnirash communications system, instigated full emergency procedures by declaring an "AIRCRAFT ACCIDENT". This alerted not only the airfield emergency services but also those from neighbouring local authorities. The fire crews were on scene within two minutes, at 0657 hrs.

Two ground dispatchers rapidly appeared in the mouth of the jetty and were hurried in their positioning of the jetty by the commander shouting through the open flight deck direct vision (DV) window. The CSD, who was standing in the flight deck doorway and listening to updates from the rear cabin crew over the interphone, then informed the commander that the smoke intensity was increasing. On hearing this, and seeing that the jetty was moving rapidly towards the forward door, the commander ordered the CSD to open the front door (door L1) and evacuate the passengers as soon as the jetty was in position. The commander then made a further PA instructing the passengers to "leave the aircraft quickly, without hand baggage, by the front door". The evacuation into the terminal lounge was fast and orderly and conducted without incident.

The flight crew did not action the evacuation checklist, but during the evacuation the first officer selected the aircraft systems (*ie* fuel, hydraulics etc) to 'off'. He suggested to the commander that the APU should also be shut-down, but the commander decided against this action and put the PACKS to 'ON' in an attempt to remove or dissipate the smoke.

At this stage, with no previous warning indications on the flight deck, the commander noticed that one 'CARGO FIRE-BOTTLE DISCHARGE LIGHT' was 'ON' and as he watched, the second 'DISCHARGE LIGHT' illuminated. This also brought to his attention the cargo fire bottle discharge messages on the engine indication and crew alerting system (EICAS) display. Although there was no associated indication of a 'CARGO FIRE', the commander ordered the first officer to carry out the 'CARGO FIRE' checklist. The first item on the checklist is to select the 'CARGO COMPARTMENT ARMING SWITCH' (for the affected cargo compartment) to 'ARM'. This action, in the case of the AFT CARGO COMPARTMENT, arms the No 1 and No 2 cargo fire extinguishers, turns off the cargo heat fan and cargo heater, turns off the recirculation fan and switches the right air conditioning pack to high flow. However, as both fire-bottle discharge lights had already illuminated the crew believed that activation of the arming switch was irrelevant and therefore did not action this checklist item.

As the fire service arrived the commander attempted, without success, to contact the fire crew on ground frequency of 121.6 MHz. However, as the flight crew vacated the aircraft to join the passengers and cabin crew in the lounge, the fire crew arrived in the cabin. The commander reported that as he left the aircraft smoke had reached the forward cabin and, whilst "thicker"

than first observed, was not too dense and visibility was approximately one third to one half of the cabin length.

The APU was still running as the fire crew boarded the aircraft and, although the commander could not remember selecting the APU to OFF before he vacated the aircraft, fire crew personnel reported that the commander did in fact select the APU off at their request.

Once on board, the fire crew used a thermal imaging camera which indicated a 'hot spot' in the rear cargo hold. The rear cargo hold was subsequently emptied of luggage, but nothing unusual was found. The panelling at the forward end of the rear cargo bay was removed and, although no fire damage was found, it was observed that the insulation material in the exposed bay had been disturbed. Further examination of this zone was performed after the arrival of AAIB and it was found that the hot air delivery duct from the APU to the pneumatic manifold had fractured (see illustration for location).

### **Use of Checklists**

The company Flying Manual, 'Non-Normal Procedures' section, details 'Procedures beyond the scope of the Quick Reference Handbook' (QRH). The relevant paragraphs are reproduced below:

'Procedures cannot be established for all conceivable Non Normal situations. The degree, complexity and variety of multiple failures is difficult to cover in the QRH. It is the responsibility of the crew to assess the situation and execute sound judgement to determine the safest course of action. Thorough knowledge of both the aircraft systems and Technical Manuals is required to enable the correct action to be taken in the event that the situation is not covered in the QRH.'

It is rare to encounter in-flight situations which are beyond the scope of established Non Normal procedures. These events can arise as a result of unusual occurrences such as mid-air collision, bomb explosion or other major malfunction. In such situations the flight crew may be required to accomplish multiple Non Normal checklists, selected elements of several different checklists (applied as necessary to fit the situation) and rely on their own technical knowledge, judgement and experience.'

The commander exercised his judgement in this situation and elected not to action the evacuation checklist. The first officer, having been instructed to carry out the cargo fire checklist, did not action any of the items on that list since he believed them to be irrelevant because both cargo fire bottles were already indicating discharge. The commander also retained the APU in operation in an attempt to effect smoke removal from the cabin.

The incident was dealt with in an expeditious and professional manner by both the flight and cabin crew. There was no formal checklist procedure to cover this situation.

The commander always has the option to initiate a full evacuation of passengers using the aircraft emergency exits and slides. However, in this situation a full evacuation was not necessary and may well have caused injury to some passengers. Such incidents may arise however, between the time that the first passenger boards the aircraft and the aircraft moves under its own power and the emergency slides are armed, when a rapid disembarkation of the passengers, using the airport facilities (jetties and/or mobile steps), is required. A suitable checklist for flight deck and cabin crew which covered this situation would formalise the procedure to be adopted. It is therefore recommended that:

96-46: The CAA Flight Operations Inspectorate should promote the introduction, by Air Operator Certificate holders, of a formalised 'rapid disembarkation' checklist procedure to expedite the deplaning of passengers using normal passenger entry facilities during potentially serious incidents which do not require a standard evacuation and which occur before aircraft push-back, or movement under engine power, and before the cabin door evacuation slides have been armed.

### **Engineering examination** (see illustrations)

Examination of the passenger cabin some three hours after the event showed that although there was a large quantity of fibreglass insulation debris in the area of the centre cabin and toilet, particularly on the right side, there was neither physical evidence nor a smell to suggest that there had been any fire.

Examination of the fuselage cavity immediately forward of the aft cargo compartment and aft of the main wheelwell revealed that the insulating blankets which had been wrapped round the 5 inch diameter titanium air duct from the APU to the pneumatic manifold had been considerably displaced and locally disrupted. The fuselage sidewall insulation had been disturbed in the floor/sidewall gap, particularly on the right side of the aircraft, and it was mainly this type of material which had been distributed into the passenger cabin.

It was observed that the transverse part of the section of APU air duct within this cavity aft of the main wheelwell was partially free to move and that the duct had separated just downstream of a bend near the left fuselage side. The duct separation had occurred at the weld which joined the bend to the transverse straight part of the duct section. At this position, the duct had been supported by a stirrup hung from a fore and aft floor beam. The stirrup clamp band was about 1<sup>3</sup>/<sub>4</sub> inches wide and had been positioned such that it had enclosed the duct welded joint within its width; there was evidence of relative movement between the straight part of the duct and the clamp liner. It was also found that the section of duct aft of the failed one had kinked towards the fuselage side at the first restraining clamp aft of the bend. The parts of the transverse duct section were removed from the aircraft for metallurgical examination of the failed weld.

The duct section assembly consisted of four parts welded together, two bend pieces with 0.035 inch wall thickness and two straight sections with 0.020 inch wall thickness. Metallurgical examination revealed the failure to have been by tensile fatigue, originating in the toe of the weld joining the upstream bend to the transverse straight section and on the edge of the weld which attached to the straight part. The failure had progressed by a fatigue mechanism round approximately 75% of the duct periphery before final rupture. The examination showed the weld to have been of very good quality with no features which might have led to premature fatigue initiation.

Inquiries revealed that, during early operation of the Boeing 767 and 757 types, the titanium pneumatic ducting, which was originally fabricated mainly from 0.020 inch thick material, was prone to cracking. As a result of this experience, the manufacturer introduced modified ducting, by Service Bulletin (BSB 757-36-0015 for B757s), with 0.035 inch thick material at the bends and strengthening rings. The modified ducting was made Mandatory by the CAA and it had been fitted to 'KF' in October 1987. Since that time 'KF' had completed 13,500 flights and 16,580 flight hours.

Although ducting of this specification has proved satisfactorily durable on Boeing 757s, as a result of continuing problems on B767 aircraft, the manufacturer later produced ducting of a further improved standard which had been stress relieved. Ducts of this latest standard were

considered, for B757s, to be a product improvement only and, although fitted from new on late build aircraft, were listed as preferred spare parts for replacement ducts on aircraft already in service.

Also within the same cavity, forward of the aft cargo compartment, were the two cargo bay fire bottles and the two temperature sensing elements for detecting hot air leaks running parallel to the air duct. Although there had been no indication of a 'Duct Burst' on the flight deck, the detection system tested serviceable. Since the fire bottles had indicated that they had discharged, they were removed; however, weighing them indicated that they were still fully charged.

Enquiries of the manufacturer revealed that the discharge sensor system for these bottles was designed to detect a relatively small drop from nominal charged pressure and incorporated variation of the trigger pressure to compensate for changes of static charged pressure with temperature. The sensors were fitted to an external boss on the bottle so that, if the bottle material were to be heated faster than its contents, the trigger pressure could rise above the charge pressure.

During the course of the investigation it became apparent that the APU duct support clamp, which was at the position at which the duct weld failed, was not correctly located. According to the design, the clamp should have been attached to the floor beam closer to the aircraft centreline (see diagram). The operator immediately called for a survey which revealed that this aircraft was the only one in their fleet to have the clamp mislocated. There was no evidence that the clamp had ever been attached to the correct floor beam, nor was there evidence that repairs or modifications had been done to this area of the floor structure.