

Beech Super King Air 200, G-BVMA

AAIB Bulletin No: 9/97 Ref: EW/A97/1/1 Category: 1.2

Aircraft Type and Registration:	Beech Super King Air 200, G-BVMA
No & Type of Engines:	2 Pratt & Whitney PT6A-41 turboprop engines
Year of Manufacture:	1980
Date & Time (UTC):	25 January 1997 at 1440 hrs
Location:	In Cruise, Overhead Brussels
Type of Flight:	Public Transport
Persons on Board:	Crew - 2 - Passengers - 6
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Top of door bent outwards
Commander's Licence:	Commercial Pilot's Licence
Commander's Age:	43 years
Commander's Flying Experience:	8,150 hours (of which 657 hours were on type) Last 90 days - 59 hours Last 28 days - 44 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and metallurgical examination of damaged components

The aircraft had departed Dusseldorf for London Gatwick at 1406hrs. During its climb out it was held for a few minutes at FL140 and then continued to its cruising level of 220. All systems, including pressurisation, were working normally. At about 1425hrs the aircraft was levelled at FL220 and the crew began the cruise checks. The Captain was about to reduce the propeller speed to 1,700 RPM when there was a loud bang and a rapid decompression. The crew carried out an emergency descent with all the occupants breathing oxygen from the emergency masks and they landed at Brussels at 1440 hrs.

It was found that there had been failures in the hook mechanisms which secure the top edge of the cabin door. This had allowed the top of the door to deform outwards, lifting the pressurisation seal. The door is hinged at its bottom edge and retained closed by two shoot bolts on each side in addition to the top edge hooks. The shoot bolts were engaged and undamaged and the door remained in place.

The failed hook mechanisms were examined by AAIB (Figure 1). In both cases the clevis pin which attached the hook arm to its operating lever had failed and, in the case of the front assembly, there was an opened crack on one side of the bifurcated section of the hook arm, between the hook and the clevis pin hole. In the front hook arm the headed end of the pin had remained trapped in the hole by plastic deformation of its shank. The headed end of another pin was found and this was taken to be from the rear hook arm. No other material was recovered from the failed pins but two other pins from the assembly were taken for metallurgical comparison. The fracture face on the separate clevis pin (rear hook arm) was typical of that occurring by simple bending fatigue. The fatigue had multiple origins but the surface was extensively corroded and had been mechanically damaged so it was not possible to analyse it in detail or to estimate the number of load cycles involved. The fractured end of the pin in the front hook arm showed much more mechanical damage over its fracture surface and any evidence of its original failure mode had been destroyed. From this damage, and from the lesser damage on the other pin it seemed that the broken pins had supported the operating levers for some time after the initial failure. The matching pin holes in the lever also showed some plastic deformation at their edges which showed that the deformed or broken pins had been causing excess edge loads in the holes and that there had been considerable movement at these pin locations. This movement would have loosened the hooks' engagement on the latch pins in the door frame. As found both hooks were almost fully retracted into their screw fittings in the ends of the hook arms *ie* almost fully adjusted in the direction which would absorb such play. The condition to which the door and hooks had been rigged in the aircraft could not be reconstructed but from the above it appears that adjustments had been made to take up play created by the failure of the pins.

Vickers hardness tests on both the failed clevis pins and the intact ones showed that they had been manufactured from steel of approximately 63 tonf/in² tensile strength which is correct for these pins. The Beech part (Part number 131323-2C15) is made from a MS20392-2C15 pin and has a solid film lubricant. The aircraft manufacturer reported that the FAA "Alert" reporting system contained two cases of worn or broken pins, the CAA's database contained none.

The crack in the front hook arm proved to be due to stress corrosion. The arm had been manufactured from steel of 102 tonf/in² and the consultant metallurgist who examined these components commented that steels above about 90 tonf/in² are susceptible to stress corrosion under high sustained surface stresses in humid atmospheric conditions. The crack was evidently secondary to the failure of the clevis pin which probably resulted, in this case, in all of the hook load being taken by only one side of the bifurcated hook arm.

The Overhaul and Replacement Schedule in the aircraft Maintenance Manual required the upper door hook mechanism (including the pins) to be replaced at every 12,000 flight hours. The aircraft had completed 11,532 hours at the time of the accident. At 4,107 hours (November 1987) the log book contained a record that the hooks had been replaced but this quoted the part number of the hook alone and not the hook arm and the rest of the assembly containing the clevis pins. The manufacturer reports that an inspection procedure specifically for the pins is under consideration.