

Cessna 152, G-BRCC

AAIB Bulletin No: 9/97 Ref: EW/C96/5/13 Category: 1.3

Aircraft Type and Registration:	Cessna 152, G-BRCC
No & Type of Engines:	1 Lycoming O-235-L2C piston engine
Year of Manufacture:	1978
Date & Time (UTC):	31 May 1996 at 1218 hrs
Location:	Lydd Airport, Kent
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - Fatal - Passengers - Fatal
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	53 years
Commander's Flying Experience:	380 hours (of which 242 were on type) Last 90 days - 3 hours Last 28 days - 3 hours
Information Source:	AAIB Field Investigation

History of the flight

The pilot had arranged to take a passenger for a local flight from Lydd, but the PA-28 was booked elsewhere. He therefore elected to undertake the flight in the Cessna 152, registration G-BRCC, which had been refuelled to full tanks earlier that morning. The aircraft took off at 1110 hrs, initially routing along the coast towards Hastings. The aircraft then flew across to Folkestone, in order to overfly the home of the passenger. Contact was maintained with Lydd Radio throughout. The pilot called when west of Dymchurch in order to rejoin the Lydd circuit. He correctly read back the AFIS information that the runway in use was 22, left hand circuit, QFE 1018 mb. As there was no other circuit traffic at the time, the pilot made a straight-in visual approach to Runway 22, with the surface wind passed as 220° at 16 kt.

As the aircraft flared for landing one eyewitness observed some yaw to the right to occur. At about this time, a divergent pitch oscillation was noted. During the third cycle, the aircraft was observed to commence a go-around. It entered a steep right turn at about 50 to 100 feet agl onto a downwind

heading. The normal circuit pattern for Runway 22 at Lydd is left hand. After a short period of time with the wings level on the downwind leg and with little additional climb, another steep bank to the right occurred as the aircraft turned back towards the runway threshold. The bank steepened to more than 60° and the aircraft appeared to enter an incipient spin. It crashed onto open ground short of the runway threshold, displaced slightly to the east of the centreline. Both occupants sustained immediately fatal multiple injuries.

Three eyewitnesses were interviewed who had observed the final flight path, two were in the Tower Visual Control Room and a third on a golf course located to the north-west of the airfield. Witnesses were not consistent in their perception of the direction of the incipient spin. Two said that the aircraft departed to the right, one thought it was to the left.

An aftercast from the Meteorological Office indicated that at the time of the accident there was a ridge of high pressure established over the continent, maintaining a strong south-westerly surface airstream over southern England. The visibility was around 7 km in haze, scattered cloud base 2,500 feet, temperature +15°C, QNH 1020 mb. The surface wind was from 240° at 15 to 20 kt with gusts of 25 to 30 kt. The anemometer in the Tower was reading 15 to 20 kt at the time of the accident. Some light to moderate low level turbulence was reported by an instructor who was airborne at the time, but the conditions had not changed significantly since the pilot's check flight earlier that morning. A strong wind warning was in effect for the airfield, forecasting gusts up to 35 kt. The pilot had been aware of this before the flight departed.

A check of the aircraft's weight and balance condition indicated that at the time of the accident, the aircraft weight was about 1,600 lbs (within the maximum allowable of 1,670 lbs), and the centre of gravity was at 32.56 inches aft of datum (allowable range 31 to 36.5 inches aft of datum).

During examination of the wreckage, the pilot was found to have had a knee board with departure information from Lydd recorded. He also had a copy of a Cessna 150/152 checklist, which was found open at Pre Take-off/After Take-off/Missed Approach/Cruise/Top of Descent page.

The passenger had no previous light aircraft flying experience. He was found in the wreckage to be holding a southern England half million scale topographical chart, folded into large sections, but not such as to show the area around Lydd. His camera was recovered from the wreckage and was found to contain a film showing that he had taken a number of aerial photographs during the flight, although none were found which covered the period around the time of the return to the airfield.

Pilot experience

The pilot completed his PPL training course at Lydd during 1985. In recent years the amount of flying he undertook had reduced considerably, such that 7.4 hours were completed during 1990, nil during 1991, 5.5 hours during 1992, 6.3 hours during 1993, 4.4 hours during 1994 and 4.6 hours during 1995. The pilot had kept his licence current with the appropriate Certificate of Test or Certificate of Experience (13 month validity, minimum 5 hours flying, of which at least 3 hours were as pilot in command) in his flying log book. The latest Certificate of Experience in the log book was signed on 28 May 1995, covering flights made during April 1995. There were no further flights between April 1995 and May 1996.

In order to ensure revalidation, the pilot recommenced flying from Lydd on 11 May 1996. He undertook a check flight of 1.2 hours duration with an instructor in a Cessna 152. During this flight

the following exercises were carried out: slow flight, stalls, steep turns, practice forced landings, circuits with touch-and-go landings, a go-around and a practice engine failure after takeoff.

The pilot's next flight was on the morning of the accident, when he arranged to undertake another check flight, this time in a PA-28-151 aircraft with a different instructor. A similar flight profile was followed, with the exception that no go-around was practised on this occasion. Neither instructor made any significant adverse comment about the pilot's performance during either of the check flights.

Medical aspects

The post-mortem examination on both occupants did not reveal any medical condition which could have caused incapacitation during the flight, nor were there any indications that drugs or alcohol had played any part in the event.

There was a medical anomaly involving the pilot's condition. He had renewed his Class One medical on 4 May 1996, which included an Electro-CardioGram (ECG). This was initially regarded with some suspicion but, on review and taken in conjunction with the previous ECGs on file, it was concluded that the tracings were, in fact, normal.

The pilot's General Practitioner (GP) was not his CAA Authorised Medical Examiner. The pilot had been to his GP on 16 April 1996, complaining of palpitations he was experiencing. These had apparently been present for some years but had become more prevalent and troublesome, with episodes immediately after waking, taking food and precipitated by energetic exercise. It was not clear whether the heart beat was irregular or merely unduly vigorous, but it did not result in pain or loss of consciousness, merely discomfort. The pilot's GP did not appreciate that flying was involved and so made no recommendation about it. The pilot was referred for a consultant's opinion and a 24 hour ECG tape, but this had not taken place by the date of the accident.

The pilot made no mention of the symptoms or consultant referral when renewing his aviation medical certificate some two weeks later. The questionnaire associated with the aircrew medical does not query whether the applicant is currently undergoing any form of consultation (merely referring to '*medications currently prescribed*', and '*have you a history of...*') which may be regarded as ambiguous. The proposed wording of the new JAA Application for an Aviation Medical Certificate poses the specific question '*Visits to medical practitioner since last medical exam. YES/NO*' with a request for further details if the question is answered in the affirmative. This should remove any possible ambiguity.

The aviation pathologist who carried out the post-mortem examination found it difficult to assess the significance of the palpitations to the accident. Given the pilot's history, he considered that it seemed unlikely if they had occurred in flight that they would have caused a loss of consciousness. However, the unpleasant sensation which had been described as accompanying them might have been sufficient, had it occurred during the approach or landing, to make co-ordination and concentration difficult.

Accident Site

GBRCC struck the ground 156 metres short of the threshold of Runway 22, 47 metres to the left of the runway centreline. The impact was within the airfield boundary, on flat horizontal ground covered with long grass. Initial impact was onto the left wing outboard leading edge, followed by

ground impact of the left main wheel, the propeller, the nose wheel and the left side of the forward fuselage. The aircraft came to rest inverted and substantially intact around 2 metres south-east of the initial impact point.

Examination of the site and the wreckage showed that the aircraft had impacted the ground in a steep descent while rolled approximately 45° left and pitched 45° nose down relative to the horizontal. The speed had been relatively low and the evidence showed that there had been very little horizontal speed component but a moderately high descent rate. The impact heading was easterly. There were no signs from the wreckage or ground marks of a substantial rate of aircraft rotation.

Detailed Wreckage Examination

The aircraft sustained heavy crushing damage to the forward part of the left wing, partial failure of the wing to fuselage attachments, bending failure of the tailboom and moderate deformation of the cabin structure. The empennage escaped virtually undamaged. The aircraft had been complete at impact.

The engine remained generally intact; examination with the assistance of the engine manufacturer revealed no signs of pre-impact problems. Signs were found indicating that the engine had been turning at the time of the accident but, given the steep impact, the power level could not be quantified. The evidence suggested that appreciable quantities of fuel had been present in each wing tank (one tank per wing) at the time of the accident.

Primary and secondary flight control systems were examined in detail; all the components of the systems were recovered. No signs of pre-accident defects or failures of the primary flight controls were found. The possibility of a control restriction could not be totally dismissed but appeared to have been unlikely. It was not possible to reliably establish the pitch trim setting.

Both seats remained in the cabin attached to the floor rails and the plunger securing each seat on the rail in the fore and aft sense had been engaged in the rail at the time of impact.

Particularly close scrutiny was given to the flap system. This consists of a flap surface on each side of the aircraft (Fig 1), each carried on two fixed flap tracks mounted behind the rear spar of the wing. The carriage at each flap track station consists of two flap-mounted rollers, attached between a pair of carrier plates mounted near the front of the flap, and located in curved slots in the track. The rollers run on needle roller bearings. In the case of the aft rollers, steel washers are installed on the roller bearing on either side, interposed between the flap track and the flap carrier plates, and a single nylon washer is installed on one side of the track. Flap surfaces are controlled by a mechanical system operated by a bellcrank in the right wing driven by an electric motorised actuator. The right flap is driven directly from the bellcrank by an operating rod; the left flap is driven from the bellcrank by a cable-pulley loop system located in the rear part of the wing. Flaps can be set from 0° (retracted) to 30° (full).

Requirements in the CAA/LAMS/FW/1978 Schedule for scheduled maintenance of the flap system are (Section 7, Item 7), at 150 Hour and Annual Checks, 'Flying Controls: Inspect - hinges; brackets; push-pull rods; bellcranks; control horns; balance weights; cables; pulleys; chains; tubes; guides and fairleads; rollers; tracks and rails; screw jacks/rams, including auxiliary gearboxes

or other power-operated systems. Check - turnbuckles/locking devices in safety. Inspect - flap asymmetric protection mechanisms.'

The possibility of GBRCC having experienced flap asymmetry during the go-around, with the left flap having remained extended further than the right flap, was considered during a detailed examination of the flap system. The flap selector was found in the flaps fully retracted position and the flap actuator extension corresponded to flaps fully retracted and, as it could not have been backdriven during the impact, had clearly attained this position before the accident. Both flaps were found fully retracted, but clear evidence of their position at the time of impact could not be found. Examination showed that the Down cable was broken in the wing centre section, but the evidence provided no positive indications as to when this failure had occurred; it was possible that the cable had been overloaded due to displacement of the left wing relative to the fuselage during the ground impact. The Up cable remained intact but part of the flange of a pulley in the right wing over which the cable passed had broken off, consistent with the effects of cable overtension. The pulley changed the cable direction by 40° and calculations showed that the geometry change associated with the pulley damage was equivalent to approximately 0.25 inch linear extension of the Up cable. This would be equivalent to between approximately 0.5 to 1.5° of flap travel increment, depending on the flap angle. The other pulleys in the system remained essentially intact and in place. The amount of additional asymmetry that could result from elastic deformation of the flap system could not be quantified.

All the flap rollers and their bearings were found in place and undamaged; most of the flap carrier plates exhibited appreciable wear from the forward rollers, in the form of annular grooves worn by the roller end faces. The wear was generally more severe on the carrier plates of the left flap, particularly on the outboard pair where grooves 0.10 to 0.15 inch deep had been worn.

Abnormal markings were found on the left flap outboard track, consisting of severe notching of the right side of the track adjacent to the aft slot by the mating steel washer of the roller/washer assembly. The damage was indicative of a heavy juddering-type motion of the roller assembly in the flap retracting direction between approximately 15° and 5° flap angle. Some markings were also found on the left flap inboard track, corresponding to approximately 15° flap angle. It appeared from the evidence that the abnormal flap track markings may have resulted after partial extension of the left flap during the impact as a result of overtension of the flap cable system due to wing displacement. The absence of any failure that would have allowed substantial slack in the Up cable-pulley system, such as a break in the Up cable, precluded the possibility of a gross flap asymmetry (in the sense of greater left flap extension) during the go-around having occurred. However, the possibility of a partial asymmetry, that had been accommodated by deformation of the cable-pulley system and the damage to the pulley in the right wing, could not be totally dismissed.

Aircraft Background

Maintenance records indicated that the aircraft (Serial No 15280986) had been constructed in the USA in 1978 and exported to the UK in 1989. In 1991 it had been bought by the owner at the time of the accident and leased to a succession of operators. It did not fly for 3 months around the end of 1995. At the time of the accident it had accumulated approximately 6,030 flying hours. The engine had operated for approximately 1,000 hours since its last overhaul in 1994. The records indicated that the aircraft and engine had been maintained in accordance with the CAA/LAMS/FW Maintenance Schedule.

Previous Cases

Reports were found of 4 occurrences of asymmetric flap in flight on aircraft models with a similar type of flap system. Available information was as follows:

1. Cessna 172, Oct 85 - [AAIB Bulletin 1/86]:

Following a simulated overshoot at 4300 ft agl with full (40°) flap, the flaps were retracted in 10° stages, retrimming between every stage. On selection of 0° flap from 10°, a loud bang was heard and the aircraft rolled right. The instructor had to apply full left aileron and rudder and close the throttle to arrest the roll. Having regained a wings level attitude he observed that the left flap was fully deployed. Control during an emergency descent was just possible provided the power was below 1600 RPM. After landing it was found that the aft roller bearing assembly at the outboard support for the left flap had fractured and broken up due to fatigue. This had severely worn the flap track slot and pieces of the roller sleeve had broken off and jammed between the roller and the slot, resulting in overload failure of the flap up drive cable to the left flap which was then free to blow back to the full flap position.

2. Cessna 150, Dec 88 - [CAA Database]:

On flap up selection during an air test a loud report was heard and the left flap was observed to be 2-5° from the up position. Re-selection to full down and up gave satisfactory operation.

3. Cessna 150, Aug 95 - [CAA General Aviation Safety Leaflet (GASIL) 2-96]:

The instructor was demonstrating the use of full 40° flap to the student. At the end of the demonstration, he applied full power and began to retract the flaps back to the zero degree position. There was a loud bang from the roof, just above his head, followed by a rapid rolling to the right. He reduced power to idle and controlled the aircraft with aileron and rudder. On looking around, he found that the left-hand flap was still in its 40° position, whereas the right-hand flap was nearly fully retracted. He returned with reduced speed and carried out a safe landing. Engineering investigation showed that the left-hand flap cable had failed.

4. Cessna 172, Florida - [Manufacturer's report]:

On flap retraction the left flap remained down. The rolling tendency was controlled. Subsequently a loud bang was heard and the left flap fully retracted.

Service Bulletin

Cessna Service Bulletin SEB953 published 10 March 1995, noted "Service experience indicates the potential for wearing of the flap support by the flap rollers. To assist in preventing this condition from occurring, an inspection of the flap supports and rollers along with a modification to install stainless steel washers on each side of the forward rollers shall be accomplished. Failure to accomplish this inspection and modification could result in damage to the flap supports and/or loss of flap control." Model effectivity included a range of 150, 152, 170, 172, 175, 180, 182, 185, 188, 206, 207 and 210 models. Compliance was recommended within the next 100 hours of operation or 12 months, whichever occurred first. The Bulletin required inspection of the roller assemblies for wear or damage; inspection of the flap support arms for wear by the rollers and the blending out of

any grooves present, to a maximum depth of 0.020 inch; and the addition of a washer on either side of each forward roller.

The Service Bulletin was not made mandatory by the CAA and had not been accomplished on GBRCC; the accident occurred approximately 14 months and 646 flying hours after the issue of the Service Bulletin.

Recommendations

Although considerable wear and abnormal marking of GBRCC's flap system was found, there was no positive evidence to indicate that flap asymmetry played a part in causing the accident. However, the possibility remained, and the previous cases identified showed the potential for flap system wear to produce severe aircraft control problems. While none of the 4 known cases had resulted in an accident, it was notable that at least 2 of them had been at altitude and the recovery to a landing had been flown by an instructor, with considerable difficulty.

Recommendation 9737

It is recommended that the CAA reconsider Cessna Service Bulletin SEB953 with a view to making it mandatory.

Reports of service experience had apparently led the aircraft manufacturer to recommend measures aimed at preventing recurrence of cases of severe flap system wear and possible flap control system failure. It is likely that the manufacturer, with a wider range of service experience and research information available, would be in a much better position than an aircraft owner/operator to judge the effectiveness of a modification in preventing a particular failure. There would seem little doubt that the flap system inspection and modification measures recommended by the manufacturer represented a significant improvement to the system and would impose no major penalty on owners/operators. However, the measures have not been made mandatory by the FAA or the CAA and the CAA has specified that the incorporation of manufacturer recommended or mandated measures should be at the discretion of owners/operators. In the light of the above, Recommendation No 9737, made following an accident to Piper PA38112, GBGZW on 26 August 1996, is restated:-

Recommendation 9738

It is recommended that the CAA review their procedures for classifying airworthiness improvement measures published by aircraft or equipment manufacturers, that are applicable to UK registered aircraft, when they are recommended or categorised as mandatory by the manufacturer. Consideration of the improvement measures, if necessary in conjunction with the prime certifying authority, should take account of the manufacturer's known service experience. It is proposed that the CAA should require that such measures are incorporated on UK registered aircraft or publish its reasons for leaving them as optional to assist owner/operators in exercising their discretion.

Similar AAIB Recommendations were made in 1994 (No 94-30, AAIB Report 6/94) and 1997 (No 97-6, AAIB Bulletin 3/97 and No 97-11, AAIB Bulletin 5/97).