

# Piper PA-38-112 Tomahawk, G-BGZW

## AAIB Bulletin No: 9/97 Ref: EW/G96/08/29 Category: 1.3

<b>Aircraft Type and Registration:</b>	Piper PA-38-112 Tomahawk, G-BGZW
<b>No &amp; Type of Engines:</b>	1 Lycoming O-235-L2C piston engine
<b>Year of Manufacture:</b>	1979
<b>Date &amp; Time (UTC):</b>	26 August 1996 at 0846 hrs
<b>Location:</b>	3 nm Southwest of Nantwich Farm, Cheshire
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 - Passengers - 1
<b>Injuries:</b>	Crew - None - Passengers - None
<b>Nature of Damage:</b>	Minor damage to right wing
<b>Commander's Licence:</b>	Private Pilot's Licence
<b>Commander's Age:</b>	25 years
<b>Commander's Flying Experience:</b>	62 hours (all on type) Last 90 days - Nil Last 28 days - 1 hour
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and AAIB inquiries and strip examination of available engine parts

## Flight History

The planned flight was from Welshpool to Manchester. The weather was good, with the 2,000 feet wind from 190°M at 8 kt, in-flight visibility of 15 km and broken cloud at 2,000 feet.

The flight was uneventful until, when nearing Manchester at an altitude of 2,000 feet, the sound of the engine changed dramatically and it lost power. The pilot trimmed to the glide speed, checked for the cause of the problem and attempted two engine restarts, without success. He then made a Mayday RT call to Manchester Approach, which was acknowledged, and selected an area for a forced landing. This was a grass-covered field adjacent to farm buildings. The approach was over trees and the initial touchdown, with full flap lowered and the stall warning horn just beginning to sound, was one third of the way into the field, followed by a single bounce. During the subsequent ground roll the pilot kept the aircraft in a nose-high attitude for as long as possible to protect the

nose landing gear from damage. As the aircraft slowed, the pilot steered it to the right to avoid a dense hedge and it passed through a single strand wire fence before coming to rest.

The pilot and passenger, each of whom was wearing a four-point harness, were unhurt. The pilot radioed this information to Manchester Approach, and both occupants evacuated the aircraft without difficulty. Damage was confined to deformation of the right wing leading edge near the tip. The pilot, who had commenced training for his Private Pilot's Licence only some 8 months before the accident and had relatively low flying experience, attributed the success of the forced landing to the high standard of training that he had received.

A partial engine strip by the aircraft operator showed that there had been a failure of the engine accessory drive train.

### **Engine Description**

The accessory drive gear train is driven by an accessory gear mounted on the aft end of the crankshaft (Fig 1). The gear is located on the crankshaft by an integral flange that registers in a counterbored recess in the crankshaft end and is retained by a  $5/16$  inch diameter bolt screwed into a threaded hole in the crankshaft. Bolt retention is by a lock washer with an outer tab locating in a slot in the gearwheel and an inner tab bent against the bolt head after the bolt has been torque-tightened. A shouldered dowel fitted into the crankshaft has a  $1/4$  inch diameter section that protrudes from the seating face and locates in a hole in the gear flange. A similar accessory drive gear design is used on all Lycoming reciprocating engines.

The engine manufacturer has stated that the design intention is for the rotational loads on the accessory gear to be reacted by torsional friction loads between the gear and the crankshaft generated by the clamping effect of the retaining bolt. The dowel is provided to ensure the correct rotational orientation of the gear on the crankshaft, and is not intended to transmit torque. The bolt has a right-hand thread and the crankshaft rotates clockwise as viewed from the rear and thus, in the event of a loss of torsional restraint between the gear and the crankshaft, gear train loads will tend to unscrew the bolt. The manufacturer considered that loosening of the gear on the crankshaft had nearly always been caused by a torsional overload on the gear or by inadequate clamping loads applied by the bolt.

Procedures for installing the crankshaft gear were recommended in Avco Lycoming Service Instruction (SI) No 1179D, issued on 29673. It noted that instances had been found of damage in the area of the crankshaft gear and attributed these to improper assembly technique or reuse of worn or damaged parts during overhaul. It noted that the eventual failure of any of these parts would result in complete engine stoppage. The procedures included checks of the crankshaft recess, the crankshaft bolt hole threads, the dowel and the gear, and reassembly with a new bolt and locking washer. They also specified modification of the gear to allow inspection after installation by cutting three  $0.25$  inch radius scallops in the rim of the flange. Compliance was recommended at overhaul.

The SI was superseded by Textron Lycoming Service Bulletin (SB) No 475 'Crankshaft Gear Modification and Assembly Procedures', originally issued on 311086. The SB expanded the procedures and required machining of the gear to enlarge the rim scallop to  $0.75$  inch radius and to counterbore the central part of the mounting face. Compliance was required during overhaul, after a propeller strike, or whenever crankshaft gear removal was required. It was categorised by the engine manufacturer as mandatory, but was not mandated by the FAA or the CAA. A supplement (No 1) requiring assembly with the bolt threads clean and dry was issued on 24588. The SB was re-

issued as No 475A on 16790, with the addition of a caution against the reworking of crankshaft threads except by Lycoming.

An FAA Airworthiness Directive, AD 911422, was issued on 19891 making SB 475A mandatory at each overhaul, after a propeller strike or sudden stoppage or whenever gear train repair was required. Compliance with the FAA AD by UK operators was mandated by CAA Airworthiness Notice No 36. The SB was reissued, as Textron Lycoming Mandatory Service Bulletin No 475B, on 23493, with additional cautions and expanded text related to ensuring correct assembly. The contents of this SB were incorporated in a revision of the Overhaul Manual issued in June 1993.

### **Aircraft Examination**


The aircraft operator made an Occurrence Report of the accident to the CAA but did not report it to the AAIB. A partial engine strip by the operator the day after the accident reportedly found that the accessory gear retaining bolt had partially unscrewed by several turns and the dowel had fractured. The bolt locking washer was found in situ, with the bolt lock tang bent at an approximately 60° angle and the centre hole grossly elongated. The operator lost the bolt, the locking washer and the fractured-off part of the dowel before AAIB obtained the engine for strip examination.

AAIB examination of the available parts showed that the dowel had fractured flush with the gear/crankshaft mating surface. Clear signs of bending fatigue cracking over approximately 75% of the dowel fracture surface were found, with the remaining part of the fracture exhibiting fast fracture features. The position of the crack origin was consistent with the fatigue having been caused by the effects of torque transmission from the crankshaft to the gear train via the dowel because of inadequate gear clamping.

The gear appeared to be to the SI 1179D standard, with small 0.25 inch radius scallops and no mounting face counterbore. The mating faces of the gear and the crankshaft were generally coated with an oil varnish-like deposit, possibly suggesting inadequate clamping. Light fretting type polishing of the gear mating face near its outer diameter and heavy wear of the outer rim of the gear flange from contact with the crankshaft counterbore register indicated that there had been significant relative movement between the gear and the crankshaft for an extended period.

In the course of the engine strip it was noted that all eight nuts securing the connecting rod big end bolts had been installed incorrectly, with the raised lip on one end of the nut, rather than the flat face at

the other end, bearing against the big end cap surface. It was reported to be possible for the lip to yield in service if the nut were installed upside down, resulting in loss of bolt preload. Avco Lycoming Service Instruction (SI) No 1106D, issued 9-672, includes a Caution: "The connecting rod bolt cannot be tightened correctly if the nut is installed upside down. The raised edge, or lip on the end face of the nut must be on the free end of the bolt; the flat face must be in contact with the rod. See figure. . . ." (as Fig 2). The SI also notes that the connecting rod bolt will loosen if under-torqued.



### **Engine History**

Maintenance records indicated that the aircraft and engine had been maintained in accordance with the CAA Light Aircraft Maintenance Schedule CAA/LAMS/FW1978. They indicated that the engine (Serial No L1642315) had been removed from another aircraft on 2586 as time expired. It had been overhauled and, in June 1988, released untested, according to a Log Book entry, although the Job Card Certificate of Release to Service was not signed until 4690. Thus at the time of completion of the overhaul, the detailed accessory gear installation procedures, including the requirement for enlarged flange scallops, had been classified as mandatory by the engine manufacturer but not by the FAA or the CAA.

The engine had been installed in GBGZW on 261092. At the time of the accident it had accumulated 2,667 hours since overhaul. This had reportedly been the last occasion on which the accessory drivetrain had been disturbed. No evidence was found to indicate that a propeller strike or accessory gear train problem had occurred since the overhaul.

### **Previous Cases**

No similar previous cases were found listed on the CAA accident and incident database and only one previous UK case was identified, to an RAF aircraft during take off. Information from the engine manufacturer listed 40 known cases of accessory gear dowel failure between 1974 and the time of the accident. Some of these cases had been discovered during maintenance but at least 33 of them had occurred in flight and had been associated with loosening of the gear and consequent engine power loss, generally total. The manufacturer believed that there had been no cases affecting engines with the AD incorporated.

### **Service Bulletin Status**

The CAA Light Aircraft Maintenance Schedule notes (Section 3, para 2.4) that "Modifications relating to the aircraft, engine, propellers and equipment recommended by the manufacturers may be carried out at the discretion of the owner/operator unless the particular modification has been classified mandatory by the CAA in accordance with Airworthiness Notice No. 36." It was believed that this was intended to mean that the modification must be carried out if classified as mandatory by the CAA but was otherwise optional, irrespective of the manufacturer's classification. While the engine manufacturer recommended the measures of SB 475 in 1973 and categorised as mandatory the similar measures of SB 475A in 1986, there was no requirement for them to be incorporated on UK registered aircraft until 1991 when an FAA AD was issued. There was therefore no airworthiness authority requirement for the measures to have been incorporated on GBGZW at the time of its accident.

### **Recommendations**

The evidence indicated that the possibility of accessory gear loosening, with resultant engine stoppage, had come to the engine manufacturer's attention many years before GBGZW's accident. This had led the manufacturer, over 25 years previously, to recommend measures aimed at preventing recurrence of the failure and, 10 years previously, to categorise them as mandatory. It is likely that the manufacturer, with a wide range of service experience and research information available, would be in a much better position than an aircraft owner/operator to judge the effectiveness of a modification in preventing a particular failure. However, the CAA specified that the incorporation of manufacturer recommended or mandated measures should be at the discretion of owners/operators.

In the case of the accessory gear measures, there would seem little doubt that they represented a substantial improvement and would impose no major penalty on owners/operators. The damage to GBGZW was fortunately minor, but forced landings do on occasion end catastrophically. The following recommendation has therefore been made:

### **Recommendation 9736**

It is recommended that the FAA and the CAA review their procedures for classifying airworthiness improvement measures published by aircraft or equipment manufacturers when they are recommended or categorised as mandatory by the manufacturer. Consideration of the improvement measures should take account of the manufacturer's known service experience. It is proposed that the CAA should require that such measures are incorporated on UK registered aircraft or publish its reasons for leaving them as optional to assist owner/operators in exercising their discretion.

Similar AAIB Recommendations were made in 1994 (No 94-30, AAIB Report 6/94) and 1997 (No 97-6, AAIB Bulletin 3/97 and No 97-11, AAIB Bulletin 5/97).