Reims Aviation SA Cessna F150L, G-HFCB, 18 July 2002

AAIB Bulletin No: 11/2002 Ref: EW/G2002/07/20 Category: 1.3

Aircraft Type and

Reims Aviation SA Cessna F150L, G-HFCB **Registration:**

1 Continental Motors Corps O-200-A piston engine No & Type of Engines:

Year of Manufacture: 1972

18 July 2002 at 1200 hrs Date & Time (UTC):

Location: Elmslett Airfield, Suffolk

Type of Flight: **Training**

Passengers -Persons on Board: Crew - 1 None

Injuries: Crew - None Passengers - N/A

Wing tip, possible spar damage and engine **Nature of Damage:**

shockloaded

Private Pilots Licence Commander's Licence:

33 years Commander's Age:

Commander's Flying

Experience:

220 hours (of which 164 were on type)

Last 90 days - 0 hours

Last 28 days - 0 hours

Aircraft Accident Report Form submitted by the pilot **Information Source:**

and further enquiries by the AAIB

The pilot had last flown two years earlier in a Piper PA28 type aircraft. He was about to undertake a flight with an instructor to renew his single-engine licence privileges. The pilot was authorised to carry out a pre-flight inspection using the flying club's C-150 checklist, start the engine and then await the instructor. The pilot reported that he used the checklist procedure to start the engine but that he inadvertently set the throttle too high. He did not set the handbrake and his seat was in a position such that his feet could not reach far enough to apply the toe-brakes (although his feet made contact with the rudder pedals). When the engine started the aircraft accelerated rapidly forwards. The pilot closed the throttle but he was unable to apply the toe-brakes. The aircraft travelled a distance of approximately 50 metres and then came to a rest when the nosewheel entered a drainage ditch. The pilot shut down the engine and then exited the aircraft via the pilot's door.

The flying club's C-150 checklist included requirements to apply the handbrake and adjust the seat position in its 'before engine start' procedure.