

No: 9/89

Ref: EW/G89/01/04

Category: 1b

Aircraft Type and Registration: DHC-6 Twin Otter 310, G-JEAC

No & Type of Engines: 2 Pratt & Whitney PT6A-27 gas turbine engines

Year of Manufacture: 1979

Date and Time (UTC): 4 January 1989 at 2130 hrs

Location: Southend Airport

Type of Flight: Airline Scheduled Cargo

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Severe collision damage to right engine and propeller; debris damage to fuselage. Collision damage to two other aircraft

Commander's Licence: Commercial Pilot's Licence with Instrument Rating

Commander's Age: 40 years

Commander's Total Flying Experience: 3048 hours (of which 161 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot, and metallurgical examination of brake unit at RAE Farnborough

During the pre-flight inspection the commander used a torch to check the condition of the brakes and tyres, which appeared satisfactory. The engines were started using external power. Upon looking up to give the ground handler the signal to disconnect external power, the commander noticed that the aircraft had started to move, even though the brakes had not been released. Another aircraft was parked a short distance ahead and the commander had to use the nosewheel steering to steer to the left, in order to avoid a collision. The footbrakes proved ineffective in slowing the aircraft, and so both engines were shut down. By this time however the aircraft had turned through 120° to the left and was heading towards two other aircraft that were parked to its left. The left propeller struck a Britten Norman Trislander, causing slight damage to its left wing. The right propeller struck a Cessna 177, removing the outboard section of its right wing. G-JEAC then came to a halt and the pilot, who was uninjured, switched off the master switch and vacated the aircraft. It was subsequently found that the left brake calliper had failed through the casting and had separated from the disc. A calliper piston was found in a pool of hydraulic fluid, close to the original parking place.

A photograph of the failed calliper, which is manufactured from magnesium alloy, is shown at Fig. 1. The fracture surfaces were examined by the Materials and Structures Department of the Royal Aerospace Establishment at Farnborough. This examination revealed that the failure had occurred from

a fatigue crack, with multiple origins located around a 158 mm length of the blending radius, on one side of the calliper slot. Cracks were also found in the blending radius on the other side of the slot. In both cases the crack origins had initiated from corrosion attack on the horizontal surface of the slot. During manufacture, the component should have been corrosion protected in accordance with a process specification that included a chromate treatment. Qualitative X-ray analysis of the surface confirmed the presence of chromium, and also other elements which most probably resulted from brake wear debris. In particular there was a high level of iron, which is likely to have helped promote the corrosion process. Thus, although there was evidence that some corrosion protection had been applied, it was apparent that it had not remained effective.

The unit had a serial number which indicated that it had been manufactured in 1978. According to the operator, it was fitted to G-JEAC in November 1986 and had achieved a total life estimated at 8000 hrs/8000 landings. The brake unit was maintained 'on condition', ie there was no requirement for periodic maintenance.

During the pre-flight inspection the commander was asked to check the condition of the brakes and gear, which appeared satisfactory. The engine was started using external power, and the aircraft was taxied to give the ground handler the signal to disconnect external power, the commander acknowledged that the aircraft had started to move, even though the brakes had not been released. Another signal was given to a short distance ahead and the commander had to use the nose wheel steering to steer to the left to avoid a collision. The brakes were found to be slipping on the runway and the aircraft was found to be sliding towards two other aircraft that were parked to the left. The left propeller struck a light aircraft causing slight damage to its tail section. The right propeller struck a light aircraft causing damage to the outboard section of its right wing. G-JEAC then came to a halt and the pilot was found to have switched off the master switch and vacated the aircraft. It was subsequently found that the calliper had failed through the casting and had deformed under the load. A calliper pin was found in a pool of hydraulic fluid close to the original parking place.

A photograph of the failed calliper, which is manufactured from magnesium alloy is shown in figure 1. The fracture surfaces were examined by the Materials and Structures Department of the Royal Aerospace Establishment at Farnborough. This examination revealed that the failure had occurred in a




Figure 1. Failed brake calliper from G-JEAC

The failed brake calliper was found to be cracked and distorted. The crack was located on the outer side of the calliper, extending from the top edge towards the center. The distortion was observed as a significant warping of the calliper's shape, particularly in the area of the brake pad. The failure was attributed to excessive heat and stress during operation, leading to material fatigue and structural failure.