

Piper PA-34-200-2 Seneca, G-BARB, 20 January 1994

Bulletin Addendum

Ref: EW/C94/1/4 Category: 1.3

Aircraft Type and Registration:	Piper PA-34-200-2 Seneca, G-BARB
No & Type of Engines:	2 Lycoming IO-360-C1E6 piston engines
Year of Manufacture:	1973
Date & Time (UTC):	20 January 1994 at 1722 hrs
Location:	Near Bloxwich, West Midlands
Type of Flight:	Private
Persons on Board:	Crew - 1 Passengers - 3
Injuries:	Crew - Fatal Passengers - Fatal
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence with Instrument Rating
Commander's Age:	29 years
Commander's Flying Experience:	1,108 hours (of which 722 were on type) Last 90 days - 28 hours Last 28 days - 8 hours
Information Source:	AAIB Field Investigation

Previous AAIB Bulletin report

The report on this accident was included in AAIB Bulletin 8/94. Despite a very detailed investigation, no cause for the accident was satisfactorily identified. The report made at that time is summarised below:

The pilot and his 3 passengers were returning to Ronaldsway after a business meeting; the same personnel had flown to Birmingham in the same aircraft early that morning. Subsequent calculations showed that G-BARB was below maximum weight for take off and was within cg limits.

At the time of departure, the visibility was 15 km and the mean sea level pressure was 1025 mb. There was scattered cloud from 2,000 to 3,000 feet, scattered to broken cloud at 6,000 feet with tops around 9,000 feet and thin layers above. The surface wind was 260°/10 kt with a temperature of plus 9°C and the wind at 6,500 feet was 310°/35 kt, with a temperature of plus 3°C. There was also the possibility of mountain wave activity in the area, but subsequent enquiries revealed no reports of turbulence.

Reconstruction of the accident flight was achieved using RT recordings and secondary radar recordings. G-BARB took off from Birmingham at 1711 hrs and once airborne, the aircraft was transferred to Birmingham Approach and then to Manchester ATC. G-BARB was then cleared to FL80, but the pilot requested and was given clearance to maintain FL60; his acknowledgement of this was the last recorded message from the aircraft. At 1722 hrs, the Manchester controller noticed that he had lost the radar return and, after unsuccessful radio calls, initiated crash action.

The radar recordings initiated with the aircraft leaving Birmingham and climbing through 100 feet. Subsequent radar returns were obtained at 8 second intervals and showed the aircraft climbing to FL60. Based on the aircraft weight, the rate of climb and speed were normal and the aircraft maintained a constant track. The aircraft climbed to FL60, but started a descent almost immediately. The radar showed the rate of descent increasing rapidly to a maximum of approximately 11,000 ft/min. During this time the aircraft track changed from north westerly to southerly. Based on the radar information, G-BARB could have rolled left with an increasingly low nose attitude or could have rolled right through the inverted position onto the southerly heading.

Various witnesses reported seeing and hearing the aircraft during the later part of the flight. There were reports of unusual engine noises and certain eyewitnesses saw the aircraft level at approximately 800 feet agl heading in a north westerly direction. A few witnesses saw some flames from the aircraft and there were reports of something falling off. All those who saw the last moments of flight described the aircraft rolling and apparently out of control. It was dark at the time of the crash.

Post-mortem examination of the occupants revealed no medical condition which could have contributed to the accident.

G-BARB had come to rest on common land about 100 yards east of the M6 motorway. The aircraft was inverted and the complete empennage and both wings outboard of the flaps were missing. It had struck the ground with high vertical velocity and with some motion towards the left (port) engine, but with little or no forward speed. Neither propeller showed evidence of power at impact. The missing portions of the wings, rear fuselage and tail were found at various locations over the adjacent built-up area of Bloxwich at distances of up to half a mile from the main wreckage. From the track of the aircraft and the winds obtained from a Meteorological Office aftercast, a wind-drift plot was compiled. This indicated that the detachment of the outboard wings and tail section had occurred over a period of not more than a few seconds at a height of approximately 1,500 to 2,000 feet agl.

The wreckage break-up pattern indicated that the right and left wingtips, each complete with an outboard fuel tank, had separated from the aircraft in a similar manner. The right wingtip had then

struck the right stabilator, causing it to break away in an upwards direction, and causing the rest of the empennage to separate at about the same time. There was no evidence of fatigue or other pre-existing structural defects. There was evidence that the wingtips had separated in a downwards bending mode associated, in the case of the right tip, with a nose-down pitching moment and there was also evidence on both wings of load reversal. This suggested a short period during the return to level flight when the aircraft had been overstressed to the point of structural failure. This was considered consistent with the high vertical speed shown by the radar data, which implied a high airspeed with a probability of high structural loads during the recovery. No evidence of flutter as an initial event was found.

The flying controls were examined in detail and although it was not possible to discount a possible temporary control jam, it was established that the controls had been connected and appeared to have been serviceable. The components of the pitch trim system functioned acceptably after the accident and bore no indications of pitch trim 'runaway'. The autopilot console, servos and amplifier all functioned normally when tested.

Detailed examination of the engines and propellers established that they were capable of operation and were in fact running at low power at impact. Both propellers had stopped in about one revolution, or less, while at pitch angles indicating transition to the feathered position. This was considered the result of loss of oil pressure to the propeller governors which would have occurred almost immediately upon inversion of the aircraft. No evidence of any fuel related problem was found. There was some evidence of an oil leak from the right engine, however examination of the oil uplifts record suggested that the leak was of a minor nature. The positions of the controls and indications on the instruments also indicated that neither engine had been shut down and that the aircraft systems were in a normal configuration. Filament analysis of several instrument lighting bulbs indicated that electrical power had been available to the system buss, and therefore to all the subsystem circuit breakers, at impact. The investigation of the vacuum instruments, system and de-icing systems showed that the attitude gyro had been running normally at impact.

The AAIB Bulletin concluded that "It was apparent that the aircraft had been recovered from this descent at some stage but that during this recovery it had been subjected to excessive forces which caused structural failure. Something happened while G-BARB was levelling at FL60 to cause the loss of control. An extensive engineering investigation was able to discount all likely engineering or technical causes which may have contributed to the accident. However, it remains possible that some technical or other problem occurred which may have been resolved in the air but which nevertheless initiated the loss of control."

Reopened Investigation

On 1 December 1994 a Dutch registered Piper Seneca III crashed at Radscheid in Germany. The aircraft was on an IFR training flight in day VMC from Stuttgart to Maastricht with an instructor on board, one student handling the controls and one student in the rear of the aircraft. The handling pilot was a commercial student near the end of his training. The accident occurred as the aircraft was approaching the border with Belgium, tracking the NTM (Nattenheim) VOR at FL100 with the KING KFC 200 autopilot in ALT HOLD mode. The aircraft was given a descent clearance to FL60 but although this was acknowledged the radar recording showed that the aircraft did not begin to descend until almost a minute later when it entered a rapidly and increasingly erratic descent during which the track reversed. The aircraft suffered structural failure losing the outer wings and the empennage; the wing also failed at the centre joint. The German Accident Investigation Bureau (LBA) found that the autopilot disconnect microswitch was defective and on the basis of that, and

others supporting evidence, concluded that the accident had been caused by failure of the autopilot to disengage when required by pilot operation of the trim switch. Such a condition would cause the autopilot to trim 'nose up' as the control wheel was pushed forward. There are specific warnings about this situation in the King KFC 200 autopilot manual and in the Seneca III Flight Manual. The radar data showed that the aircraft had lost energy initially and in this regard Piper suggested that the aircraft had probably spun following the pitch up, concluding that it had then entered an accelerating descent and had broken up in the subsequent recovery.

On 7 May 1995 an incident occurred involving a Beech 95A Travelair registration G-ATRC. This was reported in AAIB Bulletin 9/95. The Beech Travelair is a light twin, generally similar to the Seneca. In particular it has a large trim tab on the rudder. Approximately 10 minutes after taking off the pilot felt slight vibration through the rudder pedals. After applying right rudder the rudder jammed, causing the aircraft to sideslip. The vibration then became so severe that the pilot had difficulty in keeping his feet on the rudder pedals, and could not read the instruments. The sideslip continued, with the pilot unable to maintain height and experiencing pitch control difficulties. He also reported a stall warning at 120 kt IAS as power was reduced. The pilot declared an emergency and with assistance from ATC landed safely at a nearby airfield some 10 minutes later. He had eventually been able to level the aircraft using differential power at about 700 ft. The pilot stated that he had been fortunate to regain a measure of control. Subsequent examination of the aircraft showed that the rudder trim tab actuating rod had fractured at its attachment to the rudder trim jack, which is mounted in the rear of the fin. This had left the major portion of the rod still attached to the tab. Once the failure had occurred, the tab had been free to 'flutter' and to act as an uncontrolled 'servo-tab' giving rise to the violent pedal movement. On examination it was found that the failed end could be made to foul on the rudder in such a way that the tab was unable to return to centre, possibly accounting for the reported rudder jam. The failure was attributed to fatigue caused by incorrect assembly of the actuating rod. In discussion with the AAIB engineering inspector involved it was apparent how much difficulty this pilot had encountered and how little evidence on the structure there was of flutter-like damage.

As a result of these events, a re-examination of the wreckage of G-BARB was conducted and this included a search for more subtle evidence of flutter damage and for any mechanism by which the rudder tab might jam. The earlier investigation had found no trim switch defect associated with G-BARB and the autopilot was a Piper Altimatic III rather than the King type fitted to the Dutch aircraft. There was also no indication of pitch control problems either from radar and energy plots, or from the examination of the pitch trim mechanism. Some points of similarity were noted, however, in particular the rudder tab linkage attachments on the tab were both broken and in both cases a similar fragment was missing from one bracket (Figure 1 shows general arrangement of Seneca fin, rudder and trim tab; Figure 2 shows damaged brackets). The Dutch aircraft's fin and rudder had not been damaged severely in the ground impact and so it was possible to see that some minor damage had occurred due to some type of flutter-related phenomenon. In particular, the rudder top hinge had compression damage on both sides, suggesting cyclic motion against mechanical limits with large deflections of the structure. The rudder of G-BARB exhibited similar damage to the top hinge, as shown in Figure 3, but this had not been identified earlier because it had been masked by ground impact damage. There was no other evidence, such as elongated 'cutouts' or overtravel damage at the hinge points, but significant free play was found in the top and bottom rudder hinges, and significant cracking of the paintwork was found on the rudder, but not on the fin or tab. This cracking ran along lines of rivets at the leading and trailing edges and in diagonal patterns across the rudder skins in a manner suggestive of torsional deflections. Lines of corrosion had formed within the cracks, but not where the paint had completely flaked off, indicating that the cracking had existed for some time before the crash occurred (Figure 4).

Severe scoring of the paint was found inside the trailing edge of the rudder. This had been caused by forcible contact with the tab leading edge shroud and showed that the tab had been deflected 42° to the right (left rudder) at some time (Figure 5). It was possible that this could have occurred during maintenance with the tab disconnected. Normal tab travel is 22° right, 17° left, with the rudder moving 35° each way. It was not possible initially to displace the tab as far as 42° due to the rivets on the right hand leading edge of the tab fouling the rudder trailing edge skin. Many of these rivet heads had their paint removed due to contact with the rudder skin, and there were corresponding marks in the skin. The tab could be moved with some effort to align with the paint marks made by the shroud, whereupon the tab became jammed in the rudder. By comparison with the Dutch Seneca, the geometry of the tab and rudder represented an unusual combination of manufacturing limits as the rivets on the tab of the Dutch aircraft had remained clear of the rudder skin. That aircraft also had a bonding lead and bolt on the rudder centreline which had damaged the shroud of the tab, while at the same time restricting its free deflection, preventing it from reaching an angle at which a jam might occur. Figure 6 shows the area of the trim tab and rudder on G-ATRC, which exhibited no evidence of flutter or tab/rudder jamming.

Because of the possible significance of the tab having become disconnected, a metallurgical report was commissioned to examine the fracture faces of G-BARB's rudder tab brackets. The report drew a number of conclusions, the most important of which were:

A small piece of the lower bracket retained by the pivot bolt had rotated relative to the upper bracket, even though both faces of both brackets had been crushed during tightening of the pivot bolt (this tightening is normal as it ensures that all rotation relative to the operating rod takes place within the bearing).

Part of the fracture face had been damaged by 'chafing' which had destroyed the major part of any fractographic evidence.

The paint on the lower bracket contained a series of parallel cracks; these cracks contained accumulated debris suggesting that plastic deformation of the bracket had occurred some time before the accident. The report suggested that the bracket could have been bent and straightened-out at some time.

The rivets attaching the tab brackets were tubular. Drilled off rivet tails were found inside the tab. The report suggested that the rivets were part of a repair scheme.

The bearing showed no evidence of lubricant, but considerable quantities of compacted debris were found within it.

The report noted that at sub zero temperatures accumulated moisture would make the bearing stiff and that a similar mechanism was well known to apply to strip hinges such as that used to attach the tab to the rudder. As the tab was an anti-servo tab, normal movement of the rudder would result in abnormal loading of the mechanism at sub-zero temperatures, even though clear of icing conditions. Many light aircraft are fitted with similar strip hinges.

The metallurgist's report was sent to the German investigating authority who reported that no evidence of fatigue or chafing could be identified in their case. It was concluded that the Dutch aircraft had experienced flutter-like behaviour of the fin and rudder either during the attempted recovery or during the breakup, and this had caused the tab brackets to break up. G-BARB had experienced a similar motion late in the flight but, unlike the Dutch Seneca, damage due to low

amplitude flutter-like vibration had been progressively building in the rudder and tab linkage before the accident flight.

Nine other Piper Seneca aircraft were examined. On one of these it was evident from damage to paint on the rivet heads that the rudder trim tab, if over-rotated, would jam as the rivets passed under the rudder skin. In this case it was likely that the paint damage had occurred during maintenance. The eight other aircraft had greater clearance between the tab and rudder. In spite of comments from several engineering organisations that there were no particular maintenance problems with the tab brackets, the majority of the aircraft examined either had loose rivets in the area or had been repaired, in one case by substituting steel brackets, as shown in Figure 7. It was felt that these repairs, which involved mostly the replacement of loose rivets, were considered minor and sometimes were not documented.

Piper Service Bulletin 390A, dated May 30 1973, addressed the problem of excessive free play in the rudder trim tab system and advised that possible "adverse airplane vibration effects" may result when the aircraft is operated at speeds in excess of 140 mph IAS (about 120 kt). It required that the tab free play be maintained at less than 0.125 inches and that this should be inspected at 100 hour intervals. FAA AD 73-13-1, dated June 18 1973, made these requirements mandatory. Piper Service Letter 714 dated June 4 1974 stated that an improved rudder trim mechanism was available which, if fitted, removed the requirement for the 100 hour repetitive inspections and the requirements of the AD.

As part of the AAIB investigation, two independent analyses of the rudder and tab hinge moments were carried out. The moment required to breakout G-BARB's tab when jammed was measured at about 35 lb.in, a very low figure. Both analyses showed that if the tab were to jam at around 40° displacement, very large rudder hinge moments would occur so that the rudder pedals would be fully displaced and difficult to move. At the same time, however, aerodynamic forces acting on the tab would generate only very small hinge moments. In different analyses, the tab hinge moments predicted were between 30% and 100% of that required to free the tab. Flutter analysis showed that the necessary dynamic effects to cause full rudder deflection could occur at 100 kt, given reasonable assumptions. The likely effects of the full and instantaneous application of rudder were predicted to include rapid roll, large and oscillatory sideslip angles and lateral 'g' forces, and a rapid descent to exceed V_{ne} plus 10% in the descent (Figure 8) (and Figure 9). The wind drift analysis carried out at the time of the initial investigation showed that the aircraft broke up at about 1500 ft agl, *ie* 2100 ft amsl.

It was thus concluded that the most probable sequence of events was that the tab brackets had sustained cumulative damage over a long period which rapidly progressed during the last flight, until they fractured completely, releasing the tab. Due to an unusual, but not isolated, set of build tolerances the tab jammed causing the sudden and full application of left rudder. This event created a set of conditions in which the response of the aircraft was rapid and unusual, and highly disorienting to the pilot. During the ensuing descent the pilot attempted to regain control and during the recovery the aircraft broke up due to the high speed, the load factor, or both. It is not possible to be specific about the mechanism which led to the breakup of the tab brackets but it seems most likely that the tab damage and cracking caused the tab free play tolerance to be exceeded. As the free play in the tab system increased, the damage would have accumulated. At some stage the rudder motions were sufficient to cause fine cracks to occur in the paint of the rudder skins, allowing corrosion to start. This must have been some considerable time before the accident flight. Immediately before the accident flight a pre-flight external check was carried out and it seems highly unlikely that the tab was already disconnected at that time, however the tab brackets may have been badly cracked. Such

damage can increase in a highly non-linear manner and it appeared probable that between takeoff and top of climb the cracking progressed to complete failure of the tab brackets.

FAR 23.629 sub para (f) states "Freedom from flutter, control reversal and divergence up to V_d/M_d must be shown.....after the failure, malfunction or disconnection of any single element in the primary flight control system, any tab control system, or any flutter damper." BCAR 23.673 "Primary Flight Controls" differs from FAR 23.673 at para (b) and states "Primary flight control systems must be designed to minimise the likelihood of complete loss of lateral, longitudinal and directional control due to failure or jamming of any connecting or transmitting element in the control system." It is clear that the intent of these requirements is that disconnection of a tab should not create undue control difficulties. Compliance has been achieved in various ways on different aircraft but a key element has been the acceptance that whilst a disconnected tab may induce marked vibration of the associated control surface(s), it should not seriously affect control of the aircraft. In the case of the Beech Travelair, G-ATRC, the control of the aircraft was very seriously affected and it appears probable that G-BARB may have been similarly affected.

The use of tabs creates the possibility of unusual control behaviour if a tab becomes uncontrolled and remains attached to its control surface. This investigation has established that for the existing GA fleet such failures may not be benign, yet the design, construction and maintenance of associated tab systems are based on the assumption that the design achieves the intent of the certification requirements. Since fleetwide modifications of all types is clearly impractical, it is considered that the best approach would be to improve the maintenance of such tab systems. The evidence found in this investigation suggests that tab systems could be better maintained and documented. Engineers should be made more aware of the potentially critical consequences of failure of these components, and the need to achieve manufacturers' recommendations regarding free play and rigging. The following Safety Recommendations are therefore made:

96-44: The FAA, in conjunction with the Piper Aircraft Company, should assess the potential for rudder trim tabs on Piper PA-34 Seneca aircraft to jam against rudder skins, due to dimensional tolerances between tab rivets and rudder skins, if such tabs suffer control input disconnect. The FAA should also consider including other types, and manufacturers, in such an assessment of the potential jamming mechanisms on uncontrolled trim tabs.

96-45: The FAA should publish advice to private pilots, engineers and maintenance organisations emphasising the need for correct maintenance of trim tab control systems particularly in respect of free play and stiffness, and the need to correctly document and report defects to airworthiness and design authorities; also to ensure that any associated repairs are carried out in accordance with an approved repair scheme, taking due account of any additional requirements such as the rebalancing of the surfaces, if necessary.