

# SD3-60 Variant 100, G-BKMX

## AAIB Bulletin No: 6/97 Ref: EW/G97/03/03 Category: 1.1

<b>Aircraft Type and Registration:</b>	SD3-60 Variant 100, G-BKMX
<b>No &amp; Type of Engines:</b>	2 Pratt & Whitney PT6A-65R turboprop engines
<b>Year of Manufacture:</b>	1983
<b>Date &amp; Time (UTC):</b>	1 March 1997 at 1142 hrs
<b>Location:</b>	Aberdeen Airport, Scotland
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 2 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	None
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	50 years
<b>Commander's Flying Experience:</b>	15,360 hours (of which 1,640 were on type) Last 90 days - 135 hours Last 28 days - 37 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot plus enquiries by AAIB

The aircraft was on a positioning flight from Sumburgh to Aberdeen Airport with no passengers on board. The landing weight was 8,450kg. The runway in use at Aberdeen was Runway 16, which has a published landing distance available of 1,829 metres; the asphalt surface was dry. The forecast meteorological conditions included a surface wind of 190\_/22 kt gusting to 35 kt, increasing at times to 27 kt with gusts to 45 kt; the visibility was good and there was no cloud below 2,000 feet. The relevant Automatic Terminal Information Service (ATIS) broadcast contained details of wind shear forecasts for Runway 16 and information on forecast severe low-level turbulence; upon initial contact with the Approach control the pilot acknowledged that he had copied this ATIS information.

Throughout the subsequent visual approach the pilot was given six updates of the surface wind, the maximum value that was passed to him was coincident with the landing clearance and was 210\_/35 kt gusting to 45 kt. The last three updates were passed during the final minute prior to touchdown and of these the maximum was 220/38 kt which translates to a crosswind of 33 kt; the

final two wind reports were both 220\_/30 kt representing a crosswind of 26 kt. The landing crosswind limit for the aircraft is 30kt.

The commander was handling pilot for the visual approach followed by the crosswind landing which was accomplished using the approved wing-down technique. No appreciable windshear was noted and the touchdown was considered by the pilot to be normal and on the runway centreline. The nosewheel was lowered and the ground fine pitch stops were selected. The aircraft then yawed to the left and, despite applying right brake and right nosewheel steering, the aircraft left the runway and ran onto the grass. Neither pilot noted the engine parameters during this excursion nor were they aware of the right wing lifting at any time during the landing.

The fire services arrived almost immediately and advised the pilot that there was no apparent damage and that the aircraft was resting on firm ground. The aircraft was taxied back to the runway and then onto the allocated stand. An engineering inspection was carried out and no damage identified. The aircraft was returned to service.