

No: 5/89 **Ref: EW/G89/03/08** **Category: 1c**

Aircraft Type and Registration: Cessna F152, G-BHCP

No & Type of Engines: 1 Lycoming O-235-L2C piston engine

Year of Manufacture: 1979

Date and Time (UTC): 27 March 1989 at 1545 hrs

Location: Sherburn in Elmet

Type of Flight: Private (pleasure)

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Substantial

Commander's Licence: Private Pilot's Licence

Commander's Age: 56 years

Commander's Total Flying Experience: 106 hours (of which all were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot and AAIB telephone enquiries

The aircraft had taken off from Sherburn in Elmet and carried out 3 circuits. The aircraft was then flown north east to overhead Scarborough, Flamborough Head, and then towards Beverley and the Humber Bridge.

In the vicinity of Beverley, the visibility deteriorated such that the pilot could not identify the Humber estuary. He was unable to obtain a radar service and decided that a precautionary landing would be prudent. He returned northwards to an airfield he had passed earlier in the flight, which unknown to him was Leconfield, currently disused. After overflying the airfield a number of times, and observing cones and other obstructions on the runways, a perimeter strip was found that appeared to be suitable. However, just before touch-down, an obstruction described as a kerb was noticed and a go-around was carried out. During the go-around the pilot felt a slight collision and continued south where, by this time, the weather improved sufficiently for him to return to Sherburn. The aircraft was inspected as far as was possible from inside the cockpit by the pilot and passenger, but no damage was observed.

The pilot could not establish RTF contact with Sherburn, and carried out the standard procedure before making an approach to land. Just before touch-down, fuel and ignition were turned off as a precautionary measure. As the speed decayed after landing, the nose sank down and damage occurred

to the propeller, nosewheel leg, engine bearers, bulkhead and the engine was shock-loaded. The nosewheel and its fork attachment were found at Leconfield. The occupants who were wearing upper torso restraint, were uninjured.

| Information Source: | Aviation Accident Report Form submitted by the pilot and AAIIB telephone enquiries |
|--------------------------------------|--|
| Commander's Total Flying Experience: | 100 hours (of which all were on type) |
| Commander's Age: | 50 years |
| Commander's Licence: | Private Pilot's Licence |
| Nature of Damage: | Substantial |
| Injuries: | Crew - None Passengers - None |
| Persons on Board: | Crew - 1 Passenger - 1 |
| Type of Flight: | Private (pleasure) |
| Location: | Shephard in Essex |
| Date and Time (UTC): | 27 March 1989 at 1545 hrs |
| Year of Manufacture: | 1979 |
| No & Type of Engines: | 1 Lycoming 0-325-L3C piston engine |
| Aircraft Type and Registration: | Cessna F152 G-BHCP |

The aircraft had taken off from Shephard at 1545 hrs and climbed out 3 degrees. The aircraft was then flown north east to overhead Leconfield, then south west, and then towards Leconfield. The aircraft was then observed to descend and crash into the ground at Leconfield.

In the vicinity of Leconfield, the visibility deteriorated and the pilot could not identify the H-101. He was unable to obtain a radar service and decided that a precautionary landing would be prudent. He returned northwards to an airfield he had passed earlier on the flight, which was known to him as Leconfield, currently closed. After overflying the airfield a number of times, the pilot saw some and other obstructions on the runway, a number of which were found to be obstructions. However, just before touch-down an obstruction was noticed and a go-around was executed. During the go-around the pilot lost height and crashed into the ground. At this time, the weather improved sufficiently for him to return to Shephard. The aircraft was damaged as far as was possible from inside the cockpit by the pilot and passenger, but no serious injuries were observed.

The pilot could not establish RFF contact with Shephard and continued on the starboard side before making an approach to land. Just before touch-down, the fuel gauges were empty and the precautionary landing. At the point of landing, the nose gear struck a ditch and the aircraft was destroyed.