

Slingsby T61C, G-AZPC, 25 March 1996

AAIB Bulletin No: 6/96 Ref: EW/G96/02/14 Category: 1.3

Aircraft Type and Registration: Slingsby T61C, G-AZPC

No & Type of Engines: 1 Stark-Stamo MS 1500/2 piston engine

Year of Manufacture: 1972

Date & Time (UTC): 25 March 1996 at 1235 hrs

Location: Blackmill Airstrip, Feshiebridge, Inverness

Type of Flight: Private (Training)

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Substantial to propeller, main wheel and both wing leading edges

Commander's Licence: Private Pilot's Licence with FI rating on SLMGs

Commander's Age: 53 years

Commander's Flying Experience: 464 hours powered flight (of which 356 were on type), and 5,000 hours gliding

Last 90 days - 9 hours

Last 28 days - 4 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

The student pilot was undergoing his first training flight for a 'silver conversion' to a SLMG (Self Launch Motor Glider). The weather was fine with good visibility, a wind of 230°/10 kt to 15 kt and a temperature of 10°C. The grass runway surface however was covered with 1/2 inch of snow.

The flight was preceded by a lengthy pre-flight inspection and engine run-up whilst the instructor explained the start-up procedures and power checks. Instrument indications during start showed that the oil temperature and pressure were normal and that the static full power was 2650 RPM. Carburettor heat was checked and was fully functional. The fuel used was four star Mogas.

Full power was achieved as the aircraft started its takeoff run from grass Runway 22. The aircraft took off normally and was held level until a speed of 45 kt was attained. At approximately 50 to 100 feet engine power reduced rapidly and the aircraft started to descend. By this time the aircraft

was close to the upwind end of the runway with dense forest ahead and to the left. With no time to investigate the power failure the instructor levelled the wings and manoeuvred the aircraft to the right towards a wide rocky river bed, the only flat area available. As the aircraft touched down the right wing tip hit the uneven surface, yawing the aircraft to one side and quickly bringing it to a stop. The instructor and student, who were both wearing full harnesses, were uninjured.

Subsequent testing of the engine by a repair agency did not reveal any faults. Results of further tests on the fuel lines, fuel pump and carburettor are not yet available. The instructor reported that carburettor icing was a probable cause of the power failure although he believes that this would not have caused such an instantaneous loss of power.

An aftercast obtained from the Meteorological Office, Bracknell, shows that the recorded temperature conditions on the surface, in the Feshiebridge area, at the time of the accident were temperature +2°C dewpoint -3°C.

General Aviation Safety Sense Leaflet No 3A, published by the Civil Aviation Authority, entitled 'Winter Flying' includes a chart that details the effects of temperature and dewpoint on carburettor icing. Close to a 'wet' surface, as in this case, high humidity levels must be assumed. This would have put the conditions on the day of the accident in that area of the chart depicting 'Serious Carburettor Icing' at all power settings.