

Aerospatiale AS355F2 Ecureuil II, G-MENI, and Katana DV20, OE-AMH

AAIB Bulletin No: 12/1997

Ref: EW/C97/8/7 Category: 1.3

Aircraft Type and Registration:

- i) Aerospatiale AS355F2 Ecureuil II, G-MENI
- ii) Katana DV20, OE-AMH

No & Type of Engines:

- i) 2 Alison C250 turbine engines
- ii) Rotax 912 piston engine

Year of Manufacture:

- i) N/K
- ii) N/K

Date & Time (UTC): 12 August 1997 at 1128 hrs

Location: 6 nm west of York

Type of Flight:

- i) Public Transport
- ii) Private

Persons on Board:

- i) Crew - 2 - Passengers - None
- ii) Crew - 1 - Passengers - None

Injuries:

- i) Crew - None - Passengers - N/A
- ii) Crew - Minor - Passengers - N/A

Nature of Damage:

- i) Severe damage to tail boom, rotors and cabin
- ii) Substantial damage to canopy, forward fuselage and propeller

Commander's Licence:

- i) Airline Transport Pilots Licence (Helicopters)
- ii) Private Pilot's Licence

Commander's Age:

- i) 42 years
- ii) 67 years

Commander's Flying Experience: i) 5,277 hours (of which 202 were on type)

Last 90 days - 132 hours

Last 28 days - 44 hours

ii) 5,000 hours (of which 700 were on type)

Last 90 days - 100 hours

Last 28 days - 45 hours

Information Source:

AAIB Field Investigation

Synopsis

The pilot of the aircraft (OE-AMH) was on a VFR flight from Prestwick to the gliding site at Rufforth, 4 nm west of York, cruising initially at FL 055 at a speed of 100 kt. The helicopter, (G-MENI), having completed a rotors running refuel at Coney Park industrial site on the northern boundary of Leeds Bradford airfield was on a VFR flight cruising at an airspeed of 120 kt to a private landing site at Givendale, 11 nm east of York (Leeds Bradford 080°/32nm). Approximately 6 nm west of York the aircraft and the helicopter were involved in a mid-air collision, in VMC conditions, at an altitude of approximately 1,900 feet amsl.

History of the flights

At 1058 hrs the aircraft pilot made contact with the Leeds approach controller giving details of his flight and stating that he was "33 MILES OUT OF HARROGATE VRP (*Visual Reference Point*) MAINTAINING FL 055 AND TRANSPONDER IS 1460". The controller replied that he had all the details and assigned him a transponder code of 0415. One minute later the helicopter pilot contacted Leeds approach with details of his flight inbound to Coney Park to refuel.

The aircraft reached Harrogate VRP at 1120 hrs whereupon the pilot requested a descent for 'York'. The Leeds controller replied "OSCAR MIKE HOTEL ROGER I HAVE NO KNOWN CONFLICTING TRAFFIC". At the same time, the helicopter pilot, who was in contact with the Leeds tower controller, lifted from Coney Park and departed for his flight to the east of York. He was cleared to route "REMAINING NORTH OF LEEDS AT ALL TIMES.....ROUTE OUT TO THE EAST VFR NOT ABOVE 2,000 FEET ON THE QNH 1021 SQUAWK 0417". The helicopter pilot selected the assigned squawk but did not select mode 'C' (height encoding). At 1122:30 hrs he was handed over to the Leeds approach controller who transmitted "...GOOD AFTERNOON; FLIGHT INFORMATION SERVICE". Two minutes later the aircraft pilot requested permission to leave the frequency. The controller said "SQUAWK 7000 BYE BYE". The aircraft pilot complied with this instruction and changed frequency to Rufforth Air Ground Station on 129.975 MHz whereupon he was told "...OPERATING ON RUNWAY 18 LEFT-HAND CIRCUIT DO NOT FLY BELOW 800 FEET".

At 1125 hrs the helicopter pilot reported at Weatherby and asked to "QSY TO LEEMING". He was also told to squawk the conspicuity code of 7000 by the Leeds approach controller. The pilot, however, squawked 'standby' in anticipation of being assigned another code by the next ATC controller. He made a brief call to Leeming and was told to contact the Linton-on-Ouse zone controller on 129.15 MHz. The helicopter pilot established contact with the Linton controller and

transmitted "...TWIN SQUIRREL OUT OF LEEDS TO A PRIVATE SITE AT GIVENDALE WHICH IS JUST SOUTH OF THE RACE COURSE (*meaning Weatherby*) WITH ABOUT ANOTHER NINETEEN AND A HALF MILES ON ZERO EIGHT ZERO TRACK, LEVEL AT 2,000, 1021 (QNH), SQUAWKING STANDBY REQUEST RADAR INFORMATION". The transmission was given in a rather hurried manner with only the fundamental elements being assimilated by the controller. He noted the helicopter's height and heading but was confused as to its position.

The Linton-on-Ouse controller, who had not been aware of the helicopter's flight until he received the initial call, instructed the pilot to select code 2641 on his transponder. VHF Direction Finding (VDF) facilities were not available on the Linton zone frequency so the controller took some time to scan his radar display in order to locate the helicopter's primary and secondary radar return. Before he could do so the helicopter pilot transmitted "MAYDAY MAYDAY MAYDAY STARSPEED 20 A TWIN SQUIRREL HELICOPTER WITH A MID-AIR COLLISION... FORCED LANDING JUST TO THE EAST OF WETHERBY". The aircraft pilot was unable to transmit any emergency message because his radio had been destroyed.

The other helicopter crew member, also a qualified helicopter pilot seated in the front left-hand seat, did not see the aircraft. Although the helicopter was being navigated using GPS, he was referring to a map and his attention was directed within the cockpit. The helicopter commander, seated on the right, only sighted the aircraft, as a white shape on the lower left side through the left door window, a fraction of a second before the impact. He had taken immediate avoiding action by banking and turning rapidly to the right. This manoeuvre, however, was not sufficient to avoid the collision.

In the collision the helicopter lost its tail rotor and a section of tailboom. It immediately gyrated uncontrollably and the forward speed reduced to zero. The commander promptly lowered the collective lever and lowered the nose to increase the forward speed. He also instructed the other pilot to shut down both engines. Positive control was regained after several rotations as the forward speed increased to 40 to 60 kt. At approximately 100 feet agl the commander initiated the flare using cyclic pitch control. The helicopter responded by levelling in the normal attitude with the skids at corn top height. The final descent from this height was arrested by use of collective pitch control. Just prior to touchdown the helicopter developed a drift to the left causing the left skid to contact the soft soil first. The cabin rolled around the skid and settled onto its left side. It then spun through 180° as the still rotating rotor blades made contact with the surface. The two crew, who were uninjured, vacated the wreckage immediately. Once clear of the wreckage the helicopter commander used his mobile phone to summon the assistance of the emergency services.

The light aircraft suffered extensive damage to the forward fuselage in the collision but the pilot was able to carry out a forced landing into a field. Landing along the furrow line the aircraft was brought to rest without further damage. The pilot, who had suffered minor injuries to his right hand, from fragments of shattered canopy, vacated the aircraft immediately.

The weather, recorded at RAF Linton-on-Ouse at 1150 hrs, was fine with a visibility of 10 km, few clouds at 12,000 feet, broken cloud at 25,000 feet, surface wind of 230/05 kt. temperature +28°C, dew point +15°C and a QNH of 1020 mb. The helicopter commander assessed the In-flight visibility (IFV) as being 9 km.

Aircraft Examination

Figure 1, derived from damage and witness marks caused to each airframe, illustrates the relative positions of the helicopter and aircraft at the moment of collision. The initial point of contact

appeared to have been between the lower fin/sting of the helicopter and the aircraft canopy, approximately at its centreline, with the sting then striking the upper portion of the centrally mounted avionics units. As it did so, the tail rotor blades struck and caused serious damage to themselves and the right outer surfaces of the aircraft cockpit and engine cowling (see Figure 2) with the aircraft's wooden propeller disintegrating to leave two stubs as it cut through the tailboom. In the collision, the helicopter's tail boom had been completely severed by the aircraft's propeller at a position some 1 to 2 feet forward of the fin. This removed, as a unit, the tail rotor and gearbox, the fin and approximately 17 kg of trim weights (see Figure 3) which resulted in a significant forward shift of the helicopter's centre of gravity. Relatively minor damage/scuff marks were present on the upper surface of the aircraft's left wing, and the leading edge of its right tailplane had been hit by debris to leave a small area of relatively serious structural damage.

After the collision both the aircraft and helicopter landed in open countryside, some 1.75 nm apart. The helicopter landed in a field of standing wheat; the aircraft in a harvested field that had contained oil seed rape. The separated portion of the helicopter tailboom was found some 250 metres to the south-east of the main helicopter wreckage. The area between the aircraft and helicopter was strewn with minor debris, mostly comprising of aircraft canopy fragments and loose cockpit items. Despite the helicopter coming to rest on its left side, almost no fuel was spilt and there was no fire. Examination of the aircraft revealed damage associated only with the mid-air collision. The helicopter had additional serious damage to the left skid, tailboom/horizontal stabiliser and main rotor system caused during the landing.

Recorded Data

GPS data

The helicopter was equipped with a sophisticated global positioning system (GPS), comprising a Garmin GPS satellite receiver coupled to an Argus 7000CE moving map display. The Argus was connected to the helicopter's compass and so could display heading. It also contained an accurate piezo-electric sensor to determine current atmospheric pressure and hence altitude. Furthermore, it could self-calibrate the pressure sensor to QNH, whilst the helicopter was stationary on the ground, using known airport elevations from its built-in database. The altitude of the helicopter could be displayed to an accuracy of better than 50 feet provided that flight sectors were not flown in areas of high pressure gradients. The Argus had an internal battery-backed memory which would retain, even in the absence of aircraft power, a history of the last ten hours of the helicopter's progress. Spot readings of position, heading, track and altitude were taken every five seconds, date/time stamped and recorded in the memory.

With the assistance of the manufacturer and the installer of the equipment, the history data was downloaded from the Argus. The data showed that the helicopter had taken off, made a climbing right turn onto a heading of 084°M and finally levelled at between 2,100 feet and 2,350 feet.

At the time of the collision the data recorded that the helicopter was at 2,106 feet and achieving a ground speed of 123 kt. Following the collision, the helicopter made a right-hand rapid descent, achieving a maximum descent rate of 5,000 ft/min by 400 feet agl reducing to less than 1,000 ft/min prior to touchdown. The time from collision to touchdown was between thirty and thirty-five seconds. It was not possible to determine the yaw rate during the descent as the five-second recording interval of heading data was probably longer than the period of rotation of the helicopter.

Radar data

Radar Information displayed in the Leeds approach control room was recorded. Primary returns are processed from the radar head on the airfield. Secondary returns and mode 'C' information are added electronically to the radar display from the radar head at Claxby. A playback of the recorded data showed that the aircraft's primary return, secondary response and mode 'C' height readout were displayed continuously within the radar's range up to the time of the collision. The helicopter's primary return was displayed from the time of take off to the time of the collision. Its secondary squawk, without mode 'C,' was displayed until 40 seconds before the impact and again 8 seconds before the collision, when the Linton-on-Ouse assigned squawk was displayed.

Manual of Air Traffic Services (MATS) Part 1

MATS Part 1, contains instructions and guidance to controllers providing air traffic services. Chapter 1 gives details of Air Traffic Services. Relevant extracts are reproduced below:

Flight Information Service

A flight information service is a non-radar service provided for the purpose of supplying information useful for the safe and efficient conduct of flight. This includes information about weather (including SIGMET), changes of serviceability of facilities, conditions at aerodromes and any other information pertinent to safety. Some controllers may wish to allocate a discrete squawk to aircraft in receipt of a flight information service, for monitoring and coordination purposes. If this is done then the aircraft must be identified and the correct validation and verification procedure used. Pilots must be left in no doubt that they are receiving a flight information service only.

.... All air traffic units shall provide flight information and alerting service to aircraft under their jurisdiction.

.... Traffic information shall be passed and traffic avoidance given to aircraft on any occasion that a controller considers it necessary in the interests of safety.

Information literature

The Civil Aviation Authority publish a series of General Aviation Safety Sense leaflets one of which (leaflet 8C) is titled 'Air Traffic Services Outside Controlled Airspace'. Included in the contents is a section on 'Non-Radar Services'. The paragraphs relating to Flight Information Services (FIS) are reproduced below:

Flight Information Service (FIS)

This non-radar service provides information to assist with the safe and efficient conduct of your flight. You should consider this service as a minimum when planning a flight. The information available may include:

Weather.

Serviceability of navigation and approach aids.

Conditions at aerodromes.

Other aircraft reported in your area, which are in contact with the FIS.

Other information pertinent to flight safety.

Remember that use of FIS is not intended to replace pre-flight planning, nor is it intended to be a comprehensive source of information on the presence of other aircraft. The controller may be able to provide information on aircraft in your vicinity that have been reported to him, but it is unlikely that he will be aware of all aircraft that may affect your flight. ie warnings of conflicting traffic are far less likely to be given under a FIS than under RAS (Radar Advisory Service) or RIS (Radar Information Service). Most ATSU's can provide a FIS within their local areas. Those ATSU's which provide RAS and RIS can normally offer a FIS when conditions prevent them from providing a radar service.

Conclusions

The collision took place outside controlled airspace in VMC conditions when neither aircraft was receiving a service from an ATC unit. The Leeds approach controller had terminated his 'contract' with each pilot when they had changed frequency to Rufforth and Linton-on-Ouse respectively. The Rufforth A/G station could only pass airfield information to the aircraft pilot and the Linton-on-Ouse controller, who had not yet identified the helicopter, entered into a verbal 'contract' with him. The primary means for collision avoidance therefore was 'see and avoid' in which each pilot was responsible for his own lookout in order to see and avoid conflicting traffic.

The light aircraft was fitted with a 'bubble' canopy allowing excellent vision horizontally through some 270°, subject to the physical limitations of pilot head movement and fuselage structure behind him. The helicopter was however approaching the aircraft, with a closing speed of 20 kt, from behind the pilot's right shoulder; an area of the sky that was difficult, if not impossible, to scan. The helicopter was in a gentle descent at the time of the collision with the aircraft on a bearing of 350° relative. The commander's view of the area ahead, below and to the left, was obstructed by the instrument panel. The left seat occupant, who was in a better position to have seen the Katana, was 'head down' studying a map.

When the pilot of the light aircraft requested a descent from FL 055 the Leeds approach controller was not aware of any traffic to conflict with his descent. The pilot had already been assigned a squawk and the aircraft's primary and secondary radar returns, with a mode 'C' height readout, were visible on the radar display in the Leeds approach control room. Two and a half minutes later, at 1122:30 hrs, the helicopter pilot made contact with the approach controller for his flight to the east of York. He had also been assigned a Leeds squawk and the helicopter's primary and secondary returns were visible on the radar display. The helicopter's height was not displayed as mode 'C' had not been selected by the helicopter commander. In response to the helicopter pilot's initial call the controller confirmed that he was to receive a flight information service.

Notwithstanding the above, for two minutes both aircraft were in contact with the Leeds controller and both aircraft were on constant converging tracks. The controller had allocated each aircraft a discreet squawk which could have been used for monitoring and co-ordination purposes. The controller was very experienced, the traffic load was light and he could have been expected, as 'best practice' to have predicted that the aircraft would come within close proximity to each other and hence could have informed each pilot as to the possible conflict. Armed with this information both pilots would have been alerted to scan the relevant sectors of the sky thus enhancing their abilities to 'see and avoid'.

The Linton-on Ouse controller was in contact with the helicopter at the time of the collision but it had not been identified on radar and he was not providing it with any service. The helicopter's mode 'C' was not visible and, as the helicopter commander had selected standby on his transponder as he left the Leeds frequency, the only indication of the helicopter's presence on the Linton controller's display was a primary return. The pilot of the light aircraft did not contact Linton-on-Ouse, neither was he obliged to, and therefore the Linton controller was not aware of the aircraft's presence and thus of the potential conflict.