

# Piper PA-28-161 Cherokee Warrior II, G-BPWZ

**AAIB Bulletin No: 10/97 Ref: EW/G97/08/06 Category: 1.3**

**Aircraft Type and Registration:** Piper PA-28-161 Cherokee Warrior II, G-BPWZ

**No & Type of Engines:** 1 Lycoming O-320-D3G piston engine

**Year of Manufacture:** 1983

**Date & Time (UTC):** 10 August 1997 at 1615 hrs

**Location:** Field, near Whitehaven, Cumbria

**Type of Flight:** Private

**Persons on Board:** Crew - 1 - Passengers - 3

**Injuries:** Crew - Serious - Passengers - Minor

**Nature of Damage:** Substantial damage to engine and airframe

**Commander's Licence:** Private Pilot's Licence with IMC and Night Ratings

**Commander's Age:** 51 years

**Commander's Flying Experience:** 342 hours (of which 304 were on type)  
Last 90 days - 5 hours  
Last 28 days - 1 hour

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The aircraft was returning to Liverpool following an uneventful flight to Kirkbride. When abeam Workington the pilot initiated a climb from 1,500 feet to 2,500 feet in order to clear the restricted area at Sellafield. As the aircraft reached 2,300 feet the engine suddenly ran very roughly, with no improvement on using the throttle, but the engine indications were normal. A full engine failure drill was carried out, including changing fuel tanks, checking the magnetos and fuel pump, and applying carburettor heat, but the rough running continued. The pilot therefore decided to carry out a forced landing.

A Mayday call was transmitted and the transponder code set to emergency. The call was acknowledged, and the pilot was instructed to change frequency to 121.5 MHz.

Only one field appeared suitable for a forced landing and the subsequent touchdown was made just inside the boundary wall, with full flap selected. However the aircraft subsequently collided with an earth/stone embankment, since the available landing distance was no more than 150 metres. The collision caused substantial damage to the aircraft and the pilot sustained a fractured ankle.

Subsequent examination of the engine by a maintenance organisation revealed that the engine had suffered a broken cam follower for the No. 2 cylinder inlet valve. This had resulted in the loss of the hydraulic lift function of its associated tappet, leading to the push-rod becoming bent. The consequent disruption to valve operation had caused significant mechanical damage to the engine.

A UK overhaul agent for this type of engine reported that they had experienced a small number of such failures over the years. However, the CAA database had only one record of a similar failure within the last 20 years.

The engine had been overhauled in the USA in October 1994, before being installed in G-BPWZ later that month. It had achieved 1,128 hours at the time of the failure. The engine manufacturer requires that in the event that the camshaft is renewed, new cam followers should also be installed. If the old components are utilised, the manufacturer advised that the cam followers should be reinstalled in their original locations in order to avoid potential changes in wear patterns. The cam followers should not be re-profiled, although this has been known to occur at some overhaul agents. In the case of this engine, the overhaul release documentation did not contain detailed information on component replacement.