

Yak 52, LY-ALN

AAIB Bulletin No: 10/96 Ref: EW/G96/08/10 Category: 1.3

Aircraft Type and Registration:	Yak 52, LY-ALN
No & Type of Engines:	1 Vedeneev M-14P radial piston engine
Year of Manufacture:	1980
Date & Time (UTC):	11 August 1996 at 1527 hrs
Location:	Gloucestershire Airport, Staverton
Type of Flight:	Private
Persons on Board:	Crew - 1 Passengers - None
Injuries:	Crew - None Passengers - N/A
Nature of Damage:	Damage to right wing, propeller and engine cowling
Commander's Licence:	Private Pilot's Licence
Commander's Age:	48 years
Commander's Flying Experience:	882 hours (of which 22 were on type) Last 90 days - 23 hours Last 28 days - 22 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

After receiving clearance to taxi, the pilot was manoeuvring the aircraft from its parked position (by the control tower) and proceeding between the fuel pumps to the southern taxiway. Differential braking was being used to steer the aircraft. However, upon reaching a 90° turn to the right, the brakes ceased to be effective. The pilot was able to turn the aircraft through approximately 30° and applied a small burst of power in an attempt to turn the aircraft using rudder effect. However, it soon became apparent that there was insufficient space to make the turn and that a collision with a parked aircraft was inevitable. The Yak collided with a Piper Warrior (G-GFCC), engaging the mid section of the right wing.

Aircraft systems such as engine start, landing gear retraction and wheel braking on the Yak are operated pneumatically by compressed air. Air from an engine driven compressor is stored in two spherical bottles (one main, one for emergency in-flight engine start) which are always charged

whilst the engine is running. To ensure safety during maintenance, the air system may be isolated at the output side of the tanks. In a frank statement, the pilot said that prior to taxiing the aircraft he had experienced a problem with the engine tachometer, which did not seem to be working. In order to investigate the problem he shut the engine down and got out of the aircraft. He then opened the cowlings and, for safety reasons, isolated the air system. However, after rectifying the problem with the engine tachometer, the air supply system was inadvertently left isolated. Unfortunately, the design of the system is such that with the tanks isolated, sufficient compressed air remains in the various actuators to enable at least one engine start to be carried out and to provide residual pressure capable of operating the braking system for a few cycles. A modification to the system has been proposed which would ensure that no pressure would be available to any of the services after isolation, and this is currently being considered by the CAA.