

Piper PA-30, G-ASYK, 11 May 1996

AAIB Bulletin No: 9/96 Ref: EW/C96/5/17 Category: 1.3

Aircraft Type and Registration: Piper PA-30, G-ASYK

No & Type of Engines: 2 Lycoming IO-320-B1A piston engines

Year of Manufacture: 1964

Date & Time (UTC): 11 May 1996 at 1100 hrs

Location: Isle of Wight Airfield, Sandown

Type of Flight: Private (Training)

Persons on Board: Crew - 2 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Both main landing gears broken, left propeller bent, wings and fuselage severely creased

Commander's Licence: Commercial Pilot's Licence with Flying Instructor's Rating

Commander's Age: 50 years

Commander's Flying Experience: 3,000 hours (of which 22 were on type)

Last 90 days - 90 hours

Last 28 days - 20 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was being used for an instructional flight. The exercise being carried out was intended to allow the student to gain more experience in handling the aircraft, particularly with regard to approaches and landings and it was planned to conduct these exercises at Sandown, away from the aircraft's base at Bournemouth. The student had only just started flying twin engine aircraft and had not yet undergone any instruction in asymmetric powered flight.

En-route to Sandown, the student carried out a 'simulated' approach followed by a missed approach to familiarise himself with the correct power setting, speed and configuration requirements. This was completed satisfactorily and the student then contacted Sandown and gave details of the intention to perform some 'touch and go' landings. Before setting out the instructor had discussed, with the student, the fact that the aircraft was likely to become airborne at a lower airspeed than usual because of the undulations expected in the grass runway at Sandown. They had also discussed the need to retract the flaps from 'full' to the 'take-off' setting as soon as the 'go-round' decision had been made and that the student would tell the instructor when he required them to be raised.

The pre-landing checks were carried out, which included selecting the electric fuel boost pumps to 'on'. The first landing was made without difficulty and the student called for the flaps to be raised and he applied full power. The aircraft became airborne again and was held level, close to the ground, until the speed increased to above minimum control speed (V_{mca}) before climbing away. The student remarked that he needed to apply some right rudder to keep the aircraft straight and that he would be ready for it next time.

After a correctly executed circuit, the student made a good landing. The student then asked for 'take-off' flap and applied power. However, when the aircraft became airborne, the instructor noticed that the aircraft yawed and banked slowly to the left and assumed that the student was taking longer than usual to make the necessary control corrections. The student commented that the aircraft did not appear to be responding to corrective control; so the instructor took control and discovered that although he was applying full power, full right rudder and considerable right aileron, the aircraft continued to roll and yaw to the left. The aircraft deviated from the runway heading and, in an unusually nose-high attitude, was 'crabbing' towards a hangar, in front of which several aircraft were parked.

Although he had deduced that an engine had lost power, there were no audible or visible indications. The aircraft continued to roll and yaw to the left until, despite full right aileron being applied, the left wingtip touched the ground. At this point the instructor closed the throttles, moved the mixtures to cut-off and the propeller levers to feather the aircraft settled onto the ground, continuing to slide and rotate to its left before coming to rest at right angles to, and facing, the runway. The occupants left the aircraft uninjured after the instructor had made the aircraft safe. The instructor later heard comment to the effect that 'a lot of black smoke' had been seen to be coming from the left engine as the aircraft was taking off.

A bench calibration check of the left engine fuel injector assembly showed it to be correctly set up. The engine driven fuel pump was tested by fitting it to an engine which was run on a testbed and this revealed that the pump supplied fuel to the injector within the correct pressure range with the fuel inlet pressure at either unboosted (2 psi) or nominal maximum boosted pressure (26 psi). It was noted, however, that the fuel flow rate at low power settings was markedly greater with boosted inlet pressure, implying a richer mixture. Test bed running constraints precluded determining any fuel flow rate differences at high rpm/low torque conditions.

Tests performed on the left engine boost pump showed that its pressure output was considerably lower than its specification required. It was, however, capable of delivering 25 US gallons per hour (US gph) into a zero head and allowing a flow of 14 US gph into a draw of less than 1 psi.