

Sky 220-24, G-SPEL, 31 March 1997 at 0815 UTC

AAIB Bulletin No: 4/98 Ref: EW/K97 Category: 3

(BBAC Incident No 02/97)

Aircraft Type and Registration:	Sky 220-24, G-SPEL
No & Type of Engines:	Sky Triple
Year of Manufacture:	1966
Date & Time (UTC):	31 March 1997 at 0815 UTC
Location:	Near Addingham, N Yorks
Type of Flight:	Public Transport
Persons on Board:	Crew - 1 - Passengers - 12
Injuries:	Crew - None - Passengers - 1 serious 11 minor
Nature of Damage:	None
Commander's Licence:	CPL Balloons, Groups A & B
Commander's Age:	42 years
Commander's Flying Experience:	444 hours (of which 54 were on Group B) Last 90 days - 5 hours
Information Source:	Accident Report submitted by the pilot and enquiries conducted by British Balloon and Airship Club

History of the flight

The early morning flight, which was to depart from a regularly used launch site near Ribchester, Lancashire, was planned to last for approximately one hour. The pilot had obtained an Airmet Area weather forecast for the UK Northern Region using the 'Metfax' service at 0540 hrs. This was issued at 0341 hrs and was valid from 0500 hrs to 1300 hrs. It gave the general situation as an anticyclone centred to the south covering the area with a visibility of 30 km with scattered cloud at 3,000 to 4,000 feet. Included in the data was a strong wind warning with south-westerly surface winds

gusting to 25 kt in the far north-west of the region. The winds at 1,000 and 3,000 feet were forecast to be 2300/18 kt and 2400/20 kt respectively.

The Terminal Airfield Forecast (TAF) for Leeds Bradford Airport, situated approximately 7 nm east of the accident site, issued at 0624 hrs, gave the surface wind as 2500/13 kt with a 30% probability, between 1000 hrs and 1600 hrs, of becoming 2800/15 kt gusting to 25 kt. A revised TAF, issued at 0842 hrs (after the accident), increased the probability of an increase in the surface wind to 40% and brought forward the period of validity as from 0800 hrs.

When the pilot arrived at the launch site the conditions were calm with clear skies and a significant ground frost. He released a small helium balloon to check the wind speed and direction and this was observed to travel almost vertically upward. The pilot estimated that at that time the surface wind was less than 3 kt. As the actual conditions were at variance with the forecast the pilot telephoned the Meteorological Office at Manchester at 0545 hrs for clarification of the forecast. There was no record of the subsequent discussions but the pilot stated that the Duty Meteorologist assured him that the surface winds would not increase significantly for 'a good two to three hours'. The pilot therefore decided that the flight could take place and the balloon was assembled and inflated.

The twelve passengers consisted of, ten who had bought tickets for the flight, one who was the pilot's friend and who held a Private Pilot's Licence (Balloons) and his 6 year old son. When the envelope was inflated the passengers boarded the basket and the pilot carried out a standard safety briefing, emphasising to the passengers the need to face rearwards on landing, hold on to the rope handles inside the basket, bend the knees and not to leave the basket until instructed. The passengers were asked to practice the 'landing position', which they did, under the supervision of the pilot.

The take off and early part of the flight, flown at heights of between 700 and 1500 feet agl, was conducted without incident. After approximately one hour the passengers were told to prepare for landing and assumed the landing position. By this time the balloon had travelled approximately 19 nm from the launch site.

During the descent and attempted landing the pilot encountered strong windshear at low level, and aborted the approach. A second attempt was made approximately 15 minutes later and aborted for similar reasons. The balloon was now travelling towards rising moor land and the pilot once again told the passengers to prepare for landing, having selected a large field on the shoulder of a gentle hill. One of the passengers reported that an instrument in the pilot's compartment indicated a 500 feet per minute rate of descent shortly before the landing.

The selected site was a grass field which was very wet and muddy. Approximately 20 metres from the edge of the field, lying at right angles to the path of the balloon, was a raised stone track approximately 10 cm above the surrounding surface. Apart from the stone track, the field surface was virtually free from stones or other hard objects.

Having committed to the landing, the pilot started to pull the 'rip' line, releasing hot air from the crown of the balloon envelope. This is normal practice when landing in strong winds and ensures that the balloon will no longer remain buoyant. It also reduces the chance of a bounce and the length of the subsequent drag. An eye witness located approximately 800 metres from the touchdown point saw the final descent and landing. She reported that shortly before touchdown the upwind side of the balloon envelope had taken on a concave shape.

During the touchdown the left hand leading corner of the basket impacted the field immediately adjacent to and up against the raised track. This resulted in the balloon basket immediately and rapidly rotating about its leading edge onto its side. As this happened, 6 of the 7 passengers located at the rear of the balloon lost their grip on the internal basket handles and were thrown forward out of the basket.

Two of the passengers (passengers No 1 and No 2 in Figure 1) were thrown clear of the basket. The pilot's friend (passenger No 3) and his son (passenger No 4) slid along the surface until eventually being pushed clear. On the other side of the basket, passengers No 5 and No 7 were both ejected on impact and thrown clear of the balloon. Passenger No 6 was thrown forwards, became entangled in the balloon control lines and was dragged behind the balloon for approximately 160 metres before becoming disentangled. The balloon continued to drag for a further 10 metres before coming to rest. (A diagram of the landing site showing the distribution of passengers and balloon is shown in Figure 2.)

Approximately 5 minutes after the landing, the pilot's friend, realising the extent of the injuries sustained, called the emergency services using his mobile telephone. He was later able to pass the exact map grid reference of their position on information supplied by the balloon retrieve crew who arrived on scene minutes later. They attempted to make the injured persons comfortable, but did not use the first aid kit that was carried in the balloon and thrown from the basket during the impact. Furthermore there did not appear to be a contingency plan, available to the retrieve crew, that could have been implemented to deal with the occurrence.

Two ambulances arrived approximately 15 minutes later. The vehicles attempted to drive across the field to the injured but one became stuck. The four-wheel drive balloon retrieve vehicle was not able to pull the ambulance free. Eventually a local farmer was able to do so with the use of a four-wheel drive tractor.

Video evidence

Two video recordings had been taken of the event. One had been taken from the ground and one, showing the final 62 seconds of the flight, had been taken from within the basket. The audio portion of this recording revealed details of burner activity. The recording commenced with the burner already in operation and recorded the sound of the burner for a further 7 seconds. The burner was then operated again after a 19 second pause. On this occasion the burner was noticeably quieter possibly indicating the operation of the less powerful 'quiet' burner, used when flying near livestock. This burn lasted for 16 seconds, with one short interruption, after which no further burn took place. Impact occurred 26 seconds after the end of the last burn.

The video images also showed ground features readily identifiable on an Ordnance Survey map of the area. Time versus distance calculations from the video data showed that at that time the balloon was travelling at an estimated ground speed of between 23 and 30 kt.

Pilot details

The pilot held an unrestricted Commercial Pilot's Licence (CPL) for Balloons with a valid Class II medical certificate. He held type ratings to fly balloons in Group A (not exceeding 105,600 cu ft) and Group B (105,600 to 316,800 cu ft). He obtained his CPL(B) in July 1994, adding the Group B type rating in July 1996. 40 hours of his group B experience had been gained on balloons with a 140,000 cu ft capacity. He had had the required period free from duty prior to the flight. In July

1996 he successfully completed a combined base/line check for Group B balloons, valid for 13 months. He had also completed a fire fighting and first aid course during 1994.

Injuries

The passenger who had been dragged behind the balloon suffered a broken hand, concussion and minor cuts and grazing. Another passenger sustained whiplash injuries with severe bruising to the chest, neck, shoulders and knee. One passenger, who had not adopted the correct landing position suffered severe bruising to both knees. Two of the ejected passengers suffered whiplash and bruising injuries. The pilot, who was wearing a restraint harness, and the other passengers had remained in the basket. They all suffered from bruising with minor cuts and grazes. Two had suffered whiplash injuries. The pilot, who had been dazed in the impact, was assisted from his safety harness by one of the passengers.

Balloon information

The balloon, with a volume was 220,000 cuft, had flown a total of just over 6 hours since new and had a current Certificate of Airworthiness in the Public Transport Category.

The basket was of standard wicker and cane construction, woven around a central stainless steel framework. The main compartment contained the fuel cylinders and space for the pilot, two smaller compartments each side of the main compartment were capable of carrying 3 to 4 passengers. Woven into the basket on the inside of each of the passenger compartments were six rope handles. All compartments were fitted with a non-slip plywood floor.

The balloon envelope was fitted with a 'parachute' re-sealable valve to deflate the balloon, which was operated by a control 'rip' line to the basket. Similar lines operated two turning vents which released air from the envelope in order that the basket could be oriented for landing.

Balloon performance

On the day of the accident the surface temperature was 5°C. This gave a lift of 9 kg per 1,000 cu ft of envelope volume. The balloon load sheet showed the total load as being 1590 kg. The calculated lift available, in the prevailing conditions, was 1980 kg thus there was 390 kg of spare lift available. The balloon was therefore correctly loaded within prescribed limits.

Conclusions

The accident was caused by the execution of a landing with a higher than normal ground speed combined with a higher than normal rate of descent.

The concave appearance of the balloon envelope just prior to touchdown indicated that either the balloon had been hit by a severe sudden gust of wind or had already begun to deflate as a result of the rip line having been pulled by the pilot. However despite the loss of 442 kg of payload (6 passengers; 29% of the All-up Weight) during the initial impact, the balloon did not become airborne again, and dragged for 170 metres before coming to rest. This therefore suggests that partial collapse of the envelope was due to rip line activation.

The pilot was relatively inexperienced in landing balloons of this size in strong wind conditions. He had obtained the necessary Meteorological Information available prior to takeoff and having sought

clarification considered that the flight could be conducted safely. The balloon however encountered increasing wind speed conditions as it progressed north-eastwards and an early decision by the pilot to land may have been more prudent. Having delayed this decision the pilot was committed to land at altitude on the open moors, where wind speeds and conditions were liable to be higher and more turbulent.

During the touchdown 6 of the passengers were ejected from the basket. These passengers suffered varying degrees of injury including concussion, whiplash injuries, cuts and bruises. The wearing of head protection may have reduced the severity of these injuries. Furthermore one passenger became entangled in the control lines and was dragged behind the basket. Although the passengers had been briefed on the correct position to adopt during a landing several suffered injury at touchdown.

After the accident there was no evidence of any contingency plan for dealing with the aftermath, a situation exacerbated by the fact that the pilot was stunned and/or shocked and therefore effectively incapacitated.

Safety Recommendations:

In view of the conclusions above it is recommended that:

Recommendation 98-24

The CAA should consider mandating the wearing of suitable head protection for the use of all balloon occupants.

Recommendation 98-25

The CAA should ensure that balloon manufacturers design and supply control lines that are adequately routed and of a suitable length so as to reduce the possibility of inadvertent entanglement with personnel or equipment during all phases of flight.

Recommendation 98-26

The CAA should encourage operators holding a commercial balloon AOC to include, in their company operating manuals, an initial restriction on the wind speed limits applicable to pilots upgrading from their current type to significantly larger balloons.

Recommendation 98-27

The CAA consider whether commercial balloon operators should incorporate into their operations manual, or other standing instructions, a written disaster management plan and provide adequate training, in first-aid at an appropriate level, for their ground crew personnel accordingly.