

No: 10/88

Ref: EW/G88/06/08

Category: 1c

Aircraft Type and Registration: Piper PA-28R-200 Arrow, G-BMNL

No & Type of Engines: 1 Lycoming IO-360-C1C piston engine

Year of Manufacture: 1975

Date and Time (UTC): 17 June 1988 at 1230 hrs

Location: Alderney Airport, Channel Islands

Type of Flight: Private (pleasure)

Persons on Board: Crew - 1 Passengers - 3

Injuries: Crew - None Passengers - None

Nature of Damage: Severe damage to engine

Commander's Licence: Private Pilot's Licence

Commander's Age: 43 years

Commander's Total Flying Experience: 670 hours (of which 8 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot and AAIB investigation of the engine.

The aircraft was en-route from Bournemouth to Dinard, cruising at 2000 feet amsl, when a slight change of engine noise was noted. The pilot checked the engine instruments, changed fuel tanks and selected electric fuel pump ON; he then noted a further change in engine noise. He declared a Mayday and elected to divert to Alderney, approximately 7 nm away.

The engine was losing power, with worsening vibration and, about 4 nm from Alderney, the aircraft would no longer maintain altitude. The pilot only had sufficient altitude to initiate a curving approach to runway 08 and, at about 700 feet and ½ nm out, selected undercarriage and flaps down. Almost immediately the engine emitted a loud bang, with complete power loss. The pilot retracted the flaps to improve penetration and was just able to clear the perimeter fence, landing safely about 50 yards short of the runway.

Subsequent inspection showed that the No 3 (right aft) cylinder had completely detached from the crankcase and the corresponding connecting-rod (figure 1) had been wrenched from the crankshaft, with considerable damage to the piston.

During AAIB investigation of the engine it became apparent that the connecting-rod failure had occurred after the cylinder had become detached. Of the 8 bolts (figure 2) which are used to secure the cylinder

to the crankcase, at least 5 showed positive evidence of fatigue failure. The apparent sequence of failure was that the bolts had become unevenly loaded, leading to progressive fatigue failure through a portion of their cross-section with final failure in overload as the cylinder detached.

The engine had accumulated 906 hours since major overhaul. All 4 cylinders had, however, been replaced 96 hours before the engine failure.



Figure 1: No 3 piston and connecting-rod, G-BMNL




Figure 2: Crankcase from G-BMNL, showing failed bolts