

Piper PA-28-161, G-BJBV

AAIB Bulletin No: 3/97 Ref: EW/C96/5/14 Category: 1.3

Aircraft Type and Registration:	Piper PA-28-161, G-BJBV
No & Type of Engines:	1 Lycoming O-320-D3G piston engine
Year of Manufacture:	1981
Date & Time (UTC):	31 May 1996 at 1835 hrs
Location:	Near Shoreham Airfield
Type of Flight:	Training
Persons on Board:	Crew - 2 - Passengers - Nil
Injuries:	Crew - 2 - Passengers - Nil
Nature of Damage:	Damaged beyond economic repair
Commander's Licence:	Commercial Pilots Licence with Instructor and Night Ratings
Commander's Age:	60 years
Commander's Flying Experience:	4200 hours (of which 500 were on type Last 90 days - 114 hours Last 28 days - 93 hours
Information Source:	AAIB Field Investigation

History of flight

After completing the pre-flight checks, a normal take off was made from Runway 25. The initial climb was normal until approximately 250 feet when the instructor heard a severe rattling sound from the engine area. He immediately started a turn back to the airfield and transmitted a Mayday message. About 90° into the turn the engine stopped. Initially the instructor planned to land on Runway 03 but quickly realised that he had insufficient height to clear some houses between the aircraft and the airfield, and so selected the only field available. The field was small and surrounded by buildings and fences. The instructor left the final turn as late as possible and, with full flap, made his final approach into the field. During the flare he ran out of elevator control which resulted in a heavy landing.

Strip and metallurgical examination

Subsequent strip examination of the engine revealed that the crankshaft had failed at the junction of the centre bearing journal and the forward section of the crank. Metallurgical examination indicated that the failure had occurred due to a high cycle tension fatigue mechanism in simple bending across a crank pin. Higher propagating stresses (and thereby rates) associated with take off had resulted in a series of 'markers' being present in the fracture surface from which the progression of the fracture could be related to propagation per flight ('events'). Many very small progression bands were present between these take off markers. The width of each event band varied with flight profiles and the duration of each flight. It was not possible to count the number of events within the initial 0.1 inch of fatigue propagation due to localised damage. The number of events counted from this 0.1 inch boundary to the point of final fracture was between 170 and 180. The surface length of the crack corresponding to the first 0.1 inch of propagation was 0.45 inch. Extrapolation back to the point of the crack initiation at the surface indicated that the total number of events (flights) from crack initiation to final failure was in the order of 1,800.

The broken crankshaft halves were subjected to a magnetic particle crack detection test and crack indications were obtained in the blend radii between the connecting rod journals and the cranks, in similar locations to the failure but on all the other 'big end' journals.

Engine overhaul history

The engine was imported, from the USA, in 1989 with 1 hour used since its first overhaul and 2382 hours since manufacturer. In November 1994 the engine, with 1840 hours used since the first overhaul, was overhauled a second time. In May 1995, having completed 243 flights in 205 hours since the second overhaul, the engine was removed from the aircraft to which it was fitted because a magneto impulse drive had failed causing pieces of metal to enter the casing. The engine was overhauled a third time by the same approved engine overhaul organisation that carried out the second overhaul. In November 1995 the engine was fitted to the accident aircraft and on the date of the accident the engine had completed 176 flights in 97 hours since the third overhaul and 4524 hours since manufacture. The evidence from the metallurgical examination of the crankshaft failure (*ie* 1,800 flights to failure) thus indicated that the crack had initiated prior to the second overhaul. Examination of the UK engine log books did not reveal any entries to indicate that a propeller strike had occurred, but an entry in the US engine log book stated that the propeller had been replaced, for no specified reason, 34 hours prior to the first overhaul.

The documentation associated with the 2nd and 3rd overhauls was examined. On both occasions the crankshaft had been examined for cracks using the magnetic particle crack detection technique that is specified in the engine manufacturer's Overhaul Manual. The procedure specified in the Overhaul Manual and the manufacturer's Service Bulletin No. 1285A is the 'Current Flow' technique which will detect cracks running along, and up to 45° to, the longitudinal axis of the crankshaft. It will not detect cracks that are lying in a plane that is 90° to the longitudinal axis of the crankshaft. The '*Magnetic Flow*' technique, which is not specified in the Overhaul Manual, is the method required to detect the type of crack that initiated this crankshaft failure.

Non-destructive testing provisions

The engine overhaul organisation that carried out the second and third overhaul was given Joint Aviation Requirement (JAR) 145 approval in 1993. A visit by an AAIB Inspector in July 1996 found that none of the staff directly involved in Non Destructive Testing (NDT) had undergone any training as specified in paragraph 2 or paragraph 9 of Airworthiness Notice 94, which was issued by the Civil Aviation Authority (CAA) in November 1990. Two of the three individuals who carried

out the NDT inspections of this crankshaft during the two overhauls had received NDT training as part of their four year apprenticeships with another engine overhaul organisation in the late 1970's early 80's. One of them had received a Company Inspection Approval for Fluorescent Penetrant, Dye Penetrant and Ultrasonic Inspection in 1986 and both had passed the City and Guilds Parts 1 & 2 in Aeronautical Engineering Craft Studies. They started employment with the overhaul organisation that carried out the two engine overhauls in 1989 and 1992. The third individual, who began employment with the overhaul organisation as a trainee in 1991, had a Letter of Authorisation from this company, dated July 1993, allowing him to conduct Dye Penetrant Inspections and Magnetic Particle Inspections of non-ferrous components with a note, dated January 1995, that a dual inspection was required for all crankshafts. No records were available to show that these members of staff had been given any periodic checks on their NDT techniques, or eyesight tests. Assurances were given that regular competency checks had been conducted by the Quality Control Engineer, but these did not include eyesight tests. The Quality Control Engineer was granted, by the CAA, authorisation in accordance with paragraph 4.3 of Airworthiness Notice 94, issue 5, to undertake and certify Magnetic Particle Inspections during the period of validity of his Aircraft Maintenance Engineer's Licence. Neither the signature nor the identification stamp of the Quality Control Engineer was entered on any of the documentation associated with the two engine overhauls.

Paragraph 4.3 of Airworthiness Notice 94, issue 6, dated November 1990 states;

CAA approved organisations which have been utilising the services of persons not holding a recognised NDT qualification in these methods are required to advise the CAA of those named persons whose experience exceeds 12 months for such inspections and who have a need to continue to practice in these roles (see note). The CAA may be prepared to grant limited authorisation to such named persons based on previous past experience for a period of not more than 5 years from the date of this notice.

NOTE: This requirement does not apply in the case of persons qualified in accordance with paragraph 9(a)(ii) of this notice.

9(a)(ii). Personnel holding a current UK Aircraft Maintenance Engineer's Licence as limited by Airworthiness Notice No 3.

These paragraphs indicated that the Quality Control Engineer's authorisation expired in November 1995.

In March and October 1995, and February 1996 the Quality Control Engineer carried out audit inspections of the NDT Section and in November 1995 the CAA carried out a JAR 145 Audit Inspection of the overhaul organisation, but no comments regarding staff qualifications, training or records of those involved with NDT inspections were noted.

Since the visit by AAIB in July 1996, the overhaul organisation has sent two members of its staff on a recognised NDT course, which they passed at Level 2, and it is proposed to send two other members of staff on the same course early in 1997.

Safety Recommendations

As a result of the findings arising from this investigation, the following Safety Recommendations are made:

96-86: FAA should require the manufacturer of Lycoming piston engines to amend the Magnetic Inspection section of applicable engine Overhaul Manuals to include a procedure which will reliably detect cracks that lie at 90° 45° to the longitudinal axis of the crankshaft on such engines

96-87: The Civil Aviation Authority should seek assurance that the magnetic particle crack detection techniques utilised within the UK aviation industry are fully capable of reliably detecting cracks that are present in any orientation in the component being inspected.

96-88: The Civil Aviation Authority should require that only personnel qualified in accordance with paragraph 2 and paragraph 9 of Airworthiness Notice 94 are permitted to conduct NDT examinations.

96-89: The Civil Aviation Authority should ensure that all holders of authorisations granted by them in accordance with paragraph 4.3 of Airworthiness Notice 94 are aware that such authorisations expired in November 1995.