

# Piper PA-38-112 Tomahawk, G-BTJK, 22 June 1996

## AAIB Bulletin No: 11/96 Ref: EW/C96/6/9 Category: 1.3

<b>Aircraft Type and Registration:</b>	Piper PA-38-112 Tomahawk, G-BTJK
<b>No &amp; Type of Engines:</b>	1 Lycoming O-235-L2C piston engine
<b>Year of Manufacture:</b>	1979
<b>Date &amp; Time (UTC):</b>	22 June 1996 at 1130 hrs
<b>Location:</b>	Runway 25, Thruxton Airfield, Andover
<b>Type of Flight:</b>	Private (Training)
<b>Persons on Board:</b>	Crew - 1 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	Fire damage to engine cowlings and extensive burning of combustible components inside the engine compartment
<b>Commander's Licence:</b>	Private Pilot's Licence
<b>Commander's Age:</b>	61 years
<b>Commander's Flying Experience:</b>	145 hours (of which 10 were on type) Last 90 days - 5 hours Last 28 days - 2 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and further investigation by AAIB

The pilot carried out all external pre-flight checks, including lifting the engine cowlings on each side; everything appeared normal. He then completed his internal pre-start checks and, after receiving clearance, taxied to the holding point for Runway 25 where he carried out the power checks. The full power and magneto checks were normal. However, when the throttle was closed to check the idle RPM, the engine initially idled normally but then the RPM started to decay slowly and smoke appeared from behind the spinner. The smoke increased rapidly and the pilot only just had time to make a radio call, advising the tower that he had a fire, and to shut down the engine before thick smoke forced him to evacuate the cockpit. The airfield fire service attended promptly and successfully extinguished the fire.

On the previous day, after having been flown satisfactorily for a total of some 3 hours earlier in the day, the aircraft had been grounded due to fuel leaking from the vicinity of the carburettor air box. The aircraft was towed across the airfield to the operator's maintenance organisation for rectification. The carburettor was removed, the needle valve checked, the float level adjusted and the

carburettor reassembled and installed. Ground runs were satisfactory, and the aircraft was released back to the operator later in the afternoon, but was not flown again on that day. On the day of the accident the Chief Flying Instructor of the flying club which operates the aircraft carried out an 'A check' in the morning, and sent a student on a 1½ hour solo flight, which passed without incident. The fire occurred during the power checks at the start of the next detail that day.

The fire caused moderately severe heat damage to the rear part of the lower cowl on the left side, and in the area around the nose leg cut-out. The aft parts of the upper cowl panels displayed evidence of heating from within, with significant paint discolouration and blistering, particularly on the left side. Heavy 'sooting' was evident on the outer surfaces of the cowl behind the spinner, on the fuselage skins and windscreen behind the rear lip of the upper left cowl panel, and on the fuselage panels aft of the lower left cowl. The carburettor air intake lip in the cowl was moderately heated and heavily sooted, and the periphery of the air filter element was charred. Inside the cowl, the fire had burnt away most of the plastic hoses, wiring insulation and other combustible materials in the area beneath the engine on the left side, and between the rear of the engine and the firewall. There was no direct evidence of either the fire or the ignition source, but the fire damage pattern overall was consistent with initial development within the lower cowl on the left side, behind the air filter.

The starter motor was found to be engaged after the fire, but the starter solenoid wiring had been partially burnt away. Electrical continuity checks confirmed that, during the course of the fire, heat damage to the wiring insulation had allowed the battery master solenoid supply cable to 'short' across to the starter solenoid energisation cable, and this had almost certainly caused the starter to engage. The starter motor itself was undamaged, and showed no signs of significant heating.

The carburettor was removed and taken for testing under AAIB supervision at an approved overhaul agency. Carburettor fuel levels are normally tested by the overhaul agency at two fuel supply pressures: 11 inches of water, and 11 inches of mercury. It was found that whilst the fuel level in the float chamber was normal at the lower fuel inlet pressure, the float valve leaked when the higher inlet pressure was applied, resulting in fuel flooding from the carburettor after approximately 2 minutes.

The carburettor was dismantled. The float arm was found set slightly low. A visual inspection of the needle valve stem and seat showed a double *ring* indentation around the Viton tip of the valve stem, and very slight scoring of the seat; however, neither appeared excessive to the naked eye, or under a X10 magnification glass. There were no obvious signs of interference between the float body and the float chamber housing. However, subsequent microscopic examination of the needle valve seat revealed a very slight hollow in the land of the valve seat at one point, and slight pitting in the land part of the Viton seal was evident on the valve stem.