

# DHC-1 Chipmunk 22, G-BHRD, 21 January 1997

## AAIB Bulletin No: 4/97 Ref: EW/G97/01/12 Category: 1.3

<b>Aircraft Type and Registration:</b>	DHC-1 Chipmunk 22, G-BHRD
<b>No &amp; Type of Engines:</b>	1 de Havilland Gipsy Major 10 MK.2 piston engine
<b>Year of Manufacture:</b>	1952
<b>Date &amp; Time (UTC):</b>	21 January 1997 at 1035 hrs
<b>Location:</b>	Field, East of Burford, Oxon
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 2 - Passengers - None
<b>Injuries:</b>	Crew - Minor - Passengers - N/A
<b>Nature of Damage:</b>	Extensive damage to airframe and engine
<b>Commander's Licence:</b>	Private Pilot's Licence with IMC and Night Ratings
<b>Commander's Age:</b>	34 years
<b>Commander's Flying Experience:</b>	270 hours (of which 137 were on type) Last 90 days - 10 hours Last 28 days - 8 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and AAIB examination of the engine

The aircraft was on a flight from Brize Norton for the purpose of a general handling and refresher exercise for the front seat pilot. The flight proceeded uneventfully until the aircraft was about to rejoin the Brize Norton circuit when, at a height of about 1,000 ft agl and with the airfield in sight, the engine note changed, as if a spark plug had fouled. The pilot decided to lean the mixture in an attempt to clear the plug, however as he started to move the mixture lever the engine started to vibrate and to run even more roughly, with an attendant drop in oil pressure. The throttle was then adjusted, but this had no effect on the very rough running engine. The engine then stopped and the front seat pilot observed the propeller detach and pass over the aircraft. Approximately 5-6 seconds had elapsed between the onset of the rough running and the propeller departing from the aircraft. The rear seat pilot took control and turned the aircraft in an attempt to find a suitable landing field, having assessed that it would not be possible to reach the airfield. A Mayday call was transmitted to

Brize Norton. The selected field had power cables running across it, but the pilot was able to avoid these. However, the field was freshly cultivated, with the result that the main landing gear wheels 'dug in', causing the aircraft to 'nose-over' after a ground roll of approximately 45 feet. The occupants, who suffered only minor injuries, remained trapped in the inverted aircraft until assisted from it by ground witnesses.

Subsequent examination of the engine revealed that the crankshaft had failed within the No 2 main bearing journal. As a result, the front section of the crankshaft complete with the propeller and No 1 piston and connecting rod assembly had separated from the engine after associated rupture of the front of the crankcase.

Both portions of the crankshaft were subjected to a metallurgical examination which revealed that the failure had occurred as a result of high cycle torsional fatigue. Initiation was at the forward end of the second main bearing journal and had progressed aft along a helical path. However, as the torsional crack had progressed, lateral bending stresses had been induced in the opposite wall of the journal, leading to low cycle, high stress fatigue cracks. These had progressed rapidly and coalesced to produce the actual separation. No cracks were found in the remaining main bearing journals or in the crank journals. The bearing surfaces and the bearing shells yielded no evidence to indicate that there had been any lubrication problems. However, it was noted that oil sludge had accumulated in the bores and oilways of the crankshaft, and in the crank journals, as a result of a centrifuging process. Such deposits are often an indication of low utilisation, and can lead to corrosion, although there was no evidence in this case of the fatigue crack having initiated from a corrosion pit. Additional examination of the initiation region failed to reveal any evidence of machining abuse. Finally, hardness tests were conducted on the surface and core material, the results showing that there had been no surface hardening process, such as nitriding, carried out on the crankshaft. The actual hardness values were consistent with a steel strength of around 57 tonnes/in<sup>2</sup>.

The engine serial number was 11763 and the UK design authority for the Gypsy engine series was able to confirm that it had been built by de Havilland in May 1952 and exported to their Australian subsidiary. Information from the aircraft owners indicated that the engine had been imported from Malaysia into the United Kingdom in 1979 having achieved 562 operating hours, although it was not clear whether this was from 'new', or overhaul. It was installed in G-BHRD in 1980, and had achieved approximately 1400 hours at the time of the accident. The diameters of the crank pins and main bearing journal pins were measured after the accident, and were found to be nominally 1.97 inches and 2.05 inches respectively. These were the 'standard' diameters, and thus indicated that the crankshaft had never been re-ground.

In 1959, Modification 2602, applicable to Gypsy Series 10 engines, introduced a crankshaft made from an improved material (S106 steel) and which was nitrided. Nitride surface hardening improves the fatigue resistance of the component. The engine manufacturer had designated this modification as "strongly recommended", but it had not been mandated by the airworthiness authorities. Earlier marks of Gypsy Major engines continued to use the non-nitrided crankshafts. In 1960 another modification, No 2661, specified that the magneto timing should be retarded by 3° for engines fitted with pre-mod 2602 crankshafts. The stated reason was to: "...reduce the peak pressures attained during engine running, and consequently the stresses to which the crankshaft is subject" (*sic*). Documentation submitted by the aircraft owners indicated that the engine ignition timing was last checked, in accordance with the provisions of Modification 2661, in November 1995.

Although crankshaft failures have occurred in the past on Gypsy Major engines for a variety of reasons, there does not seem to be a history of failures associated with mis-timed engines fitted with

non-nitrided crankshafts. The CAA database had records of only two Gypsy crankshaft failures since 1976, involving an Auster and a Tiger Moth. The Royal Air Force database, which extends back to the early 1970s, had no record of any crankshaft failure in their Chipmunk fleet. However, much of the archived information had been deleted, and so it was not possible to establish how many of the RAF aircraft had been equipped with the nitrided shafts. The Army Air Corps fleet of Chipmunk aircraft, shortly to be retired, have had no reported crankshaft failures over 37 years. All these aircraft currently have the nitrided crankshafts. The lack of any significant crankshaft failure history amongst military Chipmunk aircraft is perhaps surprising since most of these engines were equipped with the cartridge engine start system which accelerated the engine from rest to idle RPM over a very short period, thereby imposing a significant torsional stress on the crankshaft.

In the case of G-BHRD, the failure resulted from a single crack that had grown over a long (but otherwise undefined) period. Crack initiation was not due to corrosion, nor could it be associated with the low engine utilisation since 1980. This lack of any obvious cause for the fatigue and the lack of cracks elsewhere on the crankshaft raised the question of some unrecorded event such as a propeller strike having occurred at some stage during the life of the engine.