

# Cessna 335, N2706X

## AAIB Bulletin No: 1/98 Ref: EW/G97/09/14 Category: 1.2

<b>Aircraft Type and Registration:</b>	Cessna 335, N2706X
<b>No &amp; Type of Engines:</b>	2 Continental TSIO-520-EB piston engines
<b>Year of Manufacture:</b>	1980
<b>Date &amp; Time (UTC):</b>	17 September 1997 at 1928 hrs
<b>Location:</b>	Norwich Airport, Norfolk
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 2 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	Burst nosewheel tyre, broken nose landing gear strut, propellers damaged, engines shock loaded and aircraft skin punctured and rippled
<b>Commander's Licence:</b>	Private Pilot's Licence with IMC, Night and FAA Instrument Rating
<b>Commander's Age:</b>	53 years
<b>Commander's Flying Experience:</b>	789 hours (of which 107 were on type) Last 90 days - 27 hours Last 28 days - 4 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and further enquiries by AAIB

The pilot had carried out practice instrument approaches and had landed at Norwich earlier in the day. A friend, who was an experienced pilot, occupied the right-hand seat to act as safety lookout. The return flight to Elstree was planned for that night. Weather conditions were good with visibility in excess of 10 km, clouds scattered at 3000 feet and a surface wind of 080°/04 kt. The pilot described the conditions as very clear and said that there was no misting of the aircraft's canopy.

Runway 27 was in use and the pilot reported that he lined-up the aircraft on the runway centreline and commenced the take off. At about 60 kt there was a jolt, the aircraft nose dropped and the propellers struck the ground. The aircraft then veered to the left and came to rest on the grass. There

was no fire and neither of the occupants was injured. Air Traffic Control observed the initial take-off run and subsequent deceleration, and despatched the fire vehicles when the aircraft pilot confirmed there was a problem.

Examination by the Maintenance Manager revealed that two edge lights on the southern edge of the runway had been damaged by the aircraft. These lights were white (or amber, as required by runway direction) and stood approximately 14 inches high. Tyre marks indicative of a deflating tyre were evident from the point of impact with the first light until they ran off the runway in a gentle curve. In conjunction with marks in the grass they were consistent with the damage to the lights caused by the nose wheel and nose landing gear collapse having occurred after the aircraft ran onto the grass. Both main wheel tyres appeared undamaged.

### **Runway Dimensions and Airfield Lighting**

Runway 27 at Norwich has a tarmac shoulder of approximately the same width as the runway on its southern edge. The shoulder extends for approximately 242 metres from the runway threshold and its boundary with the runway is designated by a broad white line. The line was added when the runway was resurfaced in March/April 1997 but had not been in place before that date; it continues beyond the shoulder as the runway edge line. Three sunken, bi-directional lights are located at intervals alongside the line between the runway and the shoulder. The first runway edge light is situated approximately 12 metres beyond the end of the shoulder.

The taxiway leading to the threshold of Runway 27 has centreline green lights which were installed when the runway was resurfaced. They continue onto the shoulder, at right-angles to the runway, but stop approximately 13 metres short of the boundary between the shoulder and the runway. They were in use at the time of the accident but a section of approximately 90 metres immediately beyond Holding Point 'A' was not illuminated because further wiring installation is required in that area in association with stop-bar lighting.

Unidirectional green 'turning circle' lights have been installed and provide lead-on indications from the end of the taxiway centreline. However, they were not in service at the time of the accident because of technical difficulties which have not been resolved at the time of this report. Furthermore, both the taxiway centreline and turning-circle lighting are intended for use in low visibility operations (less than 400 metres) and would not normally be used for departures in good weather.

The runway centreline lights had been renewed when the runway was resurfaced in April 1997 but had not been returned to service at the time of the accident.

### **Aircraft Position**

The take-off run for a Cessna 335 at its MTWA of 5,996 lbs is 564 metres in still air. The subject aircraft, which was at approximately 5,280 lbs, would have covered at least 200 metres to achieve the airspeed (60 kt) at which the jolt occurred. It is unlikely, therefore, that there would then have been sufficient space for it to turn left from the runway centreline following the jolt, then right to parallel the runway, before striking the first edge light. There were no witness marks on the runway which might have indicated such a sharp turn.

Notwithstanding the commander's report that he had lined up on the runway centreline it is therefore likely that the take-off was initiated in line with the runway edge.

## **Previous Recommendations and Actions**

There have been 13 reported similar incidents at Norwich and other airfields where the paved surface extends beyond the runway width. The AAIB recommended in 1991 that the CAA should carry out an audit with a view to standardising surface markings and lighting at those airfields. CAP 168 (Licensing of Aerodromes), as amended November 1994, illustrates taxiway markings which continue across the shoulder to the runway edge and which should therefore remove a source of confusion.

## **Follow-up Actions**

Following the accident, Airport Management withdrew the taxiway centreline lights from service pending a full review of the turning circle, taxiway and lead-on lighting and markings at the runway thresholds.