

Hughes 269, G-BXMY

AAIB Bulletin No: 3/98 Ref: EW/G97/12/07 Category: 2.3

Aircraft Type and Registration:	Hughes 269, G-BXMY
No & Type of Engines:	1 Lycoming HIO-360D1A piston engine
Year of Manufacture:	1974
Date & Time (UTC):	13 December 1997 at 1545 hrs
Location:	Between Clevedon and Portishead, Somerset
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Minor damage to engine cooling system
Commander's Licence:	Private Pilot's Licence
Commander's Age:	45 years
Commander's Flying Experience:	93 hours (of which 85 were on type) Last 90 days - 34 hours Last 28 days - None
Information Source:	Aircraft Accident Report Form submitted by the pilot and AAIB telephone enquires with the helicopter's maintenance organisation

On the day of the accident, the helicopter had been collected by the owner/pilot from a maintenance organisation at Chichester/Goodwood airfield after completion of a Star/Annual check and issue of a new Certificate of Airworthiness. During this inspection, cracks were discovered in the engine cooling impeller and this was replaced with a used, but serviceable, impeller. Subsequently whilst in the cruise at a height of 3,000 feet over the River Severn near Bristol, a loud bang was heard, the helicopter became 'very unsteady' and began to descend. The pilot declared a Mayday, immediately entered autorotation and turned towards the coast. It was apparent to him that he could not make landfall, but at about 500 feet he tried opening the throttle and then realised that the engine would still produce power, although this was accompanied with violent vibration. By raising the collective control lever, the pilot was however able to clear a sea wall and land in an adjacent field. After reporting on the RT to Bristol ATC that he was on the ground, due to the poor radio reception another helicopter was asked to overfly the location and was able to confirm that the

helicopter had carried out a successful forced landing. A police unit attended the scene a short time later.

Subsequently, a local licensed engineer called to examine the helicopter discovered a hole in the top of the engine cooling air scroll, and that one of the twelve cooling air impeller attachment bolts was missing. There was evidence that this bolt had struck the underside of a lip on the main gearbox and that the remaining attachment bolts were all loose. The maintenance instructions for installing an impeller onto the engine starter ring gear state that it should be loosely fastened initially at four equally spaced positions using the appropriate bolts, washers and nuts. After installing the remaining bolts, every fifth nut in a clockwise progression, starting at the 12 o'clock position, should be tightened to a torque of between 90 and 100 inch-pounds, following which all torques should be re-checked. The instructions also required that a check be made to ensure that a minimum of two full threads on each bolt extend past the end of the nuts, that the nuts have not 'bottomed-out' on the bolt shanks, and that after 100 hours of operation the torque setting on all the nuts be re-checked. In an open and frank conversation with the maintenance organisation which installed the replacement impeller, it appeared that the nut tightening sequence described above was inadvertently omitted, and not detected, during the Star/Annual check. Since this accident, the organisation concerned have discussed their maintenance practices with the CAA and have taken steps to improve their procedures.