

DC-8-62F, 9G-MKH

AAIB Bulletin No: 5/2000 Ref: EW/C99/07/07 Category: 1.1

Aircraft Type and Registration:	DC-8-62F, 9G-MKH
No & Type of Engines:	4 Pratt & Whitney JT3D-7 turbofan engines
Year of Manufacture:	1971
Date & Time (UTC):	20 July 1999 at 1104 hrs
Location:	Manston, Kent International Airport
Type of Flight:	Public Transport (Cargo)
Persons on Board:	Crew - 3 - Others - 5
Injuries:	Crew - None - Others - 1 Serious, 4 Minor
Nature of Damage:	Deformation of fuselage structure adjoining nose gear bay; nose gear doors, and nose gear components; minor damage to fuselage skins adjoining cargo and forward entrance door
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	N/A
Commander's Flying Experience:	N/A
Information Source:	AAIB Field Investigation

Introduction

The aircraft operator routinely operated DC-8 cargo flights into Manston. Because of space restrictions on the stand, the normal practice with the DC-8 was for the aircraft to position on the taxiway after landing and for a tug to manoeuvre the aircraft thereafter, the aircraft being finally pushed back onto the parking area. On the day of the accident, the aircraft had landed normally and had positioned as usual on the taxiway where it was met by the tug. A DC-8 nose landing gear ground lock pin, carried for the purpose on the tug, was then installed and the aircraft was towed without incident before being pushed back onto the stand. The nose landing gear pin was then removed by the tug crew, the tow bar disconnected from the nose leg, and the torque link reconnected. The tug then departed and unloading of the cargo began.

The ground staff involved in the unloading operations were assisted by the loadmaster from the inbound crew, and also by a second loadmaster who was scheduled to position with the aircraft

to Luxembourg, upon departure from Manston. The latter supervised and also assisted with the movement of palletised cargo from within the cargo space on the main deck to the L1 cargo door on the forward left side; the former sat in the forward vestibule area completing his paperwork. The operator maintained a small ground engineering organisation at Manston, to carry out turn-around checks on company aircraft, and to undertake routine line maintenance as required. During the turn-around period in question, there was a total of four ground engineers working on the aircraft whilst it was being unloaded. These comprised: two airframe/engine licensed engineers whose tasks included routine checks of the hydraulic fluid reservoir and checks on the No 3 engine constant speed drive (CSD), which had been the subject of an entry in the Technical Log; a supervisor; and an avionics engineer who was making an unscheduled change to a global positioning system (GPS) unit on the flight deck.

Sequence of events

The inbound flight crew vacated the aircraft in due course, and the outbound crew boarded. The flight engineer immediately positioned himself at his station on the flight deck and thereafter, throughout the relevant period, was occupied almost exclusively with the re-fuelling of the aircraft and balancing of the fuel load. The first officer (FO) was unable to occupy his seat upon boarding because it was occupied by the avionics engineer, who was busy changing the GPS unit which was situated on the right side of the pedestal, abutting the main instrument panel and immediately beneath the landing gear selector lever. On seeing this, the commander left the flight deck so as to keep out of the way of the avionics engineer, and the FO checked the Jeppesen library for the same reason. The problem with the GPS, as it had been diagnosed originally, required a replacement memory card but the card which had been supplied for the purpose was for a different model of GPS unit, and was not compatible. It had been decided, therefore, to change the whole GPS box for a type which was compatible with the replacement card, the two types of unit being comparable in all other respects. The avionics engineer reported that having pulled the circuit breaker powering the GPS system, he prepared to remove the GPS unit but was prevented from doing so by the position of the landing gear selector lever. He had changed GPS units previously on DC-8-50 series aircraft without such a problem. However, the landing gear lever on the DC-8-60 is significantly longer than on the -50 series, and in the DOWN position the end of the lever physically prevented the GPS unit from being lifted clear of its housing.

The hydraulic systems were unpressurised at this time, and the avionics engineer decided that he would have to raise the landing gear lever out of the DOWN position sufficiently to allow the GPS unit to be lifted clear. Before doing so, however, he left the flight deck and inserted ground lock pins into all three landing gears, using the aircraft set of pins. He then returned to the flight deck where he pulled the gear lever out of the DOWN detent and, lifting it just sufficiently to provide the necessary clearance, removed and replaced the GPS box. So far as he could recall, he then returned the landing gear lever to the DOWN position, in its detent, before resetting the associated circuit breaker and checking the operation of the GPS unit. He then left the flight deck, retrieved the pins from the landing gears, and returned them to their stowage on the aircraft before moving to the back of the flight deck, where he stood waiting. Meanwhile, the commander and FO had re-entered the flight deck and resumed their seats. Neither pilot recalled the position of the landing gear lever at this time, although the FO did recall seeing that the GPS unit was lit; thereafter, his attention was focused on the overhead radio panel, which was of a different configuration to other aircraft in the fleet. The flight engineer had remained at his station throughout, occupied with his re-fuelling tasks.

Shortly after the flight crew had re-entered the flight deck, the ground engineering supervisor boarded the aircraft having been asked by the engineers servicing the hydraulics reservoir to restore hydraulic power, so that the associated main landing gear door could be closed. (The reservoir was located within the main wheel well and the gear door had to be lowered, using a service panel control valve, to gain access.) Upon entering the flight deck the supervisor announced his intention, saying *OK to put the hydraulics on?*, or words to that effect. Although the pilots each recalled mention having been made of hydraulics, neither gave explicit permission for hydraulic power to be brought on line; however, the request was not refused. (The flight engineer was still occupied with re-fuelling at this time, and did not recall any mention of hydraulics.) The supervisor then selected the auxiliary (electrically powered) hydraulic pump to ON using the switch on the flight engineers overhead panel. Some 20 to 30 seconds later, the nose landing gear retracted and the nose dropped violently to the ground. The commander immediately looked across and saw that the landing gear lever was in the UP position. He therefore moved it back to the DOWN position, and instructions were given to put the ground lock pins in the main landing gears.

Injuries sustained

The sudden dropping of the nose onto the ground resulted in those standing on the flight deck (ie the avionics engineer and the supervisor) being thrown violently off their feet. A scream was also heard from the main deck, and the avionics engineer immediately moved back to investigate. However, having reached the vestibule area, he was suddenly overtaken with extreme back and neck pain, and found himself unable to continue. The scream had emanated from the loadmaster who had been involved in moving the palletised loads into the L1 doorway, and who had been standing between the pallet being moved and the forward cabin bulkhead when the nose landing gear had collapsed. When the nose had suddenly dropped, he found himself against the bulkhead with the pallet, which weighed approximately 2 tonnes), sliding towards him. With his back against the bulkhead, he had brought one knee up in front of him in an effort to brace himself against the approaching pallet, however the pallet drove his knee back, dislocating his hip.

He was subsequently taken to hospital where he underwent an operation to re-locate his hip. He then spent four weeks in traction, followed by six weeks physiotherapy. The avionics engineer was also hospitalised for three days, having suffered bruising of his lower spine and whiplash injuries to his upper spine. The supervisor attended hospital as an outpatient, for assessment of whiplash type injuries. In addition, two ground staff engaged in unloading operations also suffered minor injuries. One of them had been ahead of the pallet, and was pushed forward through the L1 door into the forward vestibule, suffering bruising to his knee. The other, who had been positioned aft of the pallet and was pushing it forward while holding onto its netting, suffered a fractured thumb as the pallet suddenly moved forward. The engineer working on the No 3 engine had just stooped beneath the forward fuselage, and was making his way back across the apron when the nose fell to the ground.

Damage to the aircraft

The aircraft sustained major structural damage in the vicinity of the nose wheel bay, and to the nose gear doors. In addition, a pivot housing which formed part of the weight-on-wheel sensing mechanism on the nose landing gear had fractured, and the fuselage skin suffered minor damage in several areas caused by contact with ground equipment as the aircraft shifted.

Technical investigation

The nose landing gear retracts forward and consequently, in the event of a retraction on the ground, there would be minimal loading on the retraction actuator even with the weight of the aircraft resting on the gear, due to the ability of the nose wheels to roll freely forward. Retraction of the nose landing gear would therefore have been expected if, with no ground lock pin installed, the system was selected to UP with the hydraulic system pressurised. (The main landing gears retract sideways, and consequently they would not be likely to retract, due to the lateral resistance from tyre friction.) A typical delay period before an unpressurised system reaches a working pressure, after switching on the auxiliary pump, is of the order of 20 to 30 seconds. In this accident the landing gear ground lock pins had been removed and the nose landing gear retracted some 20 to 30 seconds after the auxiliary hydraulic pump had been energised. Immediately afterwards, the landing gear lever was observed in the UP position. The evidence therefore indicated that the nose landing gear had been retracted by the retraction system, as a result of the selector lever having been in the UP position.

The design of the landing gear and related systems on the DC-8-60 is such that the action of pulling the landing gear lever back to disengage it from the DOWN detent will change the state of a set of microswitches in the gear indicator light circuit, causing the three gear down-and-locked green lights to extinguish, and the single gear in transit red light to illuminate; no warning horn should sound. Both the green and red landing gear lights are positioned close by the landing gear lever. If, therefore, the gear lever had been out of position, and this had not been noticed by any of those on board, it is conceivable that an abnormal gear indication would have also gone unnoticed.

Consideration was given as to whether it would have been possible for the landing gear lever to have moved from the fully DOWN position to the UP position as a result of jarring when the nose dropped to the ground. Such a scenario presented several problems, however, not least of which was the fact that the lever would have had to overcome not only the positive-lock detent at the DOWN position (which required a deliberate outward pull on the lever to clear the detent), but it would then have had to bypass a mechanical baulk which stops the lever moving out of the DOWN position whenever the aircraft is on the ground and the weight-on-wheels sensor is in ground mode. The weight-on-wheels system used a mechanical cable, mounted on the gear itself, which moved in response to oleo extension and activated a mechanical baulk at the landing gear lever quadrant. This baulk could be bypassed only by depressing a large button adjacent to the gear lever. Part of the weight-on-wheels cable mechanism had fractured, but detailed investigation revealed that all of the associated damage had been caused by contact with the nose landing gear doors as the fuselage under-side had struck the ground, i.e. the damage had occurred after the retraction process had begun. Consequently, the damage to the cable system could not have compromised the effectiveness of the baulk prior to the retraction process being initiated. Furthermore, the baulk mechanism at the gear selector quadrant was spring loaded into the baulk-engaged position, and relied on cable tension to remove the baulk; consequently, any failure of the cable/lever mechanism would have caused the system to revert to the baulk-engaged state. Tests carried out on the actual baulk engagement mechanism showed that it was wholly effective in blocking movement of the landing gear selector lever.

It was established by testing in situ that the retraction system control valves, which were operated by the landing gear selector via a system of cables and pulleys, were correctly rigged with no tendency for hydraulic fluid to be ported to the UP lines prematurely. It was also established that the lever had to be moved almost fully upward, beyond the check detent (a detent position just below the UP position, where both UP and DOWN circuits are vented to system return) before the UP line of the nose landing gear was pressurised. Consequently, for movement of the lever to have caused the retraction, it would have been necessary not only for it to have moved out of the

positive lock detent at DOWN, but then to have breached the ground mode baulk, and finally to have moved upward through the check detent position virtually into the fully UP position. On the evidence, therefore, it did not appear possible for the lever to have moved by itself from the fully DOWN position to the almost fully UP position.

Investigation into the amount of clearance needed to lift the GPS box out of its housing in the pedestal showed that in order to gain sufficient clearance, it was necessary for the landing gear selector lever to be raised well beyond the ground mode baulk, almost as far as the check detent. The avionics engineer did not recall depressing the baulk release button when he moved the lever, but he agreed that the lever must have moved beyond the baulk position in order for him to have been able to change the GPS unit. Anecdotal evidence suggested that quite large changes of nose legoleo extension can take place during cargo loading and unloading operations, caused by changes in aircraft centre of gravity as the cargo is moved. It would appear possible, therefore, that the nose landing gear weight-on-wheel system could make transient changes of state, between ground and air mode, at such times. It would also appear possible that such a change might have occurred whilst the avionics engineer was working on the GPS. If this had been the case, and if the moment when the avionics engineer had lifted the landing gear lever happened to coincide with a period when the system had reverted briefly to their mode, then the baulk would have been withdrawn already, and consequently there would have been no impediment to his moving the lever sufficiently to allow him to remove the GPS box, without any need for him to first depress the baulk release button.

Experimentation after the accident with the landing gear selector lever in different positions in its gate showed that once the lever had been lifted sufficiently to allow removal of the GPS box, it would occasionally start to creep upward, imperceptibly at first before accelerating rapidly and jumping into the check detent position. This detent did not provide a positive stop to the lever, and it was therefore possible to conceive of a situation where, if the lever was moving rapidly enough into the check detent, it might over-run the detent and reach a position on the far side where hydraulic fluid was directed to the gear-up lines. In short, it appeared possible for the lever, having first been raised sufficiently to permit removal of the GPS box, to have moved subsequently, without further intervention, into a position which would have resulted in a retraction of the nose landing gear when the hydraulic system became pressurised.

Human factors issues

The investigation identified a lack of coordination between the various personnel working on the aircraft during the turn-around, and a commensurate failure to fully supervise or control the various activities taking place.

The engineering ground staff were nominally under the supervision of the ground crew supervisor. However, whilst the latter was aware of the routine activities being carried out by the airframe and engine technicians, he had not himself tasked the avionics engineer with carrying out the GPS change. This tasking had been carried out indirectly through one of the engine/airframe technicians who, in the absence of the supervisor, had telephoned the company's technical control department earlier that morning from the hotel where he and the rest of the ground staff were temporarily residing, to ascertain whether there were any particular instructions for the Manston team. He, in turn, had then passed on the GPS tasking to the avionics engineer. (It is possibly significant that the company's Manston engineering base had been established for only a short time before this accident, and was staffed by personnel originally based at Stansted and living in temporary hotel accommodation at Manston. The supervisor usually also stayed at this hotel, but on

the morning in question had been travelling down from his home near Stansted, where he had spent the night; consequently, he was not directly involved in tasking the avionics engineer).

The supervisor reached Manston in good time for the arrival of this aircraft, and he was aware of the routine turn-around tasks being carried out by his engineers on the aircraft. In principle, the avionics engineer also came under his supervision; however, whilst the supervisor was aware that this engineer was working on the GPS unit, he did not know that this involved removal and replacement of the GPS box or, more importantly, that it would require the landing gear lever to be moved. Indeed, none of the other ground engineers or the flight crew were aware that the landing gear lever was to be moved. The implications of pressurising the hydraulic system were therefore not apparent to the supervisor, the ground engineer who had asked this of him, or the flight crew.

The accident occurred at a time when the aircraft was partly under the control of the flight crew (with the flight engineer actively controlling re-fuelling operations from the flight deck) and partly under the control of the ground supervisor. It was also being worked on independently by other ground staff engaged in offloading the cargo. Arguably, therefore, lines of demarcation and control were blurred. Although the supervisor sought permission from the flight crew to pressurise the hydraulic system, it was apparent that his request took the form of an open statement to the effect that he was proposing to carry out this action, effectively relying upon a countermand from any crew member who might object, rather than a request *per se*. The flight crew evidently presumed that the supervisor knew what he was doing, and being unaware themselves that the gear lever had been moved shortly before, said nothing to prevent him from pressurising the system. Had the supervisor, or any member of the flight crew, been aware of the true situation then it is most unlikely that the system would have been pressurised without checks being made first to ensure that it was safe to do so.

So far as the avionics engineer was concerned, his tasking had been carried out in an informal manner and he had no worksheet or written procedure to follow. Not having removed a GPS unit from a DC-8-60 aircraft before, he did not anticipate having to move the landing gear lever out of the DOWN position, and found himself having to improvise. It is often the case that, in practice, avionics engineers work independently of their airframe/engine colleagues and it is possible that this cultural separation may have contributed to the avionics engineer's failure to involve the supervisor, or indeed any of the other engineers, even though he was disturbing systems outside his normal area of responsibility or expertise. The fact that the flight crew had previously entered the flight deck only to leave it again, albeit with the best of intentions to allow him to replace the GPS unit, may also have been a factor by possibly indirectly putting pressure on him to finish his task without undue delay. Under such conditions, he is less likely to have sought advice or the involvement of the supervisor, or from one of the airframe/engine technicians; or to have sought more formal guidance on the correct procedure to follow.

Safety action

These aspects were drawn to the attention of the Operator at an early stage of the AAIB investigation, and the company also carried out its own independent internal investigation. The company subsequently reported that it had taken the following actions in the light of this accident:

Steps were taken to clarify and explain the terms of reference of the engineering supervisor, and the responsibilities of all individuals engaged on turn-around duties.

A Quality Notice was raised to address the problem caused by the need to move the landing gear selector lever when changing a GPS box on DC-8-60 series aircraft

The implications of modifications will in future be subject to scrutiny by a Modifications Committee.

A Quality Notice was raised addressing the procedures to be adopted for checking the correct positions of aircraft controls and indications prior to the application of hydraulic power.

The procedures covering control of the GPS Data Card system were reviewed by the Operations Department and, with the involvement of the Technical Records Supervisor, were revised. A Notice to Crew on this subject was raised.