

Cessna 421, G-BKNA

AAIB Bulletin No: 1/98 Ref: EW/C97/8/1 Category: 1.2

Aircraft Type and Registration:	Cessna 421, G-BKNA
No & Type of Engines:	2 Continental GTSIO-520-D piston engines
Year of Manufacture:	1968
Date & Time (UTC):	3 August 1997 at 1521 hrs
Location:	Near Shobdon Airfield, Herefordshire
Type of Flight:	Private
Persons on Board:	Crew - 2 - Passengers - 2
Injuries:	Crew - Fatal - Passengers - 1 Fatal, - 1 Serious
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	53 years
Commander's Flying Experience:	2,386 hours (last recorded log book entry 24 November 1996) Last 90 days - Unknown Last 28 days - Unknown but included 19 hours on type
Information Source:	AAIB Field Investigation

History of the flight

The aircraft was on a private flight from Elstree to Shobdon in Herefordshire. The meteorological forecast indicated that a warm front was approaching Southern England from the south-west and conditions were generally deteriorating. The visibility on departure from Elstree at 1437 hrs was greater than 10 km with a broken cloud base at 2,500 feet. When the aircraft arrived at Shobdon the visibility was estimated to be 3 to 4 km in light drizzle with a cloud base at approximately 1,200 feet, and the surface wind was 090_ /5 kt. The first radio contact between the aircraft and Shobdon was made at about 1502 hrs when the pilot called to say that he was inbound from Elstree. In response to this call he was passed the airfield details. The pilot later called when approaching Leominster and subsequently called downwind for Runway 09 which has a right-hand circuit. The

operator of the ground to air radio facility at Shobdon saw the aircraft on the downwind leg abeam the tower at what appeared to be a normal circuit height. He did not observe the aircraft downwind but shortly afterwards he heard a brief and indecipherable radio transmission which sounded like a scream. This same transmission was heard by an aircraft enthusiast who was monitoring the radio transmissions on his 'airband' radio. The radio operator repeatedly attempted to make contact with the aircraft but to no avail and so he instructed an aircraft refueller to inform the emergency services that an aircraft had crashed.

Analysis of recorded radar data from the radar head at Cleve Hill, Shropshire, indicates that the aircraft joined the downwind leg from the east at a height of 1,100 feet. This radar data shows that the aircraft then followed a normal ground track until towards the end of the downwind leg when there was an alteration of track to the left of about 20° before the aircraft entered a right turn onto the base leg. At the same time as the aircraft altered track to the left it began a slow descent, at about 350 ft/min, from 1,100 feet to 600 feet, at which stage it disappeared below radar coverage. The average ground speed on the downwind leg was 112 kt and this reduced to 100 kt as the aircraft descended.

Two witnesses saw the aircraft in a position that equates to the base leg. The witness to the east of the aircraft track first heard the sound of an aircraft engine that was unusually loud and then saw the aircraft at an estimated height of 150 to 200 feet, it was descending slowly with the wings level. A loud "cough" from one of the engines was heard "as if it had backfired" followed by a puff of white smoke and then the sound of an engine increasing in RPM. The wings were then seen to rock from side to side as the aircraft went out of sight. The second witness, to the west of the aircraft track, described the aircraft flying very low, between 50 and 100 feet, and slowly descending. He saw that the wings were "wavering", the left wing then suddenly dropped until it achieved a bank angle of about 90° at which stage the nose dropped and the aircraft disappeared behind some low trees and was heard to hit the ground. Some local farmers immediately went to the crash site. Initially there was no fire or smoke, but a small fire soon developed in the area of the right wing and this was quickly extinguished by the farmers.

Background to the flight

The aircraft was owned by a company based at Barton Airfield in Lancashire and the pilot involved in this accident was flying the aircraft on their behalf with the intention of selling either the aircraft or shares in it. On 24 November 1996 he had recorded a total of 2,386 hours flying of which 897 hours were on twin engine aircraft the majority of which had been on the Grumman Cougar. Thereafter there were no further entries in his Flying Log book. He had collected the aircraft on 18 July 1997 prior to which he had flown the aircraft three times in the previous two months for a total flying time of 2 hours, since then he had flown the aircraft from Elstree for a further 17 hours. He occupied the right-hand seat for the accident flight, although he was the pilot in command of the aircraft.

The pilot in the left-hand seat was flying the aircraft with a view to buying shares in its use. He held an Australian Private Pilot's Licence (PPL) and had limited flying experience. At the end of December 1996 he had declared a total of 280 flying hours and his only recorded time in a twin engine aircraft had been in 1995 when he logged 5 hours and 42 minutes under instruction and 6 minutes as pilot in command. There is no record of any flying after December 1996.

Aircraft fuel system

The fuel system on this aircraft consisted of a main tank and an auxiliary tank associated with each engine, the fuel selector also allowed fuel from a main tank to be fed to the opposite engine. The main tanks were located in each wing tip and the auxiliary tanks were in the main wing structure outboard of each engine. The usable fuel was 189 litres (50 US gallons) in each main tank and 182 litres (48 US gallons) in each auxiliary tank; thus the total usable capacity was 742 litres (196 US gallons).

On the day prior to the accident the aircraft had been refuelled with 60 litres of fuel into each main tank. There was no record of the fuel tanks having been completely full in the recent past. With the errors involved in attempting to produce accurate estimates of the fuel consumption since then, the resultant figures are likely to have been highly inaccurate, therefore, the exact fuel status prior to and after this refuelling is unknown. The pilot flew to Ostend, Belgium for an overnight stay; a flight time of 51 minutes. Whilst at Ostend he did not refuel, although he did buy 2 litres of engine oil. On the return flight to Elstree on 3 August 1997 he was airborne for 1 hour 46 minutes after which he refuelled with 50 litres into each auxiliary tank. The aircraft then crashed 45 minutes after take off from Elstree. Using a fuel flow of 110 litres per hour for these three flights, and allowing for each take-off and climb to 5,000 feet with the subsequent circuit to land, a fuel consumption of about 445 litres is calculated.

Medical aspects

The post-mortem examination on both pilots did not reveal any indications that drugs or alcohol had played any part in the event, however, both pilots had considerable pre-existing disease.

The pilot in command had high blood pressure, which was being treated, but there was some doubt about his compliance with his treatment. There was also evidence of coronary artery disease and he had previously suffered a heart attack.

The Australian pilot did not have a valid medical certificate and therefore was not permitted to fly as a pilot. His medical certificate had not been valid beyond 10 December 1996 since he had not complied with the requirements of the Office of Aviation Medicine, Civil Aviation Safety Authority of Australia. He was a very large man, 195 cm tall and weighing 148 kg.

It was not possible to define the precise role, if any, of the medical condition of either pilot in this accident. However, with a large person in the left-hand seat it would have been difficult for either pilot to monitor and operate the fuel selector switches, which were located on the cockpit floor between the seats.

Engineering information

The aircraft was manufactured in 1968 and had been imported from France in November 1984 when it had accumulated 3,249 flying hours. It was registered in the Private Category. The last entry in the log book recorded that on 18 July 1997 the aircraft had completed a total of 3,348 flying hours, an average utilisation of some 7.6 hours per year since its importation.

The aircraft had crashed in a level grass field, its heading was 285° and the flaps and landing gear were up. The aircraft was rolling to the left with the wings near the vertical and was descending at an angle about 30°. The left tip tank made the first contact with the ground and the aircraft had then cartwheeled across the field before coming to rest across a minor road 135 feet beyond the first impact point.

The disruption of the left wing tanks spread some fuel over a 60° arc from the impact point to a distance of approximately 80 feet, the fuel spill was identified by a discolouration of the grass, but the amount of fuel could not be assessed from the groundmarks.

Both propellers had separated as they struck the ground. The left-hand propeller blades were relatively undamaged and did not show any chord wise scoring indicative of rotation, likewise there was no blade tip damage. Note: The propeller is geared to rotate at 75% of the engine speed and will not windmill at low aircraft speed. The right propeller showed signs of rotation and had light damage to two blades; there was a small amount of forward curl on the tip of one of the blades consistent with engine power at impact.

Both engines, the left tip tank, and the rear fuselage had been detached from the fuselage by the impact sequence. A ground fire had developed under the right engine nacelle and had melted some aluminium in that local area. The fire had spread under the aircraft, blackening the under surfaces of both wings and the fuselage, and had burnt out the right tip tank. Reports indicated that the fire had been extinguished by a hand held extinguisher. The amount of fuel consumed in the fire was assessed as being relatively low. About 5 litres of fuel remained in the right wing.

The aircraft and engines were examined at Farnborough by the AAIB with the help of representatives from the aircraft and engine manufacturers. Examination of the engines showed that, at impact, they had been mechanically and electrically capable of running; the left engine was stationary and the right engine was underpower at the time of the accident.

A check of the flying controls did not reveal any damage other than that caused by the accident. The control trim positions found were:

Elevator: Unreliable reading, outside normal range.

Rudder: 4° tab left (maximum position 26°).

Aileron: 10° up position. (maximum position 21°).

Both fuel selector *valves* were found in the off position, however the selector *controls* inside the cockpit showed: left engine selected to right main tank; right engine selected to an intermediate position between right main and right off. The difference in position between selectors and valves was attributed to movement of the linkages between the fuselage mounted selector controls and the wing mounted control valves caused by flexure of the wing/fuselage area, and was identified by the Cessna representatives as a common feature found in Cessna 421 aircraft which have cartwheeled. The selector position prior to the accident could not be reliably determined.

The left-hand auxiliary fuel pump switch had been destroyed in the impact, leaving only the damaged toggle. It was not possible to determine which position the switch had been in before impact.

Although some fuel had been in the left wing at the time of the accident, examination of the diaphragm bulkhead in the front of the left tip tank did not reveal any distortion due to hydraulicing, which would have occurred on impact if a significant quantity of fuel had been present in that tank. A similar lack of distortion was evident in the right-hand tip tank.

Recollections of the survivor

At the time of the accident the sole survivor had been seated behind the pilot in the right-hand seat and was facing aft with his lap strap secured. He suffered significant injuries to the head and was not interviewed until 5 weeks after the accident at which stage he was still affected by trauma. He had approximately 1,000 hours flying experience of which about 500 hours were on twin engine aircraft. Most of this flying had been completed at Elstree and he had known the pilot in command of the accident aircraft for about 8 years.

The survivor has very little firm recall of events on the day of the accident and was very keen to differentiate between those memories that were definite and those that were less so. However, he did have some vague recollections of the flight which are summarised here.

He believes that the weather at Elstree was cloudy prior to departure but that it was a reasonable day for flying. His next recollection was that whilst downwind at Shobdon the left engine surged and then stopped. The pilot in command (right-hand seat) then tried to crossfeed fuel to the left engine; he does not recall which tanks were in use. At this stage the pilot in the left seat was flying the aircraft. The survivor believes that he looked out of the window and saw that they were flying very low over a rural landscape with some trees and open farmland. The weather was overcast with grey clouds and it was raining. The speed was low, the stall warning horn was operating and the aircraft suddenly entered a spiral to the left. He had no recollection at all of the impact but whilst in hospital he had told his mother that he remembered somebody screaming, however, at the time of the interview he could no longer remember this event. He also had the impression that there was not very much fuel on board and that the intention had been to refuel at Shobdon.

Some elements of this recollection can be verified. His description of the weather at Elstree and Shobdon are correct as is the stage of flight and the countryside in which the aircraft crashed. His memory of flying low is substantiated by the two witnesses one of whom saw the aircraft roll to the left. Furthermore the engineering evidence demonstrates that the left propeller was stationary at impact and that there was very little fuel in the aircraft.

Summary

Examination of the engines showed that they had both been mechanically and electrically capable of running, however, at impact the left engine was stationary. It was also likely that there was very little fuel onboard the aircraft at the time of the accident. It is therefore probable that mismanagement of the fuel system caused the left engine to stop. The eye witness accounts are consistent with the behaviour of a twin engine aircraft that has suffered a failure of one engine and is flown below its minimum control speed for flight on one engine. With a low power setting on the right (live) engine the speed was allowed to reduce further until the left wing stalled. There was then insufficient height available to regain control of the aircraft.