

Messerschmitt BF109G-2, G-USTV

AAIB Bulletin No:5/98 Ref: EW/C97/10/1 Category: 1.2

Aircraft Type and Registration:	Messerschmitt BF109G-2, G-USTV
No & Type of Engines:	1 Daimler-Benz DB 605A piston engine
Year of Manufacture:	1942 (Rebuild completed 1991)
Date & Time (UTC):	12 October 1997 at 1600 hrs
Location:	Duxford Airfield, Cambridgeshire
Type of Flight:	Air Display
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Substantial
Commander's Licence:	Basic Commercial Pilot's Licence
Commander's Age:	54 years
Commander's Flying Experience:	4,612 hours (of which 18 were on type) Last 90 days - 23 hours (including 1 hour on type) Last 28 days - 22 hours (including 1 hour on type)
Information Source:	AAIB Field Investigation

Accident Flight Profile

The aircraft was performing in a flying display at the Imperial War Museum's Autumn Air Show at Duxford. The aircraft took off normally from the grass Runway 24 and cleared the display area while a Spitfire aircraft performed a solo aerobatic display. It was then joined by GUSTV for a coordinated display sequence. The Spitfire then landed and G-USTV performed its planned solo aerobatic display. As the aircraft travelled from east to west along the display line, it pulled up into its penultimate planned manoeuvre, a 'half Cuban', during which a plume of white vapour became apparent streaming from the aircraft. A second similar white trail was noted as the aircraft recovered to the upright attitude and positive 'g' was applied to pull out of the dive at the completion of the manoeuvre (Figure 1). The Aerodrome Flight Information Service Officer (AFISO) advised the pilot by RTF that "there was white vapour trailing from the rear of the aircraft". The pilot acknowledged this information. Power was then reduced and the aircraft carried out a descending turn away from the crowd and into a short right-hand circuit to the south of the airfield. It was positioned for a landing on the grass Runway 06, which has a landing distance available of 890 metres. The aircraft

arrived over the airfield boundary somewhat higher and faster than normal. A touchdown was achieved on the main landing gear. The aircraft was travelling too fast for the brakes to be applied without the risk of nosing over and it was unable to stop within the remaining runway distance. The pilot therefore elected to lift off and climbed sufficiently to cross the M11 motorway which lies almost perpendicular to the runway direction adjacent to the eastern boundary of the airfield. Fortunately the aircraft was high enough to avoid any collision with vehicles on the motorway and the pilot managed to touchdown in a tail-down attitude in the field just to the east side of the motorway. The field had an unprepared grass surface and the aircraft initially rolled out normally. However, the field had been partly ploughed and once the aircraft ran onto the ploughed section, it nosed over at slow speed and came to rest inverted (Figure 2).

The pilot was unable to vacate the aircraft because the canopy was jammed closed with the aircraft inverted. Fuel was leaking around the cockpit area but fortunately there was no fire. Fire Service Rescue crews were on the scene quickly but the pilot requested that the aircraft be lifted rather than cut open in order to prevent further damage to the fuselage structure or risk to himself. A crane was brought from the airfield in order to lift the aircraft so that the pilot could be released from the cockpit.

Pilot's Debrief

The pilot holds a CAA Display Authorisation which includes flying in G-USTV and is a Display Authorisation Evaluator. He had a total of 18 hours flying experience on G-USTV gained over a period of 6.5 years since the second flight of the aircraft after its restoration to flying condition. The pilot had flown between four and seven sorties in the aircraft during each of the summer display seasons in the intervening years. The accident flight was the pilot's fifth flight in the aircraft during 1997, a total of 2 hours 20 minutes flying. Interspersed with this, in addition to his military flying, the pilot had also flown about 70 types of historic and light aircraft types including, most recently, Spitfires, Sea Hurricane and Yak-50. He is also an experienced glider pilot.

The pilot indicated that he had operated the aircraft with the cooling radiator shutters in AUTO (noted in the Flight Reference Cards as "at 12 o'clock - set 'AUTO' throughout the accident flight. The coolant temperature, engine oil temperature and oil pressure were checked prior to the first run in for the display and were found to be normal, with both the oil and coolant temperatures being about 80°C. The engine exhibited a brief period of harsh running as power was increased at the commencement of the display, but the pilot had experienced this sort of behaviour on previous occasions and discounted it as being of no significance. The display was flown with the fuel boost pump on, the propeller pitch control set to automatic and a standard mean boost setting. The engine performance was normal during the display until the aircraft was inverted during the half Cuban manoeuvre. The pilot recalled that, at this time, the cockpit filled with a blue haze accompanied by the smell of hot oil.

Power was reduced and the half roll to complete the manoeuvre was extended to a descending turn away from the crowd and towards a downwind position for Runway 06. The pilot recalled that the propeller pitch indicator was cycling rapidly back and forth. He recalled with less certainty that the coolant temperature was 80 to 85 degrees C, but could not recall the oil pressure gauge reading. The oil temperature was not checked. On being throttled to idle, the engine ran very roughly, but picked up if power was increased. The smell of hot oil did not recur.

The propeller pitch control was set to manual and the pitch hunting subsided as the engine was throttled back. The pilot was somewhat confused by conflicting indications of engine status, but was

certain that an immediate landing was essential. He made the decision to make a forced landing with the gear down on the airfield grass runway with the throttle at idle, without reliance on further power application.

The pilot's judgement at the time was that the most probable cause of the problem was an oil leak, with the consequent expectation of an imminent engine seizure, the possibility of a fire and the expectation of a very poor glide performance in the event of an engine seizure. He was aware of the need to maintain a speed of at least 200 kph in order to ensure sufficient elevator authority for the landing flare in that event.

He also assessed that the crosswind component would tend to drift the aircraft away from the airfield. In the event, the engine continued to operate and the consequence of the allowances made was an extremely tight circuit pattern and an arrival over the landing threshold with considerable excess energy. To compound this situation, there was no headwind component to reduce the landing distance required. The pilot estimated that the initial touchdown occurred at around 220 kph, with 30° flap selected.

After the fast touchdown, the pilot realised that it would not be possible to apply the brakes and to stop within the remaining runway distance. Given his belief that a total engine failure was imminent, he did not attempt to go-around but concentrated on preserving energy and lifting the aircraft clear over the motorway embankment at the end of the airfield. He turned off the magnetos at this point and managed to complete the forced landing in the field on the east side of the motorway.

After the aircraft came to rest inverted, the pilot was aware of a strong smell of fuel. He switched off the fuel selector and battery master switch. The left cockpit window was opened, which admitted more light and air into the cockpit. The pilot's harness was kept fastened while rescue was awaited.

Aircraft Handling Information

The aircraft's Flight Reference Cards (FRC's) indicated that for Forced Landings, landing on unprepared ground with the landing gear down is not recommended. However, having overshot the landing strip the pilot had little choice but to land beyond the airfield with the landing gear locked down. The procedure also contained the instruction to touchdown at as low a speed as possible with the wings level and flaps fully down (40°). From previous flight test data, the stall speed of the aircraft in the landing configuration was around 140 kph (75 kt), with wing rocking occurring some 6 kt above this speed. The operation of the auto-slat system was noted as being smooth and unobtrusive with no appreciable pitch changes. The time taken to wind the flaps manually from up to the fully down position was about 22 seconds (commented upon as being a 'cumbersome' operation) and the time for the hydraulically operated landing gear lowering was 23 seconds. The aircraft limitations specify a maximum flaps extended speed of 250 kph.

The following paragraph covers the Circuit and Landing phase:

'Sufficient time must be allowed in the circuit for the undercarriage to lock down. Typically this can take 20-25 seconds or even longer if the speed is close to the 250 kph limit. Owing to the low pressure hydraulic system the u/c movement is influenced by air loads on the gear and each leg may travel both down and up again before finally locking down. 220 kph is recommended as a suitable speed for lowering the u/c. Lowering of the manual flaps is also time consuming and should be done in concert with trimming aft. Prior to landing, the propellers should be set to 11:30 and the boost

pump turned on. The u/c down button should be pulled out once the u/c has locked down. The final turn should be flown at 200 kph, tapering to 175 kph at the threshold. The view is acceptable provided a slightly curving approach is flown. 175 kph will yield a short float. The aim should always be a 3 point landing and attention must be paid to touching down without drift and maintaining firm directional control throughout the landing roll.'

Advice sought from the engine specialists within the Messerschmitt Restoration Group (MRG) indicated that the propeller pitch change mechanism on this aircraft is slow in operation and is partly commanded by throttle lever angle rather than engine RPM. Consequently, rapid changes of lever angle may result in propeller pitch destabilisation and cycling. Rough running may also be experienced under certain combinations of throttle lever movement, airspeed and propeller pitch angle.

Meteorological Information

An aftercast from the Met Office indicated that, at the time of the accident, the surface wind was from 330° at 10 kt, variable between 310° and 350°, visibility greater than 10 km, with scattered to broken cloud above 3,000 feet. The temperature was +10°C.

With the prevailing surface wind and runway orientation of 06/24, the aircraft was subjected to a landing crosswind component of 10 kt, which is the maximum demonstrated crosswind component for landing on grass runways.

Video analysis

Video tape coverage of the aircraft's display was analysed. This showed that white vapour was trailing from the aircraft for a period of some five seconds during the pull up and some seven seconds during the recovery from the dive at the end of the manoeuvre. The white vapour appeared to be coming from the engine forward of the wing and dissipated rapidly. The manoeuvre took a total of about 32 seconds to complete, measured from a camera positioned about 2/3 of the way along the spectator line towards the western end of the airfield. The aircraft then turned away from the airfield onto a downwind leg. For some 11 seconds at the end of the downwind leg, the aircraft was banked slightly towards the airfield. A turn was then made onto a right base leg, then this was widened out with a bank away from the airfield for some four seconds, followed by a three second period of sideslip immediately before the aircraft was turned towards the runway. At this point the aircraft was already inside the airfield boundary. The initial brief touchdown occurred almost half way along the grass runway about 6 seconds after the aircraft was aligned with the runway axis. The total circuit from a beam the camera (after recovery from the final manoeuvre) to the first touchdown took 1 minute 46 seconds to complete. The aircraft speed, once aligned with the runway but prior to the first touchdown, was about 250 kph.

Aircraft History

Built under licence by Erla Maschinenwerk GmbH of Leipzig in the autumn of 1942 this aircraft, a Messerschmitt Bf 109G-2, wk.no. 10639, was allocated to a unit on the Eastern Front. This unit was transferred to Cyrenaica, via Italy, in late October of that year to support Rommel and the Afrika Korps. Within two weeks the aircraft, identified as 'Black 6', sustained some damage in combat against American P-40's and subsequently was ferried for repair to Gambut airfield south-east of Tobruk. The speed of the Allied advance, however, forced the abandonment of much equipment, including 'Black 6', and the damaged aircraft was subsequently discovered by No 3 Squadron

RAAF, who subsequently repaired and flew the aircraft. Before it could be shipped back to Australia as a 'war trophy' an order was received to despatch the aircraft, along with all available spares, to Lydda in Palestine for its overall performance to be assessed by the Allies. It transpired that No 3 Squadron had captured the first of the new G (Gustav) series and that the type was proving troublesome against Allied types, including the then current Spitfire Mk V. After further testing at Great Bitter Lakes, 'Black 6' was shipped to England to join the ranks of No 1426 Enemy Aircraft Flight at Collyweston in Lincolnshire where, after a brief overhaul, it was displayed to the press as RN228. Following the war the aircraft was placed in storage and apart from occasional appearances for static display and an abortive attempt at restoration, it remained there until the current MRG began work on the project in 1973. 'Black 6' next flew again on 17 March 1991 from RAF Benson. 'Black 6' had been the only airworthy example of a genuine German built Second World War Bf109 fitted with a Daimler Benz 605 engine, the type being built in greater numbers (in excess of 30,000 plus 24 prototypes) than any other aircraft and credited with more victories than any other fighter type in history.

Aircraft Operational Administration

The aircraft is owned by the Ministry of Defence but is on loan to the aircraft's operator and custodian, the Imperial War Museum Duxford. It is maintained on the civil register by the MRG and was operating under a CAA Permit to Fly. The operation of the aircraft is carried out under the terms of the Imperial War Museum Organisational Control Manual (OCM) for the aircraft, which has been formulated in accordance with the guidelines laid down in CAA document CAP 632, Arrangements for the Operation of ex-Military Aircraft on the UK Register with a Permit-to-Fly.

It was originally agreed between the various parties that the aircraft would be flown at displays for a period of three years, before becoming a static exhibit at the RAF Museum. This period was subsequently extended to five years, the accident occurring on the last planned flight of this extension.

A total of four pilots (all military personnel, but each also holding a civilian pilot's licence and CAA Display Authorisation) were nominated and approved pilots for G-USTV. While the OCM specified that each pilot would maintain a current civilian licence and current CAA Display Authorisation, it did not specify the method and content of any continuation training and the policy for handling in-flight emergencies. This was left to the discretion of the pilots involved. The pilot involved in this accident indicated that he had not recently practised the simulated engine failure/glide approach procedure on this aircraft.

Initial Examination

After the accident the aircraft was recovered from the field to a hangar at Duxford by lifting it, still inverted, onto a trailer where it was initially examined by the AAIB the following day. The aircraft's wings and tailplane were essentially undamaged but serious structural damage had occurred to the fin, rudder, rear fuselage and propeller. It was apparent at this time that the cooling flaps for both radiators were closed, the propeller was at a coarse pitch setting and the flaps were set symmetrically at 30°. (The flaps on this aircraft are manually positioned by a multi-turn handwheel located on the left sidewall of the cockpit, 40° being the maximum extension). There had been no fire. The airframe, particularly the fuselage, had been contaminated with earth, but there was no evidence of contamination by engine coolant (a 50/50 mix of ethylene glycol and water) or oil. A visual examination of the cockpit revealed little information of significance as most instruments had returned to their 'at rest' positions. The engine had been shut down, the propeller pitch gauge

indicated coarse pitch and the propeller control was set to 'manual'. The radiators cooling flaps rotary valve selector handle was found close to the automatic position, but not actually in the 'autom' detent.

Engine cooling system description

The powerplant in this aircraft was a Daimler Benz 605A 12 cylinder inverted 'V' supercharged liquid cooled piston engine. Heat generated by this engine is dissipated into the slipstream from two radiators, one located beneath each wing root towards the trailing edge. The cooling air flow is controlled by two hydraulic actuators which determine the position of the intake lip and upper and lower radiator flaps associated with each radiator. These flaps are controlled by the rotary selector valve, set by the pilot to one of four detented positions (Figure 3). Both radiator flaps move in association with the wing flaps. The valve settings are 'auf' (flaps fully open), 'zu' (flaps fully closed), 'ruhe' (flaps hydraulically locked at their current position) and 'autom'. It was found that it was necessary to position the rotary selector handle from the 'autom' legend by 16° in order to engage the detent. The difference between the 'as found' position and the 'detent' positions of the selector can be seen at Figure 3. When the flaps are at the closed position, and the wing flaps are retracted, the cooling flaps remain slightly apart, and maintain a minimum cooling flow through the radiators. The 'autom' setting provides for automatic modulation of the flaps position under the influence of a thermostat. This is installed in the coolant outlet pipework from the engine and normally regulates the engine coolant temperature to around 80°/85°C. At approximately 110°C, at low altitudes, the coolant may be expected to boil. The cooling system operates at elevated pressure maintained by a pressure relief valve which operates at approximately 1 bar. Any outflow of coolant from this valve is piped so as to discharge immediately ahead of the exhaust stubs on the right side of the engine, where it immediately vaporises, thereby indicating to the pilot in a direct manner that the engine has become too hot. Under these conditions it is reported that vapour may enter the cockpit although the pilot was not aware of this. The design and orientation of this relief valve are such that positive g assists the valve to open. Engine temperature is indicated to the pilot on a dual function gauge (Figure 4). This gauge normally indicates coolant temperature, unless the adjacent spring loaded button is pushed, whereupon oil temperature is displayed.

Detailed examination

After removal of the wings and tailplane, the fuselage was righted, and the engine removed. General visual examination of the aircraft by the MRG in conjunction with the AAIB at this time revealed no evidence of any pre-accident defects, or any significant engine or hydraulic oil leaks, coolant leaks, broken pipe/hoses etc, or failures within the cooling flaps operating mechanisms or water pump. All four radiator shutoff valves were found still wirelocked in the open position. A significant quantity of coolant was drained from the system components and the engine oil reservoir was found to contain a normal level of oil. The propeller was seen to be windmilling before the final touchdown on the far side of the motorway and, following its removal, the engine could be turned freely using normal effort and without evidence of distress. The visual appearance of the exhaust stubs and spark plugs examined shortly after the accident was consistent with normal combustion with no evidence to suggest that the engine had been burning oil. Also, as a borescope inspection of the valves and cylinders revealed no visible mechanical damage, it was decided that detailed strip inspection of the engine was not appropriate. However, should evidence of any unserviceability be discovered during any future engine re-build, this will be reported in a future edition of the AAIB Bulletin.

In order to establish the serviceability of the cooling system, the pressure relief valve, thermostat operated hydraulic valve, and the rotary selector valve were all removed and subjected to functional testing.

The pressure relief valve was tested using air rather than water, and shown to relieve at around 19/20 psig. A strip examination of this unit revealed the diaphragm and valve seats to have been in good condition, with no evidence of external leakage.

The thermostat/valve assembly was connected to a hydraulic supply and through appropriate ports to a slave actuator. When placed in a water bath whose temperature could be varied, the actuator began to retract at 75°C and was fully retracted at 85°C on rising temperature. On lowering, it began to extend at around 80°C and was fully extended at 65°C.

The detent mechanism associated with the rotary selector valve is integral with this unit, and was found to operate positively and smoothly between all four positions, which are set at 90° to each other. (When installed in the aircraft, however, the feel of the detent was less positive due to backlash in various joints between the handle and valve). On test it was established that hydraulic fluid ported correctly between the input and output connections, in accordance with the system diagrams in the maintenance manual, at all four detented positions. Tests were also carried out with the valve misaligned. This revealed that fluid flow through the valve was shut off if the input shaft was rotated 45° either side of the 'auf' or 'zu' detents, but the same effect could be achieved by a 20° rotation either side of the 'autom' detent. Between 15° and 20° misalignment, flow was severely restricted.

Additionally, the engine coolant temperature indicating system was tested and found to be accurate.

Analysis

In view of the findings of the detailed examination and the lack of positive evidence of a mechanical problem, a strip examination of the engine was not completed. Analysis of the video recordings of the aircraft's display suggested that the intermittent white exhaust trail occurred due to coolant discharge. The video recordings also indicate that the radiator cooling flaps were at the closed position from just after start-up to when the aircraft was lined up on the runway, but that they appeared to be open during the take-off and initial climb. However, as far as could be seen throughout most of the display these cooling flaps appeared to be near to the closed position, there being no doubt that both were fully closed during the attempted landing, almost two minutes after the cessation of the coolant discharge. Figure 1 compares the (reportedly) more typical open position of the cooling flaps during a previous display with their position towards the end of the subject display. In the absence of cooling system leaks it was considered possible that the pressure relief valve had opened, under the influence of positive g, when the engine coolant temperature had been rising above normal towards the end of the display.

Functional testing carried out on the primary engine cooling control components, and a more general examination of the system, failed to reveal any significant defects indicating that technical malfunction was unlikely to have been the cause of the overheating. Thus, if the selector valve had been set in the 'autom' detent throughout the flight, normal control of the cooling system would have been expected. However, if the 'as found' position of the cooling flaps rotary selector valve handle were its true position throughout the display (ie, aligned more closely with the 'autom' legend than when in the detent), and not been inadvertently knocked into that position during the accident or subsequent escape by the pilot, then the following sequence of events is indicated.

With the selector valve nominally at 'autom', but not in the detent (and hence the valve being displaced by about 16°), fluid flow between the rotary valve to the thermostat would have been severely restricted during this flight as demonstrated by tests on the valve. If this were the case then it might be expected that the cooling flaps would have remained shut on the ground until the engine warmed to its normal operating temperature following which, under the influence of the thermostat, they would open, albeit at a slower rate than normal. In a completely tight hydraulic system, with no internal leakage across piston and valve seals, normal pressure would eventually be developed at the actuators and the flaps would adopt the desired position against air loads. However, with a restriction through the rotary valve any such leakage would reduce the effective pressure in the actuators, and hence the flaps position against air loads, the level of reduction depending on the ratio between the rates of leakage and restricted flow through the rotary valve.

However, any overheating of the cooling system during the final manoeuvre would not explain the smell of "hot oil and blue haze" in the cockpit, as a result of which the pilot elected to make a forced landing.

At the time of writing a decision of the future of this aircraft had yet to be made. Should 'Black6' be returned to an airworthy condition then it will be possible to test the engine and the cooling flaps operating system, as a complete system. Should any relevant defects arise at that time, they will be reported upon in a future edition of the AAIB Bulletin.