

Aircraft Type and Registration:	Grob G109, G-BRCG	
No & Type of Engines:	1 Limbach L 2000-EBIA piston engine	
Year of Manufacture:	1981	
Date & Time (UTC):	6 March 2005 at 1230 hrs	
Location:	Pocklington Airfield, East Yorkshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - None	Passengers - None
Nature of Damage:	Substantial to landing gear, propeller and lower fuselage	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	49 years	
Commander's Flying Experience:	336 hours (of which 35 were on type) Last 90 days - 9 hours Last 28 days - 4 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

After an uneventful navigational exercise from Gamston, the pilot flew a shallower than normal approach to asphalt Runway 36 at Pocklington. The surface wind was 020°/10 kt and the runway was dry. The approach was flown at 60-65 kt with the throttle at idle and the airbrake marginally open; stabilising the approach on this type of motorised glider. At approximately 100 feet agl the aircraft sank rapidly. Although the pilot had time to retract the airbrakes his application of power was delayed as he had to change hands on the control column; the throttle being positioned on the opposite side to the airbrake control. Before these actions could take effect the aircraft landed heavily in rough grass in the undershoot, approximately 60 metres short of the runway threshold. The landing gear collapsed and the aircraft slid to a halt on its fuselage (Figure 1). The two occupants, who were both wearing 4 point harnesses, were able to vacate the aircraft normally without injury.

The pilot reported that, in the prevailing wind conditions, a three metre high earth bank, located 20 metres short of the runway threshold, may have created an area of sink. Exposure to this sink was exacerbated by the increased time at low level brought about by the shallower than normal approach angle. The aircraft's high aspect ratio wings are particularly susceptible to loss of lift and subsequent sink can occur very rapidly.



Figure 1